

ASS. REC. BY:

REF: CS/SMO 19010880/ Pcd 302 Special Instructions

MURIMAN

Survivor Bryan

ASSIGNMENT (Office)

From (Person): Goh Pau Loung of Sampo Date/Time: 17.6.2019 17:03 p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 75452 Insured: SR 251

at Workshop m/s Channi motor Tel: 654 25119

of BK10 # 01-05/06

Policy No: D17MTPV01002242 Claim No: CMTD 1902896

Sum Insured: Excess:

Make of Veh: D.O.A. 16.6.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 19.6.19 5:00 p.m. Person Contacted: Bryan H.O.D. Endorsement:

Vehicle: IN/OUT


Date/Time	Action/Instruction (✓) Estimate
	SHA 75452 - NA/NA/110100661(2) D.O.A. - 23/05/2011
	SR 251 - X

05/06/19 @ 17:25 pm revised PA to Goh Pau Loung
via muriman.

ASSIGNMENT

COE 2023 May
2015 May

Vehicle No.
Estimated Cost
Date of Inspection
Inspected Vehicle No.
at Workshop no.
at
Insured
Policy No.
Class No.
Time Reported
Client's (Insured)
Make of Veh.



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection

Date of Market Value:
RUC: Accident Report Consistent? Yes or No
CAR: LPR: Consistent? Yes or No
Est. Repair: 108 days Yes Yes or No
Ins. Sum: 20 % 3 Val. Yes or No

GA / REV / HRS / 24 HRS
Date Person Conducted Vehicle: IN / OUT

Vehicle No. **SHA 75452**
Type: M Car / MCycle / Bus / Van / Lorry ☒ Prime Mover
Truck / Trailer or
Make: **Hyundai I40** 1685
Colour: **Blue** AR Insured / Std / HI / HA
Cap/Modeling: **602970** (Also Insured / Std / HI / HA)
Engine: **D4FDFU500573**
CHN: **KMHLB4UMFU069071**
Gen. Cond: Good / Fair / Poor / Damd
Steering: Interd / Jammed / Leaked / Damd or
Brake: Interd / Jammed / Leaked / Damd or
Mud: ☒ SRRin / STD ARin or
Tyre Size: **205/60 R16**
R: **— 11 —**
PS / DUN / EXNOVA / GY / FS / LIZA / MIC / CHTSU / PH / SUMA /
TOYO / YOKO or **Campeon**
Front: **5** mm **5** mm
R/Ral: **5** mm **5** mm
L/Ral: **5** mm **5** mm
D.O.A: **16/06/2019** () **19/06/2019**
Survey held at **Chunni AMK**
Des. of Damages: Frt / Rear / OR / HS / DR / RoofTop or
0/8 Frnt 7 0/8 Body 7 0/8 Rev
The DR / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
Sampo SR25 SR255

17/07/19 Jirayul 2/5 11000/- into 10 days of rev
(85,386.68 Rd - 53%)

RECEIVED 18 JUL 2019

Days Of Repair: **10**
Resurvey No. of Trip: **2**

Date/Time File Para No? ☐ Prel. Report
18/02/19 Typist ☒ Final Report
File/Name File Reference

Add Fee: ☐ Site Insp. (\$) ☐ Interview (\$) ☐ Tech. Insp. (\$) ☐ Workshop (\$)

Report Format
Camp Sum / LUL: **11,000/- 4/5**

Survey Fee	
Transportation	450
5.105.24	11
Phone	
Other	
TOTAL	461

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 25 Jun 2019

Preliminary Advice

Insured Vehicle No	: SR25J	Accident Date	: 16/06/2019
TP Vehicle No	: SHA7545Z	Assignment Date	: 17/06/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 8 days
Date of Inspection	: 19/06/2019		
Inspection At	: Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front & o/s rear portion, o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,306.68
Revised Amount	:S\$	13,779.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,779.56

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jun 2019		17 Jun 2019 17:03 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

KWEE LIONG TEK, ID: S2031111H

Main Claimant:

COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R

Vehicle Reg. No.:

SHA7545Z

Date of Loss:

16/06/2019 09:00 - :59

Claim Type:

TP / CMTD1902896

Policy/Cover Note No.:

D19MTPV01002242 (Comprehensive)

Vehicle Reg. No. (Insured):

SR25J

Policy No. (Claimant):

Excess:

Repairer:

Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016

Handling Insurer:

Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/06/2019]

Adj Asg. Remarks:

WS: Lynn or Irene 6542 5119 or 7162 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

MCD619078555 / ComfortDelGro Engineering Pte Ltd - Loyal
 ENTRY DATE & TIME: 17/06/2019 13:40
 SUBMITTED BY: Janet Lim Siang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/06/2019 13:40
Date Of Accident	16/06/2019 08:25
Exact Location Of Accident	CLUNY RD TWDS NAPIER RD.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7545Z
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	NG SHEE HENG
NRIC No	S1392994G
Date Of Birth	31/08/1959
Occupation	OUTDOOR
Date Of Driving Pass	21/05/1979
Driving Experience	40 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106372
Fax Number	
Contact Number	
Email Address	SHEEHENG@HOTMAIL.COM

Address	BLK 25B JALAN MEMBINA #16-108
Postcode	164025
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) Involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED * TYPE OF ACCIDENT :- HED TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SR25J
Vehicle Make/Model/Colour	MERCEDES
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	LH FRONT
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

16/6/19
Jackson Heng
CSO

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/6/2019 at about 0825 hrs, I vehicle A was driving my taxi along Chunni road toward Napier road. Vehicle B came out from Small lane and cut cross into my lane. brushes against right front door caused the damaged. No one was injured at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

16/6/19
Jackson Heng
CSO

CHUNNI MOTOR WORKS PTE LTD

REPAIR ESTIMATE*

Son, po

VEHICLE NO : SHA 7545Z

DATE : 17.06.2019

MAKE :



TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender (RH) <i>Dented</i>			\$ 663.00	✓
	Front Fender Shield (RH) <i>deformed</i>			\$ 174.90	✓
	Front Door (RH) <i>Dented</i>			\$ 2,256.40	✓
	Front Door Gear / Regulator (RH) <i>RNH</i>			\$ 250.60	✗
	Front Door Hinge Lower (RH) <i>NH</i>			\$ 36.10	✗
	Front Door Check (RH) <i>NH</i>			\$ 39.20	✗
	Front Door Power Motor, RH <i>NH</i>			\$ 296.40	✗
	Door Centre Pillar Outer (RH) <i>Dented</i>			\$ 2,527.80	✓
	Front Windscreen Pillar Outer (RH) <i>✗ Dented</i>			\$ 1,745.50	✓
	Front Windscreen Moulding <i>✗ NH</i>			\$ 113.30	✓
	Front Wheel Rim (RH) <i>✗ deformed</i>			\$ 325.30	✓
	Front Wheel Hub Cap (RH) <i>cut</i>			\$ 107.10	✓
	Front Wheel Bearing <i>✗ Down</i>			\$ 540.50	✓
	Front Shock Absorber (Assy) (RH) <i>✗ deformed</i>			\$ 342.20	✓
	Front Shock Absorber Mounting (RH) <i>NH</i>			\$ 108.80	✗
	STG Tie End <i>✗ deformed</i>			\$ 62.60	✓
	Front Suspension Lower Arm (RH) <i>✗ deformed</i>			\$ 529.30	✓
	Knuckle Arm (RH) <i>✗ deformed</i>			\$ 552.00	✓
			9939.90		
			7951.92		
	SUB TOTAL			\$ 10,671.00	
	LESS 20%			\$ 2,134.20	
	DISCOUNTED TOTAL			\$ 8,536.80	
	Front Fender Advertisement Logo (RH) <i>NH</i>			\$ 100.00	Nett ✓
	Front Door Comfort Logo (RH) <i>NH</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (RH) <i>NH</i>			\$ 100.00	Nett ✓
	Front Tyre (RH) <i>NH</i>			\$ 216.00	Nett ✗
	Front Windscreen Sealant <i>✗ NH</i>		321.00	\$ 46.00	Nett ✓
				\$ 537.00	
	Rear Door (RH) <i>Dented</i>			\$ 2,201.10	✓
	Rocker Panel Outer Garnish (RH) <i>NH</i>			\$ 341.40	✗
	SUB TOTAL			\$ 2,542.50	
	LESS 20%			\$ 508.50	
	DISCOUNTED TOTAL			\$ 2,034.00	
			2201.10		
			1760.88		

SHA 7545Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			S 1,300.00
	Spray Painting Charge			S 1,200.00
	Wiring Charge			S 50.00
	Tuff Kote			S 80.00
	Towing Charge			S 50.00
	Remove/Refix Undercarriage (FRT)			S 100.00
	Transfer of Door		S 50.00	S 100.00
	Fit Wheel Alignment			S 120.00
	TOTAL LABOUR		1860.00	S 3,000.00
	ESTIMATE TOTAL			S 14,107.80
	19/06/2019 @ 1530m		11893.80	16386.68
	H/A Andre	S.P.P	1965.76	
	2/5m 10 days.		13859.56	
			4/811000/-	
	2 KKK Auto			
				
<div><div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance CompanyAcknowledged by Repairer Signature: Date:</div></div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 7545Z (Supplementary)

DATE : 19.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) <i>2 dots</i>			\$ 2,171.40 ✓
	Rear Windscreen Moulding <i>Mac</i>			\$ 28.30 ✓
	Rocker Panel Outer Garnish (RH) <i>HH</i>			\$ 341.40 X
	SUB TOTAL		2199.70	\$ 2,541.10
	LESS 20%		1759.76	\$ 508.22
	DISCOUNTED TOTAL			\$ 2,032.88
	Rear Windscreen Sealant <i>Hec</i>		46.00	\$ 46.00
	Labour Charge			
	Remove/Refix Rear Windscreen Glass		80.00	\$ 120.00 80/-
	TOTAL LABOUR			\$ 120.00
	ESTIMATE TOTAL			\$ 2,198.88
	19/06/2019		1885.76	
	<i>[Signature]</i>			
	<i>JKK Ando</i>			
	<i>[Signature]</i>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 7545Z (Supplementary)



DATE : 24.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Door Comfortdelgro & Apps Sticker <i>hke</i>			S 80.00	Nett ✓
<div> 26/06/2019 Lkk Ando </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 7545 Z

Technician:

Mileage: 602970

Time Printed 19.6.19 4:12 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°56'		-3°00' 3°00'
3°56'		-0°19' 5°41'
0°09'		-1°30' 1°30'
14°07'		
13°11'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°40'		-3°00' 3°00'
4°07'		-0°19' 5°41'
2°27'		-1°30' 1°30'
15°09'		
14°29'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°16'		-3°00' 3°00'
-0°12'		-3°00' 3°00'
-1°02'		-3°00' 3°00'
2°37'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°24'		-3°30' 2°30'
0°07'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°05'		-3°30' 2°30'
-0°02'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°19'		-3°00' 3°00'
0°05'		-3°00' 3°00'
0°05'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19010880/DSD3N2

Date: 23/07/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01002242
Claimant Vehicle No :	SHA7545Z	Insured Vehicle No :	SR25J
Date of Loss:	16/06/2019	Nature of Claim:	TP
		Claim No:	CMTD1902896

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7545Z		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4DFDU500573
Reg. Date:	14/05/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMFU069071
Colour:	Blue	Odometer:	602970 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Campeon 5 mm	Rear Left Side:	Campeon 5 mm
Front Right Side:	Campeon 5 mm	Rear Right Side:	Campeon 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,266.68	11,919.56	1,347.12	10.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,940.00	1,180.00	37.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,386.68	13,859.56	2,527.12	15.42
Approved Total (Overridden) (\$\$)		11,000.00		
(\$\$)	16,386.68	11,000.00	5,386.68	32.87
+ GST 7.00/7.00% (\$\$)	1,147.07	770.00	377.07	32.87
Nett Amount (\$\$)	17,533.75	11,770.00	5,763.75	32.87

INSPECTION

Date of Assignment:	17/06/2019	
Date Inspected:	19/06/2019	Inspected At: Chundi Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	10.0 days	

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2019)
Parts: 143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7545Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER (RH)	Dented	663.00 FL	*663.00 FL
2	1	*FRONT FENDER SHIELD (RH)	Deformed	174.90 FL	*174.90 FL
3	1	*FRONT DOOR (RH)	Dented	2,256.40 FL	*2,256.40 FL
4	1	*FRONT DOOR GEAR/REGULATOR (RH)	Not Necessary	250.60 FL	*- FL
5	1	*FRONT DOOR HINGE LOWER (RH)	Not Necessary	36.10 FL	*- FL
6	1	*FRONT DOOR CHECK (RH)	Not Necessary	39.20 FL	*- FL
7	1	*FRONT DOOR POWER MOTOR,RH	Not Necessary	296.40 FL	*- FL
8	1	*DOOR CENTRE PILLAR OUTER (RH)	Dented	2,527.80 FL	*2,527.80 FL
9	1	*FRONT WINDSCREEN PILLAR OUTER (RH)	Dented	1,745.50 FL	*1,745.50 FL
10	1	*FRONT WINDSCREEN MOULDING	Necessary	113.30 FL	*113.30 FL
11	1	*FRONT WHEEL RIM (RH)	Distorted	325.30 FL	*325.30 FL
12	1	*FRONT WHEEL HUB CAP (RH)	Cut	107.10 FL	*107.10 FL
13	1	*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
14	1	*FRONT SHOCK ABSORBER (ASSY)(RH)	Distorted	342.20 FL	*342.20 FL
15	1	*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	108.80 FL	*- FL
16	1	*STG TIE END	Distorted	62.60 FL	*62.60 FL
17	1	*FRONT SUSPENSION LOWER ARM (RH)	Distorted	529.30 FL	*529.30 FL
18	1	*KNUCKLE ARM (RH)	Distorted	552.00 FL	*552.00 FL
19	1	*REAR FENDER (RH)	Dented	2,171.40 FL	*2,171.40 FL
20	1	*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
21	1	*ROCKER PANEL OUTER GARNISH (RH)	Not Necessary	341.40 FL	*- FL
22	1	*FRONT FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
23	1	*FRONT DOOR COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
24	1	*FRONT DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
25	1	*FRONT TYRE (RH)	Not Necessary	216.00 FS	*- FS
26	1	*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
27	1	*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
28	1	*REAR DOOR RH	Dented	2,201.10 FL	*2,201.10 FL
29	1	*ROCKER PANEL OUTER GARNISH (RH)	Not Necessary	341.40 FL	*- FL
30	1	*REAR DOOR COMFORTDELGRO & APPS STICKER	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNetl. L=ListItemDisc.

Sub Total (\$\$)	16,417.60	14,787.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,150.92	2,868.14
Total Parts (\$\$)	13,266.68	11,919.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,300.00	800.00
2	SPRAY PAINTING CHARGE	New	1,200.00	800.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	80.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	100.00	80.00
7	TRANSFER OF DOOR	New	100.00	80.00
8	FRT WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
Gross Labour Cost (\$\$)			3,120.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >