

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 7545Z (Supplementary)



DATE : 19.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) <i>Deduct</i>			\$ 2,171.40 ✓
	Rear Windscreen Moulding <i>NOC</i>			\$ 28.30 ✓
	Rocker Panel Outer Garnish (RH) <i>HH</i>			\$ 341.40 X
	SUB TOTAL		<i>2199.70</i>	\$ 2,541.10
	LESS 20%		<i>1759.76</i>	\$ 508.22
	DISCOUNTED TOTAL			\$ 2,032.88
	 Rear Windscreen Sealant <i>HCC</i>		<i>46.00</i>	\$ 46.00 Net ✓
	 Labour Charge			
	Remove/Refix Rear Windscreen Glass		<i>80.00</i>	\$ 120.00 80/-
	TOTAL LABOUR			\$ 120.00
	ESTIMATE TOTAL			\$ 2,198.88
	 <i>19/06/2019</i>  <i>JKK And</i> 		<i>1885.76</i>	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 7545Z (Supplementary)



DATE : 24.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Door Comfortdelgro & Apps Sticker <i>nlc</i>			\$ 80.00	Nett ✓
<div> 26/06/2019 Jkk Ando </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					