

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5023K**AAD1906-150***Not Authorised*
1/1 Sep @ 7700

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 5023K

VF1ABL15AUC276779

RENAULT

LATITUDE

14.6.19

AXA

14/1/2014

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	—
2	1	BUMPER LOWER REAR	\$	<i>nd/ln</i> 768.84	—
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	} X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	}
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	
10	1	BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	—
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Bu</i> 225.95	—
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Bu</i> 225.95	—
13	1	BOOT REAR	\$	<i>Bu</i> 2,872.68	—
14	1	BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
18	1	BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36	—
19	1	BOOT BADGE	\$	<i>SL</i> 225.36	—
20	1	BOOT STRUT LH	\$	<i>SL</i> 276.08	} X
21	1	BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>SL</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>SL</i> 367.84	
24	1	BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1	BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1	BOOT LOCK	\$	<i>SL</i> 202.67	
27	1	BOOT LOCK CATCH	\$	<i>SL</i> 74.40	}
28	2	LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2	BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1906-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5023K

30	1	TAILLAMP RH	\$	SL	552.55	X
31	1	TAILLAMP PANEL RH	\$	n	986.70	X
32	1	TAILLAMP LH	\$	SL	552.55	X
33	1	TAILLAMP PANEL LH	\$	n	986.70	X
34	1	OUTER PANEL REAR (End Panel)	\$	B	1,471.77	—
35	1	OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	—
36	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	n	2,189.88	X
37	1	SPARE WHEEL PANEL TRIM	\$	SL	612.21	X
38	1	EXHAUST REAR	\$	n	7,489.05	X
39	1	EXHAUST CAP REAR	\$	n	230.49	X
TOTAL			\$		26,840.83	
10%			\$		2,684.08	
			\$		24,156.75	

Special Nett

1	1SET	PARKING AID	\$	Phan	700.00	400Jm
2	1SET	REAR BUMPER CLIP	\$	n	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	n	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	n	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	n	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	n	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	n	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	n	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	n	66.00	—
10	1	EXHAUST MOUNTING REAR	\$	SL	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	n	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	n	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	n	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	n	45.00	} X
15	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	SL	385.00	
16	1	SPARE TYRE	\$	SL	330.00	
17	2	REAR WINDSCREEN SEALANT	\$	n	80.00	
18	1	WINDSCREEN MOULDING	\$	n	100.00	
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	n	100.00	
20	1	TAILLAMP CLIP RH	\$	n	5.00	
21	1	TAILLAMP CLIP LH	\$	n	5.00	
22	1	Rear left tyre	\$	SL	330.00	}
23	1	Rear left tyre rim	\$	SL	380.00	

Trans-cab Auto Services Pte Ltd**AAD1906-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5023K

24	1	Rear right tyre	\$	330.00	X
25	1	Rear right tyre rim	\$	380.00	X
TOTAL			\$	3,519.02	

TOTAL PARTS	\$	27,675.77
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	6601
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	nn X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	6601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	nn X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	6601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To Rust-Proofing Of The Affected Areas.	\$	170.00	6601
To repair and realign rear exhaust pipe.	\$	170.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To reinstall rear bumper parking sensor.	\$	170.00	6601

Trans-cab Auto Services Pte Ltd**AAD1906-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5023K

To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i> 380.00	X
TOTAL	\$	15,440.00	
Over All Total	\$	43,115.77	

(LUMP SUM) Repair Days**~~20 DAYS~~***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: