

22/03/2019

ASS. REC. BY:

REF: CS/PC/19610882/R1+d3n2

Special Instruction:

Surveyor: Rasu

## ASSIGNMENT (Office)

From (Person): Man chua

of PC1

Date/Time: 19.6.19 5.17 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJP 4711C

Insured: SHC 3710 D

at Workshop m/s Asia Motorsports

Tel: 67453211

of 15 Kati Bukit Road 4 #01-53

Policy No:

Claim No: D19003985MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 17.6.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 19.6.2019 5.10 p.m

Person Contacted:

LOO

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJP 4711C - CS3/AXA 12023174/Vtd1 DCA-17/10/2012
	SHC 3710 D - NS1/NC 15002330/H1+bd1 DCA-04/07/2015
24/6@10:07AM	Revised via preli advise.
	lump sum \$4700/- (Red: 4687.08! 49%)

## ASSIGNMENT

From: Date: 20.6.2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJP 4711C

at Workshop m/s Asia Motorsports

of 15 Kaki Bukit Road 4 #01-53

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

30K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SJP 4711C

Yr Regn: 2009 / MAR

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA VIOS G AUTO

C.C. 1497

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading:

108977

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053449305106114

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

17/06/19

D.O.I.

20/06/19

Survey held at

ASIA MOTORSPORTS

Des. of Damages: Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 01 AUG 2019

MV: 30000/-  
 LTA: 12,152  
 NV: 17848

Date/Time, File Pass to?

1) 30/7 Typist

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I.: (\$ 4700/-)

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

170

Transportation:

50

S + RS, SI

50

Photos

74

Others

TOTAL

344



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003985MFSH

Date: 24/06/2019

Our Ref: CS/FCI19010882/R1td3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJP 4711C

Please be informed that we had conducted the inspection of the abovementioned vehicle 20/06/2019 at the premises of M/s Asia Motorsports have the following to report: -

Workshop Estimate Amount	: S\$ 9,387.08
Revised Estimate Amount	: S\$ 6,604.54
"Check" Items Amount	: S\$ 235.50
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the  
Rear O/S portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Rasul

Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	18-06-2019	<b>Our Ref No.</b> D19003985MFSH
<b>Accident Date</b>	17-06-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC3710D	<b>Third Party Vehicle.</b> SJP4711C
<b>Survey Location</b>	37A EVERITT ROAD	
<b>Contact Person.</b>	NA	
<b>Contact No.</b>	67453811/0	<b>Fax No.</b> 67465110
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	ASIA MOTORSPORTS SOLUTION PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Denise Tay (LKKAUTO)

---

**From:** Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>  
**Sent:** Monday, 29 July 2019 4:33 PM  
**To:** Rasul (LKKAUTO)  
**Subject:** Re: (Gentle Reminder) SJP 4711 C Estimate

**PROPERTY CLAIM  
(WITHOUT PREJUDICE  
TO: Any Personal Injury  
Claims)**

Hi Mr Rasul,

We are pleased to inform you that we are agreeable to your proposed lump sum repair of \$4,700.00 at 8 working days for SJP 4711 C .

In the meantime, please note that **with effect from 1<sup>st</sup> June 2019**, we have shifted to and are now operating from the following address:

**37A Everitt Road  
Singapore 428586**

**Please update your records accordingly** and send all future correspondence to the new address above.

Thank you and we hope to hear from you soon.

Regards,  
Asia Motorsports Solution Pte Ltd  
6745 3811  
6746 5110 (fax)  
[asiamotorsports@hotmail.com](mailto:asiamotorsports@hotmail.com)

---

**From:** Rasul (LKKAUTO) <Rasul@lkkauto.com>  
**Sent:** Thursday, July 25, 2019 9:45 AM  
**To:** Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>  
**Subject:** RE: (Gentle Reminder) SJP 4711 C Estimate

Hi,

Kindly refer to attachment  
Parts prices on your estimate is a little bit high need to be reduce  
Finalised amount is \$ 4,700 / 8 days lump sum  
Kindly confirm

Best Regards,  
**Rasul** | Assessor

## Denise Tay (LKKAUTO)

---

**From:** Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>  
**Sent:** Tuesday, 16 July 2019 3:19 PM  
**To:** Rasul (LKKAUTO)  
**Subject:** SJP 4711 C Estimate  
**Attachments:** SJP4711C\_marked\_estimate\_page1.jpg; SJP4711C\_marked\_estimate\_page2.jpg;  
SJP4711C\_pic1.jpg; SJP4711C\_pic2.jpg; SJP4711C\_pic3.jpg; SJP4711C\_pic4.jpg;  
SJP4711C\_pic5.jpg; SJP4711C\_pic6.jpg; SJP4711C\_pic7.jpg

**PROPERTY CLAIM  
(WITHOUT PREJUDICE  
TO: Any Personal Injury  
Claims)**

Hi Mr Rasul,

Attached is an image of your marked estimate for SJP 4711 C.

We look forward to your proposed lump sum repair cost and your recommended days of repair

In the meantime, please note that **with effect from 1<sup>st</sup> June 2019**, we have shifted to and are now operating from the following address:

**37A Everitt Road  
Singapore 428586**

Please update your records accordingly and send all future correspondence to the new address above.

Thank you and we hope to hear from you soon.

Regards,  
Asia Motorsports Solution Pte Ltd  
6745 3811  
6746 5110 (fax)  
[asiamotorsports@hotmail.com](mailto:asiamotorsports@hotmail.com)

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 24 June 2019 10:07 AM  
**To:** Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR  
**Cc:** 'May Chua Hui Chin'  
**Subject:** RE: SURVEY ASSESSMENT - D19003985MFSH/1  
**Attachments:** PRELI ADVISED SJP 4711C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJP 4711C**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 19 June 2019 5:21 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'May Chua Hui Chin' <[maychua@msfirstcapital.com.sg](mailto:maychua@msfirstcapital.com.sg)>  
**Subject:** RE: SURVEY ASSESSMENT - D19003985MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 19 June, 2019 5:17 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; May Chua Hui Chin <[maychua@msfirstcapital.com.sg](mailto:maychua@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19003985MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6215J
Vehicle Details	
Vehicle No.:	SJP4711C
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1NZX884059
Chassis No.:	MR053HY9305106114
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,472.00
Original Registration Date:	26 Mar 2009
First Registration Date:	26 Mar 2009
Transfer Count:	3
Actual ARF Paid:	\$10,731.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$12,152.00
Total Rebate Amount:	\$12,152.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Jun 2019

OK

30,000  
12152  

---

17,848



VEHICLE NO SJP 4711C TOYOTA VIOS

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	Rear bumper <i>de</i>		981.00	480
1	Rear bumper side retainers <i>RH-LH XSV</i>		130.50	47
1	Rear bumper reflector RHS <i>CR</i>		128.00	85
1	Rear bootlid <i>bt</i>		979.50	655
2	Rear bootlid hinges @49.20 <i>XSV</i>		98.40	X
1	Rear boot edge weatherstrip <i>cd</i>		264.00	184
1	Rear bootlid inner lock <i>cd</i>		238.00	100
1	Rear bootlid lock catch <i>bt</i>		87.00	50
1	Rear bootlid Toyota badge <i>na</i>		72.00	48
1	Rear bootlid Vios emblem <i>na</i>		67.50	50
1	Rear bootlid G emblem <i>na</i>		24.00	—
1	Rear bootlid insulator <i>XSV</i>		242.00	X
2	Rear bootlid rubber stopper @32.40 <i>na</i>		64.80	36
1	Rear bootlid centre chrome moulding <i>XSV</i>		278.00	X
1	RHS Taillamp ? <i>CR</i>		672.40	370
1	RHS Rear fender <i>report bt</i>		789.00	—
1	Rear exhaust silencer assembly <i>bt</i>		650.00	—
2	Rear exhaust silencer assembly mountings <i>na</i>		98.00	—
1	Rear end panel <i>bt</i> (photo)		978.00	690
1	Rear end panel outer bracket LHS ? <i>XAN</i>		72.00	—
1	Rear end panel top garnish ? <i>de</i>		242.00	185
			7156.10	
			25% 1789.02	25%
			5367.08	
<b>SPECIAL NETT ITEMS</b>				
1	Reverse sensor <i>na</i>		280.00	220
1	Rear end panel sealant <i>na</i>		100.00	60
1set	Rear bootlid insulator clips <i>na</i>		60.00	40
1	Rear windscreen sealant <i>na</i>		100.00	60
1set	Rear bumper clips <i>na</i>		60.00	40
1set	Rear end panel top garnish clips <i>na</i>		60.00	40
TOTAL PARTS			6027.08	

4541

25%

3405.75 less

460

VEHICLE NO SJP 4711C TOYOTA VIOS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas; replace the damaged parts and components.	<del>1400.00</del> 800	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	<del>1000.00</del> 800	
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	<del>150.00</del> 30	
4	To remove rear fittings, garnish, trimmings etc so as to facilitate repairs at rear	<del>150.00</del> 60	2030
5	To remove and replace rear exhaust silencer assembly and check for proper system function	<del>250.00</del> 80	
6	To remove and refix rear windscreen	<del>140.00</del> 120	
7	To remove and replace reverse sensors and check for proper function	<del>120.00</del> 60	
8	To provide anti-rust treatment on affected areas	<del>150.00</del> 80	
	Labour Total :	3360.00	
	TOTAL (PARTS & LABOUR):	9387.08	

**NOTE:** The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*[Signature]*  
24/6/19

Rasu

Hp 90010068

8 days

4/3

20/06/19 @ 1015

Resurvey after repair

3405.75

460.00

2030.00

5895.75

20%

4716.60

4/3

4,700

8 days




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010882/R1td3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-08-2019		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 3710D	Veh. Inspected	SJP 4711C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003985MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	19/06/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VIOS G AUTO	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053HY9305106114	Colour	GREY	
Odometer	108977	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	GOODYEAR	5 mm	
L/H Front Tyre	185/60 R15	GOODYEAR	5 mm	
R/H Rear Tyre	185/60 R15	GOODYEAR	5 mm	
L/H Rear Tyre	185/60 R15	GOODYEAR	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/06/2019	Inspection Date	20/06/2019	
Survey held at	15 KAKI BUKIT RD 4 #01-53			
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 4711C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	981.00	480.00
2	REAR BUMPER SIDE RETAINERS	O/S NECESSARY / N/S SERVICEABLE	130.50	47.00
1	REAR BUMPER REFLECTOR RHS	CRACKED	128.00	85.00
1	REAR BOOTLID	BENT	979.50	655.00
2	REAR BOOTLID HINGES @\$49.20	SERVICEABLE	98.40	-
1	REAR BOOT EDGE WEATHERSTRIP	CUT	264.00	184.00
1	REAR BOOTLID INNER LOCK	CUT	238.00	100.00
1	REAR BOOTLID LOCK CATCH	BENT	87.00	50.00
1	REAR BOOTLID TOYOTA BADGE	NECESSARY	72.00	48.00
1	REAR BOOTLID VIOS EMBLEM	NECESSARY	67.50	50.00
1	REAR BOOTLID G EMBLEM	NECESSARY	24.00	24.00
1	REAR BOOTLID INSULATOR	SERVICEABLE	242.00	-
2	REAR BOOTLID RUBBER STOPPER @\$32.40	NECESSARY	64.80	36.00
1	REAR BOOTLID CENTRE CHROME MOULDING	SERVICEABLE	278.00	-
1	RHS TAILLAMP	CRACKED	672.40	370.00
1	RHS REAR FENDER	BENT	789.00	789.00
1	REAR EXHAUST SILENCER ASSEMBLY	BENT	650.00	650.00
2	REAR EXHAUST SILENCER ASSEMBLY MOUNTINGS	NECESSARY	98.00	98.00
1	REAR END PANEL	BENT	978.00	690.00
1	REAR END PANEL OUTER BRACKET LHS	NOT NECESSARY	72.00	-
1	REAR END PANEL TOP GARNISH	DEFORMED	242.00	185.00
	LESS 25% DISCOUNT		-1,789.03	-1,135.25
			5,367.07	3,405.75
<b>SPECIAL NETT ITEMS</b>				
1	REVERSE SENSOR (SN)	NOT WORKING	280.00	220.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	60.00
1	SET REAR BOOTLID INSULATOR CLIPS (SN)	NECESSARY	60.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	40.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	60.00	40.00
			660.00	460.00
	<b>LABOUR</b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS; REPLACE THE DAMAGED PARTS AND COMPONENTS.		1,400.00	800.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS.		1,000.00	800.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		150.00	30.00
	TO REMOVE REAR FITTINGS, GARNISH, TRIMMINGS ETC SO AS TO FACILITATE REPAIRS AT REAR.		150.00	60.00
	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ASSEMBLY AND CHECK FOR PROPER SYSTEM FUNCTION.		250.00	80.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		140.00	120.00
	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION.		120.00	60.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.		150.00	80.00
			3,360.00	2,030.00
<b>GRAND TOTAL</b>			<b>9,387.07</b>	<b>5,895.75</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,700.00</b>

Report Ref No. CS/FCI19010882/R1td3n2

MARKET VALUE: \$30,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$12,152.00=NETT VALUE: \$17,848.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.