

ORTDELGRO ENGINEERING PTE LTD

IR ESTIMATE*

VEHICLE NO : SHC 8219Z

DATE 18/6/2019 14:37

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid — <i>But</i>			\$ 2,480.40
	Boot Lid Lock Upper <i>X sm</i>			\$ 224.00
	Boot Lid 'H' Emblem <i>X sm</i>			\$ 28.00
	Emblem -Hybrid — <i>new</i>			\$ 24.30
	Emblem -Ioniq — <i>new</i>			\$ 31.30
	Rear Bumper <i>X 14.2</i>			\$ 459.40
	Rear Bumper Reinforcement <i>X sm</i>			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X sm</i>		\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy — <i>cm</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>X sm</i>			\$ 47.50
	Rear Bumper Stay <i>X sm</i>			\$ 138.10
	Rear Bumper Side Bracket (RH) <i>X sm</i>			\$ 33.10
	Rear Bumper Cover Clips <i>+ 4</i>			\$ 22.00
	SUB TOTAL			\$ 4,510.35
	LESS 20%			\$ 902.07
	DISCOUNTED TOTAL			\$ 3,608.28
	Boot Lid Comfort Logo Sticker — <i>new</i>			\$ 30.00
	Boot Lid Tel No.Sticker — <i>new</i>			\$ 30.00
	Rear Bumper Reverse Sensor — <i>new</i>			\$ 135.70
	<i>Windscreen scratch</i>			<i>\$ 46</i>
	<i>Rear Number Plate</i>			<i>\$ 25</i>
	Acknowledged by Repairer			\$ 195.70
	Signature:			
	Date:			
	<i>Kohi 10/10/19</i>			
	<i>18/6/19 1525L</i>			
	<i>3 Days</i>			
	<i>PIP</i>			
	<i>Before Paint p/b</i>			
	Labour Charge			\$ 300
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	<i>Remove/Refix rear sensor</i>			<i>\$ 30</i>
	TOTAL LABOUR			\$ 1,370.00
	ESTIMATE TOTAL			\$ 5,173.98

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.