

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8219Z

DATE 18/6/2019 14:37

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 2,480.40
	Boot Lid Lock Upper ✕			\$ 224.00
	Boot Lid 'H' Emblem ✕			\$ 28.00
	Emblem -Hybrid ✓			\$ 24.30
	Emblem -Ioniq ✓			\$ 31.30
	Rear Bumper ✕ 14.2			\$ 459.40
	Rear Bumper Reinforcement ?			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy ✓			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy ✕			\$ 47.50
	Rear Bumper Stay ?			\$ 138.10
	Rear Bumper Side Bracket (RH)?			\$ 33.10
	Rear Bumper Cover Clips ✓			\$ 22.00
	SUB TOTAL			\$ 4,510.35
	LESS 20%			\$ 902.07
	DISCOUNTED TOTAL			\$ 3,608.28
	Boot Lid Comfort Logo Sticker ✓			\$ 30.00 Nett
	Boot Lid Tel No.Sticker ✓			\$ 30.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
				\$ 195.70
	Labour Charge			
	Panel Beating			\$ 400.00 300
	Spray Painting Charge			\$ 600.00 400
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 X
	Remove/Refix Rear Windscreen Glass			\$ 120.00 100
	TOTAL LABOUR			\$ 1,370.00
	ESTIMATE TOTAL			\$ 5,173.98
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kohi 10/06/19

18/6/19 1525L

3 Days

P/P

Before Paint pls