

ALG-LKC 30/9/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLG 3456 U

Parts	(a) Cost / List Price Items	\$	5,226.84
	Plus/Less 25%	\$	1,306.71
	Total of Cost / List	\$	3,920.13
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	3,920.13
Labour		\$	1,400.00
Total		\$	5,320.13

The above total will be subjected to 7% G.S.T.

Not Authorized
Resurvey Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 30/9/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : L Date: 30/9/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLG 3456 U**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU303535014**

Submit By : **JENNY**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper Bu	1	\$450.80		✓
2	Front bumper clip nu	10	\$40.00		✓
3	Front bumper side retainer LH su	1	\$107.20		X
4	Front bumper side retainer RH su	1	\$107.20		X
5	RH front fender R	1	\$868.70		X
6	RH front fender undershield su	1	\$185.64		X
7	RH front fender undershield clip nu	10	\$25.00		X
8	Headlamp RH su	1	\$2,531.60		X
9	Fog lamp RH su	1	\$910.70		X
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

