

INS. CASE OWNER: Irene | CC 6/CT11901 0892, K db3n2 | LOR: IDAC:

Surveyor: lcg | DOI: 26/6/19 | Date / Time: 12/6/19 | Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: sup 9342e
Name of Insured: DON TAY KUAN UROH
Insured Tel No.: HP: 13/6/19
Excess Sec II :SS D.O.A:
Is driver the owner? (YES / NO) Nature of Accident :

Claim No.: SWM190 WKS65
Policy No.: SMPLES H 2624661901
Make / Model: Rnd 1
Place of Accident: TRAFFIC JUNG OF JLN BAHAR

If NO, Driver Name / Age : OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel No. : (V/L: YES / NO) Insured Liability : % Final ? Yes / No

SMJ 427X



INSRS:
WSP:
Tel :
Liability:
RMKS: lim tan



INSRS:
WSP:
Tel :
Liability:
RMKS:



INSRS:
WSP:
Tel :
Liability:
RMKS:



INSRS:
WSP:
Tel :
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
22/7/19	Call OI:	> 25/6/19 no response
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	UTA / GIA :	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: SS (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 10/11/19 Confirm with Mandy Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Ltr:

Repair Cost: (w/631) SS 3094.58

Loss of Rental (LOR): SS - (days)

Loss of Use (LOU): SS 200.00 (\$ 50 x 4 days)

Loss of Income (LOI): SS - (\$ x days)

LOI only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search SS 7.45

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -

Total: SS 3302.03 Global Sum SS:

FINAL PAYMENT Date/Time: Confirm with: Confirm by:

Payee 1: SS 3302.03 Name 1: Lim Tan Motor Pte Ltd

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTI19010892/Kdb3

Date: 27.06.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SMJ427X

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.06.2019 at the premises of M/s Lim Tan Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,303.28
Revised Estimate Amount	: S\$	2,892.13
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 6409I

Vehicle Details

Vehicle No.: SMJ427X
Vehicle to be Exported: No
Intended Deregistration Date: 26 Jun 2019
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 STANDARD (AUTO)
Primary Colour: Silver
Manufacturing Year: 2019
Engine No.: 1ZR0D06144
Chassis No.: MR053REH604595957
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$19,741.00
Original Registration Date: 20 Feb 2019
First Registration Date: 20 Feb 2019
Transfer Count: 0
Actual ARF Paid: \$19,741.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Feb 2029
PARF Rebate Amount: \$14,805.00

Intended COE Rebate Details

COE Expiry Date: 19 Feb 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$26,170.00
COE Rebate Amount: \$25,262.00
Total Rebate Amount: \$40,067.00

The information contained herein is correct as at 26 Jun 2019

OK

Not Authorized

276

Presumy Bepaint

4- day

Q 2892.13

**ESTIMATE TO REPAIR**

VEHICLE NO. : SMJ 427 X
 MAKE : TOYOTA
 MODEL : COROLLA ALTIS 1.8 STANDARD AUTO
 YEAR : 2019
 CHASSIS NO : MR053REH604595957

SURVEYOR NAME : Kenneth (LKK)
 DATE OF SURVEY : 26th June 2019
 TIME OF SURVEY :

DATE : 19-Jun-19
 DATE OF ACCIDENT : 17-Jun-19
 THIRD PARTY REF : SLP 9342 C / CHINA TAIPING

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ Bu 486.50
2 pcs	Rear Bumper Retainer		\$ 88.50		\$ In 177.00
1 pc	Rear Bumper Reinforcement				\$ Bt 386.60
1 pc	Rear End Panel				\$ K 789.70
1 pc	Rear End Panel Garnish				\$ In 189.20
1 pc	Rear Boot Lid				\$ Bt 784.60
1 pc	Rear Boot Lock				\$ Net 458.70
1 pc	Rear Boot Rubber				\$ In 85.64
1 pc	Rear Boot Centre Emblem				\$ Net 58.70
1 pc	Rear Boot COROLLA Emblem				\$ Net 88.50
1 pc	Rear Boot ALTIS Emblem				\$ Net 85.90
					\$ 3,591.04
	Less 25%				\$ 897.76
					\$ 2,693.28
1 set	Rear Bumper Sensor	S.Nett			\$ In 200.00
	To putty and spray painting				\$ 700.00
	To anti-rust				\$ 80.00
	To check rear wiring and water leakage				\$ 30.00
	Labour charges				\$ 600.00
TG/RA-	Total				\$ 4,303.28

LKK Auto Consultants hence notify the Repairer of the following:

- To inform labourer spray painting
- To display damaged part during warranty
- To pay prices are subject to confirmation
- To carry survey in govt official registered area
- No any of weathering is allowed
- Supplementary claim must be reviewed and accepted to final approval from insurance company

Authorized by Repairer

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@lTM.sg

Website: www.LTM.sg

Co Reg No.109307277D

GST Reg No.M2-0019088-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI19010892/Kdb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 20-11-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLP 9342C	Veh. Inspected	SMJ 427X
	Policy No.	DMPCSN30625661901	Coverage (\$)	0.00
	Claim No.	SNM19D202865C02	Excess (\$)	0.00
	Assign From		Assign Date	26/06/2019
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MR053REH604595957	Colour	METALLIC SILVER
	Odometer	8477	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R15	DUNLOP	9 mm
	L/H Front Tyre	205/55 R15	DUNLOP	9 mm
	R/H Rear Tyre	205/55 R15	DUNLOP	9 mm
	L/H Rear Tyre	205/55 R15	DUNLOP	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/06/2019	Inspection Date	26/06/2019
	Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 427X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	486.50	486.50
2	REAR BUMPER RETAINER @\$88.50	SERVICEABLE	177.00	-
1	REAR BUMPER REINFORCEMENT	BENT	386.60	386.60
1	REAR END PANEL	TO REPAIR SEE LABOUR	789.70	-
1	REAR END PANEL GARNISH	SERVICEABLE	189.20	-
1	REAR BOOT LID	BENT	784.60	784.60
1	REAR BOOT LOCK	DENTED	458.70	458.70
1	REAR BOOT RUBBER	SERVICEABLE	85.64	-
1	REAR BOOT CENTRE EMBLEM	NECESSARY	58.70	58.70
1	REAR BOOT COROLLA EMBLEM	NECESSARY	88.50	88.50
1	REAR BOOT ALTIS EMBLEM	NECESSARY	85.90	85.90
	LESS 25% DISCOUNT		-897.76	-587.37
			2,693.28	1,762.13
SPECIAL NETT ITEMS				
1	SET REAR BUMPER SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
LABOUR				
	TO PUTTY AND SPRAY PAINTING .		700.00	600.00
	TO ANTI-RUST .		80.00	30.00
	TO CHECK REAR WIRING AND WATER LEAKAGE.		30.00	20.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		600.00	480.00
			1,410.00	1,130.00
GRAND TOTAL			4,303.28	2,892.13
RECOMMENDED COST OF REPAIRS				2,892.13

Report Ref No. CC6/CTI19010892/Kdb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.