

Not Authorized

278

Resurvey Bepaint

4- day

2892.13



ESTIMATE TO REPAIR

VEHICLE NO. : SMJ 427 X
MAKE : TOYOTA
MODEL : COROLLA ALTIS 1.6 STANDARD AUTO
YEAR : 2019
CHASSIS NO : MR053REH604595957

SURVEYOR NAME : Kenneth (LKK)
DATE OF SURVEY : 26th June 2019
TIME OF SURVEY :

DATE : 19-Jun-19
DATE OF ACCIDENT : 17-Jun-19
THIRD PARTY REF : SLP 9342 C / CHINA TAIPING

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ Bu 486.50 ✓
2 pcs	Rear Bumper Retainer		\$ 88.50		\$ In 177.00 ✓
1 pc	Rear Bumper Reinforcement				\$ Bu 386.60 ✓
1 pc	Rear End Panel				\$ B 789.70 ✓
1 pc	Rear End Panel Garnish				\$ In 189.20 ✓
1 pc	Rear Boot Lid				\$ Bu 784.60 ✓
1 pc	Rear Boot Lock				\$ Net 458.70 ✓
1 pc	Rear Boot Rubber				\$ In 85.64 x
1 pc	Rear Boot Centre Emblem				\$ Net 58.70 ✓
1 pc	Rear Boot COROLLA Emblem				\$ Net 88.50 ✓
1 pc	Rear Boot ALTIS Emblem				\$ Net 85.90 ✓
					\$ 3,591.04
	Less 25%				\$ 897.76
					\$ 2,693.28
1 set	Rear Bumper Sensor	S.Nett			\$ In 200.00 X
	To putty and spray painting				\$ 700.00 600
	To anti-rust				\$ 80.00 30
	To check rear wiring and water leakage				\$ 30.00 20
	Labour charges				\$ 600.00 480
TG/RA-	Total				\$ 4,303.28

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd