



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2003626
INV Date 04/05/2020
Reference CC4/EQI19010894/Ups3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SBL 9889G
Insured Veh. FBJ 9124R
Claim No. DM19HO01717-JG
Policy No.
Accident Date 14/06/2019
Inspection Date 01/07/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI19010894/Ups3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 04-05-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBJ 9124R	Veh. Inspected	SBL 9889G
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM19HO01717-JG	Excess (\$)	0.00
	Assign From	JOEL	Assign Date	19/06/2019
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A3 (A)	c.c	999
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WAUZZZ8V6H1068789	Colour	GREY
	Odometer	38059	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	GOODYEAR	7 mm
	L/H Front Tyre	205/55 R16	GOODYEAR	7 mm
	R/H Rear Tyre	205/55 R16	GOODYEAR	7 mm
	L/H Rear Tyre	205/55 R16	GOODYEAR	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/06/2019	Inspection Date	01/07/2019
	Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBL 9889G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER LH	BADLY DENTED/ BUCKLED	1,789.45	1,560.12
1	REAR TAILLAMP N/S	CRACKED	627.25	627.25
1	REAR BUMPER	DEEP CUT	1,403.55	1,403.55
1	REAR BUMPER RETAINER LH	NOT NECESSARY	47.25	-
1	REVERSE SENSOR	NOT NECESSARY	208.85	-
1	TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	149.50	-
1	REAR FENDER INNER SHIELD LH	NOT NECESSARY	177.25	-
1	REAR FENDER QUARTER GLASS LH	NOT NECESSARY	402.65	-
	LESS 5% DISCOUNT		-	-179.55
			4,805.75	3,411.37
	<u>SPECIAL NETT ITEMS</u>			
2	WINDSCREEN SEALANT @\$24.00 (SN)	NECESSARY	48.00	40.00
			48.00	40.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL LH.		1,500.00	800.00
	SPRAY PAINT ON THE AFFECTED AREAS.		900.00	600.00
	ANTI RUST COATING.		200.00	30.00
	WIRING.		40.00	20.00
	TO REMOVE &REFIT WINDSCREEN.		180.00	120.00
	TO REMOVE & REFIT CUSHION & UPHOLSTERY.		250.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR .		150.00	50.00
			-	-
			-	-
			-	-
			3,220.00	1,700.00
	GRAND TOTAL		8,073.75	5,151.37



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,100.00
---	--	--	----------

Report Ref No. CC4/EQ19010894/Ups3q2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBL 9889G

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

