



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLE7778A

Tan Boon Khung
32 Verde View
Singapore 688670

Mobile: 96738613

Vehicle & Document Information

WIP No 34352
Reg No/Reg Date SLE7778A / 27/02/2017
Date In/Mileage / 0
Chassis No WDC2533462F178881
Engine No 27492030881622
Make/Model MB/MB GLC 250 4MATIC COUPE (C253)
Colour/Trim 028 890 Cavansite B/ 041 101 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator				
CSI00001	Cash	18/06/2019/ 17:59	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : DMPCSN3004911900 // 17-6-2019								
DRIVE IN/TP VEH NUMBER : 18-6-2019 // SMK1036D - AXA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES								
RESPRAY REAR BUMPER								
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT							0.10	380.00
A BPILAB								
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT								120.00
M REAR BUMPER	der				1.00	1230.14	00.00	1230.14
M REAR LEFT SIDE BUMPER BRACKET	? XSVL				1.00	131.62	00.00	131.62
M LH BASIC MOUNTING FOR BUMPER	? XSVL				1.00	97.23	00.00	97.23
M LH TAIL PIPE CHROME COVER	replacer				1.00	403.73	00.00	403.73
M LEFT TAIL PIPE BRACKET	? XSVL				1.00	100.87	00.00	100.87
M REAR BOTTOM TRIM BUMPER	der				1.00	696.20	00.00	696.20
M REAR BUMPER CHROME MOULDING	der				1.00	415.67	00.00	415.67
M DISTANCE SENSOR	? XSVL				2.00	176.11	00.00	352.22
M SPACER RING	der				2.00	6.35	00.00	12.70
M LEFT LOWER BRACKET BUMPER	? XSVL				1.00	27.55	00.00	27.55
M LEFT REFLECTOR LENSE	? XSVL				1.00	28.84	00.00	28.84
M LOWER LEFT BRACKET BUMPER	? XSVL				1.00	53.47	00.00	53.47
M IMPACT ABSORBER	? XSVL				1.00	159.90	00.00	159.90
M LEFT BRACKET BUMPER	? XSVL				1.00	27.55	00.00	27.55
M ELECTRICAL WIRING HARNESS	? XSVL				1.00	146.04	00.00	146.04

Rasul
Hp 900 10068
3 days
28/06/19 @ 1525
Respry before paint

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

Nett 6,303.73
7% GST on 6303.73 441.26
Total Payable 6,744.99

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLE7778A

Finalization

Tan Boon Khung
32 Verde View
Singapore 688670

Vehicle & Document Information

WIP No 34352
Reg No/Reg Date SLE7778A / 27/02/2017
Date In/Mileage 25/06/2019 / 36255
Chassis No WDC2533462F178881
Engine No 27492030881622
Make/Model MB/MB GLC 250 4MATIC COUPE (C253)
Colour/Trim 028 890 Cavansite B/ 041 101 Leather Bla

Account No	Terms	Date/Time Printed	GSE	Operator
CSI00001	Cash	28/06/2019/ 19:09	CH	371 / Go Chee Han
Description of Goods / Services				
	Qty	Unit/Price	Disc%	Amount

Z REQUEST

Customer Request
M BRUNSON

POLICY NO/ACC DATE : DMPCSN3004911900 // 17-6-2019
DRIVE IN/TP VEH NUMBER : 18-6-2019 // SMK1036D - AXA
DATE IN/DATE SURVEY: 25-6-2019 1525 // Rasul - LKK
BY/AUTHORIZED ON : 22-6-2019 1228 // Hsiao Tong - LKK

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESpray REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

X REAR BUMPER

X REAR BOTTOM TRIM BUMPER

X REAR BUMPER CHROME MOULDING

X SPACER RING

960.00 ✓

600.00 ✓

380.00 ✓

120.00 ✓

1.00 1230.14 00.00

1230.14 ✓

1.00 696.20 00.00

696.20 ✓

1.00 415.67 00.00

415.67 ✓

2.00 6.35 00.00

12.70 ✓

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Confirmed & accepted by

7% GST on 4414.71
Nett 4,414.71
309.03

Authorized signatory and company stamp

Total Payable 4,723.74

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg