

Signature

REF:

INC

NB/INC17023537/Jag302-1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **GBF 8878B**

Policy No. **5090581299 210417 - 240418**

Claims No. **11/097242-02**


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time | Action / Instruction

SG 5762P - X

GBF 8878B - X

RECEIVED 21 JUN 2019

temporary close case due to not estimate provided at the time of inspection
is SART, Catherine did not reply to on the status also.

Confirmed P/P \$6481.76/- 4days. of repair. (Red to 1576.64 (17%))

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS. SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) **6481.76**

160
160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023537/Sqb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 12-12-2017



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 8878B	Veh. Inspected	SG 5762P
Policy No.	5090581299	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/12/2017	Inspection Date	11/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

Date : 20/06/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1049873-001	COMFORT TRANSPORTATION PTE LTD	SHA 5695L	GBG 8461P	30/5/2019	\$ 1,468.28	\$ 1,157.16
2	MT/1049874-001	COMFORT TRANSPORTATION PTE LTD	SHD 3005B	YL 6351M	17/6/2019	\$ 2,505.04	\$ 1,700.00
3	MT/0972422-002	SMRT BUSES LTD	SG 5762P	GBF 8878B	02/12/2017	\$ 7,521.76	\$ 6,481.76
4	MT/1045696-002	SMRT TAXIS PTE LTD	SHB 598L	FX 9725K	21/5/2019	\$ 4,876.70	\$ 1,942.93

Claim received from LKK Auto

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5090581299	SIN SENG HUP RECYCLE AUTO PARTS PTE LTD	201623869C	GCV	Third Party	GBF88788	GBF88788	21/04/2017	24/04/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	2292D
Vehicle Details	
Vehicle No.	5G5762P
Vehicle to be Exported	No
Intended De-registration Date	12 Dec 2017
Vehicle Make	MAN
Vehicle Model	A95
Primary Colour	Multi-Colour
Manufacturing Year	2015
Engine No.	50343330804337
Chassis No.	WMAA95ZZ3G7003228
Maximum Power Output	-
Open Market Value	\$596,824.00
Original Registration Date	29 Jun 2016
First Registration Date	29 Jun 2016
Transfer Count	1
Actual ARF Paid	\$0.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Rebate Amount	\$0.00
Total Rebate Amount	\$0.00

The information contained herein is correct as at 12 Dec 2017

OK



Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/12/2017 08:33
Date Of Accident	02/12/2017 18:45
Exact Location Of Accident	GAMBAS AVE JUNCTION SEMBAWANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG5762P
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88888888

Vehicle Particulars

Manufacturer	MAN
Model	BUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	DII027592MFBP
Cover Note Number	

Driver

Name of Driver	TAN KIM SOON
NRIC No	S2711087H
Date Of Birth	29/03/1962
Occupation	OUTDOOR
Date Of Driving Pass	26/10/1999
Driving Experience	18 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 25

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

ON THE MENTIONED DATE AND TIME, MY BUS WAS STATIONARY AT THE SAID JUNCTION DUE RED SIGNAL LIGHT. WHILE WAITING FOR THE SIGNAL TO CHANGE, I FELT AN IMPACT FROM THE REAR PORTION OF MY BUS. I ALIGHTED FROM THE BUS AND FOUND THAT THE FRONT PORTION OF A LORRY HAD COLLIDED ONTO THE REAR PORTION OF MY BUS. THERE WAS ANOTHER VEHICLE COLLIDED ONTO THE REAR PORTION OF THE LORRY. NO PASSENGER ON BOARD THE LORRY AND ABOUT 25 PASSENGERS ON BOARD MY BUS. NO ONE WAS HURT IN THIS HEAD TO REAR CHAIN COLLISION INVOLVING 3 VEHICLES. THAT'S ALL

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF8878B
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LIM MUI SENG
NRIC/Passport Number
Contact Number 82284299
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJF6941U

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

MOHD SHAHLAN BIN ROSLI

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature] 4-12-17

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 4/12/17

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/06/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG5762P
Case Reference Number	BUS/12/17/1002
Registration Date	18/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	TAN KIM SOON
Type of Accident	CHAIN COLLISION
Accident Date and Time	2/12/2017 6:45 PM
Accident Reported Date and Time	4/12/2017 2:50 PM
Is Surveyor Required?	Yes
Survey by	IDAC
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	000024093587
Special Instruction to ARC, if any	Rear Portion Damaged
Prepared Date and Time	07/12/2017 1:36 PM
Chassis Number	WMAA95ZZ3G7003228
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$942.00	\$0.00
Total Spare Part Cost	\$4,459.76	\$4,459.76
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$7,521.76	\$4,459.76
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	0.0
Prepared / Adjusted By	Bus Estimator Team	
ARC / Surveyor Sign Off Date	01/01/1900 12:00 AM	01/01/1900 12:00 AM
Signature		
Remarks		



Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/06/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00 1590	\$0.00
Total Labour	\$2,120.00	\$0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$942.00 432	\$0.00
Total Spray Painting & Panel Beating	\$942.00	\$0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010298		88-25225-6039	STOP LAMP LED	2.00	\$1,141.70	10.00	\$2,055.06	Replace	Replace / CRA
6010299		88-25320-6008	SIGNAL LAMP LED	1.00	\$1,274.10	10.00	\$1,146.69	Replace	Replace / CRA
6010062		F01001-CW273	REAR TAIL LAMP COVER RH	1.00	\$974.70	10.00	\$877.23	Replace	Replace / CRA
6010373		4001F09-ACCE5020	REAR REFLECTOR PANEL RH	1.00	\$107.00	10.00	\$96.30	Replace	Replace / CRA
6010371		88-25215-0001	TRIM REFLECTOR	1.00	\$77.60	10.00	\$69.84	Replace	Replace / CRA
6009375			RETAINER (MALE & FEMALE)	2.00	\$74.80	10.00	\$134.64	Replace	Replace / DM
4005301	COMMON		SMRT STICKER (S)	1.00	\$75.00	0.00	\$75.00	Replace	Replace / HSC
			60KM/H STICKER	1.00	\$5.00	0.00	\$5.00	Replace	Replace / HSC
Total					\$3,729.90		\$4,459.76		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

P/P 04/06 4days.

800840



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/06/2019

User ID : CatherineLee

Section A - Accident Details


Registration Number	SG5762P
Case Reference Number	BUS/12/17/1002
Registration Date	18/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	TAN KIM SOON
Type of Accident	CHAIN COLLISION
Accident Date and Time	2/12/2017 6:45 PM
Accident Reported Date and Time	4/12/2017 2:50 PM
Is Surveyor Required?	Yes
Survey by	IDAC
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	000024093587
Special Instruction to ARC, if any	Rear Portion Damaged
Prepared Date and Time	07/12/2017 1:36 PM
Chassis Number	WMAA95ZZ3G7003228
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,590.00
Total Spray Cost	\$942.00	\$432.00
Total Spare Part Cost	\$4,459.76	\$4,459.76
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$7,521.76	\$6,481.76
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Bus Estimator Team	
ARC / Surveyor Sign Off Date	01/01/1900 12:00 AM	01/01/1900 12:00 AM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/06/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00	\$1,590.00
Total Labour	\$2,120.00	\$1,590.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$942.00	\$432.00
Total Spray Painting & Panel Beating	\$942.00	\$432.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010298		88-25225-6039	STOP LAMP LED	2.00	\$1,141.70	10.00	\$2,055.06	Replace	Replace
6010299		88-25320-6008	SIGNAL LAMP LED	1.00	\$1,274.10	10.00	\$1,146.69	Replace	Replace
6010062		F01001-CW273	REAR TAIL LAMP COVER RH	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010373		4001F09-ACCE5020	REAR REFLECTOR PANEL RH	1.00	\$107.00	10.00	\$96.30	Replace	Replace
6010371		88-25215-0001	TRIM REFLECTOR	1.00	\$77.60	10.00	\$69.84	Replace	Replace
6009375			RETAINER (MALE & FEMALE)	2.00	\$74.80	10.00	\$134.64	Replace	Replace
4005301	COMMON		SMRT STICKER (S)	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			60KM/H STICKER	1.00	\$5.00	0.00	\$5.00	Replace	Replace
Total					\$3,729.90		\$4,459.76		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023537/Jqd3e2-1			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 25-06-2019	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 8878B	Veh. Inspected	SG 5762P
Policy No.	5090581299	Coverage (\$)	0.00
Claim No.	MT/0972422-002	Excess (\$)	0.00
Assign From		Assign Date	11/12/2017
2. Vehicle Particulars & Condition			
Make & Model	MAN A95	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WMAA95ZZ3G7003228	Colour	GREEN
Odometer	102100	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/12/2017	Inspection Date	11/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5762P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	STOP LAMP LED @\$1141.70	CRACKED	2,283.40	2,283.40
1	SIGNAL LAMP LED	CRACKED	1,274.10	1,274.10
1	REAR TAIL LAMP COVER RH	CRACKED	974.70	974.70
1	REAR REFLECTOR PANEL RH	CRACKED	107.00	107.00
1	TRIM REFLECTOR	CRACKED	77.60	77.60
2	RETAINER (MALE & FEMALE) @\$74.80	DAMAGED	149.60	149.60
	LESS 10% DISCOUNT		-	-486.64
			4,866.40	4,379.76
<u>SPECIAL NETT ITEMS</u>				
1	SMRT STICKER (SN)	NECESSARY	75.00	75.00
1	60KM/H STICKER (SN)	NECESSARY	5.00	5.00
			80.00	80.00
<u>LABOUR</u>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		2,120.00	1,590.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		942.00	432.00
			3,062.00	2,022.00
GRAND TOTAL			8,008.40	6,481.76
RECOMMENDED COST OF REPAIRS (CONFIRMED)				6,481.76

Report Ref No. NS/INC17023537/Jqd3e2-1

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.