

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C**AAD1906-171***Not Auth'd*
61 Sm @ 4250

19 JUN 2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF 649C

VF1ABL15AUC278383

RENAULT

LATITUDE

18.6.19

TOKIO MARINE

30/6/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$ <i>N</i>	2,844.66 <i>X</i>
1	DOOR GUIDE REAR RH	\$ <i>Sn</i>	176.82
1	DOOR HINGE UPPER RH	\$ <i>N</i>	274.50
1	DOOR HINGE LOWER RH	\$ <i>N</i>	300.55
1	DOOR CHECK REAR LH/RH L70Y	\$ <i>Sn</i>	203.06
1	DOOR FINISHER REAR RH	\$ <i>Sn</i>	423.10
1	DOOR MOULDING REAR RH	\$ <i>Sn</i>	176.82
1	DOOR FINISHER INNER REAR RH	\$ <i>Sn</i>	323.44
1	DOOR WHEATHESTRIIP REAR RH	\$ <i>Sn</i>	410.66
1	DOOR SEAL REAR RH	\$ <i>Sn</i>	162.02
1	DOOR CASING REAR RH	\$ <i>Sn</i>	1,509.06
1	DOOR PANEL FRT RH	\$ <i>N</i>	2,844.66 <i>X</i>
1	DOOR HINGE UPPER RH	\$ <i>N</i>	261.28
1	DOOR HINGE LOWER RH	\$ <i>N</i>	300.55
1	DOOR CHECK FRT RH	\$ <i>Sn</i>	194.77
1	DOOR LOCK FRT RH	\$ <i>N</i>	908.75
1	DOOR CATCH FRT RH	\$ <i>Sn</i>	131.23
1	DOOR HANDLE OUTER FRT RH	\$ <i>Sn</i>	477.76
1	DOOR HANDLE COVER FRT RH	\$ <i>Sn</i>	13.22
1	DOOR HANDLE MODULE FRT RH	\$ <i>Sn</i>	133.60
1	DOOR REGULATOR FRT RH	\$ <i>Sn</i>	505.19
1	DOOR REGULATOR MOTOR FRT RH	\$ <i>Sn</i>	796.46
1	DOOR REGULATOR GUIDE FRT RH	\$ <i>Sn</i>	120.97
1	DOOR WHEATHESTRIIP FRONT RH	\$ <i>Sn</i>	410.66
1	DOOR MOULDING FRONT RH	\$ <i>Sn</i>	176.82
1	DOOR FINISHER INNER FRONT RH	\$ <i>Sn</i>	323.44
1	DOOR FINISHER FRONT RH	\$ <i>Sn</i>	423.10
1	DOOR CASING FRONT RH	\$ <i>Sn</i>	1,509.06
1	DOOR BLIND FRONT RH	\$ <i>Sn</i>	741.80

Trans-cab Auto Services Pte Ltd

AAD1906-171

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C

1	DOOR SEAL FRONT RH	\$	SL	162.02	}	X
1	DOOR GLASS RUNNER SEAL FRONT RH	\$	SL	229.31		
1	DOOR WAIST SEAL OUTER FRONT RH	\$	SL	334.69		
1	DOOR WAIST SEAL INNER FRONT RH	\$	SL	115.64		
1	ROCKER PANEL INNER GARNISH RH	\$	SL	466.51		
1	ROCKER PANEL INNER RH	\$	RL	1,024.79		
1	ROCKER PANEL OUTER RH	\$	RL	1,184.99		
1	ROCKER PANEL CENTER RH	\$	RL	990.25	}	✓
1	DOOR MIRROR ASSY RH	\$	Red/Gn	1,483.40		
1	DOOR MIRROR GLASS RH	\$	SL	148.20	}	X
1	DOOR MIRROR BACK COVER RH	\$	SL	218.46		
1	DOOR HARNESS WIRE RH	\$	SL	2,670.00		
1	FENDER PANEL FRT RH	\$	RL	783.83		
1	WHEELARCH FRT RH	\$	SL	278.84		
1	FENDER BRACKET LOWER RH	\$	SL	15.79	}	
1	FENDER INSULATOR RH	\$	SL	130.84		
TOTAL		\$		27,315.55		
10%		\$		2,731.56		
		\$		24,584.00		

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	Me	300.00	60sn	}	X
1	FRONT DOOR STICKER 'Trans-Cab'	\$	Me	80.00	60sn		
1	FRONT DOOR STICKER 'Classic'	\$	Me	80.00	15sn		
1	DOOR CHECK BOLT	\$	na	22.69			
1	DOOR GUIDE SCREW	\$	na	10.85			
1	DOOR HINGE BOLT	\$	na	10.85			
1	DOOR HINGE NUT RH	\$	na	14.60			
1	DOOR CHECK BOLT	\$	na	22.69			
1	DOOR CHECK NUT	\$	na	3.75			
1	DOOR LOCK SCREW L70Y	\$	na	6.12			
1	DOOR CATCH SCREW L70Y	\$	na	10.06			
1SET	WHEELARCH CLIP FRT RH	\$	na	30.50			
1	FRONT RIGHT TYRE	\$	Sn	300.00			
1	FRONT RIGHT TYRE RIM	\$	Sn	380.00			
1SET	Front licence plate with holder	\$	Sn	80.00			
1	FRONT WINDSCREEN SEALANT	\$	Sn	253.80			
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	Sn	100.00			

Trans-cab Auto Services Pte Ltd

AAD1906-171

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C

1 FRONT WINDSCREEN MOULDING

	\$	<i>Sm</i> 120.00 <i>X</i>
TOTAL	\$	1,825.93

TOTAL PARTS	\$	26,409.93
--------------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	6,000.00	<i>500l</i>
----	----------	-------------

Putty and spray painting of the affected portion.

\$	6,000.00	<i>669</i>
----	----------	------------

To check steering geometry and computer wheel alignment

\$	<i>nn</i> 220.00	<i>X</i>
----	------------------	----------

To transfer of front windscreen fittings and conduct water seepage test.

\$	<i>nn</i> 170.00	<i>X</i>
----	------------------	----------

To transfer of tire, rim and on wheel balancing.

\$	<i>nn</i> 170.00	<i>X</i>
----	------------------	----------

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	<i>nn</i> 380.00	<i>X</i>
----	------------------	----------

To transfer of Rear door fittings, attachment and perform water seepage test.

\$	<i>nn</i> 380.00	<i>X</i>
----	------------------	----------

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$	<i>nn</i> 380.00	<i>X</i>
----	------------------	----------

To transfer of Front door fittings, attachment and perform water seepage test.

\$	380.00	<i>60l</i>
----	--------	------------

To rust-proofing of the affected areas.

\$	170.00	<i>30l</i>
----	--------	------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>20l</i>
----	--------	------------

To transfer of Front fender fittings, attachment and perform water seepage test.

\$	<i>nn</i> 380.00	<i>X</i>
----	------------------	----------

Trans-cab Auto Services Pte Ltd**AAD1906-171**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 649C

To apply paint protection system (PPS) maintain and enhancement

\$

nn 380.00 X**TOTAL \$ 15,180.00****Over All Total \$ 41,589.93****LUMP SUM (REPAIR DAY)**~~20 DAYS~~*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: