




SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S9M01R51
Reference	CS/ASM19010927/Evd3e2 
Loss Date	June 18, 2019
Report Date	Jun 20, 2019 9:03:00 AM
Request Date	June 20, 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated survey and authorize

Actions

Next Step

Wait for: Approve invoice

[Add Invoice](#)

Insured

MEHTA SHEKHAR
185 TANJONG RHU ROAD #04-01, 436924,
Singapore
91527390
SHEKHARMEHTA77@GMAIL.COM

Vehicle Information

Incident Vehicle Registration # SLW6178T

Make SUBARU

Model FORESTER 2.0

Service Address

'''

Primary Contact

MOTOR IMAGE ENTERPRISE PTE LTD
19 Toa Payoh Lorong 8, 319255, Singapore
64170333

Claim Handler

ANG Richard

Additional Instructions

1) Motor Image 2) Excess: \$1100 (Sect 1 @ \$600 + Unnamed \$500)

Messages¹ Invoices History Documents Assessment Metrics Notes

[Add](#)

REFERENCE #	DESCRIPTION	TOTAL AMOUNT	SUBMITTED	STATUS	PAID DATE	WITHDRAW
AC1909171	Final Invoice	\$267.50	9/13/19 4:25 PM	Waiting for Approval		Withdraw

Totals

Outstanding Invoices	\$267.50	Rejected and Withdrawn	\$0.00
Payments Made	\$0.00		
Total	\$267.50		