

Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
General Details		Workshop Details					
Involving	1 2017 SUBARU FORESTER 2.0 (SLW6178T)		Total Rebate Amount		46570		
Date of Loss	18 June 2019		Nett Loss Amount		\$43,430.00		
Time of Loss	10.00		Assigned Workshop		LKK AUTO CONSULTANTS PTE LTD (OD)		
Loss Description	SLW6178T (INSD) C/W INTO PROPERTY		Days of work completion *		20		
Comment							

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SLW6178T

Registration State

SINGAPORE

Mileage

20593

Purchase Date

dd/mm/yyyy

Registration Date *

26/02/2018

Age of Vehicle

1

Driver Details

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2017	2017	Driver Name	MEHTA VARSHA	
Make	SUBARU	SUBARU	Date of Birth	25 July 1980	dd/mm/yyyy
Model	FORESTER 2.0	FORESTER 2.0I-L CVT A)	Age	39	

Type

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type of Paint		
Chassis No	JF1SJ5KC5JG104369	JF1SJ5KC5JG104369
Engine No	FB20YC55581	FB20YC55581
Engine Capacity		1995
Sum Insured	0	0
Market Value	0	90000

CATEGORY	EMERGENCY INFORMATION
Education Qualification	Other
Driving Experience	3
Driver License #	
License Type	
License Issue Date	1 January 2016
License Expiration Date	
Address	185 TANJONG RHU ROAD #04-01, 436924, Singapore
Address type	Personal Correspondence

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	▼
Marital status	Unknown	▼
Identification #	S8080527F	

⏪ Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *

20/06/2019



General condition

Good ▾

Total Loss

Yes

No

Steering (Serviceable)

Yes

No

Towing Charges

0

Footbrake (Serviceable)

Yes

No

Voluntary Excess

0

Handbrake (Serviceable)

Yes

No

Compulsory Excess

1100

Young/Inexperienced/Un
named Driver Excess

0

Engine Modification

Yes

No

Other Excess

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size	225/60R17	Rear Tyre Size	225/60R17
Front left side	YOKOHAMA6mm	Rear left side	YOKOHAMA6mm
Front right side	YOKOHAMA6mm	Rear right side	YOKOHAMA6mm

<<

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Tax Eligibility & Additional Deduction for Parts						
Depr./Bttr%			Salvage%			
Discount%	20		Settlement%		100	
Paint Labour/Material Ratio						
Paint Labour Ratio	20		Paint Material Ratio		80	

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

⏪ Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary							
Parts																
Add Approve Deny Submit All	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		DUCT AIR INTAKE	Serviceable	0	0	No		20		0	0	Deny	
		0	1		RESONATOR	Serviceable	0	0	No		20		0	0	Deny	
		0	1		CASE-AIR CLNR UPR	Broken	0	108	No		20			86.4	Reviewing	
		0	1		CASE-AIR CLNR LWR	Broken	0	36	No		20			28.8	Reviewing	
		0	1		WHEEL APR FF C RPRH	Damaged	0	172.8	No		20			138.24	Reviewing	
		0	1		FRT FENDER RH	Dented	0	270	No		20			216	Reviewing	
		0	1		HOOD F CPL	Dented	0	882	No		20			705.6	Reviewing	
		0	1		HINGE COMPL F HD RH	Bent	0	43.2	No		20			34.56	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BITR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
	0	1		HINGE COMPL F HD LH	Bent	0	43.2	No		20			34.56	Reviewing	
	0	1		LOCK ASSY F HOOD ISR	Serviceable	0	0	No		20			0	Deny	
	0	1		BRKT CORNER F RH	Broken	0	36	No		20			28.8	Reviewing	
	0	1		BRKT CORNER F LH	Serviceable	0	0	No		20			0	Deny	
	0	1		BRKT SD F RH	Broken	0	12.6	No		20			10.08	Reviewing	
	0	1		BRKT SD F LH	Serviceable	0	0	No		20			0	Deny	
	0	1		MOLDING BMPR F (RH)	Necessary	0	43.2	No		20			34.56	Reviewing	
	0	1		FRT BUMPER	Broken	0	594	No		20			475.2	Reviewing	
	0	1		BACK BEAM CPL F	Dented	0	288	No		20			230.4	Reviewing	
	0	1		ENERGY ABSOR F	Dented	0	126	No		20			100.8	Reviewing	
	0	1		PACKING RAD	Serviceable	0	0	No		20			0	Deny	
	0	1		PACKING RAD	Serviceable	0	0	No		20			0	Deny	
	0	1		PNL COMPL DR F RH	Repair	0	0	No		20			0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTRS%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		LATCH & ACT AY DR FRHS	Serviceable	0	0	No		20		0	0	Deny	
		0	1		HANDLE OUT DR SMT	Serviceable	0	0	No		20		0	0	Deny	
		0	1		WSTR OUT DR F RH	Serviceable	0	0	No		20		0	0	Deny	
		0	1		WSTR DR F RH	Serviceable	0	0	No		20		0	0	Deny	
		0	1		GLASSRUN F DR RH	Serviceable	0	0	No		20		0	0	Deny	
		0	1		WSTR BODY SD FLG F	Serviceable	0	0	No		20		0	0	Deny	
		0	1		LAMP ASSY HEAD EDF	Broken	0	2380	No		20		1904	1904	Reviewing	
		0	1		FOG LAMP ASSY F	Serviceable	0	0	No		20		0	0	Deny	
		0	1		BRKT F FOG ASSY RH	Broken	0	19.8	No		20		15.84	15.84	Reviewing	
		0	2		NOZZLE F	Serviceable	0	0	No		20		0	0	Deny	
		0	1		NOZZLE H L WASHERRH	Serviceable	0	0	No		20		0	0	Deny	
		0	1		NOZZLE COVER ASSY RH	Missing	0	54	No		20		43.2	43.2	Reviewing	
		0	1		TAPE DR SASH F F RH	Serviceable	0	0	No		20		0	0	Deny	

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BITTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
	0	1		TAPE DR SASH F M RH	Serviceable	0	0	No		20		0	0	Deny	
	0	1		TAPE DR SASH F R RH	Serviceable	0	0	No		20		0	0	Deny	
	0	1		INSULATOR HOOD NA	Serviceable	0	0	No		20		0	0	Deny	
	0	1		GRILLE ASSY F UPRHG	Serviceable	0	0	No		20		0	0	Deny	
	0	1		GRILLE ASSY F CTRHG	Serviceable	0	0	No		20		0	0	Deny	
	0	1		GRILLE ASSY F LWRHG	Serviceable	0	0	No		20		0	0	Deny	
	0	1		BRKT GRILLE LWR NA	Serviceable	0	0	No		20		0	0	Deny	

Labour

			REPAIR/REPLACE (LABOUR)													
			ADD	APPROVE	DENY	SUBMIT ALL	EDIT	SR NO	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0							0	REPAIR / REPLACE FRONT BUMPER, SUPPORT PANEL, LH FRT FENDER, LH FRT DOOR & BONNET	0	1680	0	0	Reviewing		
	0							0	RESPRAY FRONT BUMPER, SUPPORT PANEL, LH FRT FENDER, RH FRT DOOR & BONNET	0	1680	0	0	Reviewing		
	0							0	TRANSFER DOOR LH FRT MECHANISM	0	0	0	0	Deny		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0		MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	0	0	0	0	Deny		
		0		FAULT DIAGNOSTIC	0	280	0	0	Reviewing		
		0		TO CONDUCT FRONT LIGHTING TEST	0	50	0	0	Reviewing		
		0		REMOVE / REFIX FRT HEADLAMP WASHER & PIPINGS	0	150	0	0	Reviewing		
		0		VEHICLE TOWED TO MOTOR IMAGE DUE TO ACCIDENT	0	180	0	0	Reviewing		

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Add	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 6 DAYS	Reviewing		0		
		0	SUNDRIES	Reviewing		0	NOT NECESSARY	

Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00			Adjusted Claim Amount	\$7,007.04	
CATEGORY		ESTIMATE	ADJUSTED				
Spare Parts		\$0.00	\$4,087.04				
Labour		\$0.00	\$4,020.00				
Excess			-\$1,100.00				

Submit for Review