



樹發汽車修理廠 SHU FATT AUTO WORKS

Q-91

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
2nd July 2019
TP- ntuc

SLL 1264 T HYUNDAI ELANTRA

		S\$
Spare Parts	1 Set rear bumper clips.	64.00 ✕
	2 Rear bumper side retainers. @\$46/-	92.00 ✕

		156.00
Less 20%		31.20

Labour	To knock rear support panel, repair rear bumper, replace damaged parts and assembly.	124.80
	To respray damaged parts.	280.00 200
	To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.	450.00 200
		60.00 30

		914.80
		=====

Taufik 97495749
- WP'

3/7/19 @ 1115.

Resurvey before & after paint.

2 days

taufik@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(19)