



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/ASM19008817/Epa3s2-1

C/O : SEAH ONG & PARTNERS LLP
36 ROBINSON ROAD #12-03 CITY HOUSE
SINGAPORE 068877

Date : 10-01-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 7886U	Veh. Inspected	SKS 3530L
Policy No.	P2064586	Coverage (\$)	0.00
Claim No.	19.27499 PD-O	Excess (\$)	0.00
Assign From	XIN YI	Assign Date	20/06/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600033818	Colour	BLACK
Odometer	139789	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/35Z R22	CONTINENTAL	6 mm
L/H Front Tyre	265/35Z R22	CONTINENTAL	6 mm
R/H Rear Tyre	265/35Z R22	CONTINENTAL	6 mm
L/H Rear Tyre	265/35Z R22	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/05/2019	Inspection Date	21/05/2019
Survey held at	CHNG BROTHER MOTOR SERVICE 2 KAKI BUKIT AVENUE 2 #02-32 KAKI BUKIT AUTOHUB SINGAPORE 417921.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------