

Attn: Edison
Fax: 67465110

VEHICLE NO: SLB 8487Z

HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Tailgate bf ✓		1960.20	1,100
1	Tailgate centre garnish X NN		525.80	
9	Tailgate centre garnish clips @5.80 X NN		52.20	
1	Tailgate inner lock X NN		410.00	
1	Tailgate inner trim board X NN		547.00	
2	Tailgate damper @298.20 X NN		596.40	
2	Tailgate rubber stopper @5.80 n - CUT		11.60	
1	Tailgate Honda emblem (badge) n - NEC		92.00	52
1	Tailgate VEZEL emblem n - NEC		98.00	33
2	RHS & LHS Tailgate reflector @587.00 X NN		1174.00	
1	RHS & LHS Taillamp @982.00 X NN		1964.00	
2 Δ	RHS & LHS side (corner) panel @342.50 X ✓ 198 CRA		685.00	396
2 Δ	RHS & LHS Wheel arch garnish @372.00 X ✓ 165 CRA		744.00	330
1	Rear boot edge weatherstrip n - DD		278.00	145
1	Rear windscreen inner seal n - NEC		172.00	120
1	Rear bumper de -		764.20	
2 Δ	Rear bumper side retainers @72.00 X ✓ 42 DIS		144.00	84
2	Rear bumper reflectors X NN	REFIX	0.00	
1	Rear compartment tool tray X NN		274.00	
1	Rear floor panel top cover X NN		240.00	
2	Rear end panel outer beam X NN		172.00	
1	Rear end panel (upper panel) bf ✓		762.00	595
1	Rear end panel top garnish R CRA -		261.00	133
			11927.40	
		less 20%	2385.48	20%
			9541.92	
SPECIAL NETT ITEMS				
1 set	Rear Bumper clips n -		60.00	30
1set	RHS & LHS Wheel arch garnish clips X ✓ NEC		120.00	X30
1set	Tailgate inner trim clips n -		60.00	30
1	Rear windscreen sealant n -		100.00	60
1	Rear number plate w/holder X		75.00	X
1 set	Reverse sensor n - 4 points		280.00	200 + 50
1	Reverse camera X		480.00	X
1	Rear end panel sealant n -		100.00	60
	TOTAL PARTS		10816.92	

VEHICLE NO: SLB 8487Z HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1400.00 600	+200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00 600	+200
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	200.00 X 30	
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	250.00 60	
5	To remove and replace reverse sensors and check for proper function	120.00 60	
6	To remove and replace reverse camera and check for proper function	120.00 X	
7	To remove and refix tailgate windscreen	140.00 120	
8	To provide anti-rust treatment on affected areas	180.00 60	
	Labour Total :	3610.00	
	TOTAL (PARTS & LABOUR):	14426.92	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

[Signature]
26/6/19

LS \$4,200
6 days
Hp 90010068

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6 days
4/5
20/06/19 @ 1030
Revy after repair