



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Didi Ahmed Mohamed ADDRESS: 20 Dunearn Road #12-01 Singapore 309422 TEL: 92323288		WIP: 43543 EXCESS: DATE: 18-Jun-19	
VEH NO:	SKX6389H	DATE IN:		CONTACT PERSON:	Jobi 63310682
CHASSIS NO:	JM6BM42A8G0328308	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA3	DATE REG.:	21-Dec-15	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER <i>de /</i>	1	MBHR3-50-031BBB		\$ 1,083.30
2	FRONT REINFORCEMENT <i>? XSVL</i>	1	MB45A-50-070A		\$ 466.80
3	CLIP, FRONT BUMPER <i>ne /</i>	12	MC274-50-133		\$ 44.40
4	FASTENER, FRONT BUMPER <i>ne /</i>	2	MB45A-56-146A		\$ 6.00
5	GROMMET, FRONT BUMPER <i>ne /</i>	2	MGHP9-50-025		\$ 5.80
6	GRILLE TOP <i>de /</i>	1	MBHN1-50-033 53		\$ 351.80
7	RIVET, GRILLE TOP <i>ne /</i>	6	MS515-51-833		\$ 24.00
8	RIVET, GRILLE TOP <i>ne /</i>	4	MTK21-50-355		\$ 36.80
9	MASCOT, FRONT <i>ne /</i>	1	MC235-51-731A		\$ 46.50
10	CHROME RHS <i>sch /</i>	1	MBHN1-50-7J1A		\$ 185.60
11	FRONT GRILLE <i>cm /</i>	1	MBJE1-50-712B		\$ 610.70
12	BRACKET RHS, FRONT GRILLE <i>? cm /</i>	1	MBHN1-50-153		\$ 15.90
13	PIN LOCATOR, FRONT GRILLE <i>ne /</i>	2	MKD45-50-1K5A		\$ 5.80
14	GROMMET, FRONT GRILLE <i>ne /</i>	2	MKD45-50-ES1		\$ 5.80
15	RIVET, FRONT GRILLE <i>ne /</i>	2	MEA01-50-037		\$ 16.00
16	FASTENER, FRONT GRILLE <i>ne /</i>	8	MGD7A-50-EA1		\$ 25.60
17	PLATE SET, FRONT REINFORCEMENT <i>? cm /</i>	1	MBHN3-50-1C0		\$ 97.40
18	FASTENER, PLATE SET <i>? ne /</i>	4	MGD7A-50-EA1		\$ 12.80
TOTAL PARTS					\$ 3,041.00
LESS 10%					\$ 304.10
TOTAL PARTS COST					\$ 2,736.90
Labour Description					
1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			990, \$ 1,550.00
2	MZ-SP-SFRT03	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP.			830, \$ 1,575.00

3	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. X	NETT	\$ 70.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES. 20	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 4,245.00
TOTAL PARTS	\$ -	\$ 2,736.90
TOTAL	\$ -	\$ 6,981.90
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
5 days
20/06/19 @ 1540
Resurvey & paint



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Didi Ahmed Mohamed ADDRESS: 20 Dunearn Road #12-01 Singapore 309422 TEL: 92323288		WIP: 43543 EXCESS: DATE: 18-Jun-19		
VEH NO:	SKX6389H	DATE IN:		CONTACT PERSON:	Jobi 63310682	
CHASSIS NO:	JM6BM42A8G0328308	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM	
MODEL:	MAZDA3	DATE REG.:	21-Dec-15	POLICY NO.:		
NATURE OF WORKS						
<u>Parts Description</u>						
NO	QTY			REVISED	PRICES	
1	FRONT BUMPER	1	MBHR3-50-031BBB	\$ 1,083.30	\$ 1,083.30	
2	FRONT REINFORCEMENT	1	MB45A-50-070A		\$ 466.80	
3	CLIP, FRONT BUMPER	12	MC274-50-133	\$ 44.40	\$ 44.40	
4	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 6.00	\$ 6.00	
5	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$ 5.80	\$ 5.80	
6	GRILLE TOP	1	MBHN1-50-033 53	\$ 351.80	\$ 351.80	
7	RIVET, GRILLE TOP	6	MS51S-51-833	\$ 24.00	\$ 24.00	
8	RIVET, GRILLE TOP	4	MTK21-50-355	\$ 36.80	\$ 36.80	
9	MASCOT, FRONT	1	MC235-51-731A	\$ 46.50	\$ 46.50	
10	CHROME RHS	1	MBHN1-50-7J1A	\$ 185.60	\$ 185.60	
11	FRONT GRILLE	1	MBJE1-50-712B	\$ 610.70	\$ 610.70	
12	BRACKET RHS, FRONT GRILLE	1	MBHN1-50-153	\$ 15.90	\$ 15.90	
13	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A	\$ 5.80	\$ 5.80	
14	GROMMET, FRONT GRILLE	2	MKD45-50-ES1	\$ 5.80	\$ 5.80	
15	RIVET, FRONT GRILLE	2	MEA01-50-037	\$ 16.00	\$ 16.00	
16	FASTENER, FRONT GRILLE	8	MGD7A-50-EA1	\$ 25.60	\$ 25.60	
17	PLATE SET, FRONT REINFORCEMENT	1	MBHN3-50-1C0	\$ 97.40	\$ 97.40	
18	FASTENER, PLATE SET	4	MGD7A-50-EA1	\$ 12.80	\$ 12.80	
SUPPLEMENTARY ITEM						
1	COVER RHS,FOGLAMP	1	MBJE1-50-C11A	\$ 48.80	\$ 48.80	
TOTAL PARTS				\$ 2,623.00	\$ 3,089.80	
LESS 10%				\$ 262.30	\$ 308.98	
TOTAL PARTS COST				\$ 2,360.70	\$ 2,780.82	
<u>Labour Description</u>						
1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER AND GRILLE TOP. REPAIR AREAS AFFECTED BY THE ACCIDENT.			\$ 990.00	\$ 1,650.00
2	MZ-SP-SFRT03	TO RESPRAY FRONT BUMPER AND GRILLE TOP.			\$ 830.00	\$ 1,575.00

3	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		\$ 70.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 2,170.00 \$ 4,245.00
			TOTAL PARTS	\$ 2,360.70 \$ 2,780.82
			TOTAL	\$ 4,530.70 \$ 7,025.82
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 4,530.70
			GST 7%	\$ 317.15 \$ -
			GRAND TOTAL	\$ 4,847.85 \$ -

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



TRANS EUROKARS PTE LTD



SUPPLEMENTARY ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Didi Ahmed Mohamed ADDRESS : 20 Dunearn Road #12-01 Singapore 309422 TEL : 92323288		WIP : 43543 EXCESS : DATE: 18-Jun-19	
VEH NO :	SKX6389H	DATE IN :		CONTACT PERSON :	Jobi 63310682
CHASSIS NO :	JM6BM42A8G0328308	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	21-Dec-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	COVER RHS, FOGLAMP	1	MBJE1-50-C11A		\$ 48.80
TOTAL PARTS					\$ 48.80
LESS 10%					\$ 4.88
TOTAL PARTS COST					\$ 43.92
Labour Description					
1					
TOTAL LABOUR				\$ -	\$ -
TOTAL PARTS				\$ -	\$ 43.92
TOTAL				\$ -	\$ 43.92
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ -	
GST 7%				\$ -	\$ -
GRAND TOTAL				\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature