

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19010941/ABA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100381333

Claimant
Vehicle No : SDP5192P **Insured Vehicle No :** SFT1701C

Date of Loss: 15/06/2019 Nature of Claim: TP Claim No: 3564361281SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDP5192P		
Make & Model:	HYUNDAI I30 PDE, 1.4 T-GDI DCT (A)	Engine No:	G4LDJD194056
Reg. Date:	22/01/2019 (Man. Year: 2018)	Chassis No:	TMAH5H13VKJ014003
Colour:	Black	Odometer:	7479 km
Engine Capacity:	1353 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,681.78	6,862.46	10,819.32	61.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,330.00	3,130.00	3,200.00	50.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,011.78	9,992.46	14,019.32	58.39
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	24,011.78	7,000.00	17,011.78	70.85
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		7,836.45		
Global Sum Settlement (S\$)		7,800.00		

INSPECTION

Date of Assignment: 19/06/2019

Date Inspected: 20/06/2019 Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22
Autobay
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,891.60 FL	*- FL
2	1		*REAR BUMPER RETAINER RH	Not Necessary	75.80 FL	*- FL
3	1		*REAR DOOR RH	Dented	1,789.50 FL	*1,789.50 FL
4	2		*REAR DOOR HINGE RH	Not Necessary	117.80 FL	*- FL
5	1		*REAR DOOR CHECKER RH	Not Necessary	69.80 FL	*- FL
6	1		*REAR DOOR LOCK RH	Not Necessary	245.30 FL	*- FL
7	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	165.30 FL	*- FL
8	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	145.80 FL	*- FL
9	1		*REAR DOOR OUTER HANDLE COVER RH	Not Necessary	50.70 FL	*- FL
10	1		*FRONT DOOR RH	Dented	1,790.80 FL	*1,790.80 FL
11	2		*FRONT DOOR HINGES RH	Not Necessary	117.80 FL	*- FL
12	1		*FRONT DOOR CHECKER RH	Not Necessary	69.80 FL	*- FL
13	1		*FRONT DOOR INNER TRIM RH	Cracked	492.50 FL	*492.50 FL
14	1		*FRONT DOOR FRAME UPPER MOULDING RH	Not Necessary	168.90 FL	*- FL
15	1		*FRONT DOOR OUTER MOLDING RH	Not Necessary	154.20 FL	*- FL
16	1		*FRONT DOOR WEATHERSTRIP RH (DOOR)	Not Necessary	158.90 FL	*- FL
17	1		*FRONT DOOR WEATHERSTRIP RH (FRAME)	Not Necessary	168.20 FL	*- FL
18	1		*FRONT DOOR REGULATOR RH	Damaged	436.80 FL	*436.80 FL
19	1		*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	345.60 FL	*- FL
20	1		*FRONT DOOR INNER LOCK RH	Damaged	248.60 FL	*248.60 FL
21	1		*FRONT DOOR POWER WINDOW SWITCH RH	Not Necessary	202.50 FL	*- FL
22	1		*FRONT DOOR GLASS RH	Not Necessary	698.70 FL	*- FL
23	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	145.80 FL	*- FL
24	1		*FRONT DOOR OUTER HANDLE COVER RH	Not Necessary	50.70 FL	*- FL
25	1		*FRONT FENDER RH	Not Necessary	645.80 FL	*- FL
26	1		*FRONT SIDE MIRROR RH	Not Necessary	1,320.30 FL	*- FL
27	1		*SIDE ROCKER PANEL RH	Dented	1,605.10 FL	*655.00 FL
28	1		*REAR FENDER RH	Repair	1,875.60 FL	*- FL
29	1		*B PILLAR RH	Repair	1,652.30 FL	*- FL
30	1		*REAR RIM RH	Cut	685.60 FL	*685.60 FL
31	1		*REAR KNUCKLE ARM RH	Bent	836.24 FL	*455.00 FL
32	1		*REAR WHEEL HUB BEARING RH	Damaged	551.37 FL	*385.00 FL
33	1		*REAR ABSORBER RH	Not Necessary	498.07 FL	*- FL
34	1		*REAR STABILIZER BAR RH	Not Necessary	542.71 FL	*- FL
35	1		*REAR TRAILING ARM RH	Bent	496.47 FL	*496.47 FL
36	1		*REAR UPPER ARM RH	Bent	409.71 FL	*409.71 FL
37	1		*REAR ASSIST ARM RH	Bent	305.60 FL	*305.60 FL
38	1		*REAR LOWER ARM RH	Bent	625.96 FL	*390.00 FL
39	1		*SET REAR BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
40	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
41	1		*SET FRONT DOOR INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
42	1		*SET REAR DOOR INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
43	2		*SET SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,052.23	8,570.58
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,370.45	1,708.12
Total Parts (\$\$)	17,681.78	6,862.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	2,600.00	1,200.00
2	TO RESPRAY AFFECTED AREAS	New	2,000.00	1,200.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	80.00
4	TO REMOVE/REFIT WIRING CHECKS AND TO RESET WINDOW MODULE	New	150.00	30.00
5	TO REMOVE/REFIT /REPLACE FRONT AND REAR DOOR MECHANISM	New	300.00	160.00
6	TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY	New	150.00	80.00
7	TO REMOVE/REFIT REAR SENSOR AND DISTANCE SETTLING	New	150.00	0.00
8	TO PERFORM COMPUTERISED ALIGNMENT BEFORE AND ARTER	New	180.00	80.00
9	TO REMOVE/REPLACE REAR UNDERCARRIAGE	New	250.00	220.00
10	TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY	New	150.00	0.00
11	LABOUR TO APPLY SEALANT ON THE AFFECTED AREA	New	200.00	80.00
Gross Labour Cost (\$\$)			6,330.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >