

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5291C**AAD1906-168**

Not Authorized
Return By pain

20 JUN 2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5291C

JTDKB3FU903078743

TOYOTA

PRIUS

18.6.2019

ERGO

19/12/2018

PART**LIST**

1	1 REAR BUMPER	\$	Bu	458.60	✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	Bu	318.80	✓
3	1 REAR BUMPER TOWING COVER	\$	mi	14.70	✓
4	1 REAR BUMPER UNDER COVER (BLACK)	\$		552.60	?
5	1 REAR BUMPER SIDE RETAINER LH	\$	Diy	112.70	✓
6	1 REAR BUMPER SIDE RETAINER RH	\$	su	112.70	X
7	1 REAR TAILGATE	\$	Bu	1,547.27	✓
8	1 REAR TAILGATE OUTER GARNISH	\$	Del/cm	905.10	✓
9	1 COVER, REAR COMBINATION LAMP, RH	\$	su	54.70	X
10	1 COVER, REAR COMBINATION LAMP, RH	\$	su	54.70	X
11	1 GARNISH, BACK DOOR SIDE, LH	\$	su	93.60	X
12	1 GARNISH, BACK DOOR SIDE, RH	\$	su	93.60	X
13	1 BOARD ASSY, BACK DOOR TRIM	\$		254.40	?
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$		51.20	?
15	1 REAR TAILGATE WEATHERSTRIP	\$	su	365.20	✓
16	1 REAR END PANEL	\$		602.10	?
17	1 TAILLAMP LOWER RH	\$	su	548.40	X
18	1 TAILLAMP UPPER RH	\$	su	557.90	X
19	1 REAR BUMPER SIDE RH	\$	su	232.00	X
20	1 REAR BUMPER SIDE LH	\$	su	232.00	X
21	1 TAILLAMP LOWER LH	\$		548.40	?
22	1 TAILLAMP UPPER LH	\$	cm	557.90	✓
23	1 PAN, REAR FLOOR	\$	re	572.10	X
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	n	77.00	X
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	n	192.90	X
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	n	77.00	X
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	n	192.90	X
28	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	n	290.50	X

Trans-cab Auto Services Pte Ltd**AAD1906-168**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5291C

29	1 REAR FENDER LH	\$	<i>17</i>	817.50	<i>X</i>
30	1 REAR FENDER RH	\$	<i>17</i>	817.50	<i>X</i>
31	1 MOULDING SUB-ASSY, ROOF TOP	\$	<i>11.1</i>	648.60	<i>✓</i>

	\$	11,954.57
25%	\$	2,988.64
	\$	8,965.93

*2,696.65***Special Nett**

1	1SET PARKING AID	\$	<i>Net</i>	700.00	<i>2000</i>
2	1SET REAR BUMPER CLIP	\$	<i>Net</i>	22.00	<i>✓</i>
3	2 REAR WINDSCREEN SELANT	\$	<i>Net</i>	80.00	<i>4000</i>
4	1 WINDSCREEN MOULDING	\$	<i>Net</i>	100.00	<i>✓</i>
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>Net</i>	100.00	<i>3000</i>
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>Net</i>	47.00	<i>✓</i>
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>Net</i>	52.90	<i>✓</i>
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>Net</i>	53.50	<i>✓</i>
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>Net</i>	80.00	<i>3000</i>
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>Net</i>	80.00	<i>3000</i>
11	1 REAR BUMPER PROTECTOR	\$	<i>Net</i>	100.00	<i>X</i>

TOTAL \$ 1,415.40**TOTAL PARTS \$ 10,381.33***605.40***LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	<i>8801</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>6001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>601</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>

Trans-cab Auto Services Pte Ltd**AAD1906-168**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5291C

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	?
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	na 170.00	X

TOTAL \$ 10,150.00**Over All Total \$ 29,497.26****(PART-BY-PART) Repair Days****20 DAYS****3 days**

17/10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: