

22/03/2002

ASS. REC. BY:

REF: CS/LPC 19010948/Kqd3er

Special Instruction:

Survivor: Kenneth

**ASSIGNMENT (Office)**

From (Person): Ong Li Li

of

LPC

Date/Time: 20.6.19

Estimated Cost:

Bill to:

**OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No:

SJS 15027

Insured:

YN 78124

at Workshop m/s

Ah Chang motor

Tel:

64835434

of

BLK 10 AMK Industrial Park 2A, AMK point #03-16

Policy No:

Claim No:

19/19/19/VCOO/021956

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18.6.2019

CA / REV / REP. / REV 24 HRS

rupi

H.O.D. Endorsement:

Date/Time:

20.6.19 500pm

Person Contacted:

Diana

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJS 15027 - CC6 / AIG 15004522 / AUM 392

DOA - 13/03/2019

YN 78124 - CC3 / AIG 15011271 / RUA 3v 2

DOA - 04/07/2019

11 Lm @ 3600 email &amp; confirmed. (Red @ 16796.60, 82%)



**Catherine Chong (LKK Auto)**

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Thursday, 20 June, 2019 4:55 PM  
**To:** Melody Yap; assignments@lkkauto.com; Admin-D (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Notice of Accident - Traffic accident involving SJS 1502 T and YN 7812 H (your insured) on 18 June 2019 at 11:20 am at/along Wan Tho Avenue ; Our ref: LCH.my/AMK10-90451.19 [External General]  
**Attachments:** 90451 (NOA).pdf

**Lonpac External - General**

Our Ref: 19/19/19/VC00/021956

Without Prejudice

Dear Nivitha

Please arrange Kenneth Kong to conduct TP survey.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

**From:** Melody Yap [mailto:mail@cheonghoh.sg]

**Sent:** Thursday, 20 June, 2019 4:35 PM

**To:** GERALD POH WEE BIN

**Cc:** MT\_Claim\_SG

**Subject:** Re: Notice of Accident - Traffic accident involving SJS 1502 T and YN 7812 H (your insured) on 18 June 2019 at 11:20 am at/along Wan Tho Avenue ; Our ref: LCH.my/AMK10-90451.19 [External General]

Dear Gerald,

We refer to the above matter.

Our client hereby nominate surveyor Kenneth Kong from LKK Auto Consultants Pte Ltd for the pre-repair survey ("PRS") of the damages to our client's vehicle.

Please be informed that our client's vehicle, SJS 1502 T is currently laying at our client's workshop, Ah Chang Motor Service Centre, Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo Kio Point #03-16 Singapore 568047. Kindly proceed to do the needful and you may contact the person in charge Mr Ng/Diana at 64835434 before your surveyor attend at the said workshop.

Kindly proceed to do the needful.

Thanks & regards,

Melody

**CHEONGHOH LAW CORPORATION**

Blk 53 Chin Swee Road #03-05 Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

On 19 Jun 2019, at 4:49 PM, GERALD POH WEE BIN <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)> wrote:

**Lonpac External - General**  
WITHOUT PREJUDICE

Our Ref : 19/19/19/VP05/021957

Dear Melody,

Please see list of motor surveyors below and revert.

1	Sharan Bin Sharif
2	Jackson Quek
3	Paul Thanapal
4	Aw Po Huat (Andrew)
5	Ng Chun Wei (Adam)
6	Mohd Taufik
7	Mohd Rasul
8	Kalvin Ang
9	Kenneth Kong
10	Adrian Ling

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

<image001.jpg>

*Lonpac External - General data is for internal / external use.*

**From:** Melody Yap [<mailto:mail@cheonghoh.sg>]

**Sent:** Wednesday, 19 June, 2019 3:42 PM

**To:** MT\_Claim\_SG

**Cc:** GERALD POH WEE BIN

**Subject:** Notice of Accident - Traffic accident involving SJS 1502 T and YN 7812 H (your insured)  
on 18 June 2019 at 11:20 am at/along Wan Tho Avenue ; Our ref: LCH.my/AMK10-90451.19

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Thanks & regards,  
Melody

**CHEONGHOH LAW CORPORATION**

Blk 53 Chin Swee Road #03-05 Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

## Shiau Chan (LKKAUTO)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 8 November 2019 3:24 PM  
**To:** 'ONG LI LI'; SUR  
**Cc:** 'MT\_Claim\_SG'; assignments  
**Subject:** RE: Notice of Accident - Traffic accident involving SJS 1502 T and YN 7812 H (your insured) on 18 June 2019 at 11:20 am at/along Wan Tho Avenue ; Our ref: LCH.my/AMK10-90451.19 [External General]

Dear Li Li,

Thank you for the email.

Dear Shiau Chan,

Kindly assist

**FYNA Our Ref : CS/LPC19010948/Kqd3**

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*Wkp: Ah Chang Motor*

---

**From:** ONG LI LI [mailto:[llong@lonpac.com](mailto:llong@lonpac.com)]  
**Sent:** Friday, 8 November 2019 3:22 PM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com); Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** RE: Notice of Accident - Traffic accident involving SJS 1502 T and YN 7812 H (your insured) on 18 June 2019 at 11:20 am at/along Wan Tho Avenue ; Our ref: LCH.my/AMK10-90451.19 [External General]

## Lonpac External - General

Dear Nivitha

We have received TP LOD, please submit your survey report.

Thanks.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse  
Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/06/2019 16:12
Date Of Accident	18/06/2019 11:20
Exact Location Of Accident	WAN THO AVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS1502T
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	KHONG MUN CHEW SAMUEL TIMOTHY ( KUANG WENCHAO )
NRIC No	S7633737C
Email Address	HICSIC@YAHOO.COM
Mobile Phone No	(LOCAL) +65-92307076
Alternative Phone No	OFFICE-92307076

#### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER 1.6 A
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5078054088-03
Cover Note Number	

#### Driver

Name of Driver	KHONG MUN CHEW SAMUEL TIMOTHY ( KUANG WENCHAO )
NRIC No	S7633737C
Date Of Birth	22/10/1976
Occupation	OUTDOOR
Date Of Driving Pass	25/09/2009
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92307076
Fax Number	
Contact Number	OFFICE-92307076
Email Address	HICSIC@YAHOO.COM

Address	BLK 417 CLEMENTI AVENUE 1 #11-273
Postcode	120417
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN. WILL REPAIR AND CLAIM AT AH CHANG MOTOR SERVICE CENTRE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7812H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

 18/06/19  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:


\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No.:

# Sketch Plan #2

## SKETCH PLAN

A-SJS1502T  
SAMUEL KHONG  
B-YN7812H



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON the 18/06/19 at 11.15am, my car was parked in front of Darul Ihsan girl's orphanage. after dropping a passenger off. My car was hit at the front from the right when a huge lorry turned out from the private property in Wan Tho avenue. As the space was very tight, the lorry did not wait for my car to leave before making a maneuver to turn to the right. Thus the back of the lorry hit my front bonnet as it turn towards the right. I was will claim and under repair at Ah Chong Motor Service Centre.


## DECLARATION

I/We declare the foregoing particulars are true in every respect.

18/06/19  
2:30pm

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# **AH CHANG MOTOR SERVICE CENTRE**

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047  
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre  
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Not Authorized  
 L1 Pay @ 3600h  
 Running After Point  
 4 days

**SJS1502T Mitsubishi Lancer**

**Accident Date: 18.06.2019**

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front bumper assy	B1 \$ 678.00	✓
2	2	Front bumper bracket	015B \$ 118.00	✓
3	2	Front bumper retainer	CM \$ 117.00	✓
4	1	Front bumper reinforcement	N \$ 278.00	X
5	2	Front grille assy	mjd1 \$ 118.00	✓
6	1	Front grille emblem	m \$ 58.00	✓
7	1	Front bonnet assy	B1 \$ 789.00	✓
8	2	Front bonnet hinges	N \$ 48.00	X
9	2	Front bonnet inner rubber	S \$ 64.00	X
10	2	Front bonnet rubber stopper	S \$ 28.00	X
11	1	Front bonnet lock mechanism	N \$ 63.00	X
12	1	Front left headlamp	S \$ 578.00	X
13	1	Front right headlamp	m3 d1 \$ 578.00	✓
14	1	Front left fender	N \$ 665.00	X
15	1	Front right fender	R1 \$ 665.00	✓
16	1	Front left fender inner cowling	CM \$ 121.00	✓
17	1	Front right fender inner cowling	CM \$ 121.00	✓
18	1	Front left fender lamp	S \$ 37.00	X
19	1	Front right fender lamp	S \$ 37.00	X
20	1	Front left fog lamp	S \$ 250.00	X
21	1	Front right fog lamp	S \$ 250.00	X
22	1	Front left fog lamp garnish	N/P \$ 78.00	X
23	1	Front right fog lamp garnish	N/P \$ 78.00	X
24	1	Front support panel assy	N \$ 563.00	X
25	2	Front support panel rubber stopper	S \$ 36.00	X
26	1	Front support panel top garnish	N/P \$ 250.00	X
27	1	Front intake air duct	S \$ 180.00	X
28	2	Front horns	S \$ 109.00	X
29	1	Front radiator assy	S \$ 1,278.00	X
30	2	Front radiator rubber mounting	S \$ 34.00	X
31	1	Front radiator fan cowling	S \$ 127.00	X
32	1	Front radiator fan blade	S \$ 83.00	X
33	1	Front radiator fan motor	S \$ 345.00	X
34	1	Front air-con condenser	S \$ 1,211.00	X
35	2	Front air-con condenser mounting	S \$ 32.00	X
36	1	Front air con condenser receiver dryer	S \$ 127.00	X
			\$ 10,192.00	
Less 10%			\$ 1,019.20	
			<u>\$ 9,172.80</u>	



# AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047  
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre  
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJS1502T Mitsubishi Lancer

Accident Date: 18.06.2019

No	Qty	Parts Description	Estimated Parts Price
37	1	Front air-con condenser fan blade	\$ 83.00 X
38	1	Front air-con condenser fan cowling	\$ 127.00 X
39	1	Front air-con condenser fan motor	\$ 315.00 X
40	1	Front wiper tank	\$ 89.00 ✓
41	1	Front left suspension assy	\$ 650.00 X
42	1	Front right suspension assy	\$ 650.00 X
43	1	Front left knuckle arm	\$ 352.00 X
44	1	Front right knuckle arm	\$ 352.00 X
45	1	Front left wheel hub bearing	\$ 252.00 X
46	1	Front right wheel hub bearing	\$ 252.00 X
47	1	Front left lower arm	\$ 430.00 X
48	1	Front right lower arm	\$ 430.00 X
			\$ 3,982.00
Less 10%			\$ 398.20
			\$ 3,583.80

## Special Nett Items

1	10	Front bumper clips	\$ 50.00 ✓
2	1	Front bumper lower spoiler	\$ 680.00 X
3	1	Front bumper lower spoiler sealant	\$ 80.00 X
4	10	Front bumper lower spoiler clips	\$ 40.00 X
5	6	Front support panel top garnish clips	\$ 30.00 X
6	4	Front grille clips	\$ 20.00 X
7	1	Front air-con gas	\$ 80.00 X
8	2	Front radiator coolant	\$ 80.00 X
9	1	Front left wheel rim	\$ 680.00 X
10	1	Front right wheel rim	\$ 680.00 X
11	1	Front left tyre	\$ 350.00 X
12	1	Front right tyre	\$ 350.00 X
13	6	Front left fender inner cowling clips	\$ 20.00 ✓
14	6	Front right fender inner cowling clips	\$ 20.00 ✓
15	1	Front no plate with garnish	\$ 80.00 450
			\$ 3,240.00

Total parts

\$ 15,996.60



# AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047  
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre  
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SJS1502T Mitsubishi Lancer

Accident Date: 18.06.2019

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,400.00	50d
2	To putty and spray painting front portion.	\$ 1,400.00	70d
3	To check wiring and focus front headlamp.	\$ 50.00	20c
4	To remove and install front bonnet lock mechanism.	\$ na 80.00	X
5	To remove and install air-con system to facilitate the repair and refill gas.	\$ na 150.00	X
6	To remove and install cooling system to facilitate the repair and check for leakage.	\$ na 150.00	X
7	To apply anti rust proofing to front affected area.	\$ 150.00	60d
8	To balance front left wheel.	\$ na 50.00	X
9	To balance front right wheel.	\$ na 50.00	X
10	To conduct wheel alignment.	\$ na 120.00	X
11	To remove and install front left undercarriage parts.	\$ na 350.00	X
12	To remove and install front right undercarriage parts.	\$ na 350.00	X
13	Towing service.	\$ 100.00	50d
<b>Total labour :</b>		<b>\$ 4,400.00</b>	

**Total parts : \$ 15,996.60**

**Total labour : \$ 4,400.00**

**Total repair cost : \$ 20,396.60**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:



**LKK Auto Consultants Pte Ltd**  
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
 TEL: 6256 3561 FAX: 6256 4315  
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS/LPC19010948/Kqd3e2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 13-11-2019	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YN 7812H	Veh. Inspected	SJS 1502T	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/19/19/VC00/021956	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	20/06/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI LANCER (A)	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JMYSTCS3A9U005735	Colour	METALLIC BLACK	
Odometer	153786	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	DOUBLESTAR	9 mm	
L/H Front Tyre	195/60 R15	DOUBLESTAR	9 mm	
R/H Rear Tyre	195/60 R15	DOUBLESTAR	9 mm	
L/H Rear Tyre	195/60 R15	DOUBLESTAR	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	18/06/2019	Inspection Date	21/06/2019	
Survey held at	AH CHANG MOTOR SERVICE CENTRE BLK 10 ANG MO KIO IND PARK 2A AMK AUTOPOINT #03-16 SINGAPORE 568047			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 1502T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER ASSY	BENT	678.00	678.00
2	FRONT BUMPER BRACKET	O/S BENT	118.00	59.00
2	FRONT BUMPER RETAINER	CRACKED	117.00	117.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	278.00	-
2	FRONT GRILLE ASSY	MTG DISTORTED	118.00	118.00
1	FRONT GRILLE EMBLEM	NECESSARY	58.00	58.00
1	FRONT BONNET ASSY	BENT	789.00	789.00
2	FRONT BONNET HINGES	TO REPAIR SEE LABOUR	48.00	-
2	FRONT BONNET INNER RUBBER	SERVICEABLE	64.00	-
2	FRONT BONNET RUBBER STOPPER	SERVICEABLE	28.00	-
1	FRONT BONNET LOCK MECHANISM	TO REPAIR SEE LABOUR	63.00	-
1	FRONT LEFT HEADLAMP	SERVICEABLE	578.00	-
1	FRONT RIGHT HEADLAMP	MTG DISTORTED	578.00	578.00
1	FRONT LEFT FENDER	TO REPAIR SEE LABOUR	665.00	-
1	FRONT RIGHT FENDER	BENT	665.00	665.00
1	FRONT LEFT FENDER INNER COWLING	CRACKED	121.00	121.00
1	FRONT RIGHT FENDER INNER COWLING	CRACKED	121.00	121.00
1	FRONT LEFT FENDER LAMP	SERVICEABLE	37.00	-
1	FRONT RIGHT FENDER LAMP	SERVICEABLE	37.00	-
1	FRONT LEFT FOG LAMP	SERVICEABLE	250.00	-
1	FRONT RIGHT FOG LAMP	SERVICEABLE	250.00	-
1	FRONT LEFT FOG LAMP GARNISH	NO SUCH PARTS	78.00	-
1	FRONT RIGHT FOG LAMP GARNISH	NO SUCH PARTS	78.00	-
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	563.00	-
2	FRONT SUPPORT PANEL RUBBER STOPPER	SERVICEABLE	36.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	NO SUCH PARTS	250.00	-
1	FRONT INTAKE AIR DUCT	SERVICEABLE	180.00	-
2	FRONT HORNS	SERVICEABLE	109.00	-
1	FRONT RADIATOR ASSY	SERVICEABLE	1,278.00	-
2	FRONT RADIATOR RUBBER MOUNTING	SERVICEABLE	34.00	-

Report Ref No. CS/LPC19010948/Kqd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RADIATOR FAN COWLING	SERVICEABLE	127.00	-
1	FRONT RADIATOR FAN BLADE	SERVICEABLE	83.00	-
1	FRONT RADIATOR FAN MOTOR	SERVICEABLE	345.00	-
1	FRONT AIR-CON CONDENSER	SERVICEABLE	1,211.00	-
2	FRONT AIR-CON CONDENSER MOUNTING	SERVICEABLE	32.00	-
1	FRONT AIR-CON CONDENSER RECEIVER DRYER	SERVICEABLE	127.00	-
1	FRONT AIR-CON CONDENSER FAN BLADE	SERVICEABLE	83.00	-
1	FRONT AIR-CON CONDENSER FAN COWLING	SERVICEABLE	127.00	-
1	FRONT AIR-CON CONDENSER FAN MOTOR	SERVICEABLE	315.00	-
1	FRONT WIPER TANK	DENTED	89.00	89.00
1	FRONT LEFT SUSPENSION ASSY	SERVICEABLE	650.00	-
1	FRONT RIGHT SUSPENSION ASSY	SERVICEABLE	650.00	-
1	FRONT LEFT KNUCKLE ARM	SERVICEABLE	352.00	-
1	FRONT RIGHT KNUCKLE ARM	SERVICEABLE	352.00	-
1	FRONT LEFT WHEEL HUB BEARING	NOT NECESSARY	252.00	-
1	FRONT RIGHT WHEEL HUB BEARING	NOT NECESSARY	252.00	-
1	FRONT LEFT LOWER ARM	SERVICEABLE	430.00	-
1	FRONT RIGHT LOWER ARM	SERVICEABLE	430.00	-
	LESS 10% DISCOUNT		-1,417.40	-339.30
			12,756.60	3,053.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
10	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT BUMPER LOWER SPOILER (SN)	NO SUCH PARTS	680.00	-
1	FRONT BUMPER LOWER SPOILER SEALANT (SN)	NOT NECESSARY	80.00	-
10	FRONT BUMPER LOWER SPOILER CLIPS (SN)	NOT NECESSARY	40.00	-
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
4	FRONT GRILLE CLIPS (SN)	NOT NECESSARY	20.00	-
1	FRONT AIR-CON GAS (SN)	NOT NECESSARY	80.00	-
2	FRONT RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
1	FRONT LEFT WHEEL RIM (SN)	SERVICEABLE	680.00	-
1	FRONT RIGHT WHEEL RIM (SN)	SERVICEABLE	680.00	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	350.00	-
1	FRONT RIGHT TYRE (SN)	SERVICEABLE	350.00	-
6	FRONT LEFT FENDER INNER COWLING CLIPS (SN)	NECESSARY	20.00	20.00
6	FRONT RIGHT FENDER INNER COWLING CLIPS (SN)	NECESSARY	20.00	20.00

Report Ref No. CS/LPC19010948/Kqd3e2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NO PLATE WITH GARNISH (SN)	DENTED	80.00	45.00
			3,240.00	135.00
	<b>LABOUR</b>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT BONNET HINGES, FRONT BONNET LOCK MECHANISM, FRONT LEFT FENDER AND FRONT SUPPORT PANEL ASSY.		1,400.00	500.00
	TO PUTTY AND SPRAY PAINTING FRONT PORTION.		1,400.00	700.00
	TO CHECK WIRING AND FOCUS FRONT HEADLAMP.		50.00	20.00
	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL AIR-CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS.	NOT NECESSARY	150.00	-
	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE.	NOT NECESSARY	150.00	-
	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA.		150.00	60.00
	TO BALANCE FRONT LEFT WHEEL.	NOT NECESSARY	50.00	-
	TO BALANCE FRONT RIGHT WHEEL.	NOT NECESSARY	50.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS.	NOT NECESSARY	350.00	-
	TO REMOVE AND INSTALL FRONT RIGHT UNDERCARRIAGE PARTS.	NOT NECESSARY	350.00	-
	TOWING SERVICE.		100.00	50.00
			4,400.00	1,330.00
<b>GRAND TOTAL</b>			<b>20,396.60</b>	<b>4,518.70</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,600.00</b>

Report Ref No. CS/LPC19010948/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.