

22/03/2003

ASS. REC. BY:

REF: CS/CT#9010967/ESd30

Special Instruction:

Surveyor: SEVA

ASSIGNMENT (Office)

From (Person): Chong Eon Sen of CTI Date/Time: 21/6/19 @ 10:33am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 3653Y Insured: GBB2420Z

at Workshop n/s: Kah Motor Tel: 8288 6309

of No. 255 Alexandra Road

Policy No: _____ Claim No: SNM19D202870

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. _____
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) 21/6/19
H.O.D. Endorsement: _____

Date/Time: 11:05am @ 21/6/19 Person Contacted: Joek Vehicle: IN OUT

| Date/Time | Action/Instruction |
|-----------|-------------------------------------|
| | <u>Schedule C</u> |
| | <u>SLF 3653Y - X</u> |
| | <u>GBB 2420Z - NA/INC10007486/r</u> |
| | <u>D.O.A. 12/04/2010</u> |
| | |
| | |
| | |

ASS. REC. BY: Steve REP: CTI

ASSIGNMENT

From: _____ Date: 24/6/19
 Estimated Cost: _____
 OD/ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLF 3653Y
 at Workshop m/s: Kah Motor
 of: No. 255 Alexandra Road
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: Morning
Jack @ 82886309
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS up
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLF 3653Y Yr Regn: 24/8/16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda HRV c.c. 1496
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 45443 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JH MRU 18306X 299263
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/62R16
 R: "
 BS/ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 19/6/19 D.O.I. 24/6/19
 Survey held at Kah Motor
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

| | |
|-----|-----|
| N/S | O/S |
| | |

| Date / Time | Action / Instruction |
|-------------|--|
| 31/7/19 | MV-72K Finalize confirm \$10,620.16, 8 days (Jack) (\$ 8,537.03 Red - 45%) |
| | RECEIVED 31 JUL 2019 |
| | <u>31/7/2019</u> |

Date/Time, File Pass to? 31/07/19 : Preli. Report
 1) Typist : Final Report
 Date/Time, File Return to? _____
 2) _____
 Report Format: _____
 Dump Sum 1.15 \$ 10,620.16 P/P
 Days Of Repair: 8
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : West end (\$)
 Survey Fee: 220
 Transportation: _____
 3 + PS. SI _____
 Photos _____
 Others _____
 TOTAL 220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 21 June 2019 10:33 AM
To: Jack Ng
Cc: assignments
Subject: RE: OUR REF: SNM19D202870/CHONGBS - ACCIDENT BETWEEN SLF 3653 Y AND YOUR INSURED GBB 2420 Z

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Jack Ng [mailto:jackng@honda.com.sg]
Sent: Friday, 21 June, 2019 10:30 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D202870/CHONGBS - ACCIDENT BETWEEN SLF 3653 Y AND YOUR INSURED GBB 2420 Z

Dear Boon Sen,

Kindly arrange LKK to survey this case.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937
DID : +65 6514 5481 FAX : +65 6362 5015
Kah Motor Co. Sdn. Bhd.
(A MEMBER OF ORIENTAL HOLDING BERHAD)
Website: www.honda.com.sg



Visit our
Facebook page

 Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, June 21, 2019 10:28 AM
To: Jack Ng <jackng@honda.com.sg>
Subject: RE: OUR REF: SNM19D202870/CHONGBS - ACCIDENT BETWEEN SLF 3653 Y AND YOUR INSURED GBB 2420 Z

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

| |
|----------------|
| ADRIAN LING |
| Kelvin Ang |
| SEE CHEW SENG |
| LOW SAR HUEI |
| HONG FOOK CHOY |
| XING QUO QIANG |
| KENNETH KONG |
| SIMON HO |
| CHUA WEIJIE |
| MARCUS CHUA |

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Jack Ng [mailto:jackng@honda.com.sg]

Sent: Friday, 21 June, 2019 10:21 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D202870/CHONGBS - ACCIDENT BETWEEN SLF 3653 Y AND YOUR INSURED GBB 2420 Z

Dear Boon Sen,

Noted and we accept 100% direct settlement in our client favor, kindly assist to arrange who to look for to survey this case.

We propose LOR \$100 / days and LOU \$70/ days.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Friday, June 21, 2019 10:18 AM

To: Jack Ng <jackng@honda.com.sg>

Subject: RE: OUR REF: SNM19D202870/CHONGBS - ACCIDENT BETWEEN SLF 3653 Y AND YOUR INSURED GBB 2420 Z

Without Prejudice

Dear Sir,

We are prepared to direct settle subject to estimate.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Jack Ng [<mailto:jackng@honda.com.sg>]

Sent: Friday, 21 June, 2019 10:10 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D202870/CHONGBS - ACCIDENT BETWEEN SLF 3653 Y AND YOUR INSURED GBB 2420 Z

Importance: High

Dear Boon Sen,

Kindly assist to advice on this case liability status.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page

 Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Lim Shu Min <shumin.lim@sg.cntaiping.com>
Sent: Thursday, June 20, 2019 4:46 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Jack Ng <jackng@honda.com.sg>
Subject: OUR REF: SNM19D202870/CHONGBS - ACCIDENT BETWEEN SLF 3653 Y AND YOUR INSURED GBB 2420 Z

Dear Boon Sen,

Please conduct PRS – SLF3653Y soonest possible.

File with Officer-In-Charge – Chong Boon Sen – 63896171.

Thank you

Lim Shu Min
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Jack Ng [<mailto:jackng@honda.com.sg>]
Sent: Thursday, 20 June, 2019 9:18 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: ACCIDENT BETWEEN SLF 3653 Y AND YOUR INSURED GBB 2420 Z

Dear all,

Kindly assist to register for direct settlement, attached is the GIA report and video footage.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this

communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|--------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 7079G |
| Vehicle Details | |
| Vehicle No.: | SLF3653Y |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 24 Jun 2019 |
| Vehicle Make: | HONDA |
| Vehicle Model: | HRV 1.5 LX CVT |
| Primary Colour: | Silver |
| Manufacturing Year: | 2016 |
| Engine No.: | L15B4530266 |
| Chassis No.: | JHMRU1830GX200263 |
| Maximum Power Output: | 96.0 kW (128 bhp) |
| Open Market Value: | \$22,809.00 |
| Original Registration Date: | 24 Aug 2016 |
| First Registration Date: | 24 Aug 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$18,933.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 23 Aug 2026 |
| PARF Rebate Amount: | \$14,199.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 23 Aug 2026 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$55,200.00 |
| COE Rebate Amount: | \$39,545.00 |
| Total Rebate Amount: | \$53,744.00 |

The information contained herein is correct as at 24 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|--|------------------------------------|
| Date Of Report | 19/06/2019 18:38 |
| Date Of Accident | 19/06/2019 16:15 |
| Exact Location Of Accident | SLIP ROAD TOWARDS ANG MO KIO AVE 1 |
| Country/State of Loss | SINGAPORE |
| DETAILS OF OWN VEHICLE | |
| Vehicle Registration Number | SLF3653Y |
| Insured/Policyholder | |
| Name Of Registered Owner | LOW SIEW YIN VIVIEN |
| NRIC No | S1707079G |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-96600162 |
| Alternative Phone No | OFFICE-96600162 |
| Vehicle Particulars | |
| Manufacturer | HONDA |
| Model | HR-V-1.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | |
| Cover Note Number | |
| Driver | |
| Name of Driver | LOW SIEW YIN VIVIEN |
| NRIC No | S1707079G |
| Date Of Birth | 05/10/1965 |
| Occupation | INDOOR |
| Date Of Driving Pass | 27/07/1990 |
| Driving Experience | 28 YEARS AND 10 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-96600162 |
| Fax Number | |
| Contact Number | OFFICE-96600162 |
| EMail Address | NOEMAIL |

| | |
|---|------------------------|
| Address | 338 SEMBAWANG CRESCENT |
| Postcode | |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |


DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------------------|
| Vehicle Registration Number | GBB2420Z - <i>China</i> |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Sketch Plan Pg. 1

Vehicle Number: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident occurred @ the slip road @ towards Anc Mo Kid Ave 1 (Junction of Meryman + Road 3 Anc Mo Kid Ave 1). Front vehicles stopped for pedestrian zebra crossing. I was able to stop on time however the vehicle behind (GBB 2420Z) didn't stop in time and hit the rear of my car.

Felt - Some discomfort on my back after the impact. Will consult medical adviser from the doctor later.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

24105 LOR
S15

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | | | |
|---------------------------|---|-----------------------|----------------------------|---------------------------|---------------|
| Customer : | CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 | Document No. : | SQT19002726 | Page | 1 |
| Registration No : | SLF3653Y | Date | : 21. Jun 2019 | Customer No. | : WZC008 |
| Chassis No : | JHMRU1830GX200263 | Svc Advisor | : JACK NG | Engine No | : L15B4530266 |
| Model : | HRV LX-SIN CVT YM 2016 | Date Time | : 21. Jun 2019 10:22:36 AM | Surveyor Name | : |
| Owner's Name : | LOW SIEW YIN VIVIEN | Survey Date | : | Authorisation Date | : |
| Ins Policy No. : | | | | | |
| Date of Accident : | 19/5/2019 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|---|-----|------------|--------|--------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER:LOW SIEW YIN VIVIEN OWNER INSURER:LIBERTY INSURANCE ACC DATE:19/06/2019 SURVEYED BY: DATE: REF NO: TP INSURER:CHINA TAIPING TP VEH:GBB 2420 Z | | | | | | |
| 33505-T7A-J01 | REFLECTOR ASSYR.RR. ? X NAI | 1 | 156.30 | 5 | 148.48 | 10.39 | 158.87 |
| 33555-T7A-J01 | REFLECTOR ASSYL.RR. X NAI | 1 | 156.30 | 5 | 148.48 | 10.39 | 158.87 |
| 04715-T7A-900ZZ | FACE,RR.BUMPER / DD | 1 | 463.70 | 5 | 440.51 | 30.84 | 471.35 |
| 04717-T7A-000ZZ | FACER.RR.BUMPER CORNER X NAI | 1 | 94.10 | 5 | 89.39 | 6.26 | 95.65 |
| 04718-T7A-000ZZ | FACEL.RR.BUMPER CORNER X NAI | 1 | 94.10 | 5 | 89.39 | 6.26 | 95.65 |
| 71593-T7A-J00 | SPACER,R.RR.BUMPER SIDE ? X NAI | 1 | 17.20 | 5 | 16.34 | 1.14 | 17.48 |
| 71598-T7A-J00 | SPACER,L.RR.BPR S X NAI | 1 | 17.20 | 5 | 16.34 | 1.14 | 17.48 |
| 91505-TM8-003 | CLIP,BUMPER / NCC | 8 | 2.30 | 5 | 17.48 | 1.22 | 18.70 |
| 68100-T7A-J20ZZ | TAIL GATE COMP / DD | 1 | 855.70 | 5 | 812.91 | 56.90 | 869.81 |
| 74440-T7A-003 | WEATHERSTRIPTAILGATE X NAI | 1 | 98.70 | 5 | 93.76 | 6.56 | 100.32 |
| 74813-T5A-003 | STRIKER ASSYTAILGATE X NAI | 1 | 24.70 | 5 | 23.46 | 1.64 | 25.10 |
| 74800-T7A-J02 | LOCK ASSYTAILGATE ? X NAI | 1 | 78.90 | 5 | 74.95 | 5.25 | 80.20 |
| 74890-T7A-J12ZS | GARNISH ASSYRR.LICENSE ? X NAI | 1 | 189.80 | 5 | 180.31 | 12.62 | 192.93 |
| 75701-T5A-000 | EMBLEMH ? / NCC | 1 | 10.70 | 5 | 10.16 | 0.71 | 10.87 |
| 90301-ST0-003 | NUTPUSH 3MM / NCC | 2 | 2.10 | 5 | 3.99 | 0.28 | 4.27 |
| 66100-T7A-300ZZ | PANEL COMPRR. ? / DD | 1 | 373.10 | 5 | 354.44 | 24.81 | 379.25 |
| 33502-T7A-J01 | LAMP UNITR. / CUT | 1 | 441.50 | 5 | 419.42 | 29.36 | 448.78 |
| 33552-T7A-J01 | LAMP UNITL. X NAI | 1 | 441.50 | 5 | 419.42 | 29.36 | 448.78 |
| 34150-T7A-J01 | LIGHT ASSY,R.LID / CUT | 1 | 269.90 | 5 | 256.40 | 17.95 | 274.35 |

Printed on 21/6/2019 11:01:33 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Acknowledged by Repairer

| | | | | | |
|------------------|--|--------------------|---------------------------|------|---|
| Customer | : CHINA TAIPING INSURANCE (S'PORE) PTE | Document No. | : SQT19002726 | Page | 2 |
| | : 3 ANSON ROAD #16-00 | Date | : 21 Jun 2019 | | |
| | : SPRINGLEAF TOWER | Customer No. | : WZC008 | | |
| | : SINGAPORE 079909 | Svc Advisor | : JACK NG | | |
| Registration No | : SLF3653Y | Engine No | : L15B4530266 | | |
| Chassis No | : JHMRU1830GX200263 | Date Time | : 21 Jun 2019 10:22:36 AM | | |
| Model | : HRV LX-SIN CVT YM 2016 | Surveyor Name | : | | |
| Owner's Name | : LOW SIEW YIN VIVIEN | Survey Date | : | | |
| Ins Policy No. | : | Authorisation Date | : | | |
| Date of Accident | : 19/5/2019 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|------------------------------------|-----|------------|----------------|----------------|---------------|------------------|
| 34155-T7A-J01 | LIGHT ASSYL.LID <i>x NMI x NMI</i> | 1 | 269.90 | 5 | 256.40 | 17.95 | 274.35 |
| NMRS-4P-TM3040L | 4PCS ACT RR.SENSOR <i>9 x NMI</i> | 1 | 320.00 | | 320.00 | 22.40 | 342.40 |
| 74940-SZW-003 | BUZZER ASSYSMART | 1 | 61.30 | 5 | 58.23 | 4.08 | 62.31 |
| 73214-T7J-H01 | RUBBER CR.WINDSHIELD DAMPER | 1 | 19.30 | 5 | 18.33 | 1.28 | 19.61 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 1 | 8.50 | 5 | 8.07 | 0.56 | 8.63 |
| 73254-T7J-H01 | RUBBER CL.WINDSHIELD DAMPER | 1 | 19.30 | 5 | 18.33 | 1.28 | 19.61 |
| 76711-T6A-003 | CAPPIVOT | 1 | 4.80 | 5 | 4.56 | 0.32 | 4.88 |
| 91501-S70-003 | FASTENER BW/SHIELD <i>npc</i> | 4 | 5.30 | 5 <i>NMI X</i> | 20.14 | 1.41 | 21.55 |
| 91502-S70-003 | FASTENER B | 2 | 5.30 | 5 | 10.07 | 0.70 | 10.77 |
| 91536-SS0-J01 | FASTENER AW/SHIELD | 2 | 3.80 | 5 | 7.22 | 0.51 | 7.73 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) | 2 | 60.00 | | 120.00 | 8.40 | 128.40 |
| Sum Item | | | | | 4456.98 | 311.97 | 4,768.95 |

| | | | | | | | |
|----------|--|---|---------|------------|---------|--------|---------|
| BOSUN | SUNDRIES | 1 | 100.00 | 50 | 100.00 | 7.00 | 107.00 |
| BOJSE | BODY JOINT SEALANT FOR TAILGATE | 1 | 150.00 | 120 | 150.00 | 10.50 | 160.50 |
| BOJSE | BODY JOINT SEALANT FOR END PANEL | 1 | 150.00 | 120 | 150.00 | 10.50 | 160.50 |
| BP00R | APPLY BODY UNDERSIDE COATING (N). | 1 | 250.00 | 200 | 250.00 | 17.50 | 267.50 |
| BML02I | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER | 1 | 380.00 | 280 | 380.00 | 26.60 | 406.60 |
| BA02R | REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 380.00 | | 380.00 | 26.60 | 406.60 |
| BC01R | REMOVE & REINSTALL REAR VIEW CAMERAS (N) | 1 | 450.00 | | 450.00 | 31.50 | 481.50 |
| BC02R | RESET & CALLIBRATE SMART ENTRY SYSTEM (N) | 1 | 450.00 | | 450.00 | 31.50 | 481.50 |
| BODAMKIT | WINDSCREEN DAM KIT. | 1 | 200.00 | 150 | 200.00 | 14.00 | 214.00 |
| BG02D | REMOVE & INSTALL RR. WINDSCREEN.(N) | 1 | 560.00 | | 560.00 | 39.20 | 599.20 |
| BKTG02R | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | 1 | 800.00 | 500 | 800.00 | 56.00 | 856.00 |
| BMI03D | REMOVE & INSTALL REAR COMPARTMENT LININGS | 1 | 800.00 | 500 (300?) | 800.00 | 56.00 | 856.00 |
| BKRP02M | CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS <i>2800-14 1680 p1x1</i> | 1 | 6000.00 | 1680 2800 | 6000.00 | 420.00 | 6420.00 |
| BP06R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>1350-14 900 p1x1</i> | 1 | 4000.00 | 900 1350 | 4000.00 | 280.00 | 4280.00 |

Printed on 21/6/2019 11:01:33 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Steve (LKK) with Proi - 206 24/6/19, 11:39am 8 to day R- b2 SM P/P

21/6/19



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|---|---------------------|----------------------------|---------------------------|---------------|
| Customer | : CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 | Document No. | : SQT19002726 | Page | 3 |
| Registration No | : SLF3653Y | Date | : 21. Jun 2019 | Customer No. | : WZC008 |
| Chassis No | : JHMURU1830GX200263 | Svc Advisor | : JACK NG | Engine No | : L15B4530266 |
| Model | : HRV LX-SIN CVT YM 2016 | Date Time | : 21. Jun 2019 10:22:36 AM | Surveyor Name | : |
| Owner's Name | : LOW SIEW YIN VIVIEN | Survey Date | : | Authorisation Date | : |
| Ins Policy No. | : | | | | |
| Date of Accident | : 19/5/2019 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|------|-------------|-----|------------|--------|------------------|-----------------|------------------|
| | | | | | Sum Labor | 14670.00 | 1,026.90 |
| | | | | | | | 15,696.90 |

| | | | | | | | |
|-------------|-------|--|--|--|---------------------------------|-----------|------------------|
| Survey By | _____ | | | | | | |
| Date & Time | _____ | | | | Total Amount | 19,126.98 | 1,338.87 |
| Excess | _____ | | | | Total (Inclusive of GST) | | 20,465.85 |
| Status | _____ | | | | | | |
| Signature | _____ | | | | | | |

19157.19

19165.25

Printed on 21/6/2019 11:01:33 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****7079G / LOW SIEW YIN
Chassis No: JHMRU1830GX200263
License No: SLF3653Y
Mileage: 38952
Engine No: L15B4530266

Document No: SVO19039956
Printed By: JACKNG
Order Date: 24. June 2019
Order Time: 11:44:00 AM
Service Advisor: JACK NG

| ITEM | DESCRIPTION | QTY | UNIT PRICE | DISC % | AMOUNT | 7% GST Amount | Amount incld GST |
|-------------------|----------------------------------|-----|------------|--------|--------------|---------------|------------------|
| 75722-T7W-A01 | EMBLEMRR. / <i>MP</i> | 1 | 13.30 | 25% | 9.97 | 0.70 | 10.67 |
| 75725-T8N-T00 | EMBLEM,RR. I-VTEC / <i>MP</i> | 1 | 14.50 | 25% | 10.87 | 0.76 | 11.63 |
| 91513-T6A-003 | CLIPTAILGATE SPOILER / <i>MP</i> | 5 | 2.50 | 25% | 9.37 | 0.66 | 10.03 |
| SUM PARTS: | | | | | 30.21 | 2.12 | 32.33 |
| TOTAL SGD | | | | | 30.21 | 2.12 | 32.33 |

Total Payable (SGD)

32.33

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

| | | | |
|--------------------|------------------------|-------------------------|---------------|
| Customer: | WZC008 / CHINA TAIPING | Document No: | SVO19039956 |
| Chassis No: | JHMRU1830GX200263 | Printed By: | JACKNG |
| License No: | SLF3653Y | Order Date: | 24. June 2019 |
| Mileage: | 38952 | Order Time: | 11:44:00 AM |
| Engine No: | L15B4530266 | Service Advisor: | JACK NG |

| ITEM | DESCRIPTION | QTY | UNIT | DISC % | AMOUNT | 7% GST Amount | Incld GST |
|-----------------|---|-----|--------|--------|-----------------|---------------|-----------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER:LOW SIEW YIN VIVIEN OWNER INSURER:LIBERTY INSURANCE ACC DATE:19/06/2019 SURVEYED BY: DATE: REF NO: TP INSURER:CHINA TAIPING TP VEH:GBB 2420 Z SUPPLEMENTARY PART | | | | | | |
| 04715-T7A-900ZZ | FACE,RR.BUMPER | 1 | 463.70 | 5 | 440.51 | 30.84 | 471.35 |
| 91505-TM8-003 | CLIP,BUMPER | 8 | 2.30 | 5 | 17.48 | 1.22 | 18.70 |
| 68100-T7A-J20ZZ | TAIL GATE COMP | 1 | 855.70 | 5 | 812.91 | 56.90 | 869.81 |
| 75701-T5A-000 | EMBLEMH | 1 | 10.70 | 5 | 10.16 | 0.71 | 10.87 |
| 90301-ST0-003 | NUTPUSH 3MM | 2 | 2.10 | 5 | 3.99 | 0.28 | 4.27 |
| 66100-T7A-300ZZ | PANEL COMPRR. | 1 | 373.10 | 5 | 354.44 | 24.81 | 379.25 |
| 33502-T7A-J01 | LAMP UNITR. | 1 | 441.50 | 5 | 419.42 | 29.36 | 448.78 |
| 34150-T7A-J01 | LIGHT ASSY,R.LID | 1 | 269.90 | 5 | 256.40 | 17.95 | 274.35 |
| 73214-T7J-H01 | RUBBER CR.WINDSHIELD DAMPER | 1 | 19.30 | 5 | 18.33 | 1.28 | 19.61 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 1 | 8.50 | 5 | 8.07 | 0.56 | 8.63 |
| 73254-T7J-H01 | RUBBER CL.WINDSHIELD DAMPER | 1 | 19.30 | 5 | 18.33 | 1.28 | 19.61 |
| 76711-T6A-003 | CAPPIVOT | 1 | 4.80 | 5 | 4.56 | 0.32 | 4.88 |
| 91502-S70-003 | FASTENER B | 2 | 5.30 | 5 | 10.07 | 0.70 | 10.77 |
| 91536-SS0-J01 | FASTENER AW/SHIELD | 2 | 3.80 | 5 | 7.22 | 0.51 | 7.73 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) | 2 | 60.00 | | 120.00 | 8.40 | 128.40 |
| 75722-T7W-A01 | EMBLEMRR. | 1 | 13.30 | 5 | 12.63 | 0.88 | 13.51 |
| 75725-T8N-T00 | EMBLEM,RR, I-VTEC | 1 | 14.50 | 5 | 13.77 | 0.96 | 14.73 |
| 91513-T6A-003 | CLIPTAILGATE SPOILER | 5 | 2.50 | 5 | 11.87 | 0.83 | 12.70 |
| | SUM PARTS: | | | | 2,540.16 | 177.79 | 2,717.95 |
| BOSUN | SUNDRIES | 1 | 50.00 | | 50.00 | 3.50 | 53.50 |
| BOJSE | 1718 BODY JOINT SEALANT FOR TAILGATE | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BOJSE | 1718 BODY JOINT SEALANT FOR END PANEL | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BP00R | 1718 APPLY BODY UNDERSIDE COATING (N). | 1 | 250.00 | | 250.00 | 17.50 | 267.50 |
| BML02I | 1438 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N) | 1 | 280.00 | | 280.00 | 19.60 | 299.60 |
| BA02R | 1466 REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 380.00 | | 380.00 | 26.60 | 406.60 |
| BC01R | 1466 REMOVE & REINSTALL REAR VIEW CAMERAS (N) | 1 | 450.00 | | 450.00 | 31.50 | 481.50 |
| BC02R | PARKING ASSIST SYSTEM RESET & CALLIBRATE SMART ENTRY SYSTEM (N) | 1 | 450.00 | | 450.00 | 31.50 | 481.50 |

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMRU1830GX200263
License No: SLF3653Y
Mileage: 38952
Engine No: L15B4530266

Document No: SVO19039956
Printed By: JACKNG
Order Date: 24. June 2019
Order Time: 11:44:00 AM
Service Advisor: JACK NG

| | | | | | | |
|----------------------------|---|---|--------------------|------------------|---------------|------------------|
| BODAMKIT | | 1 | 150.00 | 150.00 | 10.50 | 160.50 |
| | WINDSCREEN DAM KIT. | | | | | |
| BG02D | 1438 | 1 | 560.00 | 560.00 | 39.20 | 599.20 |
| | REMOVE & INSTALL RR. WINDSCREEN. (N) | | | | | |
| BKTG02R | 1466 | 1 | 560.00 | 560.00 | 39.20 | 599.20 |
| | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N) | | | | | |
| BMI03D | 1466 | 1 | 560.00 | 560.00 | 39.20 | 599.20 |
| | REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N) | | | | | |
| BKRP02M | 1466 | 1 | 2,800.00 | 2,800.00 | 196.00 | 2,996.00 |
| | CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM | | | | | |
| BP06R | 1718 | 1 | 1,350.00 | 1,350.00 | 94.50 | 1,444.50 |
| | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | | | | | |
| | | | SUM LABOUR: | 8,080.00 | 565.60 | 8,645.60 |
| | | | TOTAL SGD | 10,620.16 | 743.39 | 11,363.55 |
| Total Payable (SGD) | | | | | | 11,363.55 |

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 04 Jul 2019 | | 04 Jul 2019 13:53 Edit Adj Rpt | S\$10,620.16 Edit Estimates | S\$10,620.16 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|----------------------------------|---|--|--|----------------|----------------|--------------------|---------------------|-------------------|--------------|
| CLAIM SUBFOLDER DETAILS | | [Created by insurer] | | | | | | | |
| Insured: | -, Co. Reg. No.: - | | | | | | | | |
| Main Claimant: | LOW SIEW YIN VIVIEN , ID: S1707079G | | | | | | | | |
| Vehicle Reg. No.: | SLF3653Y | Date of Loss: | 19/06/2019 16:00 - :59 [33 Months and 26 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / SNM19D202870C02 | Policy/Cover Note No.: | DMCVSN30686918000 | | | | | | |
| Vehicle Reg. No. (Insured): | GBB2420Z | Policy No. (Claimant): | | | | | | | |
| | | Excess: | S\$0.00 | | | | | | |
| Repairer: | Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671 | | | | | | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen] | | | | | | | | |
| Claimant's Insurer: | Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 15/07/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | View All Compose Case Mail | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | View All Search Tasks Create New Task Complete | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SLF3653Y (SNM19D202870C02)

[GBB2420Z]

TP

LOW SIEW YIN VIVIEN

Jun 19 2019 4:00PM

[-]

Kah Motor Co Sdn Bhd

| Upload Documents | | Upload Photos | | Compose New Letter | | View <input type="button" value="View In Browser"/> | |
|----------------------|-----------------|--|--|--------------------|-----------|---|-------------------------------------|
| Video | | | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Kah Motor Co Sdn Bhd (Ubi) | | | Thumbnail | Print | |
| 1 | 19/06/19 18:55 | Video - Accident [Linked Accident Report Documents] | | | Load MP4 | | |
| Photos/Images | | | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | Thumbnail | Print | |
| 1 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 31/07/19 10:16 | Odometer Reading | | | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 31/07/19 10:16 | Odometer Reading | | | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 28 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 29 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 30 | 31/07/19 10:16 | General View | | | Load JPG | <input checked="" type="checkbox"/> | |
| 31 | 31/07/19 10:17 | Photographs of Damaged Items | | | Load JPG | <input checked="" type="checkbox"/> | |
| 32 | 31/07/19 10:17 | Photographs of Damaged Items | | | Load JPG | <input checked="" type="checkbox"/> | |
| 33 | 31/07/19 10:17 | Photographs of Damaged Items | | | Load JPG | <input checked="" type="checkbox"/> | |

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|-------|----------------|------------------------------|------------|-------------------------------------|
| No | Finalized On | Kah Motor Co Sdn Bhd (Ubi) | Thumbnail | Print |
| 34 | 31/07/19 10:17 | Photographs of Damaged Items | Load JPG | <input checked="" type="checkbox"/> |
| 35 | 31/07/19 10:17 | Photographs of Damaged Items | Load JPG | <input checked="" type="checkbox"/> |
| 36 | 31/07/19 10:17 | Photographs of Damaged Items | Load JPG | <input checked="" type="checkbox"/> |
| 37 | 31/07/19 10:17 | Photographs of Damaged Items | Load JPG | <input checked="" type="checkbox"/> |
| 38 | 31/07/19 10:17 | Photographs of Damaged Items | Load JPG | <input checked="" type="checkbox"/> |
| 39 | 31/07/19 10:17 | Photographs of Damaged Items | Load JPG | <input checked="" type="checkbox"/> |
| 40 | 31/07/19 10:17 | Photographs of Damaged Items | Load JPG | <input checked="" type="checkbox"/> |
| 41 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 42 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 43 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 44 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 45 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 46 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 47 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 48 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 49 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 50 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |
| 51 | 31/07/19 10:17 | Reinspection Photo | Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 13/08/19 15:23 | Supplementary | Load PDF | |

Linked Accident Report Documents

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|-------|----------------|----------------------------|------------|-------------------------------------|
| No | Finalized On | Kah Motor Co Sdn Bhd (Ubi) | Thumbnail | Print |
| 1 | 19/06/19 18:55 | Video - Accident | Load MP4 | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------------------|------------|-------------------------------------|
| No | Finalized On | Kah Motor Co Sdn Bhd (Ubi) | Thumbnail | Print |
| 1 | 19/06/19 18:55 | Accident Statement | Load HTM | |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|----------------------------|------------|-------------------------------------|
| No | Finalized On | Kah Motor Co Sdn Bhd (Ubi) | Thumbnail | Print |
| 1 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 19/06/19 18:46 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|--|--|------------|-------------------------------------|
|---------------|--|--|------------|-------------------------------------|

View

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|-------|----------------|----------------------------|------------|-------------------------------------|
| No | Finalized On | Kah Motor Co Sdn Bhd (Ubi) | | Thumbnail Print |
| No | Finalized On | Kah Motor Co Sdn Bhd (Ubi) | | Thumbnail Print |
| 1 | 19/06/19 18:46 | Sketch Plan | | Load TIF |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) |
|--|
| <div style="border: 1px solid black; height: 40px;"></div> |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19010967/ESD3E2

Date: 14/08/2019

REFERENCE

| | | |
|---|------------------------------|---------------------------|
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: DMCVSN30686918000 | |
| Claimant Vehicle No: SLF3653Y | Insured Vehicle No: GBB2420Z | |
| Date of Loss: 19/06/2019 | Nature of Claim: TP | Claim No: SNM19D202870C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | |
|--|--|-------------------------------|
| Reg No: SLF3653Y | | Engine No: L15B4530266 |
| Make & Model: HONDA HR-V, 1.5 LX CVT (A) | | Chassis No: JHMUR1830GX200263 |
| Reg. Date: 24/08/2016 (Man. Year: 2016) | | Odometer: 45443 km |
| Colour: Silver | | |
| Engine Capacity: 1496 cc | | |
| Market Value/New Car Price: N/A | | |
| Sum Insured (S\$): Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 215/60 R16 | Rear Tyre Size: | 215/60 R16 |
| Front Left Side: | Dunlop 6 mm | Rear Left Side: | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 4,595.25 | 2,590.16 | 2,005.09 | 43.63 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 14,570.00 | 8,030.00 | 6,540.00 | 44.89 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 19,165.25 | 10,620.16 | 8,545.09 | 44.59 |
| + GST 7.00/7.00% (S\$) | 1,341.57 | 743.41 | 598.16 | 44.59 |
| Nett Amount (S\$) | 20,506.82 | 11,363.57 | 9,143.25 | 44.59 |

INSPECTION

| | | | |
|---------------------|------------|---------------|--|
| Date of Assignment: | 04/07/2019 | | |
| Date Inspected: | 24/06/2019 | Inspected At: | Kah Motor Co Sdn Bhd (Ubi) NO. 255 ALEXANDRA ROAD SINGAPORE 159937 |

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | |
|----------------------|--|
| Reference | |
| Part Source: | (Last Synchronised: 14 Aug 2019) |
| Parts: | N/A HONDA HR-V 1.5 LX CVT (A) (Model not available in database) |
| Labour: | Repairer's (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLF3653Y) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|---------------|------------|------------|
| 1 | 1 | | *REFLECTOR ASSYR.RR. | Not Necessary | 148.48 FS | *- FS |
| 2 | 1 | | *REFLECTOR ASSYL.RR. | Not Necessary | 148.48 FS | *- FS |
| 3 | 1 | | *FACE,RR.BUMPER | Dented | 440.51 FS | *440.51 FS |
| 4 | 1 | | *FACER.RR.BUMPER CORNER | Not Necessary | 89.39 FS | *- FS |
| 5 | 1 | | *FACEL.RR.BUMPER CORNER | Not Necessary | 89.39 FS | *- FS |
| 6 | 1 | | *SPACER,R.RR.BUMPER SIDE | Not Necessary | 16.34 FS | *- FS |
| 7 | 1 | | *SPACER,L.RR.BPR S | Not Necessary | 16.34 FS | *- FS |
| 8 | 1 | | *CLIP,BUMPER (8PCS) | Necessary | 17.48 FS | *17.48 FS |
| 9 | 1 | | *TAIL GATE COMP | Dented | 812.91 FS | *812.91 FS |
| 10 | 1 | | *WEATHERSTRIPTAILGATE | Not Necessary | 93.76 FS | *- FS |
| 11 | 1 | | *STRIKER ASSYTAILGATE | Not Necessary | 23.46 FS | *- FS |
| 12 | 1 | | *LOCK ASSYTAILGATE | Not Necessary | 74.95 FS | *- FS |
| 13 | 1 | | *GARNISH ASSYRR.LICENSE | Not Necessary | 180.31 FS | *- FS |
| 14 | 1 | | *EMBLEMH | Necessary | 10.16 FS | *10.16 FS |
| 15 | 1 | | *NUTPUSH 3MM (2PCS) | Necessary | 3.99 FS | *3.99 FS |
| 16 | 1 | | *PANEL COMPRR. | Dented | 354.44 FS | *354.44 FS |
| 17 | 1 | | *LAMP UNITR. | Cut | 419.42 FS | *419.42 FS |
| 18 | 1 | | *LAMP UNITL. | Not Necessary | 419.42 FS | *- FS |
| 19 | 1 | | *LIGHT ASSY,R.LID | Cut | 256.40 FS | *256.40 FS |
| 20 | 1 | | *LIGHT ASSYL.LID | Not Necessary | 256.40 FS | *- FS |
| 21 | 4 | | *ACT RR.SENSOR | Not Necessary | 320.00 FS | *- FS |
| 22 | 1 | | *BUZZER ASSYSMART | Not Necessary | 58.23 FS | *- FS |
| 23 | 1 | | *RUBBER CR.WINDSHIELD DAMPER | Necessary | 18.33 FS | *18.33 FS |
| 24 | 1 | | *DAMPERSTD 5X5 | Necessary | 8.07 FS | *8.07 FS |
| 25 | 1 | | *RUBBER CL.WINDSHIELD DAMPER | Necessary | 18.33 FS | *18.33 FS |
| 26 | 1 | | *CAPPIVOT | Necessary | 4.56 FS | *4.56 FS |
| 27 | 4 | | *FASTENER BW/SHIELD | Not Necessary | 20.14 FS | *- FS |
| 28 | 1 | | *FASTENER B (2PCS) | Necessary | 10.07 FS | *10.07 FS |
| 29 | 2 | | *FASTENER AW/SHIELD | Necessary | 7.22 FS | *7.22 FS |
| 30 | 2 | | *WINDSCREEN SEALANT | Necessary | 120.00 FS | *120.00 FS |
| 31 | 1 | | *SUNDRIES | Necessary | 100.00 FS | *50.00 FS |
| 32 | 1 | | *EMBLEMRR. | Necessary | 12.63 FS | *12.63 FS |
| 33 | 1 | | *EMBLEM,RR.I-VTEC | Necessary | 13.77 FS | *13.77 FS |
| 34 | 1 | | *CLIPTAILGATE SPOILER (5PCS) | Necessary | 11.87 FS | *11.87 FS |

F=Franchise part. S=SpcNett.

| | | |
|---------------------------|-----------------|-----------------|
| Total Parts (\$\$) | 4,595.25 | 2,590.16 |
|---------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|------------------|-----------------|
| Labour Items | | | | |
| 1 | BODY JOINT SEALANT FOR TAILGATE | New | 150.00 | 120.00 |
| 2 | BODY JOINT SEALANT FOR END PANEL | New | 150.00 | 120.00 |
| 3 | APPLY BODY UNDERSIDE COATING | New | 250.00 | 250.00 |
| 4 | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER | New | 380.00 | 280.00 |
| 5 | REMOVE & RENEW REVERSE SENSORS - 4PCS | New | 380.00 | 380.00 |
| 6 | REMOVE & REINSTALL REAR VIEW CAMERAS | New | 450.00 | 450.00 |
| 7 | RESET & CALIBRATE SMART ENTRY SYSTEM | New | 450.00 | 450.00 |
| 8 | WINDSCREEN DAM KIT | New | 200.00 | 150.00 |
| 9 | REMOVE & INSTALL RR.WINDSCREEN | New | 560.00 | 560.00 |
| 10 | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | New | 800.00 | 560.00 |
| 11 | REMOVE & INSTALL REAR COMPARTMENT LININGS | New | 800.00 | 560.00 |
| 12 | CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS | New | 6,000.00 | 2,800.00 |
| 13 | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P) | New | 4,000.00 | 1,350.00 |
| Gross Labour Cost (S\$) | | | 14,570.00 | 8,030.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >