

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CT1

Date/Time: 21.6.19 11.01a.m

Minimum

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGM 3813A Insured:

at Workshop m/s Lai Huat Tel: 645 38110

of 160 Sin ming Drive #04-01

Policy No: DMPCSN 1760351801 Claim No: SNM1917702716

Sum Insured: Excess: \$1000.00

Make of Veh: D.O.A. 6.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 21.6.19 11.27a.m Person Contacted: Debrah Vehicle: IN / OUT

| Date/Time | Action/Instruction (✓) Estimate  |
|-----------|--|
|           | SGM 3813A - X  |
| 24/06/19  | @ 14:29 pm revised PA to Chong Boon Sen via mer-mex.                         |
| 24/06/19  | @ 14:30 pm mandate requested authorize repair to Chong Boon Sen via mer-mex. |

ASS. REC. BY:

REF: CT2 / CS / CT1 19010970 / ksd3

ASSIGNMENT

Kenneth

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop mv's \_\_\_\_\_ C / Ink

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 1000

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|                                     |                                     |
|-------------------------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| N/S                                 | O/S                                 |
| <input type="checkbox"/>            | <input type="checkbox"/>            |

Bal. or Market Value: 882/c

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 24 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / 0526

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: PGM 3813A Yr Regn: 10, 06

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MIT Evo 9 c.c. 1997

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: CT9A. 040555P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / R/Rim / STD A/Rim or

Tyre Size: F: GY 215/40R18

R: Yokoo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 6/6/19 D.O.I. 21/6/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis Frame / Body Structure affected due to collision. ✓

| Date / Time | Action / Instruction   |
|-------------|--|
| 26/06/19    | File pass to @ 09:28 am mandate approved by Alfred Koh via m:mer.                          |
| 26/06/19    | @ 10:22 am inform CIA to Jenny (repairer) via email vehicle has towed out, not yet repair. |

RECEIVED 27 SEP 2019

Date/Time, File Pass to? 26/09/19 : Prell. Report

1) Typ: 4 : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 24

Resurvey No. of Trip: \_\_\_\_\_

|                 |     |
|-----------------|-----|
| Survey Fee:     | 220 |
| Transportation: |     |
| S + RS, SI      |     |
| Fixings         |     |
| Others          |     |
| TOTAL           |     |

- Add Fee:
- Site Insp (\$)
  - Interview (\$)
  - Tech Invs (\$)
  - Weekend (\$)

Report Format: Prell:

Lump Sum / I.B.I: (\$)

**...CLAIM SUBFOLDER...(New Assignment)**

| CLAIM SUBFOLDER TRACKING |                             |                                      |                                |         |               |            |                                      |
|--------------------------|-----------------------------|--------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Case                     | Notified                    | Est Submitted                        | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
| Main                     | 20 Jun 2019<br>Sendback Est | 21 Jun 2019<br>09:49<br>S\$35,409.65 | 21 Jun 2019<br>11:01<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS**

Insured: **PANG SENG JIAN**, ID: S7608188C, Tel: +6597491898, Email: JEFFPANG3813@GMAIL.COM

|                   |                                  |                        |   |
|-------------------|----------------------------------|------------------------|---|
| Vehicle Reg. No.: | <b>SGM3813A</b>                  | Date of Loss:          | 06/06/2019 16:00 - :59<br>[151 Months and 21 Days From LTA Reg Date (Man Yr)] |
| Claim Type:       | <b>OD / SNM19D202716-CHONGBS</b> | Policy/Cover Note No.: | DMPCSN1760351801<br>(Comprehensive)   |
|                   |                                  | Excess:                | S\$1,000.00   |

Repairer: **Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)** 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Chong Boon Sen**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Final Rpt due 02/07/2019]

Driver/Custodian: **PANG SENG JIAN (43 / Male)**, NRIC: S7608188C, Tel: +6597491898 Email: JEFFPANG3813@GMAIL.COM

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

RE: SGM 3813A OD Date of Loss - 06/06/2019

Jenny Lim <jenny.lim@laihuat.com.sg>

Thu 26/9/2019 4:39 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Dear Shirley

The vehicle has towed out.

Thank you.

Kind regards.

Jenny Lim  
for LAI HUAT (MENG KEE) MOTOR PTE LTD  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03  
Sin Ming Autocity  
Singapore 575722  
Tel: 64538110  
Fax: 64596267

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Thursday, 26 September, 2019 4:00 PM  
**To:** 'Jenny Lim'  
**Subject:** Re: SGM 3813A OD Date of Loss - 06/06/2019

Hi Jenny,

If vehicle has been repaired, please finalize with us.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 26 June 2019 10:21 AM  
**To:** 'Jenny Lim' <jenny.lim@laihuat.com.sg>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** SGM 3813A OD Date of Loss - 06/06/2019

Dear Jenny,

As instructed by our client, please proceed to repair the insured vehicle **SGM 3813A (Excess \$ 1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 26 June 2019 10:22 AM  
**To:** 'Jenny Lim'  
**Cc:** SUR  
**Subject:** SGM 3813A OD Date of Loss - 06/06/2019

Dear Jenny,

As instructed by our client, please proceed to repair the insured vehicle **SGM 3813A (Excess \$ 1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### View Received Message

This mail is associated with :  
**SGM3813A (SNM19D202716-CHONGBS)**  
OD  
Jun 6 2019 4:00PM  
[PANG SENG JIAN]  
Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 26/06/2019 09:28 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$35275.65) - SGM3813A - Claim Handler: Chong Boon Sen

Approved:35275.65:Proceed to authorize repairs UP TO \$35,275.65 BEFORE Excess of \$1,000.00. RE-INSPECTION of vehicle required.

**DOCUMENTS SUMMARY**  
There are no documents.

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 24 Jun 2019

**Preliminary Advice**

|                    |  |                         |                    |
|--------------------|--|-------------------------|--------------------|
| Vehicle No         | : SGM3813A   | Accident Date           | : 06/06/2019       |
| Make               | : MITSUBISHI LANCER EVOLUTION IX   | Policy No.              | : DMPCSN1760351801 |
| Assignment Date    | : 21/06/2019   | Excess                  | : S\$1,000.00      |
| Date of Inspection | : 21/06/2019   | Est. Duration of Repair | : 24 days          |
| Inspection At      | : Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)<br>160 Sin Ming Drive #04-01, Sin Ming AutoCity<br>Singapore 575722 |                         |                    |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion, and parts claimed are consistent to the accident. The undercarriage & body structure affected due to collision.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 35,409.65 |
| Revised Amount              | :S\$ | 27,011.15 |
| Check Items (Estimated)     | :S\$ | 8,264.50  |
| Total                       | :S\$ | 35,275.65 |
| Lump Sum Repair             | :S\$ |           |

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 82,000.00 |
| COE / PARF Rebate  | :S\$ | 32,060.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 49,940.00 |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                 |
|----------------------------|---------------------------------|
| Date Of Report             | 08/06/2019 11:46                |
| Date Of Accident           | 06/06/2019 16:45                |
| Exact Location Of Accident | FROM KPE TO BUANGKOK EAST DRIVE |
| Country/State of Loss      | SINGAPORE                       |

### DETAILS OF OWN VEHICLE

|  |   |
|--|---|
| Vehicle Registration Number  | SGM3813A                                      |
| <b>Insured/Policyholder</b>  |   |
| Name Of Registered Owner   | PANG SENG JIAN                                |
| NRIC No  | S7608188C                                     |
| Email Address  | JEFFPANG3813@GMAIL.COM                        |
| Mobile Phone No  | (LOCAL) +65-97491898                          |
| Alternative Phone No   | OTHERS-97491898                               |
| <b>Vehicle Particulars</b>   |   |
| Manufacturer   | MITSUBISHI                                    |
| Model  | EVO-9 MR GSR 2.0M                             |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE                                   |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES   |
| If No, Please state action to be taken                                       |   |
| Vehicle Category   | PRIVATE CAR                                   |
| <b>Insurance Company</b>   |   |
| Name of Insurance Company  | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage   | COMPREHENSIVE                                 |
| Fleet Policy   | NO  |
| Policy Number  | DMPCSN1760351801                              |
| Cover Note Number  |   |
| <b>Driver</b>  |   |
| Name of Driver   | PANG SENG JIAN                                |
| NRIC No  | S7608188C                                     |
| Date Of Birth  | 22/03/1976                                    |
| Occupation   | INDOOR  |
| Date Of Driving Pass   | 20/09/2000                                    |
| Driving Experience   | 18 YEARS AND 8 MONTHS                         |
| Gender   | MALE  |
| Mobile Number  | (LOCAL) +65-97491898                          |
| Fax Number   |   |
| Contact Number   | OTHERS-97491898                               |
| EMail Address  | JEFFPANG3813@GMAIL.COM                        |

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The incident took place at a bend coming out of KPE from Buangkok exit, along Buangkok East Drive near lamp post 148F.

Condition of road is wet due to heavy rain, which resulted in the car skidding while negotiating with the bend.

It was still drizzling when accident occur

Accident : 06 JUN 2019 / 4:45 PM

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

*[Signature]*  
 Policyholder's Signature  
 Date & Time: 08 JUN 2019

*[Signature]*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 8 JUN 2019

*[Signature]*  
 Reporting Centre Personnel's Signature  
 Name: Doh Kwee Choo  
 NRIC/FIN No.: S6840583A



**SINGAPORE  
POLICE FORCE**



T/20190606/7014

2 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190606/7014

## CONTINUATION OF REPORT

| Details of Person Involved        |                |  |                                   |
|-----------------------------------|----------------|--|-----------------------------------|
| Any Pedestrian Involved: No       |                |  |                                   |
| No. of Pedestrians Injured: NIL   |                | Use of Pedestrian Crossing: NA         |                                   |
| Passenger                         |                |  |                                   |
| Name                              | TAN HUI LING   | ID No.                                 | S8505423F                         |
| Related Vehicle                   | SGM3813A (Car) | Contact No.                            | 81861438                          |
| Hospital/Clinic                   | NIL            | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL            | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL            | Degree of Injury                       | NIL                               |
| Driver                            |                |  |                                   |
| Name                              | PANG SENG JIAN | ID No.                                 | S7608188C                         |
| Related Vehicle                   | SGM3813A (Car) | Contact No.                            | 97491898                          |
| Hospital/Clinic                   | NIL            | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL            | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL            | Degree of Injury                       | NIL                               |

**Brief Details.**

The incident took place at a bend coming out of KPE from Buangkok exit, along Buangkok East Drive near lamppost 148F.

Condition of the road is wet due to the heavy rain, which resulted in the car skidding while negotiating with the bend.

It was still drizzling when accident occurred.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 8188C

**Vehicle Details**

Vehicle No.: SGM3813A  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 14 Jun 2019  
Vehicle Make: MITSUBISHI  
Vehicle Model: EVO-9 MR GSR 2.0 M  
Primary Colour: Yellow  
Secondary Colour: Black  
Manufacturing Year: 2006  
Engine No.: 4G63LS2069  
Chassis No.: CT9A0405558  
Maximum Power Output: 206.0 kW (276 bhp)  
Open Market Value: \$33,026.00  
Original Registration Date: 16 Oct 2006  
First Registration Date: 16 Oct 2006  
Transfer Count: 3  
Actual ARF Paid: \$36,329.00

**Intended PARF Rebate Details**

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 31 May 2026  
COE Category: B - Car (1601cc & above)  
COE Period(Years): 10  
PQP Paid: \$46,048.00  
COE Rebate Amount: \$32,060.00  
**Total Rebate Amount: \$32,060.00**

The information contained herein is correct as at 14 Jun 2019

OK



中国太平保险(新加坡)有限公司  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
Co. Reg. No. 200208384E

MX1F  
R SN  
AN0444A  
Cov.Type: C

MOTOR PRIVATE CAR

**CERTIFICATE OF INSURANCE**

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1959  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

|  |   |  |
|--|---|--|
| CERTIFICATE No.  | DMPCSN1760351801  | Engine No :4G63LS2069<br>ChaNo:CT9A0405558   |
| 1. Index Mark and Registration Number of Vehicle   | SGM3813A  | AUTOSAFE<br>*****  |
| 2. Name of Policy Holder   | PANG SENG JIAN  |  |
| 3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment | 16 October 2018   | Named Drivers Ex Sect. I ..... S\$1,500.00<br>Additional Ex Other than Named Drivers:<br>Ex Sect. I - Age <= 25..... S\$3,000.00 |
| 4. Date of Expiry of insurance   | 15 October 2019   | Ex Sect. I - Age >= 26..... S\$500.00<br>* Age as at date of accident<br>EX ON WINDSCREEN ..... S\$100.00                        |
| 5. Persons or Classes of Persons entitled to drive*  | <p>(a) The Policyholder.</p> <p>(b) Any other person who is driving on the Policyholder's order or with his permission.</p> <p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor vehicle.</p>  |  |
| 6. Limitations as to use**   | <p>Use for social, domestic and pleasure purposes and for the Policyholder's business.<br/>The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.</p> <p>Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.<br/>One time waiver of Excess for the first S\$500 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised workshops for each Policy Year.</p> |  |

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: ..... META AGENCY PTE LTD .....  
Authorised Officer

.....  
Authorised Signatory

# Lai Huat (Meng Kee) Motor Pte Ltd

160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming  
Autocity  
575722

Claim Reference: DMPCSN1760351801  
Assessment number: 70580  
Version: 1810  
Date calculated: 20/06/2019 11:39 AM

Full Report  
Registration: SGM 3813A  
Printed: 20/06/2019 11:39 AM

## Summary Information

### Claim

|                        |                  |                   |   |
|------------------------|------------------|-------------------|---|
| Location:              | Singapore (SG)   | Work Provider:    | China Taiping Insurance (Singapore) Pte Ltd |
| Printed by:            | Jenny Lim        | Currency:         | SGD   |
| Claim Reference:       | DMPCSN1760351801 | Date of Incident: | 06/06/19                                    |
| Estimated Repair Time: |                  | Hire Car Start:   |   |
| Actual Repair Days:    |                  | Hire Car End:     |   |

## Vehicle Details

### Vehicle

|                     |            |
|---------------------|------------|
| Manufacturer:       | MITSUBISHI |
| Model:              | LANCER     |
| Sub Model:          | VR-X       |
| Model Sheet Number: | 32 07 44   |
| Registration:       | SGM 3813A  |
| VIN number:         |            |
| Odometer:           |            |

### Model Specs

|                      |                   |                     |                 |
|----------------------|-------------------|---------------------|-----------------|
| 4-DOOR               | FROM 06/2006      | AIR CONDITIONING    | REAR SPOILER    |
| FOG LAMPS            | HEADLAMP WASHERS  | DARK REAR WINDOWS   | REAR BRAKE DRUM |
| 2.0 LTR 89 KW        | 5 SPEED GEARBOX   | TWIN AIRBAGS        | FRONT SKIRT     |
| SILL PANEL MOULDINGS | TWO COAT METALLIC | PREPARE OFF VEHICLE |                 |



*Not Authorized*  
*Lily @ ?*  
*Resurvey After Paint*  
*Ex \$1000/.*

*Ref: 62564315*

## Labour

| Code       | Description  | Time Base 10 WU/h | Price = 42.00 SGD/h |           |
|------------|--|-------------------|---------------------|-----------|
|            |  |                   | WU                  | Price SGD |
| GROUP42B   | PREPARATION TIME PER JOB   |                   | 2.0                 | 8.40      |
| 321222 10) | R + R R/ENGINE MOUNTING  |                   | 2.0                 | 8.40      |
| NO NUMBER  | R + R ENGINE SUSPENSION BRACKET  |                   | 3.0                 | 12.60     |
| 514121 10) | RENEW FRONT BUMPER COVER (BUMPER REMOVED)<br>INCLUDES: R + R FRONT FOG LAMPS AND REINFORCEMENT |                   | 7.0                 | 29.40     |
| 514121 10  | ADDITIONAL FOR AERODYNAMIC PARTS   |                   | 4.0                 | 16.80     |
| 425111 10) | RENEW BONNET (REMOVED)<br>INCLUDES: CONVERT ATTACHED PARTS                                     |                   | 3.0                 | 12.60     |
| NO NUMBER  | SEAL BONNET FOLDS AND SEAMS  |                   | 1.0                 | 4.20      |
| 422022 10  | ADDITIONAL FOR L/AERODYNAMIC PARTS   |                   | 8.0                 | 33.60     |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: \_\_\_\_\_

**Lai Huat (Meng Kee) Motor Pte Ltd**

**160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming  
Autocity  
575722**

Claim Reference: DMPCSN1760351801

Assessment number: 70580

Version: 1810

Date calculated: 20/06/2019 11:39 AM

Full Report  
Registration: SGM 3813A  
Printed: 20/06/2019 11:39 AM

|            |  | WU   | Price SGD |
|------------|--|------|-----------|
| 422022 10  | ADDITIONAL FOR R/AERODYNAMIC PARTS   | 8.0  | 33.60     |
| 421020 YE  | RENEW FRONT PANEL CPL<br>INCLUDES: R + R BUMPER, FRONT WINGS,<br>SPLASH SHIELD, BONNET, HEADLAMPS,<br>RADIATOR AND ATTACHED PARTS IN THE<br>REPAIR SECTION | 96.0 | 403.20    |
| 421020 ZAX | RENEW R/F SIDE MEMBER  | 46.0 | 193.20    |
| 423121 10) | R + R FRONT SCREEN<br>INCLUDES: R + R HEADLINING   | 28.0 | 117.60    |
| 522010 10) | R + R L/F SEAT BELT<br>INCLUDES: R + R B-PILLAR TRIM   | 2.0  | 8.40      |
| 522020 10) | R + R R/F SEAT BELT<br>INCLUDES: R + R B-PILLAR TRIM   | 2.0  | 8.40      |
| 528511 10) | R + R AIRBAG CONTROL UNIT  | 3.0  | 12.60     |
| 523111 10) | RENEW INSTRUMENT PANEL CPL<br>(INSTRUMENT PANEL REMOVED)<br>INCLUDES: R + R INSTRUMENT PANEL PAD   | 5.0  | 21.00     |
| 523110 10) | R + R INSTRUMENT PANEL CPL<br>INCLUDES: R + R COMBINATION INSTRUMENT   | 11.0 | 46.20     |
| 161161 10) | R + R FAN BELT   | 3.0  | 12.60     |
| 122020 10) | R + R OIL FILTER   | 2.0  | 8.40      |
| 153110 10) | R + R EXHAUST MANIFOLD   | 4.0  | 16.80     |
| 153210 10) | R + R FRONT EXHAUST PIPE   | 2.0  | 8.40      |
| 162110 10) | R + R STARTER CPL  | 6.0  | 25.20     |
| 375054 10) | R + R RETURN HOSE  | 3.0  | 12.60     |
| 375020 10) | R + R OIL RESERVOIR  | 3.0  | 12.60     |
| 311015 10) | FIT + BALANCE L/F TYRE<br>(WHEEL REMOVED)  | 4.0  | 16.80     |
| 311015 10) | FIT + BALANCE R/F TYRE<br>(WHEEL REMOVED)  | 4.0  | 16.80     |
| 266121 10) | R + R L/F STEERING KNUCKLE<br>INCLUDES: R + R WHEEL, BRAKE DISC, WHEEL<br>HUB, WHEEL BEARING AND SEALING RINGS   | 12.0 | 50.40     |
| 266121 10) | R + R R/F STEERING KNUCKLE<br>INCLUDES: R + R WHEEL, BRAKE DISC, WHEEL<br>HUB, WHEEL BEARING AND SEALING RINGS   | 12.0 | 50.40     |
| 333411 10) | R + R FRONT STABILIZER   | 8.0  | 33.60     |
| 358303 84) | R + R L/F SPEED SENSOR<br>(WHEEL REMOVED)  | 3.0  | 12.60     |
| 333110 10) | R + R L/F CONTROL ARM<br>(STEERING KNUCKLE REMOVED)  | 4.0  | 16.80     |
| 333110 10) | R + R R/F CONTROL ARM  | 4.0  | 16.80     |

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01,**  
**#04-02 & #07-03, Sin Ming**  
**Autocity**  
**575722**

Claim Reference: DMPCSN1760351801  
 Assessment number: 70580  
 Version: 1810  
 Date calculated: 20/06/2019 11:39 AM

Full Report  
 Registration: SGM 3813A  
 Printed: 20/06/2019 11:39 AM  
 WU Price SGD

|            |   |            |           |          |
|------------|---|------------|-----------|----------|
|            | (STEERING KNUCKLE REMOVED)              |            |           |          |
| 353121 10) | R + R LEFT FRONT BRAKE HOSE             | 3.0        |           | 12.60    |
| 333311 10) | R + R L/F SUSPENSION STRUT              | 4.0        |           | 16.80    |
|            | (STEERING KNUCKLE REMOVED)              |            |           |          |
| 333311 10) | R + R R/F SUSPENSION STRUT              | 4.0        |           | 16.80    |
|            | (STEERING KNUCKLE REMOVED)              |            |           |          |
| 266180 80) | R + R L/F DRIVE SHAFT                   | 3.0        |           | 12.60    |
|            | (STEERING KNUCKLE REMOVED)              |            |           |          |
| 321150 10) | R + R ENGINE SIDEMEMBER                 | 4.0        |           | 16.80    |
| NO NUMBER  | VENT FRONT BRAKE SYSTEM                 | 2.0        |           | 8.40     |
| 553110 10) | R + R COMPRESSOR                        | 2.0        |           | 8.40     |
|            | INCLUDES: R + R POWER STEERING OIL PUMP |            |           |          |
|            | DOES NOT INCLUDE: FILL AIR CONDITIONING |            |           |          |
| 553210 10) | R + R CONDENSER                         | 3.0        |           | 12.60    |
|            | (RADIATOR REMOVED)                      |            |           |          |
| 550000 90) | FILL AIR CONDITIONING                   | 3.0        |           | 12.60    |
| 555511 10) | R + R AIR CONDITIONING INTAKE HOSE      | 4.0        |           | 16.80    |
| NO NUMBER  | R + R AIR CONDITIONING CONNECTION PIPE  | 2.0        |           | 8.40     |
| NN         | ENGINE OIL COOLER R&R / NEW PARTS       | 10.0*      | —         | 42.00    |
| 9973       | TEST DRIVE KN                           | 10.0*      | —         | 42.00    |
| 1117       | L/F WHEELHOUSE REPAIR                   | 30.0*      | —         | 126.00   |
| 1118       | R/F WHEELHOUSE REPAIR                   | 30.0*      | —         | 126.00   |
| 1201       | L/F SIDE MEMBER CPL REPAIR              | 80.0*      | —         | 252.00   |
|            |   |            |           |          |
|            | <b>Labour Cost</b>                      | <b>Hrs</b> | <b>WU</b> |          |
|            | <b>Panel / Mechanical Labour</b>        | 47.90      | 479.0     | 2,011.80 |
|            | <b>Total of Labour</b>                  |            |           | 2,011.80 |

**Paint**

| Paint Work  | SYSTEM AZT                             | Time Basis 10WU/h | WU   | Price SGD |
|-------------|--|-------------------|------|-----------|
| <b>Code</b> | <b>Description - TWO COAT METALLIC</b> |                   |      |           |
|             | BONNET NEW PART PAINTING               |                   | 22.0 |           |
|             | L/F WING NEW PART PAINTING             |                   | 10.0 |           |
|             | R/F WING NEW PART PAINTING             |                   | 10.0 |           |
|             | FRONT PANEL CPL SURFACE PAINT          |                   | 7.0  |           |
|             | R/F SIDE MEMBER CPL SURFACE PAINT      |                   | 4.0  |           |
|             | FRONT BUMPER COVER NEW PART PAINT K1R  |                   | 12.0 |           |
|             | GRILLE NEW PART PAINT K1R              |                   | 3.0  |           |
|             | LEFT FRONT DOOR REPAIR PAINTING <50%   |                   | 15.0 |           |
|             | L/F WHEELHOUSE SURFACE PAINT           |                   | 6.0  |           |

**Lai Huat (Meng Kee) Motor Pte Ltd**

**160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming**

**Autocity**

**575722**

Claim Reference: DMPCSN1760351801

Assessment number: 70580

Version: 1810

Date calculated: 20/06/2019 11:39 AM SYSTEM AZT

Full Report

Registration: SGM 3813A

Printed: 20/06/2019 11:39 AM

Time Basis 10WU/h

| Code | Description - TWO COAT METALLIC   | WU  | Price SGD |
|------|-----------------------------------|-----|-----------|
|      | R/F WHEELHOUSE SURFACE PAINT      | 6.0 |           |
|      | L/F SIDE MEMBER CPL SURFACE PAINT | 4.0 |           |
|      | RIGHT FRONT DOOR SURFACE PAINT    | 7.0 |           |

**Paint Material Per Part**

| Code | Description                           | Price SGD |
|------|---------------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING              | 71.21     |
| 0741 | L/F WING NEW PART PAINTING            | 18.58     |
| 0742 | R/F WING NEW PART PAINTING            | 18.58     |
| 1009 | FRONT PANEL CPL SURFACE PAINT         | 16.43     |
| 1202 | R/F SIDE MEMBER CPL SURFACE PAINT     | 2.24      |
| 0283 | FRONT BUMPER COVER NEW PART PAINT K1R | 55.60     |
| 0411 | GRILLE NEW PART PAINT K1R             | 0.49      |
| 1481 | LEFT FRONT DOOR REPAIR PAINTING <50%  | 23.58     |
| 1117 | L/F WHEELHOUSE SURFACE PAINT          | 10.21     |
| 1118 | R/F WHEELHOUSE SURFACE PAINT          | 10.21     |
| 1201 | L/F SIDE MEMBER CPL SURFACE PAINT     | 2.24      |
| 1482 | RIGHT FRONT DOOR SURFACE PAINT        | 18.18     |

**Labour Cost - Paint**

| Factor                         | 42.00 SGD/h | Hrs            | WU           | Price SGD     |
|--------------------------------|-------------|----------------|--------------|---------------|
| Time Paint                     |             |                | 106.0        |               |
| Preparation Main Work Metal    |             | 2.50           | 25.0         | 105.00        |
| Preparation Comp. Work Plastic |             | 0.50           | 5.0          | 21.00         |
| <b>Total</b>                   |             | <b>10 WU/h</b> | <b>136.0</b> | <b>571.20</b> |

**Material Cost - Paint**

|                                     | Price SGD     |
|-------------------------------------|---------------|
| New Part Painting                   | 108.37        |
| New Part Painting - Plastic K1R     | 56.09         |
| Repair Painting                     | 23.58         |
| Surface-/Blend Paint                | 59.51         |
| Material-constant Metal Preparation | 28.60         |
| Material-constant Plastic           | 9.00          |
| <b>Total</b>                        | <b>285.15</b> |

**Spare Parts**

prices as at 2015-06-01

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01,**  
**#04-02 & #07-03, Sin Ming**  
**Autocity**  
**575722**

Claim Reference: DMPCSN1760351801  
 Assessment number: 70580  
 Version: 1810

Full Report  
 Registration: SGM 3813A  
 Printed: 20/06/2019 11:39 AM

Date calculated: 20/06/2019 11:39 AM

| Part Number | Supplier                      | Price SGD |
|-------------|-------------------------------|-----------|
| 0283        | FRONT BUMPER COVER MN150927   | 650.00    |
| 0411        | GRILLE 7450A214WA             | 290.00    |
| 0471        | BONNET 5900A138               | 1,220.00  |
| 0493        | BONNET LOCK 5908A002          | 40.00     |
| 0524        | BONNET FRONT SEAL MR525054    | 20.00     |
| 0561        | L/F HEADLAMP CPL MN161163     | 1,510.00  |
| 0562        | R/F HEADLAMP CPL MN161164     | 1,510.00  |
| 0707        | L/F REPEATER LAMP MR991187    | 30.00     |
| 0708        | R/F REPEATER LAMP MR991187    | 30.00     |
| 0741        | L/F WING MN150623             | 620.00    |
| 0742        | R/F WING MN150624             | 620.00    |
| 0841        | L/F SPLASH PANEL MN150569     | 90.00     |
| 0842        | R/F SPLASH PANEL MN150570     | 90.00     |
| 1009        | FRONT PANEL CPL MN150613      | 450.00    |
| 1202        | R/F SIDE MEMBER CPL MR990414  | 960.00    |
| 1401        | WINDSCREEN MR991639           | 525.00    |
| 1410        | WINDSCREEN BOND KIT KNGKW12   | 0.00      |
| 1411        | WINDSCREEN REP KIT Z2156737   | 0.00      |
| 1413        | FRT SCREEN MNTG KIT           | 0.00      |
| 1423        | UPPER MOULDING MR520285       | 20.00     |
| 1424        | SPACER MR957780               | 0.00      |
| 2207        | L/SILL EXTENSION 6512A593     | 610.00    |
| 4325        | PASSENGER AIRBAG MN185262     | 1,670.00  |
| 4331        | INSTRUMENT PANEL MR590217     | 890.00    |
| 4455        | COMPRESSOR 7813A040           | 1,315.00  |
| 4465        | CONDENSER MN151100            | 1,060.00  |
| 4481        | AIR INTAKE HOSE MR513046      | 435.00    |
| 4490        | CONNECTION TUBE MN124693      | 0.00      |
| 4661        | L/F SEAT BELT MN134963HA      | 525.00    |
| 4662        | R/F SEAT BELT MN134964HA      | 525.00    |
| 7035        | L/DRIVE SHAFT MR953745        | 905.00    |
| 7053        | L/LOWER CONTROL ARM 4013A461  | 430.00    |
| 7054        | R/LOWER CONTROL ARM 4013A462  | 430.00    |
| 7077        | L/F STRUT MR961192            | 920.00    |
| 7078        | R/F STRUT MN101957            | 920.00    |
| 7081        | L/F STEERING KNUCKLE MR403403 | 420.00    |
| 7082        | R/F STEERING KNUCKLE MR403404 | 420.00    |
| 7091        | L/F STRUT BEARING MR455018    | 100.00    |
| 7101        | L/F DUST COVER MR455020       | 15.00     |
| 7103        | L/F DAMPER BUFFER MR961189    | 25.00     |
| 7131        | L/F WHEEL HUB MR519922        | 325.00    |
| 7165        | L/F BRAKE HOSE MR407889       | 30.00     |

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01,**  
**#04-02 & #07-03, Sin Ming**  
**Autocity**  
**575722**

Claim Reference: DMPCSN1760351801  
 Assessment number: 70580  
 Version: 1810

Full Report  
 Registration: SGM 3813A  
 Printed: 20/06/2019 11:39 AM

| Date calculated: 20/06/2019 11:39 AM | Part Number          | Supplier    | Price SGD |   |
|--------------------------------------|----------------------|-------------|-----------|---|
| 7201                                 | L/F WHEEL            | 4250A222    | 885.00    | ✓ |
| 7202                                 | R/F WHEEL            | 4250A222    | 885.00    | ✓ |
| 7245                                 | L/F ABS SENSOR       | MR527311    | 340.00    | ? |
| 7261                                 | FRONT STABILISER     | MN101581    | 220.00    | ? |
| 7269                                 | L/F STABILISER BUSH  | MN100250    | 10.00     | ? |
| 7270                                 | R/F STABILISER BUSH  | MN100250    | 10.00     | ? |
| 7271                                 | L/F OUT MOUNTING KIT | 4056A161    | 75.00     | ? |
| 7443                                 | AIRBAG CONTROL UNIT  | MN141000    | 770.00    | ✓ |
| 7479                                 | STEERING OIL TANK    | MR403657    | 100.00    | ✓ |
| 7481                                 | PWR STRG INLET PIPE  | MN100326    | 165.00    | ✓ |
| 7761                                 | RADIATOR             | 1350A253    | 715.00    | ✓ |
| 7765                                 | FAN/MOTOR            | MN185142    | 630.00    | ? |
| 7767                                 | RADIATOR SHROUD      | MR968365    | 115.00    | ? |
| 7773                                 | LWR RADIATOR HOSE    | MN156854    | 28.00     | ? |
| 7793                                 | L/BLOWER FAN         | MR464708    | 55.00     | ? |
| 7797                                 | L/FAN MOTOR          | MR314718    | 340.00    | ? |
| 7801                                 | L/LWR RADIATOR BRKT  | MB605173    | 15.00     | ✓ |
| 7802                                 | R/LWR RADIATOR BRKT  | MB605173    | 15.00     | ✓ |
| 8041                                 | OIL FILTER           | TS200004    | 17.00     | ? |
| 8402                                 | AIR FILTER HOUSING   | MR552102    | 150.00    | ✓ |
| 8501                                 | STARTER MOTOR        | MR994325    | 835.00    | ? |
| 8622                                 | ENGINE SUPPORT       | MD374652    | 90.00     | ? |
| 8624                                 | R/ENGINE BRACKET     | MR491479    | 75.00     | ? |
| 8652                                 | ENGINE CARRIER       | MR554735    | 825.00    | ? |
| 8801                                 | EXHAUST MANIFOLD     | 1555A043    | 495.00    | ? |
| 8804                                 | EXHAUST MANIFOLD     | MR266587    | 75.00     | ? |
|                                      | CVR                  |             |           |   |
| 8815                                 | FRONT EXHAUST PIPE   | MN180782    | 390.00    | ? |
| 8919                                 | FRT GEARBOX CARRIER  | MR554244    | 95.00     | ? |
| 9645                                 | L/HORN               | MR558257    | 70.00     | ✓ |
| 9974                                 | POWER STEERING OIL   |             | 12.00     | ✓ |
| 9984                                 | ENGINE OIL           |             | 122.50    | ? |
| 9987                                 | COOLANT/ANTIFREEZE   |             | 20.00     | ✓ |
| 1001                                 | R/F WING TOP GARN    | RENEW       | 22.00     | ? |
| 1002                                 | R/RAD TOP BRKT BUSH  | RENEW       | 0.00      | ✓ |
| 1003                                 | BONNET STAND CLIP    | RENEW       | 5.00      | ✓ |
| 1004                                 | FAN BELT             | RENEW       | 125.00    | ? |
| 1005                                 | ENGINE OIL COOLER    | RENEW       | 565.00    | ? |
| 1006                                 | ENGINE OIL COOLER    | INLET PIPE  | 145.00    | ✓ |
| 1007                                 | ENGINE OIL COOLER    | OUTLET PIPE | 145.00    | ✓ |
| 1008                                 | INTERCOOLER          | RENEW       | 1,165.00  | ? |
| 1009                                 | INTERCOOLER HOSE LH  | RENEW       | 80.00     | ? |
| 1010                                 | INTERCOOLER HOSE RH  | RENEW       | 85.00     | ? |

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01,**  
**#04-02 & #07-03, Sin Ming**  
**Autocity**  
**575722**

Claim Reference: DMPCSN1760351801  
 Assessment number: 70580  
 Version: 1810

Full Report  
 Registration: SGM 3813A  
 Printed: 20/06/2019 11:39 AM

Date calculated: 20/06/2019 11:39 AM  
 Part Number  
 1011 L/INTERCOOLER PIPE RENEW  
 1012 R/INTERCOOLER PIPE RENEW

Supplier  
 Price SGD  
 315.00 ✓  
 315.00 ✓

f: OEM Parts  
 n: Non-OEM Parts  
 u: Used parts

**Savings** 0.00  
**Subtotal** 32,256.50  
**Fixed Sundry Parts Price** 100.00  
**Total** 32,356.50

**Extras**

| Code                | Description        | Price SGD     |
|---------------------|--------------------|---------------|
| 1013                | IU BRACKET SN      | 15.00*        |
| 1014                | WHEEL ALIGNMENT SN | 80.00* 601    |
| 1015                | W/S SEALANT SN     | 40.00*        |
| 1016                | AIR CON GAS SN     | 50.00*        |
| <b>Total Extras</b> |                    | <b>185.00</b> |

**Final Calculation**

|                                       | SGD       | SGD                    |
|---------------------------------------|-----------|------------------------|
| <b>Parts</b>                          |           |                        |
| Fixed Sundry Parts Price              | 32,256.50 |                        |
| <b>Total Parts</b>                    | 100.00    | <b>32,356.50</b>       |
| <b>Labour Time Base 10 WU/h</b>       |           |                        |
| Total 479.0 WU X 42.00 SGD/h          | 2,011.80  |                        |
| <b>Total of Labour</b>                |           | <b>2,011.80</b> 1927.8 |
| <b>Total Of Extras</b>                |           | <b>185.00</b>          |
| <b>Paint Work Time Base 10 WU/h</b>   |           |                        |
| Labour Cost 136.0 WU X 42.00 SGD/h    | 571.20    |                        |
| Material Cost                         | 285.15    |                        |
| <b>Total Paint Including Material</b> |           | <b>856.35</b>          |
| <b>Repair Cost Excludes GST</b>       |           | <b>35,409.65</b>       |
| GST (+7.0%)                           |           | 2,478.68               |
| <b>Repair Cost Included GST</b>       |           | <b>37,888.33</b>       |

**Lai Huat (Meng Kee) Motor Pte  
Ltd**

**160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming**

**Autocity**

**575722**

**Claim Reference: DMPCSN1760351801**

**Assessment number: 70580**

**Version: 1810**

**Date calculated: 20/06/2019 11:39 AM**

**Full Report**

**Registration: SGM 3813A**

**Printed: 20/06/2019 11:39 AM**

---

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |   |  |  |  |  |             |   |
|--------------------------|---|--|--|--|--|-------------|---|
| Case                     | Notified                                    | Est Submitted                              | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
| Main                     | 20 Jun 2019<br><a href="#">Sendback Est</a> | 21 Jun 2019<br>09:49<br><b>\$35,409.65</b> | 21 Jun 2019<br>11:01<br><a href="#">Edit Adj Rpt</a> | <b>\$27,011.15</b><br><a href="#">Edit Estimates</a> | <b>\$27,011.15</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference   | Claim Details          | Documents   | <a href="#">Show All</a> |         |             |              |            |       |
|---|---|------------------------|---|--------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>  |   |                        |   |                          |         |             |              |            |       |
| Insured:  | <b>PANG SENG JIAN</b> , ID: S7608188C, Tel: +6597491898, Email: JEFFPANG3813@GMAIL.COM  |                        |   |                          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>SGM3813A</b>   | Date of Loss:          | 06/06/2019 16:00 - :59<br>[151 Months and 21 Days From LTA Reg Date (Man Yr)] |                          |         |             |              |            |       |
| Claim Type:   | <b>OD / SNM19D202716-CHONGBS</b>  | Policy/Cover Note No.: | DMPCSN1760351801 (Comprehensive)  |                          |         |             |              |            |       |
|   |   | Excess:                | \$1,000.00  |                          |         |             |              |            |       |
| Repairer:   | <b>Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)</b> 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110 |                        |   |                          |         |             |              |            |       |
| Handling Insurer:   | <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]                |                        |   |                          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 02/07/2019]    |                        |   |                          |         |             |              |            |       |
| Driver/Custodian:   | PANG SENG JIAN (43 / Male) , NRIC: S7608188C, Tel: +6597491898 Email: JEFFPANG3813@GMAIL.COM                                      |                        |   |                          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |   |                        |   |                          |         |             |              |            |       |
| • CHINA_TAIPING (26/06/2019): <b>Alert - Adj Mandate Approved (\$35275.65) - SGM3813A - Claim Handler: Chong Boon...</b>  |   |                        |   |                          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |   |                        |   |                          |         |             |              |            |       |
| Due Date  | Priority  | Type                   | Task Group  | Subject                  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |   |                        |   |                          |         |             |              |            |       |



## Claim Documents

**SGM3813A (SNM19D202716-CHONGBS)**

OD

Jun 6 2019 4:00PM

[PANG SENG JIAN]

Lai Huat (Meng Kee) Motor Pte Ltd

| <a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> |                 |   | View         | View in Browser ▼                   |                                     |
|---|-----------------|---|--------------|-------------------------------------|-------------------------------------|
| <b>Assessment Reports</b>   |                 |   | 1 per page ▼ | <input checked="" type="checkbox"/> |                                     |
| No  | Finalized On    | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)                |              | Thumbnail                           | Print                               |
| 1   | 08/06/19 12:59  | <b>Accident Statement</b>                                   | 1            | Load HTM                            | <input type="checkbox"/>            |
| 2   | 21/06/19 09:49  | <b>Repairer Estimates</b>                                   | 1            | Load HTM                            | <input type="checkbox"/>            |
| No  | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                           |              | Thumbnail                           | Print                               |
| 1   | 24/06/19 14:29  | <b>Adjuster Immediate Advice</b>                            | 1            | Load HTM                            | <input type="checkbox"/>            |
| <b>Photos/Images</b>  |                 |   | 3 per page ▼ | <input checked="" type="checkbox"/> |                                     |
| No  | Finalized On    | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)                |              | Thumbnail                           | Print                               |
| 1   | 08/06/19 12:59  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 2   | 08/06/19 12:59  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 3   | 08/06/19 12:59  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 4   | 08/06/19 12:59  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 5   | 08/06/19 12:59  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 6   | 08/06/19 12:59  | <b>Accident Photo</b><br>[Linked Accident Report Documents] | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 7   | 08/06/19 12:59  | <b>CHASSIS NUMBER</b><br>[Linked Accident Report Documents] | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 8   | 20/06/19 15:55  | <b>Rear View</b>  | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 9   | 20/06/19 15:55  | <b>Rear View Right</b>                                      | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 10  | 20/06/19 15:55  | <b>Rear View Left</b>                                       | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 11  | 20/06/19 15:55  | <b>Front View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 12  | 20/06/19 15:55  | <b>Front View Right</b>                                     | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 13  | 20/06/19 15:55  | <b>Front View Left</b>                                      | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 14  | 20/06/19 15:55  | <b>Front View Left</b>                                      | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 15  | 20/06/19 15:55  | <b>Chassis Number</b>                                       | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 16  | 20/06/19 15:55  | <b>Chassis Number</b>                                       | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                           |              | Thumbnail                           | Print                               |
| 1   | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 2   | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 3   | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 4   | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 5   | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 6   | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 7   | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 8   | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 9   | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 10  | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 11  | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 12  | 24/06/19 14:18  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 13  | 24/06/19 14:19  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 14  | 24/06/19 14:19  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 15  | 24/06/19 14:19  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 16  | 24/06/19 14:19  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |
| 17  | 24/06/19 14:19  | <b>General View</b>   | 1            | Load JPG                            | <input checked="" type="checkbox"/> |

| Assessment Reports |                 |   | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|---|------------|-------------------------------------|
| No                 | Finalized On    | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)                          | Thumbnail  | Print                               |
| 18                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 19                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 20                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 21                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 22                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 23                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 24                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 25                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 26                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 27                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 28                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 29                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 30                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 31                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 32                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 33                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 34                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 35                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 36                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 37                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 38                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 39                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| 40                 | 24/06/19 14:19  | General View  |            | <input checked="" type="checkbox"/> |
| Documentation      |                 |   | 1 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)                          | Thumbnail  | Print                               |
| 1                  | 08/06/19 12:13  | Sketch Plan<br>[Linked Accident Report Documents]                     |            | <input type="checkbox"/>            |
| 2                  | 08/06/19 12:13  | POLICE REPORT<br>[Linked Accident Report Documents]                   |            | <input type="checkbox"/>            |
| 3                  | 08/06/19 12:13  | CERTIFICATE OF INSURANCE<br>[Linked Accident Report Documents]        |            | <input type="checkbox"/>            |
| 4                  | 08/06/19 12:14  | DRIVER'S NRIC + DRIVING LICENCE<br>[Linked Accident Report Documents] |            | <input type="checkbox"/>            |
| 5                  | 21/06/19 09:48  | E-filed GIA report  |            | <input type="checkbox"/>            |
| 6                  | 21/06/19 09:48  | Driver's NRIC & Driving Licence                                       |            | <input type="checkbox"/>            |
| 7                  | 21/06/19 09:48  | Certificate of Insurance  |            | <input type="checkbox"/>            |
| 8                  | 21/06/19 09:48  | Enquire PARF / COE Rebate for Registered Vehicle                      |            | <input type="checkbox"/>            |
| 9                  | 21/06/19 09:48  | Audatex Report  |            | <input type="checkbox"/>            |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                     | Thumbnail  | Print                               |
| 1                  | 24/06/19 14:16  | SGM 3813A GIA.pdf   |            | <input type="checkbox"/>            |
| 2                  | 24/06/19 14:16  | POLICE REPORT.pdf   |            | <input type="checkbox"/>            |
| 3                  | 24/06/19 14:16  | ESTIMATE.pdf  |            | <input type="checkbox"/>            |
| 4                  | 24/06/19 14:16  | AUDATEX.pdf   |            | <input type="checkbox"/>            |

## Linked Accident Report Documents

| Assessment Reports |                |  | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|------------|-------------------------------------|
| No                 | Finalized On   | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) | Thumbnail  | Print                               |
| 1                  | 08/06/19 12:59 | Accident Statement                           |            | <input type="checkbox"/>            |
| Photos/Images      |                |  | 3 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) | Thumbnail  | Print                               |
| 1                  | 08/06/19 12:59 | Accident Photo                               |            | <input checked="" type="checkbox"/> |
| 2                  | 08/06/19 12:59 | Accident Photo                               |            | <input checked="" type="checkbox"/> |
| 3                  | 08/06/19 12:59 | Accident Photo                               |            | <input checked="" type="checkbox"/> |
| 4                  | 08/06/19 12:59 | Accident Photo                               |            | <input checked="" type="checkbox"/> |
| 5                  | 08/06/19 12:59 | Accident Photo                               |            | <input checked="" type="checkbox"/> |

| Assessment Reports |                |  | 1 per page | <input checked="" type="checkbox"/>          |
|--------------------|----------------|--|------------|--|
| No                 | Finalized On   | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) |            | Thumbnail Print                              |
| 6                  | 08/06/19 12:59 | <b>Accident Photo</b>                        |            | Load JPG <input checked="" type="checkbox"/> |
| 7                  | 08/06/19 12:59 | <b>CHASSIS NUMBER</b>                        |            | Load JPG <input checked="" type="checkbox"/> |

| Documentation |                |  | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|--|------------|-------------------------------------|
| No            | Finalized On   | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) |            | Thumbnail Print                     |
| 1             | 08/06/19 12:13 | <b>Sketch Plan</b>                           |            | Load TIF                            |
| 2             | 08/06/19 12:13 | <b>POLICE REPORT</b>                         |            | Load TIF                            |
| 3             | 08/06/19 12:13 | <b>CERTIFICATE OF INSURANCE</b>              |            | Load TIF                            |
| 4             | 08/06/19 12:14 | <b>DRIVER'S NRIC + DRIVING LICENCE</b>       |            | Load TIF                            |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. |       |      |       |

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

**Show Remarks To:**  Repairer  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CT119010970/KSD3S2  
**Date:** 08/10/2019

### REFERENCE

Insured/Claimant: PANG SENG JIAN Policy No: DMPCSN1760351801  
Date of Loss: 06/06/2019 Nature of Claim: OD Claim No: SNM19D202716-CHONGBS

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGM3813A**  
Make & Model: MITSUBISHI LANCER EVOLUTION IX, 2.0 MR GSR (M) Engine No: 4G63LS2069  
Reg. Date: 16/10/2006 (Man. Year: 2006) Chassis No: CT9A0405558  
Colour: Yellow Odometer: 0 km  
Engine Capacity: 1997 cc  
Market Value/New Car Price: S\$82,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/40 R18 Rear Tyre Size: 215/40 R18  
Front Left Side: Goodyear 8 mm Rear Left Side: Yokohama 8 mm  
Front Right Side: Goodyear 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                      | Repairer's       | Adjuster's       | Difference       | Diff %       |
|-------------------------------------|------------------|------------------|------------------|--------------|
| Parts                               | 32,256.50        | 23,962.00        | 8,294.50         | 25.71        |
| Miscellaneous Items                 | 285.00           | 265.00           | 20.00            | 7.02         |
| Labour                              | 2,011.80         | 1,927.80         | 84.00            | 4.18         |
| Paintwork Labour                    | 856.35           | 856.35           | 0.00             | 0.00         |
| Towing                              | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b> | <b>35,409.65</b> | <b>27,011.15</b> | <b>8,398.50</b>  | <b>23.72</b> |
| - Excess (S\$)                      | 0.00             | 1,000.00         | -1,000.00        |              |
| (S\$)                               | 35,409.65        | 26,011.15        | 9,398.50         | 26.54        |
| + GST 7.00/7.00% (S\$)              | 2,478.68         | 1,820.78         | 657.90           | 26.54        |
| <b>Nett Amount (S\$)</b>            | <b>37,888.33</b> | <b>27,831.93</b> | <b>10,056.40</b> | <b>26.54</b> |

### INSPECTION

Date of Assignment: 21/06/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)  
Date Inspected: 21/06/2019 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)  
Estimated Period of Repair: 24.0 days 160 Sin Ming Drive #04-01, Sin Ming AutoCity  
Singapore 575722

**Adjuster:** KENNETH KONG

**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/8/2019

Adjuster Report

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$8264.50 NETT)

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 Oct 2019)**Parts:** 143 MITSUBISHI LANCER EVOLUTION IX 2.0 MR GSR (M) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SGM3813A)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

| No. | Qty | Part No. | Particulars                | Condition       | Repairer's  | Amount      |
|-----|-----|----------|----------------------------|-----------------|-------------|-------------|
|     |     |          |                            |                 | 32,256.50 F | -           |
| 1   | 1   |          | *Spare Parts               |                 | -           | *650.00 F   |
| 2   | 1   |          | *FRONT BUMPER COVER        | Missing         | -           | *290.00 F   |
| 3   | 1   |          | *GRILLE                    | Missing         | -           | *1,220.00 F |
| 4   | 1   |          | *BONNET                    | Cracked         | -           | *40.00 F    |
| 5   | 1   |          | *BONNET LOCK               | Bent            | -           | *20.00 F    |
| 6   | 1   |          | *BONNET FRONT SEAL         | Missing         | -           | *1,510.00 F |
| 7   | 1   |          | *L/F HEADLAMP CPL          | Missing         | -           | *1,510.00 F |
| 8   | 1   |          | *R/F HEADLAMP CPL          | Missing         | -           | *30.00 F    |
| 9   | 1   |          | *L/F REPEATER LAMP         | Missing         | -           | *30.00 F    |
| 10  | 1   |          | *R/F REPEATER LAMP         | Missing         | -           | *620.00 F   |
| 11  | 1   |          | *L/F WING                  | Cracked         | -           | *620.00 F   |
| 12  | 1   |          | *R/F WING                  | Cracked         | -           | *90.00 F    |
| 13  | 1   |          | *L/F SPLASH PANEL          | Bent            | -           | *90.00 F    |
| 14  | 1   |          | *R/F SPLASH PANEL          | Bent            | -           | *450.00 F   |
| 15  | 1   |          | *FRONT PANEL CPL           | Bent            | -           | *960.00 F   |
| 16  | 1   |          | *R/F SIDE MEMBER CPL       | Bent            | -           | *525.00 F   |
| 17  | 1   |          | *WINDSCREEN                | Cracked         | -           | *-F         |
| 18  | 1   |          | *WINDSCREEN BOND KIT (NPA) | Necessary       | -           | *-F         |
| 19  | 1   |          | *WINDSCREEN REP KIT (NPA)  | Necessary       | -           | *-F         |
| 20  | 1   |          | *FRT SCREEN MNTG KIT (NPA) | Necessary       | -           | *20.00 F    |
| 21  | 1   |          | *UPPER MOULDING            | Necessary       | -           | *-F         |
| 22  | 1   |          | *SPACER (NPA)              | Necessary       | -           | *610.00 F   |
| 23  | 1   |          | *L/SILL EXTENSION          | Cracked         | -           | *1,670.00 F |
| 24  | 1   |          | *PASSENGER AIRBAG          | Burst           | -           | *890.00 F   |
| 25  | 1   |          | *INSTRUMENT PANEL          | Torn            | -           | *1,315.00 F |
| 26  | 1   |          | *COMPRESSOR                | Dented / Jammed | -           | *1,060.00 F |
| 27  | 1   |          | *CONDENSER                 | Bent            | -           | *435.00 F   |
| 28  | 1   |          | *AIR INTAKE HOSE           | Dented          | -           | *-F         |
| 29  | 1   |          | *CONNECTION TUBE (NPA)     | Not Necessary   | -           | *525.00 F   |
| 30  | 1   |          | *L/F SEAT BELT             | Jammed          | -           | *525.00 F   |
| 31  | 1   |          | *R/F SEAT BELT             | Jammed          | -           | *905.00 F   |
| 32  | 1   |          | *L/DRIVE SHAFT             | Bent            | -           | *430.00 F   |
| 33  | 1   |          | *L/LOWER CONTROL ARM       | Bent            | -           | *-F         |
| 34  | 1   |          | *R/LOWER CONTROL ARM       | *Check          | -           | *920.00 F   |
| 35  | 1   |          | *L/F STRUT                 | Bent            | -           | *-F         |
| 36  | 1   |          | *R/F STRUT                 | *Check          | -           | *420.00 F   |
| 37  | 1   |          | *L/F STEERING KNUCKLE      | Bent            | -           | *420.00 F   |
| 38  | 1   |          | *R/F STEERING KNUCKLE      | Bent            | -           | *100.00 F   |
| 39  | 1   |          | *L/F STRUT BEARING         | Necessary       | -           | *15.00 F    |
| 40  | 1   |          | *L/F DUST COVER            | Missing         | -           | *25.00 F    |
| 41  | 1   |          | *L/F DAMPER UPPER          | Missing         | -           | *325.00 F   |
| 42  | 1   |          | *L/F WHEEL HUB             | Bent            | -           | *-F         |
| 43  | 1   |          | *L/F BRAKE HOSE            | *Check          | -           | *885.00 F   |
| 44  | 1   |          | *L/F WHEEL                 | Bent            | -           | *885.00 F   |
| 45  | 1   |          | *R/F WHEEL                 | Bent            | -           | *-F         |
| 46  | 1   |          | *L/F ABS SENSOR            | *Check          | -           |             |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                | Condition | Repairer's               | Amount           |                  |
|-----|-----|----------|----------------------------|-----------|--------------------------|------------------|------------------|
| 47  | 1   |          | *FRONT STABILIZER          | *Check    | -                        | *-F              |                  |
| 48  | 1   |          | *L/F STABILIZER BUSH       | *Check    | -                        | *-F              |                  |
| 49  | 1   |          | *R/F STABILIZER BUSH       | *Check    | -                        | *-F              |                  |
| 50  | 1   |          | *L/F OUT MOUNTING KIT      | *Check    | -                        | *-F              |                  |
| 51  | 1   |          | *AIRBAG CONTROL UNIT       | Necessary | -                        | *770.00 F        |                  |
| 52  | 1   |          | *STEERING OIL TANK         | Dented    | -                        | *100.00 F        |                  |
| 53  | 1   |          | *PWR STRG INLET PIPE       | Dented    | -                        | *165.00 F        |                  |
| 54  | 1   |          | *RADIATOR                  | Bent      | -                        | *715.00 F        |                  |
| 55  | 1   |          | *FAN / MOTOR               | *Check    | -                        | *-F              |                  |
| 56  | 1   |          | *RADIATOR SHROUD           | *Check    | -                        | *-F              |                  |
| 57  | 1   |          | *LWR RADIATOR HOSE         | *Check    | -                        | *-F              |                  |
| 58  | 1   |          | *L/BLOWER FAN              | *Check    | -                        | *-F              |                  |
| 59  | 1   |          | *L/FAN MOTOR               | *Check    | -                        | *-F              |                  |
| 60  | 1   |          | *L/LWR RADIATOR BRKT       | Repair    | -                        | *-F              |                  |
| 61  | 1   |          | *R/LWR RADIATOR BRKT       | Repair    | -                        | *-F              |                  |
| 62  | 1   |          | *OIL FILTER                | *Check    | -                        | *-F              |                  |
| 63  | 1   |          | *AIR FILTER HOUSING        | Bent      | -                        | *150.00 F        |                  |
| 64  | 1   |          | *STARTER MOTOR             | *Check    | -                        | *-F              |                  |
| 65  | 1   |          | *ENGINE SUPPORT            | *Check    | -                        | *-F              |                  |
| 66  | 1   |          | *R/ENGINE BRACKET          | *Check    | -                        | *-F              |                  |
| 67  | 1   |          | *ENGINE CARRIER            | *Check    | -                        | *-F              |                  |
| 68  | 1   |          | *EXHAUST MANIFOLD          | *Check    | -                        | *-F              |                  |
| 69  | 1   |          | *EXHAUST MANIFOLD CVR      | *Check    | -                        | *-F              |                  |
| 70  | 1   |          | *FRONT EXHAUST PIPE        | *Check    | -                        | *-F              |                  |
| 71  | 1   |          | *FRT GEARBOX CARRIER       | *Check    | -                        | *-F              |                  |
| 72  | 1   |          | *L/HORN                    | Dented    | -                        | *70.00 F         |                  |
| 73  | 1   |          | *POWER STEERING OIL        | Necessary | -                        | *12.00 F         |                  |
| 74  | 1   |          | *ENGINE OIL                | *Check    | -                        | *-F              |                  |
| 75  | 1   |          | *COOLANT / ANTIFREEZE      | Necessary | -                        | *20.00 F         |                  |
| 76  | 1   |          | *R/F WING TOP GARN         | *Check    | -                        | *-F              |                  |
| 77  | 1   |          | *R/RAD TOP BRKT BUSH (NPA) | Missing   | -                        | *-F              |                  |
| 78  | 1   |          | *BONNET STAND CLIP         | Missing   | -                        | *5.00 F          |                  |
| 79  | 1   |          | *FAN BELT                  | *Check    | -                        | *-F              |                  |
| 80  | 1   |          | *ENGINE OIL COOLER         | *Check    | -                        | *-F              |                  |
| 81  | 1   |          | *ENGINE OIL COOLER         | Bent      | -                        | *145.00 F        |                  |
| 82  | 1   |          | *ENGINE OIL COOLER         | Bent      | -                        | *145.00 F        |                  |
| 83  | 1   |          | *INTERCOOLER               | *Check    | -                        | *-F              |                  |
| 84  | 1   |          | *INTERCOOLER HOSE LH       | *Check    | -                        | *-F              |                  |
| 85  | 1   |          | *INTERCOOLER HOSE RH       | *Check    | -                        | *-F              |                  |
| 86  | 1   |          | *L/INTERCOOLER PIPE        | Dented    | -                        | *315.00 F        |                  |
| 87  | 1   |          | *R/INTERCOOLER PIPE        | Dented    | -                        | *315.00 F        |                  |
|     |     |          |                            |           | <b>Total Parts (S\$)</b> | <b>32,256.50</b> | <b>23,962.00</b> |

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

| No                         | Qty | Particulars                       | Repairer's    | Amount        |
|----------------------------|-----|-----------------------------------|---------------|---------------|
| <b>Miscellaneous Items</b> |     |                                   |               |               |
| 1                          | 1   | <b>Air con gas</b><br>(NECESSARY) | 50.00         | 50.00         |
| 2                          | 1   | <b>IU bracket</b><br>(NECESSARY)  | 15.00         | 15.00         |
| 3                          | 1   | <b>Sundry part</b>                | 100.00        | 100.00        |
| 4                          | 1   | <b>W/S sealant</b><br>(NECESSARY) | 40.00         | 40.00         |
| 5                          | 1   | <b>Wheel alignment</b>            | 80.00         | 60.00         |
| <b>Sub Total (S\$)</b>     |     |                                   | <b>285.00</b> | <b>265.00</b> |

## Recommended Labour

| No                             | Particulars                           | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---------------------------------------|----------|-----------------|-----------------|
| <b>Paintwork Labour</b>        |                                       |          |                 |                 |
| 1                              | <b>Total Paint Including Material</b> | New      | 856.35          | -               |
| 2                              | <b>PAINTWORK: LABOUR.</b>             | New      | -               | 571.20          |
| 3                              | <b>PAINTWORK: MATERIAL.</b>           | New      | -               | 285.15          |
| <b>Labour Items</b>            |                                       |          |                 |                 |
| 4                              | <b>Total of Labour</b>                | New      | 2,011.80        | 1,927.80        |
| <b>Gross Labour Cost (S\$)</b> |                                       |          | <b>2,868.15</b> | <b>2,784.15</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >