

## Shirley Hiew (LKK Auto)

---

**From:** Kenneth Kong (LKKAuto)  
**Sent:** Tuesday, 21 April 2020 12:16 pm  
**To:** Shirley Hiew (LKK Auto)  
**Subject:** SGM 3813A

Right front wing Buckled  
Left front wing Buckled  
Left splash panel Bent  
Right splash panel Bent  
Side memberSPL Bent

Labour for 99,100,103 Necessary  
Remove undercarriage \$320  
Spray painting \$1100  
Reset fault code \$120