




CARFEELS 1-Stop Services PTE LTD

160 Sin Ming Drive #05-18 Sin Ming Autocity Singapore 575722



TAX INVOICE

Date: 24.02.2020
Model: Mitsubishi Evo 9 GSR 2.0M
Vehicle No : SGM3813A

Ref No: 2020020141
Accident Date: 06.06.2019
TP Vehicle No: OD

S/N	DESCRIPTION	QTY	UNIT PRICE		Total Price		
			SGD	SGD	SGD	SGD	
1	Front bonnet	1	\$	1,500.00	\$	1,500.00	
2	Front bonnet netting assy	1	\$	250.00	\$	250.00	
3	Front bumper top netting	1	\$	85.00	\$	85.00	
4	Front bumper lower netting	3	\$	60.00	\$	180.00	
5	Font bumper LOGO	1	\$	95.00	\$	95.00	
6	Front bumper lower lip	1	\$	320.00	\$	320.00	
7	Front bumper	1	\$	650.00	\$	650.00	
8	Front bonnet lock	1	\$	135.00	\$	135.00	
9	Front bonnet Lock Cable	1	\$	85.00	\$	85.00	
10	Front bonnet front seal	3	\$	65.00	\$	195.00	
11	Front bonnet under heat shield	1	\$	180.00	\$	180.00	
12	Front RHS headlamp assy	1	\$	950.00	\$	950.00	
13	Front LHS headlamp assy	1	\$	950.00	\$	950.00	
14	Front headlamp hid ballast kits	2	\$	850.00	\$	1,700.00	
15	Front RHS repeater lamp	1	\$	55.00	\$	55.00	
16	Front LHS repeater lamp	1	\$	55.00	\$	55.00	
17	Right Front Wing	1	\$	650.00	\$	650.00	A ✓ BUC
18	Left Front Wing	1	\$	650.00	\$	650.00	A ✓ BUC
19	Left Front Splash panel	1	\$	1,350.00	\$	1,350.00	A ✓ BT
20	Right Front Splash panel	1	\$	1,350.00	\$	1,350.00	A ✓ BT
21	Front support panel	1	\$	420.00	\$	420.00	
22	Right Front Side member SPL	1	\$	1,720.00	\$	1,720.00	A ✓ BT
23	Front Windscreen	1	\$	1,850.00	\$	1,850.00	
24	Upper Rubber moulding	2	\$	60.00	\$	120.00	
25	Spacer Bush	8	\$	6.00	\$	48.00	
26	Left Still extension	1	\$	220.00	\$	220.00	
27	Front Passengerr airbag	1	\$	1,130.00	\$	1,130.00	
28	Instrument Panel	1	\$	840.00	\$	840.00	




Page 1 of 4 *

Office : (65) 6452 8817
Fax: (65) 6452 9817
Email: carfeels@gmail.com
Co. Reg. No./GST No.: 200802100N



CARFEELS 1-Stop Services PTE LTD

160 Sin Ming Drive #05-18 Sin Ming Autocity Singapore 575722




S/N	DESCRIPTION	QTY	UNIT PRICE		Total Price	
			SGD	SGD	SGD	SGD
29	Air con compressor	1	\$	950.00	\$	950.00
30	Air con condenser	1	\$	280.00	\$	280.00
31	Air intake hose	1	\$	86.00	\$	86.00
32	Connection Tube	1	\$	65.00	\$	65.00
33	Front RHS seat belt assy	1	\$	720.00	\$	720.00
34	Front LHS seat belt assy	1	\$	720.00	\$	720.00
35	LHS Drive shaft	1	\$	680.00	\$	680.00
36	LHS lower control arm	1	\$	550.00	\$	550.00
37	RHS lower control arm	1	\$	550.00	\$	550.00
38	Front LHS coil over	1	\$	650.00	\$	650.00
39	Front RHS coil over	1	\$	650.00	\$	650.00
40	Front LHS steering knuckle	1	\$	430.00	\$	430.00
41	Front RHS steering knuckle	1	\$	430.00	\$	430.00
42	Front LHS strut bearing	1	\$	105.00	\$	105.00
43	Front LHS dust cover	1	\$	35.00	\$	35.00
44	Front LHS Damper buffer	1	\$	40.00	\$	40.00
45	Front LHS wheel hub	1	\$	620.00	\$	620.00
46	Front LHS brake hose	1	\$	68.00	\$	68.00
47	Front LHS Wheel and tyres	1	\$	900.00	\$	900.00
48	Front RHS Wheel and tyres	1	\$	900.00	\$	900.00
49	Front LHS ABS Sensor	1	\$	120.00	\$	120.00
50	Front Stabiliser	1	\$	320.00	\$	320.00
51	Front LHS stabiliser bush	1	\$	30.00	\$	30.00
52	Front RHS stabiliser bush	1	\$	30.00	\$	30.00
53	Front LHS stabiliser linkage	1	\$	95.00	\$	95.00
54	Lower Front out mounting kit	1	\$	250.00	\$	250.00
55	Airbag control unit	1	\$	760.00	\$	760.00
56	Power steering oil tank	1	\$	184.00	\$	184.00
57	Power steering inlet pipe	1	\$	120.00	\$	120.00
58	Radiator	1	\$	700.00	\$	700.00
59	Fan motor	1	\$	230.00	\$	230.00
60	Radiator shroud	1	\$	110.00	\$	110.00





CARFEELS *1-Stop Services* PTE LTD

180 Sin Ming Drive #05-18 Sin Ming Autocity Singapore 575722




S/N	DESCRIPTION	QTY	UNIT PRICE		Total Price	
			SGD	SGD	SGD	SGD
61	Lower radiator hose	1	\$	85.00	\$	85.00
62	LHS blower fan motor	1	\$	180.00	\$	180.00
63	LHS fan motor	1	\$	195.00	\$	195.00
64	LHS lower radiator bracket	1	\$	20.00	\$	20.00
65	RHS lower radiator bracket	1	\$	20.00	\$	20.00
66	Oil filter	1	\$	35.00	\$	35.00
67	Air filter housing	1	\$	170.00	\$	170.00
68	Starter motor	1	\$	520.00	\$	520.00
69	Engine support	1	\$	350.00	\$	350.00
70	Right engine bracket	1	\$	210.00	\$	210.00
71	Engine under-sub frame	1	\$	1,200.00	\$	1,200.00
72	Exhaust manifold	1	\$	480.00	\$	480.00
73	Exhaust manifold cover	1	\$	150.00	\$	150.00
74	Front exhaust pipe	1	\$	1,140.00	\$	1,140.00
75	Front gearbox carrier	1	\$	450.00	\$	450.00
76	Horn	2	\$	95.00	\$	190.00
77	Gearbox housing	1	\$	900.00	\$	900.00
78	Gear oil	3	\$	60.00	\$	180.00
79	LHS intercooler pipe	1	\$	170.00	\$	170.00
80	RHS intercooler pipe	1	\$	190.00	\$	190.00
81	Intercooler	1	\$	1,180.00	\$	1,180.00
82	LHS intercooler hose	1	\$	75.00	\$	75.00
83	RHS intercooler hose	1	\$	80.00	\$	80.00
84	Fan belt	1	\$	195.00	\$	195.00
85	Power steering fluid	1	\$	65.00	\$	65.00
86	Engine oil	5	\$	45.00	\$	225.00
87	Coolant oil base	1	\$	45.00	\$	45.00
88	Right Front Wing Top Garnish	1	\$	320.00	\$	320.00
89	Radiator Top bracket bush	2	\$	45.00	\$	90.00
90	Bonnet stand clip	1	\$	15.00	\$	15.00
91	Engine oil cooler	1	\$	400.00	\$	400.00
92	Engine oil cooler inlet pipe	1	\$	195.00	\$	195.00





CARFEELS 1-Stop Services PTE LTD

160 Sin Ming Drive #05-18 Sin Ming Autocity Singapore 575722



S/N	DESCRIPTION	QTY	UNIT PRICE SGD	Total Price SGD
93	Engine oil cooler outlet pipe	1	\$ 210.00	\$ 210.00
94	Front Number plate	1	\$ 30.00	\$ 30.00
PARTS TOTAL:				\$ 40,071.00
<u>LABOUR CHARGES & MISC</u>				
95	To remove, cuts, pulling, welding, adjustment & align body parts	1	\$ 2,800.00	\$ 2,800.00
96	To remove, dismantle & assembly gear box to replace housing	1	\$ 950.00	\$ 950.00
97	To replace front dashboard air bag set	1	\$ 120.00	\$ 120.00
98	To vacuum, replace lub oil & refill ac gas	1	\$ 120.00	\$ 120.00
99	To refill gear box oil	1	\$ 35.00	\$ 35.00
100	To replace engine oil	1	\$ 30.00	\$ 30.00
101	Electronic wheel alignment	1	\$ 80.00	\$ 80.00
102	To check wirings in good functioning	1	\$ 60.00	\$ 60.00
103	To test & check oil leakage (after repair)	1	\$ 30.00	\$ 30.00
104	To remove undercarriage & refix	1	\$ 650.00	\$ 650.00
105	To replace front wiindscreen	1	\$ 320.00	\$ 320.00
106	To spray paint on damage parts	1	\$ 1,500.00	\$ 1,500.00
107	To diagnostic scan & reset fault code	1	\$ 180.00	\$ 180.00
108	Tuff cote on welded portion	1	\$ 30.00	\$ 30.00
LABOUR TOTAL:				\$ 6,905.00
Singapore Dollars:				
Thirty thousand four hundred and ninety-five only				
SUBTOTAL:				\$ 46,976.00
Less ADJUSTMENTS:				\$ 16,976.00
Less EXCESS :				\$ 1,500.00
GST 7% :				\$ 1,995.00
TOTAL AMOUNT :				\$ 30,495.00

A ✓ NEC

A ✓ NEC

A ✓ NEC

A ✓ 320.00

A ✓ 1100.00

A ✓ 120.00

