

SS. REC. BY:

REF: CS/FCI19010971/ES d30 Special Instruction:

Surveyor: STAVK

ASSIGNMENT (Office)

From (Person): Henry Kao of FCI Date/Time: 8:20am @ 2/16/19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 3663L Insured: SHC0020G

at Workshop m/s: 8MPF Tel: 88583556

of: Go woodlands Ind. Park Ct

Policy No: Claim No: D19003964MPF#

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 27/5/2019

CA / REV / REP. / REV 24 HRS ^{1up} H.O.D. Endorsement:

Date/Time: 10:13am @ 2/16/19 Person Contacted: Mr. Peh Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	PC3663L - CC9 / III18021217 / Jfb3	
	SHC0020G - NR / INCI6020147 / h1	
01/07/19	@ 17:47 pm revised PA to Henry via email.	

JOA: 17/8/16
GDA: 24/10/16

IP
ASH RES IN

Steve

REF

FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____

(Frny Condition)

Remarks: The veh had commenced its repair at the time of inspection.

N/S	O/S

Balance Market Value: _____
 IDAC / Accra Report: _____ Consistent? : Yes or No
 GIA / Ref. Sam: _____ Consistent? : Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Vehicle No: PC 3663L Yr Regn: 23/3/15
 Type: M.Car / M.Cycle (Bus) Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mitsubishi Rosa CC: 2998
 Colour: Multi-Colour A/C: Insured / Std / NI / NA
 Sp. Reading: 221796 T/Radio: Insured / Std / NI / NA
 Eng. No: _____
 C/No: BE64JJ10175
 Gen. Cond: Good / (Fair) / Poor / Burnt
 Steering: (Inorder) / Jammed / Leaked / Burnt or
 Brake: (Inorder) / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / (STD A/Rim) or

Tyre Size: F: 7.00R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Chao Yang

Front		Rear	
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm	
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm	
D.O.I. <u>27/5/19</u>		D.O.I. <u>27/6/19</u>	

Survey held at SMRT
 Desc. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
From RH
 The U/C / Chassis frame / Body Structure affected due to collision.

Dets. Title Action / Instruction

10/07/19 Comb. med Ls \$ 5,000/- @ 5 days with Steve
(\$ 3,418.54 Red - 41%)

RECEIVED 15 JUL 2019

Date Time to Report

15/07/19
Typical

: Preli. Report
 : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 1

Date Time to Resurvey

2)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S+RS: _____
 Photos: _____
 Others: _____
 TOTAL: _____

160
50
50
22
282

Report Format:

Lump Sum I.B.I. (\$ 5,000/- Ls)

MOTOR SURVEY ASSIGNMENT

Date	18-06-2019	Our Ref No. D19003964MFSH
Accident Date	27-05-2019	Claim Type. Third Party
Insured Vehicle	SHC0020G	Third Party Vehicle. PC3663L
Survey Location	60, WOODLANDS INDUSTRIAL PARK E4	
Contact Person.	PEH ENG HOCK	
Contact No.	68662673/ 88583556	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SMRT AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3524H
Vehicle Details	
Vehicle No.:	PC3663L
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jun 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	ROSA BUS BE641JRMDEB
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	4P10B45331
Chassis No.:	BE641JJ10175
Maximum Power Output:	-
Open Market Value:	\$58,550.00
Original Registration Date:	23 Mar 2015
First Registration Date:	23 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$2,928.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$53,202.00
COE Rebate Amount:	\$30,478.00
Total Rebate Amount:	\$30,478.00

The information contained herein is correct as at 27 Jun 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 1 July 2019 5:47 PM
To: 'Henry Kao Cai Jie'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003964MFSH/1
Attachments: PC 3663L - Preli Advise .pdf

Dear Henry,

Enclosed preliminary revised of vehicle PC 3663L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 21 June 2019 10:17 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003964MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 21 June 2019 8:12 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie

<HenryKao@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19003964MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003964MFSH

Date: 01 July 2019

Our Ref: CS/FCI19010971/Esd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. PC 3663L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/06/2019 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,418.55</u>
Revised Estimate Amount	: S\$ <u>5,924.75</u>
"Check" Items Amount	: S\$ _____
Total	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the front RH portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 days

Yours faithfully,
Chen Tsue Yee
Automotive Assessor

MS FIRST CAP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/05/2019 18:58
Date Of Accident	27/05/2019 11:55
Exact Location Of Accident	MOUNT ALVERNIA HOSPITAL SHUTTER BUS LOT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC3663L
Insured/Policyholder	
Name Of Registered Owner	BUS-PLUS SERVICES PTE LTD
Co Reg No	199403524H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MINI BUS
Model	MINI BUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093204MFBP
Cover Note Number	

Driver

Name of Driver	KUNG HSIANG-LU
NRIC No	S2683679D
Date Of Birth	16/06/1956
Occupation	OUTDOOR
Date Of Driving Pass	13/02/2014
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address NIL
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 11

Details of Police Action

Was the accident reported to the police? NO
 If Yes,Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes,against whom?

Circumstances of Accident

ON MENTIONED DATE & TIME.I WAS AT MOUNT ALVERNIA HOSPITAL SHUTTER BUS LOT TO PICK UP PASSENGER.WHEN I WAS STARTED TO MOVE SUDDENLY A VEHICLE (SHC20G) CUT INTO MY LANE AND HIT ONTO FRONT RIGHT SIDE OF MY BUS.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC20G
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Kung 27/5/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

A. 27/5/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Vehicle Repair Estimate

Group : **Buses / Taxis / Private Car**

Reg. No. : PC 3663 L

Make / Model : Mitsubishi Rosa

Chassis No : _____

Name of Driver : KUNG HSIANG-LU

Date/Time of Accident : 27/05/2019 11:55

Surveyer is Required ? **YES / NO**

If Yes, VICOM / LKK / AIS / Others : _____ MSIG : _____

Vehicle is Towed Back ? YES / NO Date / Time : _____

Accident reporting date : 27/05/2019 18:58

Type of Accident : Skid / Head-Rear / **Head-On** / Side Swipe / Others


Special Instruction to ARC, if any :
INSURANCE LUMP SUM

Ref. No. BBS/05/19/3002

Reg. Date : _____

Mileage : _____

Rental/Replacement Vehicle : _____



Signed : _____ Date : _____

Accident Repair Job Card No : _____ Date Prepared : _____

Summary of Repair Estimates : _____ Repair Completed : _____

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	\$ 800.00	\$ -
Total Spray Painting Charges	\$ 1,000.00	\$ -
Total Material Charges	\$ 5,978.55	\$ -
Other Charges	\$ 640.00	\$ -
TOTAL	\$ 8,418.55	\$ -

Lump Sum Repair, if any : _____

No. of Repair Days : [] days [] days

Signature : Prepared by: _____ Adjusted by: _____

QN No. _____ Invoice No. _____ Date : _____

Signed : _____ Date : _____

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign hydraulic, and aligned all parts	\$ 800.00	
Total Labour Cost	\$ 800.00	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 1,000.00	
Spray Painting	\$ 1,000.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page (

Job Scope	Quotation from ARC	
To tuffcoat affect areas	\$ 250.00	
To remover /refit wiring check	\$ 60.00	
Remove / replace door mechanism	\$ 180.00	
To removeand refix front door glass	\$ 150.00	
Total Other Costs	\$ 640.00	

Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC

Part Number	Parts Description	Qty	Cost Price (\$)	COST DISCOUNT 10%	Final Price (\$)	Repair (R) Replace (/)
1	FRONT BUMPER	1	\$ 1,562.91	10%	\$1,406.62	
2	FRONT DOOR RH	1	\$ 2,955.68	10%	\$2,660.11	
3	FRONT DOOR INNER SEAL RH	1	\$ 85.75	10%	\$ 77.18	
4	FRONT DOOR SIGNAL LAMP RH	1	\$ 205.16	10%	\$ 184.64	

Special Nett Items	Parts Description	Qty	Cost Price (\$)	Discount	Final Price (\$)	Repair (R) Replace (/)
1	FRONT BUMPER STICKER	1	\$ 450.00	-	\$ 450.00	
2	FRONT PANEL STICKER	1	\$ 600.00	-	\$ 600.00	
3	FRONT DOOR STICKER RH	1	\$ 600.00	-	\$ 600.00	

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign hydraulic, and aligned all parts	\$ 800.00	
Total Labour Cost	\$ 800.00	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 1,000.00	
Spray Painting	\$ 1,000.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page (

Job Scope	Quotation from ARC	
To tuffcoat affect areas	\$ 250.00	
To remover /refit wiring check	\$ 60.00	
Remove / replace door mechanism	\$ 180.00	
To removeand refix front door glass	\$ 150.00	
Total Other Costs	\$ 640.00	

Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC

Part Number	Parts Description	Qty	Cost Price (\$)	COST DISCOUNT 10%	Final Price (\$)	Repair (R) Replace (/)
1	FRONT BUMPER	1	\$ 1,562.91	10%	\$1,406.62	
2	FRONT DOOR RH	1	\$ 2,955.68	10%	\$2,660.11	
3	FRONT DOOR INNER SEAL RH	1	\$ 85.75	10%	\$ 77.18	
4	FRONT DOOR SIGNAL LAMP RH	1	\$ 205.16	10%	\$ 184.64	

Special Nett Items	Parts Description	Qty	Cost Price (\$)	Discount	Final Price (\$)	Repair (R) Replace (/)
1	FRONT BUMPER STICKER	1	\$ 450.00	-	\$ 450.00	
2	FRONT PANEL STICKER	1	\$ 600.00	-	\$ 600.00	
3	FRONT DOOR STICKER RH	1	\$ 600.00	-	\$ 600.00	

TOTAL MATERIALS

\$ 6,459.50	-	\$ 5,978.55
-------------	---	-------------

Surveyor Remark:



SMRT Accident Vehicle Repair Estimates

*MS First-CAR
and survey*

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/06/2019

User ID : PehEngHock

Section A - Accident Details	
Registration Number	PC3663L
Case Reference Number	BPS/05/19/3004
Registration Date	3/23/2015
Company Type	Bus-Plus Services Pte Ltd
Make	MITSUBISHI
Model	MITSUBISHI ROSA 4.9L
Name of Driver	Kung Hsiang-Lu
Type of Accident	Side Swipe
Accident Date and Time	5/27/2019 11:55 AM
Accident Reported Date and Time	5/27/2019 4:20 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	OUR BUS DAMAGED FRONT RIGHT TP-SHC20G (CITYCAB)
Prepared Date and Time	6/10/2019 10:34 AM
Chassis Number	BE641JJ10175
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$800.00	\$0.00
Total Spray Cost	\$1,000.00	\$0.00
Total Spare Part Cost	\$5,978.54	\$0.00
Total Other Cost	\$640.00	\$0.00
TOTAL COST	\$5,978.54 <i>8418.55</i>	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	10/06/2019 10:51 AM	
Signature	x	x
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	




SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/06/2019

User ID : PehEngHock

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope	Quotation from AR						Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$800.00						600		
Total Labour	\$800.00								
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope	Quotation from ARC						Adjusted by Surveyor, if applicable		
TO RESPRAY ALL AFFECTED AREA	\$1,000.00						750		
Total Spray Painting & Panel Beating	\$1,000.00								
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope	Quotation from ARC						Adjusted by Surveyor, if applicable		
TO POLISH AFFECTED AREA	\$250.00						X		
TO REMOVE AND REFIT WIRE HARDESS	\$60.00						30		
TO TRANSFER DOOR MECHANISM	\$180.00						50		
TO REMOVE/INSTALL DOOR BOARD OUTER HANDLE TO FACILITATE REPAIR.	\$150.00						X		
Total Other Costs	\$640.00								
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			FRONT BUMPER	1.00	\$1,562.91	10.00	\$1,406.62	Replace	X H/R
			FRONT DOOR RH	1.00	\$2,955.68	10.00	\$2,660.11	Replace	- AP
			FRONT DOOR INNER SEAL RH	1.00	\$85.75	10.00	\$77.17	Replace	X H/R
			FRONT DOOR SIGNAL LAMP RH	1.00	\$205.16	10.00	\$184.64	Replace	- CR
			FRONT BUMPER STICKER	1.00	\$450.00	0.00	\$450.00	Replace	- APC
			FRONT PANEL STICKER	1.00	\$600.00	0.00	\$600.00	Replace	- APC
			FRONT DOOR STICKER RH	1.00	\$600.00	0.00	\$600.00	Replace	- APC
Total					\$6,459.50		\$5,978.54		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									


 Steve (LKK)
 37/19 8392 8813
 steve.chen@lkkauto.com

with Project 27/6/19, 4.15 pm
 5 days
 LIS
 Roy AL spy

889950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:



SMRT Accident Vehicle Repair Estimates

ALAN REPAIRS

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63635592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/07/2019

User ID : PehEngHock

Section A - Accident Details	
Registration Number	PC3663L
Case Reference Number	BPS/05/19/3004
Registration Date	3/23/2015
Company Type	Bus-Plus Services Pte Ltd
Make	MITSUBISHI
Model	MITSUBISHI ROSA 4.8L
Name of Driver	Kung Hsiang-Lu
Type of Accident	Side Swipe
Accident Date and Time	5/27/2019 11:55 AM
Accident Reported Date and Time	5/27/2019 4:20 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24102294
Special Instruction to ARC, if any	OUR BUS DAMAGED FRONT RIGHT TP-SHC20G (CITYCAB)
Prepared Date and Time	6/10/2019 10:34 AM
Chassis Number	BE641JJ10175
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$800.00	\$600.00
Total Spray Cost	\$1,000.00	\$750.00
Total Spare Part Cost	\$5,978.54	\$3,595.80
Total Other Cost	\$540.00	\$80.00
TOTAL COST	\$8,418.54	\$5,025.80
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	5.0
Prepared / Adjusted By	Peh Eng Hock	STEVE CHEN
ARC / Surveyor Sign Off Date	10/06/2019 10:51 AM	01/07/2019 11:11 AM
Signature	[Signature]	[Signature]
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 75705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/06/2019

User ID : PehEngHock

Shirley

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$800.00	600
Total Labour	\$800.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY ALL AFFECTED AREA	\$1,000.00	750
Total Spray Painting & Panel Beating	\$1,000.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO POLISH AFFECTED AREA	\$250.00	X
TO REMOVE AND REFIT WIRE HARDESS	\$60.00	30
TO TRANSFER DOOR MECHANISM	\$180.00	50
TO REMOVE/INSTALL DOOR BOARD OUTER HANDLE TO FACILITATE REPAIR.	\$150.00	X
Total Other Costs	\$640.00	

1430 /

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			FRONT BUMPER	1.00	\$1,562.91	10.00	\$1,406.62	Replace	X HFR
			FRONT DOOR RH	1.00	\$2,955.68	10.00	\$2,660.11	Replace	/ AH
			FRONT DOOR INNER SEAL RH	1.00	\$85.76	10.00	\$77.17	Replace	X NNI
			FRONT DOOR SIGNAL LAMP RH	1.00	\$205.16	10.00	\$184.64	Replace	/ GR
			FRONT BUMPER STICKER	1.00	\$450.00	0.00	\$450.00	Replace	/ APC
			FRONT PANEL STICKER	1.00	\$600.00	0.00	\$600.00	Replace	/ APC
			FRONT DOOR STICKER RH	1.00	\$600.00	0.00	\$600.00	Replace	/ APC
Total					\$6,459.50		\$5,978.54		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

4494
LESS 20%
3595.80 /

Steve (LKK)
8392 8813
steveclin@lkkauto.com

nrk provide 97/6/19, 4.15 pm
5 days
LIS
Ray AL spy

5/7/19 — Finalize confirm with Mr Ah \$5000, 5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010971/Esd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-08-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 20G	Veh. Inspected	PC 3663L
Policy No.		Coverage (\$)	0.00
Claim No.	D19003964MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	21/06/2019
2. Vehicle Particulars & Condition			
Make & Model	mitsubishi ROSA	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	BE641JJ10175	Colour	MULTI COLOUR
Odometer	221706	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	7.00 R16	CHAO YANG	5 mm
L/H Front Tyre	7.00 R16	CHAO YANG	5 mm
R/H Rear Tyre	7.00 R16	CHAO YANG	5 mm
L/H Rear Tyre	7.00 R16	CHAO YANG	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT RH PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/05/2019	Inspection Date	27/06/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 3663L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,562.91	-
1	FRONT DOOR RH	DENTED	2,955.68	2,955.68
1	FRONT DOOR INNER SEAL RH	NOT NECESSARY	85.75	-
1	FRONT DOOR SIGNAL LAMP RH	BROKEN	205.16	205.16
	LESS 10% DISCOUNT		-	-316.08
			4,809.50	2,844.76
	SPECIAL NETT ITEMS			
1	FRONT BUMPER STICKER (SN)	NECESSARY	450.00	450.00
1	FRONT PANEL STICKER (SN)	NECESSARY	600.00	600.00
1	FRONT DOOR STICKER RH (SN)	NECESSARY	600.00	600.00
			1,650.00	1,650.00
	LABOUR			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		800.00	600.00
	TO RESPRAY ALL AFFECTED AREA.		1,000.00	750.00
	TO POLISH AFFECTED AREA.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIT WIRE HARDESS.		60.00	30.00
	TO TRANSFER DOOR MECHANISM.		180.00	50.00
	TO REMOVE / INSTALL DOOR BOARD OUTER HANDLE TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
			2,440.00	1,430.00
	GRAND TOTAL		8,899.50	5,924.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00

Report Ref No. CS/FCI19010971/Esd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.