

ASS. REC. BY:

REF: CS/CTI19010972/Rlvds

Special Instruction: n2

Surveyor: Rajul

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTI

Date/Time: 21/6/19 @ 9:34am

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDR 84R

Insured: 9Y 2096X

at Workshop in/s: Comfordelgro

Tel: 6867 6919

of: 45 penden Road

Policy No: _____ Claim No: 8NM19D202762 C02/6

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12/06/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 9:50am @ 21/6/19 Person Contacted: Cheng

Vehicle: IN/OUT

Date/Time	Action/Instruction
	<u>SDR 84R - X</u>
	<u>9Y 2096X - C8/PC 8018197 / Vrgl</u>
	<u>D.O.A: 24/12/2007</u>
<u>17/11/19</u>	<u>Ls \$6500 confirmed by email (Ref 4051-70, 387)</u>

ASSIGNMENT

From: _____ Date: *21.6.2019*

Veh No: *SDR 84R* Yr Regn: *2011 JUM*

Estimated Cost: _____

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: *SDR 84R*

Make: *MERCEDES BENZ E 250 CGI* c.c. *1796*

at Workshop n/s: *ComfoAdi gro*

Colour: *GREEN* A/C: Insured / Std / NI / NA

of *45 Pandan Road*

Sp. Reading: *16387* T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: *W002120472A385432*

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: *3.30pm Omar Wahing*

Modi: Nil / S/Rim / STD A/Rim or


wong chee wei 68676919

Tyre Size: F: *245/45R17*

(Policy Condition)

R: _____

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value: *56k*

Front R/Bal. *6* mm

IDAC Accident Rpt: Consistent? Yes or No

Rear R/Bal. *6* mm

GIA / PR Seen: Consistent? Yes or No

L/Bal. *6* mm

Est. Repairs: _____ days Res.: Yes or No

D.O.A. *12/6/19* D.O.I. *21/6/19*

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at *ComfoAdi gro*

CA / REV / REP. / 24 HRS *wp''*

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or *Rear o/s*

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 01 JUL 2019

Date/Time, File Pass to? : Preli. Report : Final Report

Days Of Repair: *4* Resurvey No. of Trip: *2*

1) _____
2) *1/7 - typist*

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Survey Fee:	
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	<i>220</i>

Report Format: *merimen*

Lump Sum / I.B.I: (\$) *6500k*

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 1 July 2019 10:40 AM
To: CDGE Pandan Private Cars Crash Repair Counter; Rasul (LKKAuto); SUR
Subject: RE: SDR84R - DOA@12.06.2019 - Finalization cost of repair

Dear Chee Wei,

WITHOUT PREJUDICE

Confirmed Lump Sum \$6500 @ 4 working days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Sent: Saturday, 29 June 2019 11:24 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: SDR84R - DOA@12.06.2019 - Finalization cost of repair

Hi Rasul ,

With refer to attached our finalization form and photo after repair for your advice and confirm .

Thank you.

Wong Chee Wei
Pandan Crash Repair
ComfortDelgro Engineering Pte. Ltd.
DID 68676919

From: ApeosPort-III C4400 <fujixerox@sparkcarcare.com>
Sent: Saturday, 29 June 2019 10:34 AM

To: CDGE Pandan Private Cars Crash Repair Counter
Subject: Scan Data from CDG_PANDAN_SC2_A4400

Number of Images: 4
Attachment File Type: PDF

Device Name: ApeosPort-III C4400
Device Location:

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Friday, 21 June 2019 9:34 AM
To: pandan_cr@sparkcarcare.com; assignments@lkkauto.com
Subject: FW: OUR REF: SNM19D202762C02/6 - Check liability accident involving for our client vehicle no. SDR84R and Your insured vehicle no.GY2096X DOA@12/06/2019
Attachments: img-618161415-0001.pdf; SAS2617219.PDF

WITHOUT PREJUDICE

Your Ref: SDR84R
Our Ref: SNM19D202762C02/6 (GY2096X)

Dear Chee Wei,

We refer to your email of 21.06.19.

Liability clear.

In view of the above, we agree to go for Direct Settlement, subject to consistency of damages, based on M/s LKK Auto's findings, with supporting documents.

** Please amend your client's SAS report (wrong vehicle number).

Aside to LKK,

Please liaise with TP workshop on survey.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: CDGE Pandan Private Cars Crash Repair Counter [mailto:pandan_cr@sparkcarcare.com]
Sent: Friday, 21 June, 2019 8:34 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Cc: stephenyeap@orion.com.sg
Subject: Fw: OUR REF: SNM19D202762 - CHEONGML - Check liability accident involving for our client vehicle no. SDR84R and Your insured vehicle no.GY2096X DOA@12/06/2019

Dear Survey Team And Ms Elaine

With refer to below email dated 20.06.2019 .

We still pending your to confirm today afternoon 14.30 - 15.30 pm appointment survey for our client vehicle no. SDR84R

Hope to hear soonest ,Thank you.

Wong Chee Wei
Pandan Crash Repair
ComfortDelgro Engineering Pte. Ltd.
DID 68676919

From: CDGE Pandan Private Cars Crash Repair Counter
Sent: Thursday, 20 June 2019 10:07 AM
To: Elaine Cheong
Cc: stephenyeap@orion.com.sg
Subject: Fw: OUR REF: SNM19D202762 - CHEONGML - Check liability accident involving for our client vehicle no. SDR84R and Your insured vehicle no.GY2096X DOA@12/06/2019

Hi Elaine ,

Please arrange appointment survey our client vehicle no. SDR84R on tomorrow date 21.06.2019 time 14.30 - 15.30 p.m

Please reply to confirm.

Thank you.

Wong Chee Wei
Pandan Crash Repair
ComfortDelgro Engineering Pte. Ltd.
DID 68676919

From: Lim Shu Min <shumin.lim@sg.cntaiping.com>
Sent: Tuesday, 18 June 2019 5:39 PM
To: CDGE Pandan Private Cars Crash Repair Counter; Elaine Cheong; Chee So Chow
Subject: OUR REF: SNM19D202762 - CHEONGML - Check liability accident involving for our client vehicle no. SDR84R and Your insured vehicle no.GY2096X DOA@12/06/2019

WARNING: This email originated from an external party outside ComfortDelGro. Sender of this email could not be validated and name in the "From" field may be forged.

Dear Elaine,

Please conduct PRS – SDR84R soonest possible.

File with Officer-In-Charge – Elaine Cheong – 63896530

Thank you

Lim Shu Min

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: CDGE Pandan Private Cars Crash Repair Counter [mailto:pandan_cr@sparkcarcare.com]

Sent: Tuesday, 18 June, 2019 5:01 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Check liability accident involving for our client vehicle no. SDR84R and Your insured vehicle no.GY2096X
DOA@12/06/2019

Dear Sir / Madam ,

With reference attached for above mentioned matter ,Please advice and arrange survey at 45 Pandan Road .

Best Regards,
Chen Chee Kiong
Pandan Crash Repair
ComfortDelgro Engineering Pte. Ltd.
DID 68676919

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1135D
Vehicle Details	
Vehicle No.:	SDR84R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jun 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250CGI
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	27186030187090
Chassis No.:	WDD2120472A385432
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$55,808.00
Original Registration Date:	13 Jun 2011
First Registration Date:	13 Jun 2011
Transfer Count:	1
Actual ARF Paid:	\$55,808.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2021
PARF Rebate Amount:	\$30,694.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,100.00
COE Rebate Amount:	\$10,828.00
Total Rebate Amount:	\$41,522.00

The information contained herein is correct as at 24 Jun 2019

OK

56,000
 41,522

 14,478

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/06/2019 17:45
Date Of Accident	12/06/2019 14:35
Exact Location Of Accident	CHINATOWN CARPARK PARK CRESCENT 4TH LEVEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDR84R
Insured/Policyholder	
Name Of Registered Owner	YEAP BENG CHYE STEPHEN
NRIC No	S1301135D
Email Address	STEPHENYEAP@ORION.COM.SG
Mobile Phone No	(LOCAL) +65-96651747
Alternative Phone No	OFFICE-96651747

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18V06911/VPE/R02
Cover Note Number	

Driver

Name of Driver	YEAP BENG CHYE STEPHEN
NRIC No	S1301135D
Date Of Birth	23/07/1958
Occupation	OUTDOOR
Date Of Driving Pass	04/06/1979
Driving Experience	40 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96651747
Fax Number	
Contact Number	OFFICE-96651747
EEmail Address	STEPHENYEAP@ORION.COM.SG

Address	61 MOUNT SINAI DRIVE
Postcode	277113
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY2096X
Vehicle Make/Model/Colour	TOYOTA / LITACE
Details Of Properties	FRONT PORTION
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAY KOK WAH (ZHONG QUOHUA)
NRIC/Passport Number	S8902225H
Contact Number	92278934
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : Own Damage
 3rd Party
 Windscreen

Ins Company : CHINA TAIPING

Excess : _____

Date of Accident : 12/06/2019

Suggested Days of Repair : _____

Vehicle No. SDR84R

Make & Model MERCEDES BENZ E 250CGI

Year of Manufacture 2013

Chassis No. WDD2120472A385432

Engine No. 27186030187090

Policy No. _____

Time of Accident _____

In-house Vehicle Assessor

Name WONG CHEE WEI / CK

Repair Estimates

Parts (a) List Price Items	\$9,824.00
LESS 10 %	\$(982.40)
(b) Nett Price Items	_____
Less _____ %	_____
(c) Special Nett Items	\$195.00
Total Parts Cost (Appendix A)	\$9,036.60
Labour (Appendix B)	\$1,300.00
Total Repair Cost	\$10,336.60

Signature _____

Contact No 68676919

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

The above total will be subjected to 7% G.S.T.

10,551.70

[Handwritten signature]

24/6/19

Name of Surveyor : Rasul

Company : LKK

Survey conducted on : 21/06/19 at 1530

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s) L/S

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: 21/06/19

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandna Road S (609286)
Tel: 68676919 Fax: 62626950

Appendix A

Spare Parts

Vehicle No. : SDR84R Submit By : WONG CHEE WEI / CK
 Make & Model : MERCEDES BENZ E 250CGI Year Manufacture : 2013
 Chassis No. : WDD2120472A385432 Engine No. : 27186030187090

TP

S/Order : _____

S/No.	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price
1	REAR BUMPER <i>de /</i>	1			\$1,550.00	
2	REAR BUMPER CLIPS <i>ne /</i>	10			\$80.00	
3	REAR BUMPER CHORME LHS <i>ne /</i>	1			\$125.00	
4	REAR BUMPER CHORME CENTER <i>ne /</i>	1			\$175.00	
5	REAR BUMPER CHORME LHS <i>ne /</i>	1			\$128.00	
6	REAR BUMPER SKIRT <i>de /</i>	1			\$485.00	
7	REAR BUMPER SKIRT CLIPS <i>nee /</i>	10			\$80.00	
8	REAR BOOT LID top <i>bt /</i>	1			\$2,600.00	
9	REAR BOOT LID HINGE RH <i>X 9</i>	1			\$135.00	
10	REAR BOOT LID HINGE LH <i>X 9 17</i>	1			\$135.00	
11	REAR BOOT LOCK <i>X 9</i>	1			\$270.00	
12	BOOT LID RH TAIL LAMP <i>sca /</i>	1			\$450.00	
13	BOOT LID LH TAIL LAMP <i>X 17</i>	1			\$450.00	
14	BOOT LID CENTER CHORME GARNISH <i>? X SUC</i>	1			\$115.00	
15	EMBLEM - CDI <i>ne /</i>	1			\$135.00	
16	REAR MERCEDES LOGO <i>ne /</i>	1			\$45.00	
17	EMBLEM - E 250 <i>ne /</i>	1			\$75.00	
18	REAR RHS FENDER TAIL LAMP <i>sca /</i>	1			\$620.00	
19	REAR LHS FENDER TAIL LAMP <i>X 17</i>	1			\$620.00	
20	EMBLEM - CYCLE CARRIAGE <i>nee /</i>	1			\$80.00	
21	REAR SENSOR <i>ne /</i>	2			\$265.00	
22	REAR BUMPER TOWING CAP COVER <i>mis /</i>	1			\$55.00	
23	REAR BUMPER SPONGE <i>? X SUC</i>	1			\$265.00	
24	REAR BUMPER REINFORCEMENT <i>? X SUC</i>	1			\$750.00	
25	REAR LHS BUMPER BRACKET <i>? X SUC</i>	1			\$68.00	
26	REAR RHS BUMPER BRACKET <i>? X SUC</i>	1			\$68.00	
27						
28	BODY SEALANT <i>nee /</i>	1			40	\$80.00
29	ANTI RUST	1			40	\$80.00
30	REAR NUMBER PLATE WITH HOLDER	1			17 X	\$35.00

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Finalize form

ComfortDelgro Engineering Pte Ltd
45 Pandan Road S (609286)
Tel : 68676919 Fax : 62626950

**Amended
Finalization Form**

Bill To : CHINA TAIPING INS Vehicle No. : SDR84R

Attention : Mr Rasul DOA @ 12.06.2019

A. Spare parts
List Price : \$ 7,937.00
10% Discount / Plus : \$ -793.70
7,143.30

B. Nett Price : \$ _____
_____ Discount / Plus : \$ -

C. Special Nett : \$ 80.00

D. Labour : \$ 970.00

Finalized Total : : \$ 8,193.30

E. Lump Sum (less 20%) : \$ -1,638.66

: \$ 6,554.64

F. Less Excess : \$ _____

Total Amount : : \$ 6,500.00

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm & revert by fax. Thanks

Submitted By / Date : Wong Chee Wei / 29.06.2019

Confirmed By / Date : _____

COMFORTDELGRO ENGINEERING PTE LTD

Appendix A

45 Pandan Road S (609286)

Tel:68676919 Fax: 62626950

Spare Parts

Vehicle No. : SDR84R Submit By : WONG CHEE WEI / CK
 Make & Model : MERCEDES BENZ E 250CGI Year Manufacture : 2013
 Chassis No. : WDD2120472A385432 Engine No. : _____
 Cost / List

Supplementary C.O.R

S/No.	Part Description	Qty	Unit Price	List Price	Disposition by Surveyor
1	L/ LWR BRACKET RR BUMPER <i>cm</i>	1		<i>\$72.00</i>	
2	R/LWR BRACKET RR BUMPER <i>cm</i>	1		<i>\$72.00</i>	
3	UPPER CTR BRACKET <i>cm</i>	1		<i>\$95.00</i>	
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		1			
21		1			
22		1			
23		1			
24		1			
25		1			
26		1			
27		1			
28		1			
29		1			
30		1			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19010972/R1VD3N2

Date: 03/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN6013351913		
Claimant Vehicle No :	SDR84R	Insured Vehicle No :	GY2096X		
Date of Loss:	12/06/2019	Nature of Claim:	TP	Claim No:	SNM19D202762C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDR84R	Engine No:	27186030187090
Make & Model:	MERCEDES-BENZ E250, 2.0 (A)	Chassis No:	WDD2120472A385432
Reg. Date:	13/06/2011 (Man. Year: 2010)	Odometer:	163387 km
Colour:	Grey		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R17	Rear Tyre Size:	245/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,171.70	7,183.30	1,988.40	21.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	1,010.00	370.00	26.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,551.70	8,193.30	2,358.40	22.35
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	10,551.70	6,500.00	4,051.70	38.40
+ GST 7.00/7.00% (S\$)	738.62	455.00	283.62	38.40
Nett Amount (S\$)	11,290.32	6,955.00	4,335.32	38.40

INSPECTION

Date of Assignment: 21/06/2019

Date Inspected: 21/06/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Pandan)
45 Pandan Road
Singapore 609286

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2019)
Parts: 143	MERCEDES-BENZ E250 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDR84R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,550.00 FL	*1,550.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	80.00 FL	*80.00 FL
3	1		*REAR BUMPER CHROME LHS	Necessary	125.00 FL	*125.00 FL
4	1		*REAR BUMPER CHROME CENTER	Necessary	175.00 FL	*175.00 FL
5	1		*REAR BUMPER CHROME LHS	Necessary	128.00 FL	*128.00 FL
6	1		*REAR BUMPER SKIRT	Deformed	485.00 FL	*485.00 FL
7	10		*REAR BUMPER SKIRT CLIPS	Necessary	80.00 FL	*80.00 FL
8	1		*REAR BOOT LID	Bent	2,600.00 FL	*2,600.00 FL
9	1		*REAR BOOT LID HINGE RH	Not Necessary	135.00 FL	*- FL
10	1		*REAR BOOT LID HINGE LH	Not Necessary	135.00 FL	*- FL
11	1		*REAR BOOT LOCK	Not Necessary	270.00 FL	*- FL
12	1		*BOOT LID RH TAIL LAMP	Scratched	450.00 FL	*450.00 FL
13	1		*BOOT LID LH TAIL LAMP	Not Necessary	450.00 FL	*- FL
14	1		*BOOT LID CENTER CHROME GARNISH	Serviceable	115.00 FL	*- FL
15	1		*EMBLEM-CDI	Necessary	135.00 FL	*135.00 FL
16	1		*REAR MERCEDES LOGO	Necessary	45.00 FL	*45.00 FL
17	1		*EMBLEM-E250	Necessary	75.00 FL	*75.00 FL
18	1		*REAR RHS FENDER TAIL LAMP	Scratched	620.00 FL	*620.00 FL
19	1		*REAR LHS FENDER TAIL LAMP	Not Necessary	620.00 FL	*- FL
20	1		*EMBLEM-CYCLE CARRIAGE	Necessary	80.00 FL	*80.00 FL
21	2		*REAR SENSOR	Necessary	265.00 FL	*265.00 FL
22	1		*REAR BUMPER TOWING CAP COVER	Missing	55.00 FL	*55.00 FL
23	1		*REAR BUMPER SPONGE	Serviceable	265.00 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	750.00 FL	*750.00 FL
25	1		*REAR LHS BUMPER BRACKET	Serviceable	68.00 FL	*- FL
26	1		*REAR RHS BUMPER BRACKET	Serviceable	68.00 FL	*- FL
27	1		*L/LWR BRACKET RR BUMPER	Cracked	72.00 FL	*72.00 FL
28	1		*R/LWR BRACKET RR BUMPER	Cracked	72.00 FL	*72.00 FL
29	1		*UPPER CTR BRACKET	Cracked	95.00 FL	*95.00 FL
30	1		*BODY SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,178.00	7,977.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,006.30	793.70
Total Parts (\$\$)	9,171.70	7,183.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI RUST	New	80.00	40.00
2	TO DISMANTLE AND TRANSFER REAR BOOT LID FITTING AND MECHANISM TO NEW BOOT LID	New	120.00	60.00
3	REMOVE AND REPLACE REAR BUMPER,BOOT LID,TAIL LAMP BY REALIGN DAMAGE PARTS WITH PANEL BEATING	New	600.00	450.00
4	SPRAY PAINTING FOR REAR BOOT LID,REAR BUMPER,END PANEL AND SURFACE FOR REAR BOTH QUOTER PANEL	New	500.00	400.00
5	CHECK WIRING FOR REVERSES ENSOR AND TAIL LAMP	New	80.00	60.00
Gross Labour Cost (S\$)			1,380.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >