

ASS. REC. BY:

REF:

08/FC119010974/Kvd3m

Special Instruction:

Summary: Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Henry Kao

of

FEL

Date/Time:

8:20am @ 2/6/19

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SHB9798S

Insured:

SHB3590M

at Workshop m/s

Transcarb

Tel:

62876666

of

No. 2 Amk St - G3

Policy No.:

Claim No.:

019004013MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/06/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9:08am @ 2/6/19

Person Contacted:

Amendin

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Is Initial?
	SHB9798S-CS / MSG19010417 / Kvd3	DOA: 9/6/19
	SHB3590M-C03/AXA/0028129 / R/w2u2y2	DOA: 15/12/2016
24/6/19	Email preli revised to FCS	

ASSIGNMENT

From:

Date:

21/06/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHB 97985

at Workshop m/s

Transcab

of

No. 2 Amk St. 63

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

IDS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 97985

Yr Regn:

07 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c

1995

Colour

m. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

588 227

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 273443

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

18/6/19

D.O.I.

21/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/6/19

11 Rm 817001 (Red 31,703.25, 951)

RECEIVED 24 JUN 2019

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2) 24/6- typist

Days Of Repair:

2

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

3 + RS. SI

Pins

Other:

TOTAL:

350

Report Format:

CWS

Lump Sum / LBS:

1700/-

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004013MFSH

Our ref: CS/FCI19010974/Kvd3

Date : 24/6/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 9798S


We thank for your instruction on 21/6/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/6/2019 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$33,403.25
Revised Estimate Amount	: S\$1,700.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	19-06-2019	Our Ref No. D19004013MFSH
Accident Date	18-06-2019	Claim Type. Third Party
Insured Vehicle	SHB3590M	Third Party Vehicle. SHB9798S
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571333
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 24 June 2019 3:43 PM
To: Veron Chen (LKKAUTO)
Subject: FW: SHB 9798S-DOA:18/6/2019 -- AAD1906-174
Attachments: MARKING.pdf

Hi Veron

We confirmed COR amount \$1,700 (b4 GST).

Will send u the photo when I get it from our workshop.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 24 June, 2019 2:36 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; calvin.er@transcab.com.sg; SUR <sur@lkkauto.com>
Cc: jasminetan@transcab.com.sg
Subject: SHB 9798S-DOA:18/6/2019

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$1700, @2 working days.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 24 June 2019 2:36 PM
To: Ng Wai Yin; calvin.er@transcab.com.sg; SUR
Cc: jasminetan@transcab.com.sg
Subject: SHB 9798S-DOA:18/6/2019
Attachments: MARKING.pdf

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$1700, @2 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 24 June 2019 2:33 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004013MFSH/1, SHB 9798S
Attachments: SHB 9798S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHB 9798S
Date of survey: 21/6/2019
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 21 June 2019 9:07 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004013MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 21 June 2019 8:20 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie

<HenryKao@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19004013MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB97985
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000300
Chassis No.:	VF1ABL15AUC273443
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Jul 2013
First Registration Date:	31 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2021
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	30 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,810.00
COE Rebate Amount:	\$13,701.00
Total Rebate Amount:	\$22,449.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Jun 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 97985**AAD1906-174**

Not Notarized
L1 Reg @ 1700

Vehicle No.:

21 JUN 2019

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB 97985

VF1ABL15AUC273443

RENAULT

LATITUDE

18.6.19

FIRST CAPITAL

31/7/2013

		PART		LIST
1	1	BUMPER COVER REAR	\$	<i>RM</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>RM</i> 768.84 X
3	1	BUMPER BRACKET CTR REAR	\$	<i>RM</i> 113.47 X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>RM</i> 135.97 X
5	1	BUMPER RETAINER RH REAR	\$	<i>RM</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>RM</i> 43.61 X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>RM</i> 135.97 ✓
8	1	BUMPER RETAINER LH REAR	\$	<i>RM</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>RM</i> 43.61 ✓
10	1	BUMPER BEAM REAR	\$	<i>RM</i> 777.52
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>RM</i> 225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>RM</i> 225.95
13	1	OUTER PANEL REAR (End Panel)	\$	<i>RM</i> 1,471.77
14	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>RM</i> 404.56
15	1	TAILLAMP RH	\$	<i>RM</i> 552.55
16	1	TAILLAMP PANEL RH	\$	<i>RM</i> 986.70
17	1	TAILLAMP LH	\$	<i>RM</i> 552.55
18	1	TAILLAMP PANEL LH	\$	<i>RM</i> 986.70
19	1	BOOT REAR	\$	<i>RM</i> 2,872.68 } X
20	1	BOOT FINISHER	\$	<i>RM</i> 470.06
21	1	BOOT WHEATERSTRIP	\$	<i>RM</i> 323.05
22	1	BOOT REFLECTOR LAMP LH	\$	<i>RM</i> 493.35
23	1	BOOT REFLECTOR LAMP RH	\$	<i>RM</i> 493.35
24	1	BOOT BADGE 'RENAULT'	\$	<i>RM</i> 225.36
25	1	BOOT BADGE	\$	<i>RM</i> 225.36
26	1	BOOT STRUT LH	\$	<i>RM</i> 276.08
27	1	BOOT STRUT RH	\$	<i>RM</i> 276.08
28	1	BOOT HINGE LH	\$	<i>RM</i> 367.84
29	1	BOOT HINGE RH	\$	<i>RM</i> 367.84

Trans-cab Auto Services Pte Ltd

AAD1906-174

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9798S

30	1	BOOT INNER TRIM	\$	586.45	}	X
31	1	BOOT SWITCH	\$	168.13		
32	1	BOOT LOCK	\$	202.67		
33	1	BOOT LOCK CATCH	\$	74.40		
34	1	FENDER PANEL INNER TRIM REAR LH	\$	671.45		
35	1	FENDER PANEL REAR LH	\$	3,299.13		
36	1	WHEELARCH REAR LH	\$	543.47	}	
37	1	FUEL FLAP	\$	343.57		
TOTAL			\$	20,904.50	48	
10%			\$	2,090.45		
			\$	18,814.05		

Special Nett

1	1SET	PARKING AID	\$	700.00	400cm	}	X
2	1SET	REAR BUMPER CLIP	\$	66.00			
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00			
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00			
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00			
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00			
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00			
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00			
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00			
10	1	BOOT STICKER "Trans-cab"	\$	30.00			
11	1	BOOT STICKER "6555-3333"	\$	30.00			
12	2	REAR WINDSCREEN SEALANT	\$	80.00			
13	1	WINDSCREEN MOULDING	\$	100.00			
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00			
15	1	BOOT INNER TRIM CLIP	\$	45.00			
16	1	FENDER INNER TRIM CLIP LH	\$	28.00			
17	1	TAILLAMP CLIP RH	\$	5.00			
18	1	TAILLAMP CLIP LH	\$	5.00			
19	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00			
20	1SET	BOOT FINISHER CLIP	\$	24.20			
21	1	REAR LEFT TYRE	\$	300.00			
22	1	REAR LEFT TYRE RIM	\$	380.00			
TOTAL			\$	2,109.20			

TOTAL PARTS \$ 20,923.25

Trans-cab Auto Services Pte Ltd**AAD1906-174**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9798S**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	200/
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	220/
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	~ 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1906-174**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9798S

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>bol</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>bol</i>
TOTAL	\$	12,480.00
Over All Total	\$	33,403.25 <i>23</i>

LUMP SUM (REPAIR DAY)~~15 DAYS~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010974/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3590M	Veh. Inspected	SHB 9798S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004013MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	21/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC273443	Colour	METALLIC WHITE / RED	
Odometer	588227	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/06/2019	Inspection Date	21/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9798S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	DISTORTED	135.97	135.97
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SCRATCHED	43.61	43.61
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-

Report Ref No. CS/FCI19010974/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
1	FENDER PANEL INNER TRIM REAR LH	TO REPAIR SEE LABOUR	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FUEL FLAP	SERVICEABLE	343.57	-
	LESS 10% DISCOUNT		-2,090.45	-128.80
			18,814.03	1,159.24
SPECIAL NETT ITEMS				
1	SET PARKING AID (SN)	SHORTED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-

Report Ref No. CS/FCI19010974/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	REAR LEFT TYRE (SN)	SERVICEABLE	300.00	-
1	REAR LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
			2,109.20	499.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR,BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,OUTER PANEL REAR (END PANEL),TAILLAMP PANEL RH,TAILLAMP PANEL LH,BOOT REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,BOOT LOCK CATCH,FENDER PANEL INNER TRIM REAR LH AND FENDER PANEL REAR LH.		4,500.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	220.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19010974/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
			12,480.00	490.00
GRAND TOTAL			33,403.23	2,148.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CS/FCI19010974/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.