



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLQ 2132 H

Parts	(a) Cost / List Price Items	\$	<u>3,492.95</u>
	Plus/Less <u>25%</u>	\$	<u>873.24</u>
	Total of Cost / List	\$	<u><u>2,619.71</u></u>
	(b) Nett Price Items		_____
	Less _____		_____
	Total of Nett Item		_____
	(c) Special Nett Items		_____
Total Parts Cost		\$	<u><u>2,619.71</u></u>
Labour		\$	<u><u>2,120.00</u></u>
Total		\$	<u><u>4,739.71</u></u>

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLQ 2132 H
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU903561682

Submit By : SERENCE
Year Manufacture : 2017
Engine No. : 2ZRS056884

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper	1	\$497.50		
2	Rear bumper clip	10	\$40.00		
3	Rear bumper side retainer LH	1	\$112.70		
4	Rear bumper side retainer RH	1	\$112.70		
5	Rear bumper reinforcement	1	\$398.90		
6	Rear bumper lower garnish centre	1	\$582.60		
7	Rear bumper lower garnish RH	1	\$149.70		
8	Rear bumper tow cover	1	\$31.70		
9	Rear bumper under cover	1	\$355.20		
10	Rear bumper under cover RH	1	\$187.60		
11	Rear bumper under cover clip	4	\$14.00		
12	Tail lamp RH - UPPER	1	\$498.75		
13	Tail lamp RH - LOWER	1	\$511.60		
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLQ 2132 H Submit By : SERENCE
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	
3	To tuff coat.	\$50.00	
4	TO Check wiring	\$50.00	
5	To remove & refit reverse sensor	\$150.00	
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2019 13:40
Date Of Accident	01/06/2019 14:25
Exact Location Of Accident	ALONG SIMS AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ2132H
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	NA

Driver

Name of Driver	ONG KIAN SENG
NRIC No	S1796314G
Date Of Birth	13/09/1967
Occupation	OUTDOOR
Date Of Driving Pass	20/04/1989
Driving Experience	30 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97350167
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE DATE AND TIME MENTIONED, I WAS DRIVING ALONG THE SAID MENTIONED ROAD AND MADE A STOP DUE TO CONGESTION. WHEN MY VEHICLE WAS STATIONARY, IT WAS HIT FROM THE REAR BY VEHICLE B. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ2349L
Vehicle Make/Model/Colour	HYUNDAI ELANTRA AD 1.6 GLS AT
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	TAY WEI HAN
NRIC/Passport Number	S6811596E
Contact Number	98254412
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED, I WAS DRIVING ALONG THE SAID MENTIONED ROAD AND MADE A STOP DUE TO CONGESTION. WHEN MY VEHICLE WAS STATIONARY, IT WAS HIT FROM THE REAR BY VEHICLE B. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

3 June 2019 at 2:57 AM

Date/Time:

3 June 2019 at 2:57 PM