



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLQ 2132 H Submit By : SERENCE
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

| S/No | Labour Description | Estimated Price | Adjusted Price |
|------|---|-----------------|----------------|
| 1 | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT) | \$800.00 | 2000 |
| 2 | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT) | \$800.00 | 3000 |
| 3 | To tuff coat. <i>nn</i> | \$50.00 | X |
| 4 | TO Check wiring | \$50.00 | 150 |
| 5 | To remove & refit reverse sensor | \$150.00 | 50 |
| 6 | To conduct water leakage tests to ensure proper air and sealing <i>nn</i> | \$120.00 | X |
| 7 | To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i> | \$150.00 | X |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.