

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

PUNGGOL EAST CAR RENTAL
663C PUNGGOL DRIVE
#12-232
S 823663

TP Erya
Khanchan.

Date :25.06.2019
Vehicle No :SGP 9706 X
Make/Model :HYUNDAI AVANTE
Accident date :14.05.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front LH door <i>Repair</i>	1	\$ 1141.8 <i>x</i>
2	Front LH door glass	1	\$ 253.7 <i>x</i>
3	Front LH door glass outer moulding	1	\$ 57.2 <i>x</i>
4	Front LH door outer handle	1	\$ 60.5 <i>x</i>
5	Front LH door side mirror	1	\$
6	Front LH door side mirror cover	1	\$ 471.5 <i>x</i>
7	Front LH door side mirror housing	1	\$
8	Rear LH door <i>Dented</i>	1	\$ 1031.8 <i>✓</i>
9	Rear LH door glass	1	\$ 231.7 <i>x</i>
10	Rear LH door glass outer moulding	1	\$ 68.2 <i>x</i>
11	Rear LH door outer handle	1	\$ 60.5 <i>x</i>
12	Rear LH door top hinge	1	\$ 46.2 <i>x</i>
13	Rear LH door lower hinge	1	\$ 46.2 <i>x</i>
14	Rear LH door stopper	1	\$ 19.8 <i>x</i>
15	Rear LH door inner lock	1	\$ 262.7 <i>x</i>
			\$ 3751.8
			\$ 750.4
			\$ 3001.4

Less 20% Disc

Total

Labour Cost

- 1 Remove & reinstall door *glass* *fitting*
- 2 Remove ,replace & repair consistent to the accident
- 3 Respray painting
- 4 Tuff kote

\$ 200 *100*
\$ 1000 *300*
\$ 1000 *500*
\$ 100 *x*
Total \$ 2300

Grand Total

\$ 5301.4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

ature:

total: 1880.44

N/S : 1.5K

03 Days.

1.5K
03 Days