

Surveyor: Marcus

ASSIGNMENT (Office)

rws

From (Person): Mayerof PCIDate/Time: 21/6/19 @ 3:18pm

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 7061R

Insured:

SHD 4850X

at Workshop m/s

Yew Tee Automobile

Tel:

6256 2081 / 6702 3113

of

39 woodlands close #01-12

Policy No:

Claim No:

D1900 3949MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

24/6/19

H.O.D. Endorsement:

Date/Time:

3:44pm @ 21/6/19

Person Contacted:

Shu YiVehicle IN/OUT

Date/Time

Action/Instruction

Echmote

✓

Insp: 25 Kaki Bukit Rd 4 # 01-61

SKF 7061R - XsynergySHD 4850X-C03/C11/8014353K/cu3n2DOA: 4/8/201825/6 @ 3:44pm Rensedpreli advise via email

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From:

Date: 24/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKF 7061R
at Workshop m/s Yew Tee Automobile
of 25 Leeki Bukit Rd 4 #01-61

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

486.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKF 7061R

Yr Regn:

10 / 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Nissan Teana

2.0

c.c

1997

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

234559

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1B04J3220000156

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

14/6/19

D.O.I.

24/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

coe 15-10-2028 17430042

27/6/19 1/5 #4700 Confund with May (Red: 4408; 48%)

MV 450007-

LTA: 300421-

NV: 14,9581-

RECEIVED 20 JUN 2019

Date/Time, File Pass to?



: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

3 x RS: SI

Photos:

Others:

TOTAL

170

50

50

67

337

Report Format:

TP

Lump Sum / L.R. / S

47001



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003949MFSH

Date: 25/06/2019

Our Ref: CS/FCI19011012/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKE 7061R

Please be informed that we had conducted the inspection of the abovementioned vehicle 24/06/2019 at the premises of M/s Yew Tee Automobile have the following to report: -

Workshop Estimate Amount	: S\$ <u>9,108.00</u>
Revised Estimate Amount	: S\$ <u>5,207.31</u>
"Check" Items Amount	: S\$ <u>542.43</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the Front n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 25 June 2019 3:44 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003949MFSH/1
Attachments: PRELI ADVISED SKF 7061R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKF 7061R**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 21 June 2019 3:50 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003949MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 24/06/2019.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 21 June 2019 3:17 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003949MFSH/1

MOTOR SURVEY ASSIGNMENT

Date	17-06-2019	Our Ref No. D19003949MFSH
Accident Date	14-06-2019	Claim Type. Third Party
Insured Vehicle	SHD4850X	Third Party Vehicle. SKF7061R
Survey Location	39 WOODLANDS CLOSE, #01-12 MEGA@WOODLANDS	
Contact Person.	SHUYI	
Contact No.	62562081/ 0	Fax No. 67604895
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEW TEE AUTOMOBILE TECH PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

NEW CAR DISCOUNTS & OFFERS

BEST DEAL DAILY!

VIEW ALL PROMOTIONS

Teana

Price Range

Depreciation

> 10 year

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Millenia Motor » Nissan Teana 2.0A (COE till 01/2024)

Nissan Teana 2.0A (COE till 01/2024)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$35,000

Depreciation \$7,600 /yr

Reg Date 25-Feb-2009
(4yrs 7mths 7days COE left)

Mileage N.A.

Manufactured 2008

Road Tax \$1,210 /yr

Transmission Auto

Dereg Value \$14,440 as of today (change)

OMV \$31,129

COE \$15,668

ARF \$31,129

Engine Cap 1,997 cc

Power 100.0 kW (134 bhp)

Curb Weight 1,450 kg

No. of Owners 2

Type of Vehicle Luxury Sedan

Features

Powerful And Fuel Efficiency 2.0L DOHC Engine, Keyless Entry, Push Start, Dual Zone Climate Aircon Control, Rear Aircon. View specs of the Nissan Cefiro (2003-2008)

Accessories

Factory Fitted Audio, Leather Interior, Driver Electric Seat, In Car Recorded, Remote Boot Release, Retractable Side Mirror, Parking Sensor.

Description

Luxury Sedan, High Omv \$31k. For This Good Working Condition Till Coe End Or Optional Renew 5 Years/10 Years Coe. Very Good Condition. 10 Years Coe Selling At \$53,800.

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Shortlist

Report Error

Compare

More Actions

Add note

Seller Information

Company

Millenia Motor

» dealer's pricelist
» 12 vehs sold | 6 vehs available

Address

160 Sin Ming Drive #03-15
Search cars nearby this location

Location

Sin Ming AutoCity

Contact Person(s)

Mike

93389606

Posted on: 12-Jun-2019 | Last Updated on: 20-Jun-2019

Upfront Payment
Compare

» more Financial info

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	8530E

Vehicle Details

Vehicle No.:	SKF7061R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jun 2019
Vehicle Make:	NISSAN
Vehicle Model:	TEANA 2.0L CVT ABS D/AIRBAG 2WD
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	MR20688010A
Chassis No.:	JN1BDUJ32Z0000556
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,317.00
Original Registration Date:	16 Oct 2008
First Registration Date:	16 Oct 2008
Transfer Count:	2
Actual ARF Paid:	\$26,317.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	15 Oct 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$32,279.00
COE Rebate Amount:	\$30,042.00
Total Rebate Amount:	\$30,042.00

The information contained herein is correct as at 24 Jun 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : FIRST CAPITAL INSURANCE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTKB/TP/1906/010
Policy No:	5055378147-06	Date of Loss:	14/06/2019
Vehicle Reg. No.:	SKF7061R	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SHD4850X
Any Injuries?	no	Contact No:	
Insured/Claimant:	SOO KIM HONG	Driver:	LAI KIEN HUA

Make/Model:	Nissan, Teana 2.0 - JN1BDUJ32Z	Vehicle Reg. Date:	16 Oct 2008
Vehicle Colour:		Engine Number:	
Chassis No:	JN1BDUJ32Z0000556	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION-MAJOR/MINOR RD
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	6,333.00
Miscellaneous Items	520.00
Labour	1,030.00
Paintwork Labour	1,145.00
Towing	80.00
Gross Total(S\$):	9,108.00
GST 7.00%(S\$):	637.56
Nett Amount(S\$):	9,745.56

This claim is handled by: may chai

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Allowed
2/5 #4700
24/6/19
Wheeler Agency
Shy.

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BONNET <i>20/500</i>	0.00	1,025.40	-30.00	717.78
2	1	FRONT BONNET HINGE RH <i>1</i>	0.00	61.70	-10.00	55.53
3	1	FRONT BONNET HINGE LH <i>1</i>	0.00	61.70	-10.00	55.53
4	1	FRONT GRILLE <i>one</i>	0.00	562.00	-10.00	505.80
5	1	FRONT GRILLE EMBLEM <i>one</i>	0.00	72.00	-10.00	64.80
6	1	FRONT BUMPER <i>D.S</i>	0.00	649.00	-30.00	454.30
7	1	FRONT BUMPER BRACKET <i>11</i>	0.00	47.70	-10.00	42.93
8	1	FRONT BUMPER LOWER COVER <i>11</i>	0.00	107.50	-10.00	96.75
9	1	FRONT BUMPER SIDE RETAINER <i>one</i>	0.00	53.40	-10.00	48.06
10	1	FRONT BUMPER FOG LAMP LH <i>one</i>	0.00	385.50	-10.00	346.95
11	1	FRONT BUMPER FOG LAMP COVER LH <i>one</i>	0.00	321.60	-10.00	289.44
12	1	FRONT BUMPER CHROME LH <i>3/20</i>	0.00	121.20	-10.00	109.08
13	1	FRONT BUMPER INNER SPONGE <i>18</i>	0.00	291.60	-10.00	262.44
14	1	FRONT REINFORCEMENT <i>27</i>	0.00	364.10	-10.00	327.69
15	1	FRONT FENDER LH <i>300</i>	0.00	594.00	-30.00	415.80
16	1	FRONT FENDER INNER SHIELD LH <i>20/700</i>	0.00	99.40	-10.00	89.46
17	1	FRONT HEADLAMP LH <i>one</i>	0.00	586.10	-30.00	410.27
18	1	FRONT HEADLAMP PANEL <i>1</i>	0.00	288.40	-10.00	259.56
19	1	AIR CON CONDENSER <i>17</i>	0.00	517.90	-30.00	362.53
20	1	AIR GUIDE LH <i>1000</i>	0.00	40.00	-10.00	36.00
21	1	RADIATOR <i>17</i>	0.00	834.80	-30.00	584.36
22	1	SUPPORT PANEL <i>one</i>	0.00	746.10	-10.00	671.49
23	1	FRONT BONNET RUBBER <i>one</i>	0.00	85.50	-10.00	76.95
24	1	FRONT HEADLAMP HID BALLAST LH <i>17</i>	0.00	55.00	-10.00	49.50

Total Parts (\$\$) 6,333.00

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIP <i>one</i>	0.00	35.00	0.00	35.00
2	1	FRONT FENDER INNER SHIELD CLIP <i>one</i>	0.00	35.00	0.00	35.00
3	1	FRONT HEADLAMP HID BULB LH <i>one</i>	0.00	450.00	0.00	450.00

Sub Total (\$\$) 520.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,000.00	1,000.00	0.00	1,000.00
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00

Gross Labour Cost (\$\$) 1,030.00

P-2854.50 P-2436.20
 302 102
1998.15 2192.58

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	200.00	200.00	0.00	200.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	900.00	900.00	0.00	900.00

Gross Labour Cost (S\$) 1,145.00

< END OF ESTIMATES >

9028

L - 1998.15
 N - 2192.58
 S.N - 70.00
 1.6m - 1620.00

 4880.73
 4700



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19011012/Utd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4850X	Veh. Inspected	SKF 7061R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003949MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	21/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN TEANA 2.0 (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1BDUJ32Z0000556	Colour	GREY	
Odometer	234559	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2019	Inspection Date	24/06/2019	
Survey held at	BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUK			
Repairer	YEW TEE AUTOMOBILE TECH PL (HQ)			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 7061R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	DENTED / BUCKLED	1,025.40	1,025.40
1	FRONT BUMPER	DISTORTED	649.00	649.00
1	FRONT FENDER LH	BUCKLED	594.00	594.00
1	FRONT HEADLAMP LH	CRACKED	586.10	586.10
1	AIR CON CONDENSER	NOT NECESSARY	517.90	-
1	RADIATOR	NOT NECESSARY	834.80	-
	LESS 30% DISCOUNT		-1,262.16	-856.35
			2,945.04	1,998.15
NETT ITEMS				
1	FRONT BONNET HINGE RH (N)	TO REPAIR SEE LABOUR	61.70	-
1	FRONT BONNET HINGE LH (N)	TO REPAIR SEE LABOUR	61.70	-
1	FRONT GRILLE (N)	CRACKED	562.00	520.70
1	FRONT GRILLE EMBLEM (N)	NECESSARY	72.00	45.00
1	FRONT BUMPER BRACKET (N)	NOT NECESSARY	47.70	-
1	FRONT BUMPER LOWER COVER (N)	NOT NECESSARY	107.50	-
1	FRONT BUMPER SIDE RETAINER (N)	CRACKED	53.40	29.00
1	FRONT BUMPER FOG LAMP LH (N)	CRACKED	385.50	320.70
1	FRONT BUMPER FOG LAMP COVER LH (N)	DISTORTED	321.60	105.00
1	FRONT BUMPER CHROME LH (N)	BROKEN	121.20	121.20
1	FRONT BUMPER INNER SPONGE (N)	NO SUCH PARTS	291.60	-
1	FRONT REINFORCEMENT (N)	DENTED	364.10	364.10
1	FRONT FENDER INNER SHIELD LH (N)	DEFORMED / TORN	99.40	99.40
1	FRONT HEADLAMP PANEL (N)	TO REPAIR SEE LABOUR	288.40	-
1	AIR GUIDE LH (N)	TORN	40.00	40.00
1	SUPPORT PANEL (N)	CRACKED	746.10	746.10
1	FRONT BONNET RUBBER (N)	NECESSARY	85.50	45.00
1	FRONT HEADLAMP HID BALLAST LH (N)	NOT NECESSARY	55.00	-

Report Ref No. CS/FCI19011012/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-376.44	-243.62
			3,387.96	2,192.58
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	35.00	35.00
1	FRONT HEADLAMP HID BULB LH (SN)	NOT NECESSARY	450.00	-
			520.00	70.00
	LABOUR			
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGE RH,FRONT BONNET HINGE LH AND FRONT HEADLAMP PANEL.		1,000.00	650.00
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		30.00	30.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		200.00	60.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	NOT NECESSARY	45.00	-
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		900.00	880.00
			2,175.00	1,620.00
	GRAND TOTAL		9,028.00	5,880.73
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,700.00

Report Ref No. CS/FCI19011012/Utd3n2

MARKET VALUE: \$45,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$30,042.00=NETT VALUE: \$14,958.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.