

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0778/2019/DY/GW
Date	:	20-Jun-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Dr. Wong See Ah Shera
Address	:	42 Queen's Road
	:	Singapore 266753
Telephone	:	(HP)+65 98301256
Type of Claim	:	Own Damage Claims
Policy No.	:	2100510342-01
Vehicle No	:	SKL 438 C
Model Code	:	Audi A5 SportsBack 2.0 TFSI
Model / Year	:	30/6/2017
Engine No	:	CVK 034574
Chassis No	:	WAUZZZF51HA033662
Mileage	:	25972 KM
Date In	:	20-Jun-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Jun-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKL 0438 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00 ✓	
2	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N \$	400.00 ✓	
3	To dismantle and renew front bumper, rhs front fender, rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	2,400.00 1250	1000
4	To respray front bumper, rhs front fender and rhs wing mirror cover.	\$	2,500.00 1250	550 x 2 = 1100 Mirror : 150
5	To renew rhs front rim and carry out wheel alignment . Inspect rhs front suspension for further damages.	S/N \$	280.00 ✓	
6	To carry out diagnostic check.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	<u>\$ 6,252.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKL 0483 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>reld</i>	\$ 2,073.00	✓
2	FRONT BUMPER FIXING PARTS	\$ 368.00	+
3	FRONT BUMPER CLOSING ELEMENT	\$ 207.00	+
4	FRONT BUMPER AIR GUIDE	\$ 56.00	+
5	FRONT BUMPER AIR GUIDE GRILLE	\$ 431.00	+
6	FRONT BUMPER GUIDE SECTION-RH ?	\$ 33.00	?
7	FRONT BUMPER SEAL RING <i>re</i>	\$ 12.00	+
8	FRONT FENDER-RH <i>Dented</i>	\$ 968.00	✓
9	FRONT FENDER ATTACHMENT PART-RH ?	\$ 48.00	?
10	FRONT FENDER CLOSING ELEMENT-RH ?	\$ 68.00	?
11	FRONT FENDER BRACKET-RH ?	\$ 32.00	?
12	FRONT FENDER CENTRE BRACKET-RH ?	\$ 32.00	?
13	FRONT FENDER BRACE-RH ?	\$ 107.00	?
14	FRONT FENDER DEFORMATION BRACKET-RH <i>re</i>	\$ 45.00	+
15	FRONT WHEEL HOUSING LINER-RH <i>re</i>	\$ 82.00	+
16	FRONT WHEEL SPOILER <i>re</i>	TBC	+
17	FRONT FENDER END PLATE-RH <i>re</i>	\$ 33.00	+
18	FRONT STONE CHIP GUARD-RH <i>re</i>	\$ 46.00	✓
19	FRONT FENDER TRIM BRACKET-RH <i>re</i>	\$ 22.00	+
20	FRONT FENDER TRIM -RH <i>re</i>	\$ 145.00	✓
SUB TOTAL SPARE PARTS CHARGES		\$ 4,808.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKL 0483 C

S/N	Parts Description		Damaged Parts S/Nett
21	FRONT FENDER LEDGE COVER-RH <i>green</i>	\$	32.00 ✓
22	FRONT FENDER TOP LEDGE COVER-RH	\$	14.00 ✓
23	LED HEADLIGHT-RH <i>new</i>	\$	7,204.00 ✓
24	FRONT ALUMINIUM RIM-RH <i>new</i>	\$	943.00 ✓
25	RUBBER VALVE <i>new</i>	4 \$	13.00 ✓
26	FRONT EXTERIOR MIRROR MOUNTING-RH <i>new</i>	\$	999.00 ✓
27	FRONT MIRROR CAP-RH <i>green</i>	\$	220.00 +
28	FRONT MIRROR GLASS-RH	\$	1,553.00 +
29	SUNDRIES ?	\$	300.00 ?
TOTAL SPARE PARTS CHARGES		\$	16,086.00
TOTAL LABOUR CHARGES		\$	6,252.00
GRAND TOTAL		\$	22,338.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 21/06/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 hrs.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant