

INS. CASE OWNER:

CC 4, FWD 190 11054, U *plaza*

LKK:
IDAC:

Surveyor: Maricus

DOI: ASSIGNMENT
25/6/19

Date / Time: 21/6/2019
Registered in Merimen: 24/6/2019

Pre-assign / CCU / FTE



Insured Vehicle No: SKX 8106 U
Name of Insured: Leah Gony Sm
Insured Tel No: _____ HP: _____
Excess Sec II :SS _____ D.O.A: 20/6/2019

Claim No. : _____
Policy No. : _____
Make / Model : _____
Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____
If NO, Driver Name / Age: _____
Driver Tel No. : _____ (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability : _____ % Final ? Yes / No

SBW 7280S



INSRS: _____
WSP: Hup motor
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR: <input checked="" type="checkbox"/>	
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS	days) Reduction:	% Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>29/7/19</u>	Confirm with: <u>David</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No. : <u>27</u>	If NO or B 28, Ass. Lia :
Repair Cost:	SS <u>4500.00</u>		
Loss of Rental (LOR):	SS <u>700.00</u>	(<u>7</u> days) <u>> 1100.00</u>	
Loss of Use (LOU):	SS <u>-</u>	(<u>5</u> x days)	
Loss of Income (LOI):	SS <u>-</u>	(<u>5</u> x days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	SS <u>2.00</u>		
Medical:	SS <u>-</u>		
Disbursement:	SS <u>-</u>	(e.g. Tow/ Independent)	
Legal Cost	SS <u>-</u>		
Total:	SS <u>5202.00</u>	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS <u>5202.00</u>	Name 1: <u>Hup Motor Trading & Service</u>	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2953/06/19

Your Ref:

Date: 21st JUNE 2019

MR CHAN KHOON MENG
BLK 401, #05-08
ADMIRALTY LINK, S (750401)

u/s 4500

25/6/19
Whip W. Alvin
u/s \$4500
not Alvin
u/s \$4500
6dy.

Estimate cost of repair to TOYOTA COROLLA 1.6 (M) Saloon - SBW 7280 S

1 pc boot lid		<i>DD/200</i>	\$ 768.90	✓
1 pc boot lid 'TOYOTA' emblem		<i>ru</i>	34.80	✓
1 pc boot lid 'GLI' emblem		<i>ru</i>	40.50	✓
1 pc boot lid logo emblem		<i>ru</i>	37.80	✓
1 pc boot lid reflector		<i>one</i>	402.90	✓
1 pc boot lid lock		<i>twi</i>	72.60	✓
1 pc boot lid lock stricker		<i>11</i>	24.20	X
2 pcs boot lid o/s & n/s hinge	⊕ \$	<i>11</i>	76.80 153.60	X
1 pc boot lid weatherstrip		<i>twi</i>	157.10	✓
2 pcs o/s & n/s tail lamp assy	⊕ \$	<i>one</i>	305.60 611.20	✓
4 pcs o/s & n/s tail lamp clips & stopper	⊕ \$	<i>11</i>	4.20 16.80	X
2 pcs o/s & n/s apron panel	⊕ \$	<i>1581</i>	48.50 97.00	1PC
8 pcs o/s & n/s apron panel rivets	⊕ \$	<i>ru</i>	4.50 36.00	✓
1 pc rear bumper		<i>D-5</i>	384.50	✓
10 pcs rear bumper clips	⊕ \$	<i>ru</i>	3.80 38.00	✓
1 pc rear bumper beam		<i>301</i>	95.10	2
2 pcs rear bumper o/s & n/s stay	⊕ \$	<i>11</i>	34.30 68.60	X
2 pcs rear bumper o/s & n/s side retainer	⊕ \$	<i>301</i>	14.80 29.60	✓
4 pcs rear bumper top screw nut	⊕ \$	<i>ru</i>	3.80 15.20	✓
2 pcs rear bumper o/s & n/s side bracket clips	⊕ \$	<i>11</i>	4.80 9.60	X
2 pcs rear o/s & n/s licence lamp assy	⊕ \$	<i>11</i>	52.10 104.20	X
1 pc rear number plate bracket holder		<i>301</i>	42.60	✓
1 pc rear number plate		<i>one</i>	60.00	20 S. ✓
1 pc rear end panel		<i>301</i>	466.00	✓
1 pc rear end panel top garnish		<i>21/11</i>	66.80	✓
5 pcs rear end panel top garnish clips	⊕ \$	<i>11</i>	3.90 19.50	X
1 pc rear spare tyre cover board		<i>301</i>	206.60	✓
2 pcs o/s & n/s tail lamp panel	⊕ \$	<i>n/s beat</i>	199.60 399.20	1PC
1 pc rear floor board panel		<i>2</i>	702.90	X
1 pc rear floor board panel insulator		<i>11</i>	302.70	X
2 pcs rear o/s & n/s fender	⊕ \$	<i>2</i>	846.30 1,692.60	X
16 pcs rear o/s & n/s tender inner shield clips	⊕ \$	<i>11</i>	3.80 60.80	X
2 pcs rear o/s & n/s wheel mudflap	⊕ \$	<i>n/s mis</i>	32.30 64.60	1PC
1 pc rear exhaust muffler tail pipe		<i>2</i>	472.60	X
2 pcs rear exhaust muffler o/s & n/s mounting	⊕ \$	<i>11</i>	40.30 80.60	X
			\$ 7,835.70	3786.6
1 set rear reverse camera		<i>200 S. ✓</i>		
		Less 25%	\$ 1,958.93	2839.95
			\$ 5,876.77	

To wiring check up for affected wiring system.

40.00 *30*

\$ 5,916.77

Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 37809100W

Our Ref: TF 2953/06/19 Your Ref: _____ Date: 21st June 2019

MR CHAN KHOON MENG.,

Balance B/P... \$ 5,916.77

To remove & refix rear cushion seat, carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts.	150.00	so
To remove & refix fuel tank, hose, pipe & necessary parts.	17 150.00	X
To jack, straighten & knocking out rear exhaust muffler, tail pipe & necessary parts.	17 150.00	X
To respray Tuff-Kote on all affected accident parts.	150.00	60
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear fender & necessary parts, to weld, renew & align above parts.	1,500.00	1100
To putty & respray painting on all affected accident parts.	1,600.00	1200
	<u>\$ 9,616.77</u>	
	=====	

Dollars : Nine Thousand Six Hundred Sixteen And Cents Seventy Seven Only,

HUP MOTOR TRADING & SERVICE



L&S Auto Care (Singapore) Pte Ltd The following work is being carried out: • Body repair/painting • To inspect and rectify any necessary • Part replacement • This work is being carried out on a "Provisional" basis • All work is subject to approval • Subject to final approval from insurance company
Acknowledged by Receiver Signature: _____ Date: _____

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SBW7280S
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	COROLLA 1.6M
Chassis No. :	AE1013041030
Propellant :	Petrol
Engine No. :	4AB226835
Engine Capacity :	1587 cc
Maximum Power Output :	-
Maximum Laden Weight :	-
Unladen Weight :	-
Year Of Manufacture :	1992
Original Registration Date :	12 Feb 1993
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
PQP Paid :	\$25,525.00
COE Expiry Date :	31 Mar 2029
Road Tax Expiry Date :	31 Oct 2019
Inspection Due Date :	31 Jan 2020
Intended Transfer Date :	20 Jun 2019
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

500+ dealers competed to buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR



Advanced Search

Corolla Price Range Depreciation > 10 year(s) Vehicle Type Submit

Home > Used Cars > Corsica Trading > Toyota Corolla 1.6A (COE till 03/2029)

Toyota Corolla 1.6A (COE till 03/2029)

- Overview Financial Accessories Similar Research Photos Map

Price	\$34,800	Reg Date	08-Jan-1992 (9yrs 9mths 6days COE left)
Depreciation	\$3,560 /yr	Manufactured	1991
Mileage	N.A.	Transmission	Auto
Road Tax	\$1,104 /yr	OMV	\$16,887
Dereg Value	\$24,945 as of today (change)	ARF	\$25,331
COE	\$25,525	No. of Owners	More than 6
Engine Cap	1,587 cc		
Curb Weight	N.A.		
Type of Vehicle	Mid-Sized Sedan		



- Shortlist Compare Add note Report Error More Actions

Description
28 Years Old Corolla 1.6 Auto. Still In Excellence Engine Working Condition And New Paint Work And 4 Pcs New Engine Mounting. With 28 Years Old Number No Repairs Required.

Category
COE Car

Status
Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started

Posted on: 23-Jun-2019 | Last Updated on: 23-Jun-2019

> more Financial info

Upfront Payment		
Transfer Fee	\$25	Maximum 30% Loan Based on 3.25% interest rate
Down Payment	\$10,440 (change)	
1st Instalment	\$366	

Compare

Seller Information

Company	Corsica Trading	
	• dealer's pricelist	
	• 22 vens sold 9 vens available	
Address	1 Bukit Batok Crescent #02-61	
	Search cars nearby this location	
Location	WCEGA Plaza	
Office No	67775005	
Contact Person(s)	Woo Kok Wah	900866
	Kelvin Goh	967866

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 6226E

Vehicle Details

Vehicle No.: SBW7280S
 Vehicle to be Exported: No
 Intended Deregistration Date: 25 Jun 2019
 Vehicle Make: TOYOTA
 Vehicle Model: COROLLA 1.6M
 Primary Colour: Grey
 Manufacturing Year: 1992
 Engine No.: 4AB226835
 Chassis No.: AE1013041030
 Maximum Power Output: -
 Open Market Value: \$16,163.00
 Original Registration Date: 12 Feb 1993
 First Registration Date: 12 Feb 1993
 Transfer Count: 4
 Actual ARF Paid: \$24,245.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2029
 COE Category: A - Car (1600cc & below)
 COE Period(Years): 10
 PQP Paid: \$25,525.00
 COE Rebate Amount: \$24,928.00
Total Rebate Amount: \$24,928.00

The information contained herein is correct as at 25 Jun 2019

OK

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	24 Jun 2019 11:44	Cim Dtl Modified	Claimant's Name: -> CHAN KHOON MENG. Claimant's ID: -> 57046226E.	[A] HOW MEI KWAN
2	24 Jun 2019 11:44	Cim Veh Model Changed	(201021) TOYOTA COROLLA 1.6 (M).	[A] HOW MEI KWAN
3	24 Jun 2019 11:44	Cim Created	Reg No: SBW72805. Acct Date: 2019/06/20. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: Hup Motor Trading & Service (HQ)	[A] HOW MEI KWAN
4	24 Jun 2019 11:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ);; RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : RT Appraisal Pte Ltd.	[A] HOW MEI KWAN
5	24 Jun 2019 11:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/03	[A] HOW MEI KWAN
6	24 Jun 2019 11:44	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	24 Jun 2019 11:44	Label Added	(20005):Direct Settlement .	[A] HOW MEI KWAN
8	24 Jun 2019 11:44	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
9	24 Jun 2019 18:01	Cim Registration Modified	Pol No:->PNPV2016-00000666-02.	[I] Eileen Bay
10	24 Jun 2019 18:04	Cim Registration Modified	Acct Time:08:00:00->07:00:00.	[I] Eileen Bay
11	01 Jul 2019 15:02	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/07/03	[A] HOW MEI KWAN
12	23 Jul 2019 15:53	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	23 Jul 2019 15:53	Cim Dtl Modified	JPJ Reg. Date: -> 1993/02/12.	[A] JOANNE LEE KHANG MIN
14	23 Jul 2019 15:53	Cim Details Notified		[A] JOANNE LEE KHANG MIN
15	23 Jul 2019 16:18	Adj Mandate Request	Cur.Req:5202.00:LIABILITY: 100%(BOLA 27) QUANTUM: (a) COR: \$4,500.00 + (b) LO R: \$700.00 (7days x \$100) + (c) DISBURSEMENT: \$2.00 Total: a+b+c = 5,202.00 VEH MODEL: Toyota Corolla(1587cc) FOR YOUR APPROVAL/INSTRUCTION.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2188230	24/06/2019 18:02	Motor	FWD Singapore Pte. Ltd. (HQ)	FWD Singapore Pte. Ltd. (HQ)	SBW72805	GOH SONG SIN	xx.xx
2196338	01/07/2019 15:02	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SBW72805	SKX8106U	11.77

Print Received Message

This mail is associated with :

***SBW7280S (1201900017375)**
[SKX8106U]
TP
CHAN KHOON MENG
Jun 20 2019 7:00AM
[Goh Song Sin]
Hup Motor Trading & Service

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 26/07/2019 12:44 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5202.00) - SBW7280S - Claim Handler: Lionel Tan

Approved: 5202.00.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 29 July 2019 10:40 AM
To: David Ang
Cc: Admin A
Subject: RE : ACCIDENT ON : 20/06/19, INVOLVING CLIENT'S (SBW 7280 S) & YOUR INSURED (SKX 8106 U) ALONG JUNCTION OF ADMIRALTY RD WEST & SENOKO RD// LKK REF: CC4/FWD19011054/Upa3
Attachments: DV_SBW7280S.pdf

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as follows: -

1. Cost of Repair	\$ 4,500.00
2. Loss of Rental (7days x \$100.00)	\$ 700.00
3. LTA/ GIA Search Fee	\$ 2.00
Total	\$ 5,202.00

Please duly sign the DV enclosed and return together with the following document to us(LKK) for our necessary action: -

- **Rental Receipt**

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: David Ang <hupmotor@gmail.com>
Sent: Tuesday, 2 July 2019 10:05 AM
To: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE : ACCIDENT ON : 20/06/19, INVOLVING CLIENT'S (SBW 7280 S) & YOUR INSURED (SKX 8106 U) ALONG JUNCTION OF ADMIRALTY RD WEST & SENOKO RD

Dear Jia Le,

Attach our letter of demand, final bill, car rental bill, GIA third party insurer search fee & owner authorisation letter for your reference & attention, Please let us have your direct settlement soonest, we will forwards the original documents to yours by mail,

On Mon, 24 Jun 2019 at 12:23, David Ang <hupmotor@gmail.com> wrote:

Noted with thanks.



Virus-free. www.avg.com

On Mon, 24 Jun 2019 at 12:02, Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SKX 8106U AND SBW 7280S ON 20/06/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Monday, 24 June 2019 11:54 AM
To: David Ang; Jia Le (LKK Auto)
Cc: CS A Team; Admin A
Subject: RE: RE : ACCIDENT ON : 20/06/19, INVOLVING CLIENT'S (SBW 7280 S) & YOUR INSURED (SKX 8106 U) ALONG JUNCTION OF ADMIRALTY RD WEST & SENOKO RD

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Jia Le,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: David Ang <hupmotor@gmail.com>
Sent: Monday, 24 June, 2019 11:48 AM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Subject: Fwd: RE : ACCIDENT ON : 20/06/19, INVOLVING CLIENT'S (SBW 7280 S) & YOUR INSURED (SKX 8106 U) ALONG JUNCTION OF ADMIRALTY RD WEST & SENOKO RD

Dear Mei Kwan,

Please revert & confirm client's third party claims liability, as we are looking for direct settlement,

----- Forwarded message -----

From: David Ang <hupmotor@gmail.com>
Date: Fri, 21 Jun 2019 at 15:08
Subject: RE : ACCIDENT ON : 20/06/19, INVOLVING CLIENT'S (SBW 7280 S) & YOUR INSURED (SKX 8106 U) ALONG JUNCTION OF ADMIRALTY RD WEST & SENOKO RD
To: <motorclaims.sg@fwd.com>

Dear Sirs,

Attach our estimate bill, GIA third party insurer search fee, Client's GIA report, insurance certificate & log card for your reference & attention,

Kindly assign your panel surveyor (LKK Auto Consultants Pte Ltd) to survey client's damaged vehicle On : 25/06/19 (at 10am to 12pm) as owner waiting,

Kindly revert & confirm client's third party claims liability, reference & OIC, as we are looking for direct settlement,

Please let us hear from yours soon,

Best Regards
David Ang
Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655
Mailing Address :

Hup Motor Trading & Service
Blk 9004 Tampines St 93
#01-120
Singapore 528838



Virus-free. www.avq.com

--

Best Regards
David Ang
Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655
Mailing Address :

Hup Motor Trading & Service
Blk 9004 Tampines St 93
#01-120
Singapore 528838

--

Best Regards
David Ang
Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655
Mailing Address :
Hup Motor Trading & Service
Blk 9004 Tampines St 93
#01-120
Singapore 528838

--

Best Regards
David Ang
Tel : 6784 0039, Fax : 6784 0076, HP : 9815 4655
Mailing Address :
Hup Motor Trading & Service
Blk 9004 Tampines St 93
#01-120
Singapore 528838

HT

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: http://hupmotor.com.sg Reg. No. 378091/00W

Our Ref: TP 2953/06/19 Your Ref: 004/PWD19003467/4pb3 Date: 29th July 2019



The Claim's Manager
Motor Claims Dept.
FWD Singapore Pte. Ltd.
6, Temasek Boulevard,
#18-01, Suntec Tower 4,
Singapore 038986

Dear Sirs,

RE: ACCIDENT ON 20/06/19 ALONG JUNCTION OF ADMIRALTY RD WEST & SENCKO
INVOLVING : SBW 7280 S & YOUR INSURED : SKX 8106 U

We act for Mr Chan Khoo Meng., NRIC No : S7046226B
Who is the registered owner of motor vehicle No : SBW 7280 S

We refer to your letter dated on 29/07/19

We accept your offer of \$ 5,202.00 being for full and final settlement.

As requested, My Client's (owner of SBW 7280 S) had signed the enclosed discharge voucher and return to you.

Please kindly forward the fullsettlement of the claims to M/S Hup Motor Trading & Service as my client's did not pay us any single amount.

Please let us have your cheque soonest.

Thank you.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

Mr David Ang B. Y.

Encl : Discharge Voucher & Car rental receipt.

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: <http://hupmotor.com.sg> Reg. No. 378091/00W

Our Ref: TF 2953/06/19 Your Ref: _____ Date: 2nd July 2019

The Claim's Manager
Motor Claims Dept.
PWD Singapore Pte. Ltd.
6, Temasek Boulevard, #18-01
Suntec Tower 4, Singapore 038986

Dear Sirs,

RE : ACCIDENT ON 20/06/19 ALONG JUNCTION OF ADMIRALTY RD WEST & SENOKO RD
INVOLVING : SEW 7280 S & YOUR INSURED : SKX 8106 U

We act for Mr Chan Khoon Meng., NRIC No.: S7046226E
Who is the registered owner of Veh. No : SEW 7280 S Which was involved
in the above accident with Veh. No : SKX 8106 U Which we understand
is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and
we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am,
therefore, seeking compensation from you for my financial losses as
itemised below : -

Cost of repair	\$ 4,500.00
Car rental for 7 days (1 day X \$ 100.00)	700.00
LTA Search Fee & GIA-RMC Search Fee	2.00
Survey Fee	0.00

\$ 5,202.00

We have enclosed copies of relevant documents to support my client's
claim. There was no receipt enclosed, as my client's did not pay us
any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

Mr David Ang B. Y.

Encl : Final Bill, Car Rental Bill, LTA Search Fee, Owner Authorisation
Letter, ~~GIA Report, Survey Report & Ins. Cert.~~

Remark : Kindly acknowledge receipt.

Note : Car rental total 7 days, due to 30/06/19 was Sunday, Not a working Day.

TO : FWD SINGAPORE PTE. LTD.

AUTHORIZATION TO ACT

I, CHAN KHOON MENG (S7046226E) ("the third party claimant")

of BLK 401, #05-08, ADMIRALTY LINK, S (750401) (address),

owner of SBW 7280 S (vehicle no.) hereby authorize

Hup Motor Trading & Service,

("The workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my

Vehicle No. SBW 7280 S that was damaged pursuant to the

accident which occurred on 20/06/19 (date) along ADMIRALTY

RD WEST & SENOKO RD JUNCTION (location)


involving Vehicle No/s SKX 8106 U

("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.


I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 2nd day of July (month) 20 19 (year)



CHAN KHOON MENG (S7046226E)
Signed by "the third party claimant"
Owner Of SBW 7280 S

HUP MOTOR TRADING & SERVICE



Signed by "the workshop"

RELEASE

Claim Reference:	TP / 1201900017375
Surveyor's Reference:	CC4/FWD19011054/Upa3q2
TP Reference:	TP 2953/06/19 (SBW7280S)

We, **HUP MOTOR TRADING & SERVICE** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SBW 7280S** ("Vehicle") to accept the sum of **\$5,202.00**, being the amount claimed for **\$4,500.00** (repair costs), **\$700.00** (loss of rental/ use), **\$ -** (loss of income), **\$2.00** (disbursement) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **20/06/2019** (date of accident) at / along **X-JUNCTION OF ADMIRALTY RD WEST / SENOKO RD** (location) involving vehicle no/s. **SBW 7280S** and **SKX 8106U**.

This is pursuant to the inspection conducted on **25/06/2019** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SKX 8106U** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 01 day of Aug 2019

CLAIMANT

HUP MOTOR TRADING & SERVICE



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



cks.

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2953/06/19 Your Ref: _____ Date: 2nd July 2019

MR CHAN KHOON MENG
BLK 401, #05-08
ADMIRALTY LINK
SINGAPORE 750401

Cost of repair to TOYOTA COROLLA 1.6 (M) Saloon - SBW 7280 S

To supply boot lid, emblems, reflecter, lock, stricker, hinge, weatherstrip, tail lamp assy, apron panel, rivets, rear bumper, clips, reinforcement, side retainer, licence lamp assy, stay, rear number plate, holder, rear end panel, top garnish, clips, spare tyre cover board, tail lamp panel, wheel mudflaps & necessary parts.

To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre, tool set & necessary parts, including wiring check up for affected wiring system.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear o/s & n/s fender, o/s tail lamp panel & necessary parts, to weld, renew & align above parts.

To putty & respray painting on all affected accident parts, including respray Tuff-Kote on all affected parts.

Lump Sum Repair : \$ 4,500.00

Dollars : Four Thousand And Five Hundred Only.

HUP MOTOR TRADING & SERVICE

B & O VEHICLE RENTAL

Blk 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)
 Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000
 Reg. No: 53060835M
TOWING SERVICE: 9760 2211 (After 10.30 pm)

Truck Rental
 Motor Repair
 Motor Insurance Claims
 Insurance Agent
 Dealer in Used Car
 Authorised Castrol Service Centre

卡车及罗渣出租
 汽车维修
 保险赔偿
 代理保险
 买卖汽车
 维修服务中心

VEHICLE RENTAL AGREEMENT

I/We CHAN KHOON MENG (Owner Of SBW 7280 S
 of BLK 401, #05-08, ADMIRALTY LINK, S (750401)

I/C No : S7046226E
 Tel No : 84688849
 Pager : _____

hereinafter called "the Hirer" hereby confirm having agreed to hire this day from B & O VEHICLE RENTAL hereinafter called "the Owner" the undementioned Vehicle at the rental fees as shown below and I further agree that I shall be held responsible for:-

- a) **THIRD PARTY ONLY MOTOR VEHICLE COVERAGE**
 the Excess which is the maximum amount of \$1000 to cover for any third party damage or injury claims and also bear the full cost of any damage caused to the hired Vehicle resulting from any single accident including loss from inability to let the same Vehicle out on hire or loss resulting from theft and destruction of the Vehicle.
- b) **COMPREHENSIVE MOTOR VEHICLE COVERAGE**
 the Excess which is the maximum amount of \$2000 for any damage caused to the hired Vehicle from any single accident or any loss resulting from third party damage claim, injury claim, theft or destruction of the Vehicle.

whether or not such damage or loss is by person/persons known or unknown to me or by negligence or any breach by me of the Terms and Condition of Hire, hereafter mentioned and printed at the back hereof;

Vehicle Regd. No: <u>SGE 1672 U</u> <u>TOYOTA ALTIS 1.6 (A)</u> <u>SALOON</u>		Agreement No.: <u>19526</u>
Driver's Particulars		Odometer: <u>212221 (+ tank Fuel)</u>
Name: <u>CHAN KHOON MENG</u>		Date & Time Out: <u>25/06/19 (10:00hrs)</u>
Address: <u>AS ABOVE</u>		Date & Time In: <u>02/07/19 (10:30hrs)</u>
I/C No: <u>S7046226E</u>	Dr/Licence No: <u>S7046226E</u> Hour @\$
Date of Issue: <u>08/09/13</u> <u>YOD : 20/09/96</u>	Occupation: <u>Engineer</u>	<u>7</u> Days @\$ <u>100-00</u>
Date of Birth: <u>17/12/70</u>	Tools: <u>One Set</u> Spare Tyre: <u>One</u> Wks @\$
a) Third Party Only Policy Excess <u>3,500</u>	b) Comprehensive Policy Excess <u>3,000</u> Mths @\$

The hirer should be responsible for Insurance Coverage 1000 dollars Excess under Third Party Claim.
 NOTICES: Driving experiences should over 2 years and min. Age 23 to max. Age 70

I/We hereby declare that the particulars of the hirer and licence given above are correct in every respect and that I am the holder of a current driving licence enabling me to drive the above-mentioned vehicle and am not disqualified from driving.

Deposit : NIL

Balance To Pay : \$ 700-00

Remarks:

1. Do not carry soil, sand, cement, scrap metal or goods that are dirty. Carwash fees are chargeable for those who return a dirty vehicle.
 2. Extra charges are required for those vehicle that run out petrol.
 3. Please check Radiator Water & Engine Oil daily.
 4. Hirer and/or driver is liable for all parking, traffic and smoky exhaust violation.
1. 车辆不可载泥土、洋灰、废料及肮脏货物。车身脏乱者，另付洗车费用。
 2. 半途汽油不足，须额外付费。
 3. 请注意水箱里的水及引擎里的机油须每天检查。
 4. 租车者或司机须负所有停车、违反交通及排过量黑烟法例负起一切的责任。

Date: _____

承租者签名 Signature of Hirer: _____



RECEIVED 29/07/2019 14:02 67840076

HUP MOTOR

B & O VEHICLE RENTAL

Blk 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)
Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000
Reg. No: 53080835M

正式收據
OFFICIAL RECEIPT

DATE: 2/7/19.

茲收到 RECEIVED FROM: Mr. Chan Kuan Meng

金額 AMOUNT: Seven hundred only

BEING PAYMENT OF: 係對 運 Rental of S6E16A24 for 25/06/19 To

(SUBJECT TO CHEQUE CLEARANCE) 2/7/19.
此收據必須俟支票過帳之後始屬有效。

\$ 700/-
CASH/CHEQUE
現銀/支票

B & O VEHICLE RENTAL





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-098219
Date of Request: 20/06/2019

Your Ref No: Online Purchase

Hup Motor Trading & Service
Blk 9004 Tampines Street 93
#01-120
Singapore 528838

Dear Sir/Madam,

Enquiry Date 20/06/2019
Enquiry By David Ang Beng Yeow
TP Vehicle No. SKX8106U
Accident Date 20/06/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement
















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jun 2019 Edit Reg		21 Jun 2019 00:00 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Goh Song Sin , ID: S7313561C								
Main Claimant:	CHAN KHOON MENG , ID: S7046226E								
Vehicle Reg. No.:	SBW7280S	Date of Loss:	20/06/2019 07:00 - :59 [316 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900017375	Policy/Cover Note No.:	PNPV2016-00000666-02 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKX8106U	Policy No. (Claimant):	5057640744-06						
Excess:									
Repairer:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (26/07/2019): Alert - Adj Mandate Approved (S\$5202.00) - SBW7280S - Claim Handler: Lionel Tan									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SBW7280S (1201900017375)**
[SKX8106U]
TP
CHAN KHOON MENG
Jun 20 2019 7:00AM
[Goh Song Sin]
Hup Motor Trading & Service

Upload Documents Upload Photos Compose New Letter			View View in Browser <input type="button" value="v"/>
Letters/Correspondences			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	<input type="button" value="1"/> Edit
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	01/07/19 15:02	Adjuster Immediate Advice	<input type="button" value="1"/> Load HTM
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
2	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
3	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
4	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
5	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
6	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
7	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
8	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
9	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
10	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
11	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
12	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
13	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
14	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
15	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
16	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
17	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
18	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
19	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
20	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
21	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
22	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
23	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
24	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
25	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
26	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
27	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
28	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
29	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
30	23/07/19 10:53	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
32	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
33	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
34	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
35	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
36	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
37	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
38	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
39	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
40	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
41	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
42	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
43	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
44	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
45	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
46	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
47	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
48	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
49	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
50	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
51	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
52	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
53	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
54	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
55	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
56	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
57	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
58	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
59	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
60	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
61	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
62	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
63	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
64	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
65	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
66	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
67	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
68	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
69	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
70	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
71	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
72	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
73	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
74	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
75	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
76	23/07/19 10:53	Odometer Reading		<input checked="" type="checkbox"/>
77	23/07/19 10:53	General View		<input checked="" type="checkbox"/>
78	23/07/19 10:53	Chassis Number		<input checked="" type="checkbox"/>
79	23/07/19 10:53	General View		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/06/19 11:45	ACKNOWLEDGEMENT EMAIL TO FWD DD 21.06.2019	Load PDF	
2	24/06/19 11:45	TP ESTIMATE + TP GIA REPORT	Load PDF	
3	24/06/19 11:50	OI GIA REPORT	Load PDF	
4	02/07/19 09:38	TP ESTIMATE	Load PDF	
5	23/07/19 16:06	WORKSHOP INVOICE	Load PDF	
6	23/07/19 16:06	LOD	Load PDF	
7	23/07/19 16:06	GIA SEARCH	Load PDF	
8	05/08/19 09:05	AUTHORISATION TO ACT FORM	Load PDF	
9	05/08/19 09:05	Release Voucher	Load PDF	
10	05/08/19 09:05	RENTAL RECEIPT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKX8106U (Insd veh)	Model:	TOYOTA COROLLA 1.6 (M)
	SBW7280S (TP veh)		
Date of Accident:	20/06/2019		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	: \$		9,916.77
Final Repair Cost	: \$		4,500.00
Loss of Use	: \$		_____ days at \$0.00 per day
Rental (if any)	: \$		700.00 7 days
LTA / GIA Search Fee	: \$		2.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		5,202.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability ___100___(%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	Hup Motor Trading & Service	: \$ 5,202.00
2)		: \$
3)		: \$

JOANNE LEE KHANG MIN

05 Aug
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19011054/UPA3Q2

Date: 05/08/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2016-00000666-02

Claimant Vehicle No: SBW7280S Insured Vehicle No: SKX8106U

Date of Loss: 20/06/2019 Nature of Claim: TP Claim No: 1201900017375

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBW7280S	Engine No:	4AB226835
Make & Model:	TOYOTA COROLLA, 1.6 (M)	Chassis No:	AE1013041030
Reg. Date:	12/02/1993 (Man. Year: 1992)	Odometer:	315369 km
Colour:	Silver		
Engine Capacity:	1587 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,176.77	3,159.95	3,016.82	48.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	2,470.00	1,270.00	33.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,916.77	5,629.95	4,286.82	43.23
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	9,916.77	4,500.00	5,416.77	54.62
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,202.00		

INSPECTION

Date of Assignment: 21/06/2019

Date Inspected: 25/06/2019 Inspected At:

Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2019)
Parts: 143	TOYOTA COROLLA 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SBW7280S)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented / Buckled	768.90 FL	*768.90 FL
2	1		*BOOT LID TOYOTA EMBLEM	Necessary	34.80 FL	*34.80 FL
3	1		*BOOT LID GLI EMBLEM	Necessary	40.50 FL	*40.50 FL
4	1		*BOOT LID LOGO EMBLEM	Necessary	37.80 FL	*37.80 FL
5	1		*BOOT LID REFLECTOR	Cracked	402.90 FL	*402.90 FL
6	1		*BOOT LID LOCK	Twisted	72.60 FL	*72.60 FL
7	1		*BOOT LID LOCK STRICKER	Not Necessary	24.20 FL	*-FL
8	2		*BOOT LID O/S & N/S HINGE	Not Necessary	153.60 FL	*-FL
9	1		*BOOT LID WEATHERSTRIP	Twisted	157.10 FL	*157.10 FL
10	2		*O/S & N/S TAIL LAMP ASSY	Cracked	611.20 FL	*611.20 FL
11	4		*O/S & N/S TAIL LAMP CLIPS & STOPPER	Not Necessary	16.80 FL	*-FL
12	1		*O/S & N/S APRON PANEL	N/S Bent	97.00 FL	*48.50 FL
13	8		*O/S & N/S APRON PANEL RIVETS	Necessary	36.00 FL	*36.00 FL
14	1		*REAR BUMPER	Distorted	384.50 FL	*384.50 FL
15	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
16	1		*REAR BUMPER BEAM	Bent	95.10 FL	*95.10 FL
17	2		*REAR BUMPER O/S & N/S STAY	Not Necessary	68.60 FL	*-FL
18	2		*REAR BUMPER O/S & N/S SIDE RETAINER	Bent	29.60 FL	*29.60 FL
19	4		*REAR BUMPER TOP SCREW NUT	Necessary	15.20 FL	*15.20 FL
20	2		*REAR BUMPER O/S & N/S SIDE BRACKET CLIPS	Not Necessary	9.60 FL	*-FL
21	2		*REAR O/S & N/S LICENCE LAMP ASSY	Not Necessary	104.20 FL	*-FL
22	1		*REAR NUMBER PLATE BRACKET HOLDER	Bent	42.60 FL	*42.60 FL
23	1		*REAR NUMBER PLATE	Cracked	45.00 FS	*20.00 FS
24	1		*REAR END PANEL	Badly Dented	466.00 FL	*466.00 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed / Torn	66.80 FL	*66.80 FL
26	5		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	19.50 FL	*-FL
27	1		*REAR SPARE TYRE COVER BOARD	Torn	206.60 FL	*206.60 FL
28	1		*O/S & N/S TAIL LAMP PANEL	N/S Bent	399.20 FL	*199.60 FL
29	1		*REAR FLOOR BOARD PANEL	Repair	702.90 FL	*-FL
30	1		*REAR FLOOR BOARD PANEL INSULATOR	Not Necessary	302.70 FL	*-FL
31	2		*REAR O/S & N/S FENDER	Repair	1,692.60 FL	*-FL
32	16		*REAR O/S & N/S FENDER INNER SHIELD CLIPS	Not Necessary	60.80 FL	*-FL
33	1		*REAR O/S & N/S WHEEL MDUFLAP	N/S Missing	64.60 FL	*32.30 FL
34	1		*REAR EXHAUST MUFFLER TAIL PIPE	Repair	472.60 FL	*-FL
35	2		*REAR EXHAUST MUFFLER O/S & N/S MOUNTING	Not Necessary	80.60 FL	*-FL
36	1		*SET REAR REVERSE CAMERA	Shorted	300.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,120.70	4,106.60
- List Item Discount on L Items 25.00/25.00% (S\$)	1,943.93	946.65

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	6,176.77	3,159.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	40.00	30.00
2	TO REMOVE & REFIX REAR CUSHION SEAT ,CARPET ,FLOOR MAT & GARNISH ,FLOOR BOARD COVER ,SPARE TYRE ,TOOL SET & NECESSARY PARTS	New	150.00	80.00
3	TO REMOVE & REFIX FUEL TANK ,HOSE ,PIPE & NECESSARY PARTS	New	150.00	0.00
4	TO JACK ,STRAIGHTEN & KNOCKING OUT REAR EXHAUST MUFFLER ,TAIL PIPE & NECESSARY PARTS	New	150.00	0.00
5	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	150.00	60.00
6	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR FLOOR BOARD PANEL ,REAR FENDER & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,500.00	1,100.00
7	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,600.00	1,200.00
Gross Labour Cost (S\$)			3,740.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >