

Trans-cab Auto Services Pte Ltd

AAD1906-187

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

24 JUN 2019

Not Authorized
L/Prp 84950t

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 339H

VF1ABL15AUC282743

RENAULT

LATITUDE

19.6.19

FIRST CAPITAL

22/3/2016

PART		LIST	
1	BUMPER COVER FRT	\$	R 1,259.42
1	BUMPER SPOILER FRT	\$	SL 181.75
1	BUMPER ABSORBER FRT	\$	SL 394.68
1	BUMPER RETAINER FRT LH	\$	SL 151.41
1	BUMPER SUPPORT FRT	\$	SL 123.88
1	BUMPER UNDERTRAY FRT	\$	SL 472.83
1	BUMPER GRILLE LOWER FRT	\$	SL 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	SL 207.21
1	BUMPER BEAM FRT	\$	R 914.08
1	HEADLAMP LH	\$	mgm 1,184.43
1	HEADLAMP PANEL FRT LH	\$	R 152.15
1	FENDER PANEL FRT LH	\$	R 783.83
1	WHEELARCH FRT LH	\$	Dir 278.84
1	FENDER BRACKET LOWER LH	\$	SL 15.79
1	FENDER INSULATOR LH	\$	SL 130.84
1	FRONT BRACE PANEL	\$	R 177.22
1	RADIATOR GRILLE	\$	SL 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL 225.36
1	RADIATOR GRILLE FRAME	\$	SL 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	SL 615.90
1	FRAME FULL SUPPORT BRACKET	\$	R 89.79
1	BONNET	\$	R 1,941.63
1	BONNET INSULATOR	\$	SL 405.73
1	BONNET STRUT LH	\$	SL 88.61
1	BONNET STRUT RH	\$	SL 88.61
1	BONNET HINGE LH	\$	R 348.31
1	BONNET HINGE RH	\$	R 348.31
1	BONNET LOCK	\$	R 305.48
1	BONNET CABLE	\$	SL 119.19

Trans-cab Auto Services Pte Ltd**AAD1906-187**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

1	BONNET CABLE COVER	\$	S ₂	161.03	X
1	BONNET SEAL OUTER	\$	S ₂	92.36	
1	BONNET SEAL INNER	\$	S ₂	157.28	
1	AIR CLEANER BOX	\$	S ₂	464.20	
1	AIR CLEANER HOSE	\$	S ₂	175.85	
1	AIR CLEANER LOWER	\$	S ₂	271.26	
1	AUTO COMPUTER	\$	S ₂	5,032.17	
1	INJECTION COMPUTER	\$	S ₂	4,706.30	
1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S ₂	5,154.52	
1	STEERING PUMP ELECTRIC L70Y	\$	S ₂	2,306.90	
1	STEERING PINION RACK L70Y	\$	S ₂	4,413.11	
1	DOOR PANEL FRT LH	\$	B ₂	2,844.66	X
1	DOOR HINGE UPPER LH	\$	A	261.28	
1	DOOR HINGE LOWER LH	\$	A	300.55	
1	DOOR CHECK FRT LH	\$	S ₂	194.77	
1	DOOR LOCK FRT LH	\$	A	908.75	
1	DOOR CATCH FRT LH	\$	S ₂	131.23	
1	DOOR HANDLE OUTER FRT LH	\$	S ₂	477.76	
1	DOOR HANDLE COVER FRT LH	\$	S ₂	13.22	
1	DOOR HANDLE MODULE FRT LH	\$	S ₂	133.60	
1	DOOR REGULATOR FRT LH	\$	A	505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	S ₂	796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	S ₂	120.97	
1	DOOR MOULDING FRONT LH	\$	S ₂	176.82	
1	DOOR FINISHER INNER FRONT LH	\$	S ₂	323.44	
1	DOOR FINISHER FRONT LH	\$	S ₂	423.10	
1	DOOR CASING FRONT LH	\$	S ₂	1,509.06	
1	DOOR BLIND FRONT LH	\$	S ₂	741.80	
1	DOOR WHEATHESTRIIP FRONT LH	\$	S ₂	410.66	
1	DOOR SEAL FRONT LH	\$	S ₂	162.02	
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	S ₂	229.31	
1	DOOR WAIST SEAL OUTER FRONT LH	\$	S ₂	334.69	
1	DOOR WAIST SEAL INNER FRONT LH	\$	S ₂	115.64	
1	DOOR MIRROR ASSY LH	\$	S ₂	1,483.40	
1	DOOR MIRROR GLASS LH	\$	S ₂	148.20	
1	DOOR MIRROR BACK COVER LH	\$	S ₂	218.46	
1	DOOR PANEL REAR LH	\$	A	2,844.66	
1	DOOR HARNESS WIRE LH	\$	S ₂	2,670.00	

Trans-cab Auto Services Pte Ltd**AAD1906-187**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

1	LOWER ARM LH L70Y	\$	685.76	X
1	KNUCKLE ARM LH L70Y	\$	846.98	X
1	ABSORBER FRT LH L70Y	\$	360.54	X
1	DRIVESHAFT LH	\$	1,747.45	}
1	STABILIZER BAR FRT	\$	604.65	
1	ROCKER PANEL INNER GARNISH LH	\$	466.51	
1	ROCKER PANEL INNER LH	\$	1,024.79	
1	ROCKER PANEL OUTER LH	\$	1,184.99	
1	ROCKER PANEL CENTER LH	\$	990.25	X

TOTAL \$ 63,660.19**10% \$ 6,366.02****\$ 57,294.17****Special Nett**

1	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X
1	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	X
1	WHEELARCH CLIP FRT LH	\$	30.50	✓
1	FRONT LEFT TYRE	\$	300.00	}
1	FRONT LEFT TYRE RIM	\$	380.00	
1SET	Front licence plate with holder	\$	80.00	
1	WINDSCREEN SEALANT	\$	253.80	
1	FRONT WINDSCREEN MOULDING	\$	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00	}
6	BONNET INSULATOR CLIP L70Y	\$	7.30	
2	BONNET STRUT L70Y	\$	88.61	
2	BONNET CABLE CLIP L70Y	\$	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	10.85	
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	}
1SET	RADIATOR GRILLE SCREW	\$	16.00	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	80.00	605n
1	FRONT DOOR STICKER 'Classic'	\$	80.00	155n
1	REAR DOOR STICKER '6555-3333'	\$	80.00	605n
1	DOOR CHECK BOLT	\$	22.69	X

Trans-cab Auto Services Pte Ltd

AAD1906-187

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

1	DOOR GUIDE SCREW	\$	na	10.85	}	X
1	DOOR HINGE BOLT	\$	na	10.85		
1	DOOR HINGE NUT LH	\$	na	14.60		
1	DOOR CHECK BOLT	\$	na	22.69		
1	DOOR CHECK NUT	\$	na	3.75		
1	DOOR LOCK SCREW L70Y	\$	na	6.12		
1	DOOR CATCH SCREW L70Y	\$	na	10.06		
TOTAL		\$		2,064.51		

TOTAL PARTS	\$	59,358.68
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	6,000.00	5001
----	----------	------

To transfer of front bumper fittings, attachment and perform water seepage test.

\$	na	380.00	X
----	----	--------	---

To transfer of front fender fittings, attachment and perform water seepage test.

\$	na	380.00	X
----	----	--------	---

To transfer of front windscreen fittings and conduct water seepage test.

\$	na	170.00	X
----	----	--------	---

To check steering geometry and computer wheel alignment

\$		220.00	601
----	--	--------	-----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	na	380.00	X
----	----	--------	---

To remove and renew power steering pump, oil cooler pipe and final checking and testing.

\$	na	440.00	X
----	----	--------	---

To transfer of bonnet fittings, attachment and perform water seepage test.

\$	na	380.00	X
----	----	--------	---

To transfer of tire, rim and on wheel balancing.

\$	na	170.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd**AAD1906-187**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 339H

Putty and spray painting of the affected portion.	\$	6,000.00	6601
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	601
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	601
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
To check ABS brake efficiency, final checking and testing.	\$	nn 380.00	X
Towing Fees	\$	nn 150.00	X
TOTAL	\$	17,290.00	
Over All Total	\$	76,648.68	

LUMP SUM (REPAIR DAY)**20 days**
3 days

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--