



(/listing/usedbike/yamaha-yamaha-xt1200z-super-tenere/10341/)

**SGD\$25000**

Reg : 01/11/2016

Type: Sport Tourers

1199cc

45177km

Well maintain. Trade in/Loan of vehicle available. Interested buyers are welcome to neg. Come visit Albert Motor Supply.

Posted on : 19/06/2019

★ PAID AD    ★ DEALER AD

■ COMPARE    DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-XT1200Z-SUPER-TENERE/10341/)

**Yamaha XT1200Z Super Tenere** (/listing/usedbike/yamaha-yamaha-xt1200z-super-tenere/13033/)



(/listing/usedbike/yamaha-yamaha-xt1200z-super-tenere/13033/)

**SGD\$17500**

Reg : 22/07/2014

Type: Sport Tourers

1199cc

-

Yamaha XT1200Z Super Tenere for sale. Interested parties are welcome to Neg. Trade/Loan available. Do visit us at Wing Fuat @ Sims Place. No Early Settlement Fee.

Posted on : 14/06/2019

★ PAID AD    ★ DEALER AD

■ COMPARE    DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-XT1200Z-SUPER-TENERE/13033/)

**Yamaha XT1200Z Super Tenere** (/listing/usedbike/yamaha-yamaha-xt1200z-super-tenere/12305/)



**QUOTATION**

Customer :

FIRST CAPITAL INSURANCE LTD  
06 RAFFLES QUAY #21-00  
SINGAPORE 048580

NO. : 34308

DATE : 20/06/2019  
CLAIM NO. : 11364  
POLICY NO. :  
FROM : RAYMOND

*not about  
new  
4/5 \$400  
3 day.  
2/7/19*

VEHICLE NO. : FBH8110Y  
MAKE/MODEL : YAM / XT1200Z

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BIG FOOT SIDE STAND(ALTRIDER)	REPLACE	1.00	\$248.00	248.00
2	BOLT P/N: 46879	REPLACE	1.00	\$3.00	3.00
3	COVER HANDLE LH P/N: 44649	REPLACE	1.00	\$35.00	35.00
4	CRASH BAR HEPCO BECKER	REPLACE	1.00	\$749.00	749.00
5	DAMPER 2	REPLACE	1.00	\$9.00	9.00
6	FOOTREST FRONT LH P/N: 46861	REPLACE	1.00	\$58.00	58.00
7	GASKET CRANKCASE COVER	REPLACE	1.00	\$12.00	12.00
8	GUARD (SWMOTECH) ENGINE YAMAHA TENERE XT1200 P/N: 63088	REPLACE	1.00	\$648.00	648.00
9	LABOUR P/N: 06766	Supply/Install	5.00	\$35.00	175.00
10	PEDAL GEAR P/N: 45270	REPLACE	1.00	\$98.00	98.00
11	PIN DOWEL	REPLACE	1.00	\$2.00	2.00
12	PROTECTOR P/N: 56734	REPLACE	1.00	\$32.00	32.00
13	Protector fork spray paint black	REPLACE	2.00	\$70.00	140.00







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19011057/Utd3s2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-09-2019



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3977B	Veh. Inspected	FBH 8110Y
Policy No.		Coverage (\$)	0.00
Claim No.	D19003948MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	21/06/2019

## 2. Vehicle Particulars & Condition

Make & Model	YAMAHA XT1200Z	c.c	1199
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JYADP011000002745	Colour	BLUE
Odometer	94219	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/80 R19	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70 R17	PIRELLI	6 mm
L/H Rear Tyre			mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	15/06/2019	Inspection Date	02/07/2019
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

## 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 8110Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BIG FOOT SIDE STAND (ALTRIDER)	DAMAGED	248.00	248.00
1	BOLT	NECESSARY	3.00	3.00
1	COVER HANDLE LH (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	35.00	-
1	CRASH BAR HEPCO BECKER	TO REPAIR SEE LABOUR	749.00	-
1	DAMPER 2	NOT NECESSARY	9.00	-
1	FOOTREST FRONT LH	CUT	58.00	58.00
1	GASKET CRANKCASE COVER	NOT NECESSARY	12.00	-
1	GUARD (SWMOTECH) ENGINE YAMAHA TENERE	SERVICEABLE	648.00	-
1	PEDAL GEAR	BENT	98.00	98.00
1	PIN DOWEL	NECESSARY	2.00	2.00
1	PROTECTOR	NOT NECESSARY	32.00	-
1	RUBBER FOOTREST FRONT LH./RH	NOT NECESSARY	12.00	-
1	SLIDER FORK FRONT AXLE (MOTOVATIVE)	NOT NECESSARY	105.00	-
1	STAND MAIN	TO REPAIR SEE LABOUR	303.00	-
1	STAND SIDE	TO REPAIR SEE LABOUR	118.00	-
	LESS 10% DISCOUNT		-	-40.90
			2,432.00	368.10
<b>SPECIAL NETT ITEMS</b>				
2	STICKER COWLING FRONT (YAMAHA) (SN) @ \$10.00	NOT NECESSARY	20.00	-
1	STICKER HANDLE GUARD SUPER TENERE (SN)	NOT NECESSARY	181.00	-
			201.00	-
<b>LABOUR</b>				
	LABOUR. INCLUSIVE OF THE REPAIR OF CRASH BAR HEPCO BECKER, STAND MAIN AND STAND SIDE.		175.00	150.00
	PROTECTOR FORK SPRAY PAINT BLACK.	NOT NECESSARY	140.00	-
			315.00	150.00
<b>GRAND TOTAL</b>			<b>2,948.00</b>	<b>518.10</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			400.00
---	--	--	--------

Report Ref No. CS/FC119011057/Utd3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.