

Survisor: RasuASSIGNMENT (Office)From (Person): Lionel TANof FWDDate/Time: 23.6.19 20:25 p.m

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKX 8106U

Insured: _____

at Workshop m/s ETHOZ ProtectTel: 88228339of 30 Bukit Putok CrescentPolicy No: PNPV2016-00006666-02Claim No: 1201900017575

Sum Insured: _____

Excess: \$500.00

Make of Veh: _____

D.O.A. 20.6.2019

(Client's Record)

CA REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 24.6.19 9.41 a.mPerson Contacted: JacksonVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKX 8106U - (C4) FWD K1011054 / d13 DOA - 20/06/2019
24/6/19 @ 2:11pm	request to Lionel Tan via Maximilian.
24/6/19 @ 3:42pm	Lionel Tan informed C/A via Maximilian.
25/6/19 @ 4:47pm	Informed Lee Chan sin C/A by ex: \$500 by email.
11/7/19 @ 10:45am	Rasu finalised final fig \$7173, 6 days
	(Paid \$3752, 31%) no lump sum.

Shiraz, Rasool

REF:

3561c

ASSIGNMENT

Front: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. SKT 81064
 at Workshop m/s ETHOZ
 of 30, PARKER PARK CEMENT
 Insured: FWD
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 500
 (Client's Record)
 Make of Veh: _____

Veh No: SKX81064 Yr Regn: 2015 / DEC
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Vezel 1.5 X CVT cc: 1496
 Colour: BLUE A/C: Insured / Std / NI / NA
 Sp. Reading: 120550 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU11104870
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Normal / Jammed / Leaked / Burnt or _____
 Brake: Normal / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/60R16
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Bal. or Market Value: 65K
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front 5 mm R/Bal. 5 mm
 L/Bal. 5 mm
 D.O.A. 20/06/19
 Survey held at ETHOZ
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
Rasul,
pls see my remark
RECEIVED 17 JUL 2019
16/7/2019
25/6

Date/Time. File Pass to? : Preli. Report
 11/07/19 Rasul : Final Report
 Date/Time. File Return to? _____

Days Of Repair: 6
 Resurvey No. of Trip: 1

Report Format: MER-10
 Lump Sum / I.B.I: (\$) 775

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee: 250
 Transportation: 50
 S + RS: 50
 Photos: 11
 Others: _____
 TOTAL: 361

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jun 2019 Sendback Est	21 Jun 2019 14:27 S\$10,427.00	23 Jun 2019 20:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			
Insured:	GOH SONG SIN, ID: 57313561C, Tel: +6597950979, Email: songsin12@gmail.com		
Vehicle Reg. No.:	SKX8106U	Date of Loss:	20/06/2019 07:00 - :59 [41 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900017375	Policy/Cover Note No.:	PNPV2016-00000666-02 (Comprehensive)
Vehicle Reg. No. (TP):	SBW7280S	Policy No. (TP):	
		Excess:	S\$500.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/07/2019]		
Driver/Custodian:	GOH SONG SIN (46 / Male), NRIC: 57313561C, Tel: +6597950979 Email: songsin12@gmail.com		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	
No results.										

Shiau Chan (LKKAuto)

From: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Sent: Thursday, 11 July 2019 11:02 AM
To: Rasul (LKKAuto)
Cc: SUR
Subject: RE: FINALIZATION REPORT OF SKX-8106-U HONDA VEZEL (OD)(FWD)

Hi Rasul,

Thanks for confirm finalize amount.

Appreciate you could assist offer at merimen.

Thank you.

Warmest Regards,
Lee Chen Sin

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Thursday, July 11, 2019 10:42 AM
To: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Subject: RE: FINALIZATION REPORT OF SKX-8106-U HONDA VEZEL (OD)(FWD)

Hi Sin,

Finalised amount confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Lee Chen Sin [mailto:ChenSin.Lee@ethozgroup.com]
Sent: Wednesday, 10 July, 2019 6:07 PM
To: Rasul (LKKAuto)
Subject: FINALIZATION REPORT OF SKX-8106-U HONDA VEZEL (OD)(FWD)

Hi Rasul,

Attached are the finalization report, supplier invoice, check item photo and photo before paint of above mention vehicle.

Please send acceptance once the COR is confirm.

COR : \$ 7,175.00 (Part By Part)

Repair days : 6
Excess : \$500.00

Kindly revert.

Thank you.

Warmest Regards,
Lee Chen Sin
Motor Claims Operations

ETHOZ
ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075
DID: 6654 7520 | FAX: 6654 7542 | Mobile: 8822 8339
www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 25 June 2019 4:47 PM
To: 'Lee Chen Sin'
Cc: SUR
Subject: OD VEHICLE SKX 8106U (DOA: 20/06/2019)

Dear Chen Sin,

As instructed by our client, please proceed to repair the insured vehicle SKX 8106U (excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	20 Jun 2019 12:40	Cim Veh Model Changed	(204586) HONDA VEZEL 1.5 X CVT (A).	[R] JACKSON TEO Ban Chye
2	20 Jun 2019 12:40	Cim Created	Reg No: SKX8106U. Policy No: PNPV2016-00000666-02. Acct Date: 2019/06/20. Claim Type: OD. Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: ETHOZ Protect Pte Ltd (Bukit Batok). Created from SAS:MOR119080286	[R] JACKSON TEO Ban Chye
3	21 Jun 2019 14:27	Cim Submitted	10427.00.	[R] Lee Chen Sin
4	23 Jun 2019 20:25	Cim Registration Modified	Excess: -> 500.00.	[I] Lionel Tan
5	23 Jun 2019 20:25	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : LKK Auto Consultants Pte Ltd.	[I] Lionel Tan
6	23 Jun 2019 20:25	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/02	[I] Lionel Tan
7	23 Jun 2019 20:25	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Lionel Tan
8	24 Jun 2019 08:24	Assignment 1st Accessed		[A] LEE SU THING
9	24 Jun 2019 13:07	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LEE SU THING
10	24 Jun 2019 14:04	Adj Rpt Initiated		[A] SHIAU CHAN
11	24 Jun 2019 14:09	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/07/02	[A] SHIAU CHAN
12	24 Jun 2019 14:11	Adj Mandate Request	Cur.Req:8277.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	24 Jun 2019 18:42	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/02	[I] Lionel Tan
14	24 Jun 2019 18:42	Adj Mandate Set	Approved:8277.00.	[I] Lionel Tan

Date From



Date To

Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2184331	20/06/2019 12:40	Motor	ETHOZ Protect Pte Ltd	ETHOZ Protect Pte Ltd (Bukit Batok)	SKX8106U		xx.xx
2187484	24/06/2019 14:04	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKX8106U		11.77

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199007198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 24 Jun 2019

Preliminary Advice

Vehicle No	: SKX8106U	Accident Date	: 20/06/2019
Make	: HONDA VEZEL	Policy No.	: PNPV2016-00000666-02
Assignment Date	: 23/06/2019	Excess	: S\$500.00
Date of Inspection	: 24/06/2019	Est. Duration of Repair	: 6.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,427.00
Revised Amount	:S\$	5,995.00
Check Items (Estimated)	:S\$	2,282.00
Total	:S\$	8,277.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	42,393.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,607.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	3561C
Vehicle Details	
Vehicle No.:	SKX8106U
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4024873
Chassis No.:	RU11104870
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,386.00
Original Registration Date:	29 Dec 2015
First Registration Date:	29 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$9,386.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2025
PARF Rebate Amount:	\$7,039.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,301.00
COE Rebate Amount:	\$35,354.00
Total Rebate Amount:	\$42,393.00

The information contained herein is correct as at 24 Jun 2019

OK

65,000
 42,393

 22,607

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/06/2019 11:50
Date Of Accident	20/06/2019 07:45
Exact Location Of Accident	JUNCTION OF ADMIRALTY ROAD & SENOKO RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX8106U
Insured/Policyholder	
Name Of Registered Owner	GOH SONG SIN
NRIC No	S7313561C
Email Address	SONGSIN12@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97950979
Alternative Phone No	OTHERS-97950979

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2016-00000666-02
Cover Note Number	

Driver

Name of Driver	GOH SONG SIN
NRIC No	S7313561C
Date Of Birth	15/04/1973
Occupation	INDOOR
Date Of Driving Pass	02/12/1993
Driving Experience	25 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97950979
Fax Number	
Contact Number	OTHERS-97950979
Email Address	SONGSIN12@GMAIL.COM

Address	BLK 487 ADMIRALTY LINK #12-139
Postcode	750487
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO SKETCH PLAN.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBW7280S
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WERE TRAVELING BEHIND THE CAR WHEN WE WERE REACHING THE JUNCTION. WE WERE TRAVELLING AT LESS THAN 60KM/H AND I WERE ABOUT 2 CAR DISTANT AWAY. WHEN WE WERE NEAR AT THE JUNCTION, HE MADE A HARD BRAKE WHEN THE GREEN LIGHT TURNED TO AMBER. BY THE TIME I REACTED AND BRAKED WITH MY CAR. I COULD PREVENT THE CAR FROM COLLIDING INTO HIS CAR.

AA

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

✓	- Reporting Only
	- Claim OD
	- Claim TP
	- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

 20/6/19
Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name:
Nric/Fin No.

DRIVING LICENCE

Licence Number: **S7313561C**

(Name)
GOH SONG SIN
(WU SONGXIN)

Birth Date: **15 Apr 1973**
 Issue Date: **03 Nov 2003**

00097A2A1D




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7313561C**

Name
GOH SONG SIN
(WU SONGXIN)
 吴松新

Race
CHINESE

Date of Birth
15-04-1973 M

Country of Birth
SINGAPORE




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

CLASS DATE

Class 2 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 02 Dec 1993

NP428A

Licence No. **S7313561C**




200283

S7313561C

ART. BLK. BY ADMIRAL BY ANG 12 1993
 SINGAPORE 750487

NR. NO. **S7313561C** DATE **25/03/2010** NO. **6437836**





CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2016-0000666-02 (Comprehensive - Prestige Plan)

Car plate number: SKX8106U

Your name (As the policyholder): Goh Song Sin

Coverage start date: 29/12/2018

Coverage end date: 28/12/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

- (a) You; and
- (b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Maybank

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 22/11/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2016-00000666-02	Date of Loss:	20/06/2019
Vehicle Reg. No.:	SKX8106U	Driveable?	
Driver Age/Info:	46 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	GOH SONG SIN	Contact No:	+6597950979
Driver:	GOH SONG SIN		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	29/12/2015
Vehicle Colour:	MICA DARK BLUE		
Engine No:	RU11104870	Chassis No:	L15B4024873
Odometer:	120531 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Description of Accident/Loss	KINDLY REFER TO SKETCH PLAN.
Remarks:	VEHICLE AT ETHOZ BUKIT BATOK
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)

COST OF CLAIMS	Amount
Parts	7,777.00
Miscellaneous Items	65.00
Labour	2,585.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,427.00
+ GST 7.00% (S\$)	729.89
Nett Amount (S\$)	11,156.89

This claim is handled by: JACKSON TEO BAN CHYE / SIN / 88228339

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jun 2019)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SKX8106U/21/06/2019 14:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>bt</i>	0.00	0.00	*580.00 F
2	1		*FRONT BONNET HINGE LH <i>bt</i>	0.00	0.00	*40.00 F
3	1		*FRONT BONNET HINGE RH <i>bt</i>	0.00	0.00	*40.00 F
4	10		*FRONT BONNET INSULATOR CLIP <i>ne</i>	0.00	0.00	*30.00 F
5	1		*FRONT BONNET LOCK <i>bt</i>	0.00	0.00	*75.00 F
6	1		*FRONT FENDER LH REPAIR	0.00	0.00	-
7	1		*FRONT FENDER RH <i>- repair</i>	0.00	0.00	*220.00 F
8	1		*FRONT FENDER INNER SHIELD RH <i>X suc</i>	0.00	0.00	*80.00 F
9	10		*FRONT FENDER INNER SHIELD CLIP <i>X n</i>	0.00	0.00	*30.00 F
10	1		*FRONT DOOR RH <i>X suc</i> REPAIR	0.00	0.00	-
11	1		*HEADLAMP LH <i>ca</i>	0.00	0.00	*980.00 F
12	1		*HEADLAMP RH <i>ca</i>	0.00	0.00	*980.00 F
13	1		*HEADLAMP LOWER BRACKET LH <i>ca</i>	0.00	0.00	*36.00 F
14	1		*HEADLAMP LOWER BRACKET RH <i>ca</i>	0.00	0.00	*36.00 F
15	1		*FRONT GRILLE (INNER) <i>ca</i>	0.00	0.00	*220.00 F
16	1		*FRONT GRILLE (OUTER) <i>ca</i>	0.00	0.00	*160.00 F
17	1		*FRONT GRILLE CHROME MOULDING LH <i>ne</i>	0.00	0.00	*36.00 F
18	1		*FRONT GRILLE CHROME MOULDING RH <i>ne</i>	0.00	0.00	*36.00 F
19	1		*FRONT GRILLE LOGO <i>ne</i>	0.00	0.00	*35.00 F
20	1		*FRONT GRILLE BRACKET LH <i>ca</i>	0.00	0.00	*24.00 F
21	1		*FRONT GRILLE BRACKET RH <i>ca</i>	0.00	0.00	*24.00 F
22	1		*FRONT GRILLE BRACKET CENTRE <i>ca</i>	0.00	0.00	*30.00 F
23	1		*FRONT BUMPER (UPPER) <i>de</i>	0.00	0.00	*320.00 F
24	1		*FRONT BUMPER (LOWER) <i>ca</i>	0.00	0.00	*200.00 F
25	1		*FRONT BUMPER SIDE RETAINER LH <i>ne</i>	0.00	0.00	*24.00 F
26	1		*FRONT BUMPER SIDE RETAINER RH <i>ne</i>	0.00	0.00	*24.00 F
27	1		*FRONT BUMPER LOWER GRILLE <i>ca</i>	0.00	0.00	*70.00 F
28	1		*FOG LAMP LH <i>ca</i>	0.00	0.00	*240.00 F
29	1		*FOG LAMP RH <i>X suc</i>	0.00	0.00	*240.00 F
30	1		*FRONT BUMPER REINFORCEMENT <i>bt</i>	0.00	0.00	*200.00 F
31	1		*SUPPORT PANEL <i>ca</i>	0.00	0.00	*380.00 F
32	1		*SUPPORT PANEL TOP GARNISH <i>ca</i>	0.00	0.00	*75.00 F
33	10		*SUPPORT PANEL TOP GARNISH CLIP <i>ne</i>	0.00	0.00	*30.00 F
34	1		*RADIATOR AIR GUIDE (LH) <i>X suc</i>	0.00	0.00	*36.00 F
35	1		*RADIATOR AIR GUIDE (RH) <i>X suc</i>	0.00	0.00	*36.00 F
36	1		*CONDENSER <i>X bt</i>	0.00	0.00	*450.00 F
37	1		*RADIATOR <i>X suc</i>	0.00	0.00	*900.00 F
38	1		*RADIATOR FAN COWLING <i>X</i>	0.00	0.00	*95.00 F
39	1		*RADIATOR FAN MOTOR <i>X</i>	0.00	0.00	*220.00 F
40	1		*RADIATOR FAN BLADE <i>X</i>	0.00	0.00	*60.00 F
41	1		*AIR COND FAN COWLING <i>X</i>	0.00	0.00	*90.00 F
42	1		*AIR COND FAN MOTOR <i>X</i>	0.00	0.00	*220.00 F
43	1		*AIR COND FAN BLADE <i>X</i>	0.00	0.00	*70.00 F

ETHOZ Protect Pte Ltd/SKX8106U/21/06/2019 14:27. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
44	1		*RADIATOR SPARE TANK X SUC	0.00	0.00	*45.00 F
45	1		*WIPER TANK X SUC	0.00	0.00	*60.00 F
Total Parts (\$\$)						7,777.00

F=Franchise part.

ETHOZ Protect Pte Ltd/SKX8106U/21/06/2019 14:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT NUMBER PLATE <i>cm ✓</i>	35.00
2	1	RADIATOR COOLANT <i>? ✓</i>	30.00
Sub Total (S\$)			65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR TO CARRY OUT FRONT REPAIR	New	900.00 <i>660 ✓</i>
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	35.00
3	TO SPRAY PAINTING ON FRONT AFFECTED AREA	New	200.00 <i>720 ✓</i>
4	TO REMOVE & FIX AIR COND CONDENSER INCLUDING TOP UP AIR COND GAS	New	150.00 <i>100 ✓</i>
5	TO PULL OFF STRAIGHTENING FRONT CHASSIS MEMBER LH RH <i>- photo ✓</i>	New	300.00 <i>220 ? ✓</i>
Gross Labour Cost (S\$)			2,585.00

ETHOZ Protect Pte Ltd/SKX8106U/21/06/2019 14:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD 30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>
Company Registration No. 199005791M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

25/6/19

Rasul

Hp 90010068

6 days

P/R

EXCESS: 500

Revet

28/06/19 @ 1120

Revy below part



INSURER: FWD Singapore Pte. Ltd. (HQ)

*FINALIZATION REPORT***PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2016-00000666-02	Date of Loss:	20/06/2019
Vehicle Reg. No.:	SKX8106U	Driveable?	
Driver Age/Info:	46 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	GOH SONG SIN	Contact No:	+6597950979
Driver:	GOH SONG SIN		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	29/12/2015
Vehicle Colour:	MICA DARK BLUE		
Engine No:	RU11104870	Chassis No:	L15B4024873
Odometer:	120531 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Description of Accident/Loss	KINDLY REFER TO SKETCH PLAN.
Remarks:	VEHICLE AT ETHOZ BUKIT BATOK
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)

COST OF CLAIMS

	Amount
Parts	7,777.00
Miscellaneous Items	65.00
bour	2,585.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,427.00
+ GST 7.00% (S\$)	729.89
Nett Amount (S\$)	11,156.89

This claim is handled by: JACKSON TEO BAN CHYE / SIN / 88228339

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jun 2019)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SKX8106U/21/06/2019 14:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>bt</i>	0.00	0.00	*580.00F
2	1		*FRONT BONNET HINGE LH <i>bt</i>	0.00	0.00	*40.00F
3	1		*FRONT BONNET HINGE RH <i>bt</i>	0.00	0.00	*40.00F
4	10		*FRONT BONNET INSULATOR CLIP <i>ne</i>	0.00	0.00	*30.00F
5	1		*FRONT BONNET LOCK <i>bt</i>	0.00	0.00	*75.00F
6	1		*FRONT FENDER LH REPAIR	0.00	0.00	-
7	1		*FRONT FENDER RH <i>-repair</i>	0.00	0.00	*220.00F
8	1		*FRONT FENDER INNER SHIELD RH <i>X</i>	0.00	0.00	*80.00F
9	10		*FRONT FENDER INNER SHIELD CLIP <i>X</i>	0.00	0.00	*30.00F
10	1		*FRONT DOOR RH <i>X</i> REPAIR	0.00	0.00	-
11	1		*HEADLAMP LH <i>CPA</i>	0.00	0.00	*980.00F
12	1		*HEADLAMP RH <i>CPA</i>	0.00	0.00	*980.00F
13	1		*HEADLAMP LOWER BRACKET LH <i>CPA</i>	0.00	0.00	*36.00F
14	1		*HEADLAMP LOWER BRACKET RH <i>CPA</i>	0.00	0.00	*36.00F
15	1		*FRONT GRILLE (INNER) <i>CPA</i>	0.00	0.00	*220.00F
16	1		*FRONT GRILLE (OUTER) <i>CPA</i>	0.00	0.00	*160.00F
17	1		*FRONT GRILLE CHROME MOULDING LH <i>ne</i>	0.00	0.00	*36.00F
18	1		*FRONT GRILLE CHROME MOULDING RH <i>ne</i>	0.00	0.00	*36.00F
19	1		*FRONT GRILLE LOGO <i>ne</i>	0.00	0.00	*35.00F
20	1		*FRONT GRILLE BRACKET LH <i>CPA</i>	0.00	0.00	*24.00F
21	1		*FRONT GRILLE BRACKET RH <i>CPA</i>	0.00	0.00	*24.00F
22	1		*FRONT GRILLE BRACKET CENTRE <i>CPA</i>	0.00	0.00	*30.00F
23	1		*FRONT BUMPER (UPPER) <i>de</i>	0.00	0.00	*320.00F
	1		*FRONT BUMPER (LOWER) <i>de</i>	0.00	0.00	*200.00F
25	1		*FRONT BUMPER SIDE RETAINER LH <i>ne</i>	0.00	0.00	*24.00F
26	1		*FRONT BUMPER SIDE RETAINER RH <i>ne</i>	0.00	0.00	*24.00F
27	1		*FRONT BUMPER LOWER GRILLE <i>CPA</i>	0.00	0.00	*70.00F
28	1		*FOG LAMP LH <i>CPA</i>	0.00	0.00	*240.00F
29	1		*FOG LAMP RH <i>X</i>	0.00	0.00	*240.00F
30	1		*FRONT BUMPER REINFORCEMENT <i>bt</i>	0.00	0.00	*200.00F
31	1		*SUPPORT PANEL <i>repair</i> ? <i>CHECK ITEM</i>	0.00	0.00	*380.00F
32	1		*SUPPORT PANEL TOP GARNISH <i>de</i>	0.00	0.00	*75.00F
33	10		*SUPPORT PANEL TOP GARNISH CLIP <i>ne</i>	0.00	0.00	*30.00F
34	1		*RADIATOR AIR GUIDE (LH) ?	0.00	0.00	*36.00F
35	1		*RADIATOR AIR GUIDE (RH) ?	0.00	0.00	*36.00F
36	1		*CONDENSER ? <i>CHECK ITEM</i>	0.00	0.00	*450.00F
37	1		*RADIATOR ?	0.00	0.00	*900.00F
38	1		*RADIATOR FAN COWLING <i>X</i>	0.00	0.00	*95.00F
39	1		*RADIATOR FAN MOTOR <i>X</i>	0.00	0.00	*220.00F
40	1		*RADIATOR FAN BLADE <i>X</i>	0.00	0.00	*60.00F
41	1		*AIR COND FAN COWLING <i>X</i>	0.00	0.00	*90.00F
42	1		*AIR COND FAN MOTOR <i>X</i>	0.00	0.00	*220.00F
43	1		*AIR COND FAN BLADE <i>X</i>	0.00	0.00	*70.00F

ETHOZ Protect Pte Ltd/SKX8106U/21/06/2019 14:27. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE (1P ✓)	35.00
2	1	RADIATOR COOLANT ? CHECK ITEM	30.00
Sub Total (S\$)			65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO CARRY OUT FRONT REPAIR	New	660 900.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	35.00
3	TO SPRAY PAINTING ON FRONT AFFECTED AREA	New	720 1200.00
4	TO REMOVE & FIX AIR COND CONDENSER INCLUDING TOP UP AIR COND GAS	New	100? 150.00
5	TO PULL OFF STRAIGHTENING FRONT CHASSIS MEMBER LH RH	New	220? 300.00
Gross Labour Cost (S\$) 1735			2,585.00

ETHOZ Protect Pte Ltd/SKX8106U/21/06/2019 14:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD 30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>
Company Registration No. 199005791M

COR: \$7,175.00 (PBP)
6 DAYS REPAIR
EXCESS: \$500.00

Passue
Hy Sodium 68
6 days
P/R
EXCESS: 500
Repair
28/06/19 @ 1120
Ready before print


PARTS: \$5375.00
S/N: \$65.00
LABOUR: \$1735.00

\$7175.00

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M



lo.: M2-00252314

ECLI

102 PROTECT PTE LTD
22 TAMPINES ST 92
: 8106 U(P/O:171778)
MER BY: BRYAN

TAX INVOICE NO.: TL128855
INVOICE DATE : 26/06/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : TBS
PAGE(S) : 1

AX INVOICE

TS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
				(SIN)	(SIN)
00-T7A-000ZZ	HOOD,FR		1 PCS	580.000	580.00
70-T7A-000ZZ	HINGE,HOOD,LH		1 PCS	40.000	40.00
20-T7A-000ZZ	HINGE,HOOD,RH		1 PCS	40.000	40.00
26-F2000	CLIP-HOOD INSULATING PAD MTG		10	3.000	30.00
20-T7A-003	LOCK ASSY,HOOD		1	75.000	75.00
50-T7S-E11	HEADLAMP ASSY,LH		1 PCS	980.000	980.00
00-T7S-E11	HEADLAMP ASSY,RH		1 PCS	980.000	980.00
90-T7A-000	BEAM,FR BUMPER,UPR LH		1 PCS	36.000	36.00
40-T7A-000	BEAM,FR BUMPER,UPR RH		1 PCS	36.000	36.00
21-T7A-000	BASE,FR RAD GRILLE		1 PCS	220.000	220.00
22-T7A-000	MOULDING,FR RAD GRILLE		1 PCS	160.000	160.00

DUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

SIGNATURE

11.25




Lee Chien Sin

SIGNATURE

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6369 / 6384 2235 Fax: 6384 2245
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M



lo.: M2-00252314

ECLI

102 PROTECT PTE LTD
22 TAMPINES ST 92
: 8106 U(P/O:171778)
MER BY: BRYAN

TAX INVOICE NO.: TL128855
INVOICE DATE : 26/06/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : TBS
PAGE(S) : 2

AX INVOICE

TS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
				(SIN)	(SIN)
28-T7A-000	MOULDING,FR RAD GRILLE,LH		1 PCS	36.000	36.00
23-T7A-000	MOULDING,FR RAD GRILLE,RH		1 PCS	36.000	36.00
00-S9A-G00	H-EMBLEM,FR		1 PCS	35.000	35.00
52-T7A-000	BEAM,FR GRILLE SIDE,UPR LH		1 PCS	24.000	24.00
51-T7J-H00	BEAM,FR GRILLE SIDE,UPR RH		1	24.000	24.00
50-T7A-000	BEAM,FR GRILLE,CTR UPR		1 PCS	30.000	30.00
01-T7A-000ZH	FRT BUMPER		1 PCS	320.000	320.00
02-T7A-000	FACE,FR BUMPER,LOWER		1 PCS	200.000	200.00
98-T7A-000	SPACER,FR BUMPER,SIDE LH		1 PCS	24.000	24.00
93-T7A-000	SPACER,FR BUMPER,SIDE RH		1 PCS	24.000	24.00
03-T7A-000	GRILLE,FR BUMPER,LWR CTR		1 PCS	70.000	70.00

DUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL



SIGNATURE

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6309 / 6384 2235 Fax: 6384 2245
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197802013M



lo.: M2-00252314

ECLI
10Z PROTECT PTE LTD
22 TAMPINES ST 92
: 8106 U(P/O:171778)
MER BY: BRYAN

TAX INVOICE NO.: TL128855
INVOICE DATE : 26/06/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : TBS
PAGE(S) : 3

AX INVOICE

TS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
150-SLE-J51 ✓	LAMP ASSY, FR FOG, LH		1 PCS ✓	(SIN) 240.000	(SIN) 240.00
130-T7A-000Z ✓	BEAM ASSY, FR BUMPER		1 PCS ✓	200.000	200.00
129-T7A-000 ✓	COVER, FR RAD GRILLE, UPR		1 PCS ✓	75.000	75.00
105-TM8-003 ✓	CLIP, BUMPER		10 PCS	3.000	30.00
				GST Excl Amount :	4545.00
				Special Discount :	
				GST @ 7 % :	318.15

DUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

PRINT BY :
TBS 26/06/2019 10:29:04



TOTAL 4863.15

SIGNATURE

豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)
No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493588/67496958 Fax: 67495866/67495007
25 Kaki Bukit Road 4, #01-23 Synergy @ KB Singapore 417800. Tel: 6396 6309 / 6384 2235 Fax: 6384 2245
Blk 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197802013M



lo.: M2-00252314

ECLI
10Z PROTECT PTE LTD
22 TAMPINES ST 92
: 8106 U(P/O:171778)
MER BY: BRYAN

TAX INVOICE NO.: TL128867
INVOICE DATE : 27/06/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : TBS
PAGE(S) : 1

AX INVOICE

TS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
100-T7A-300Z	PANEL ASSY, FR SUPPORT		1 PCS ✓	(SIN) 380.000	(SIN) 380.00
110-T7A-J01	A/C CONDENSER ASSY		1 PCS ✓	450.000	450.00
				GST Excl Amount :	830.00
				Special Discount :	
				GST @ 7 % :	58.10

DUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

PRINT BY :
TBS 27/06/2019 10:31:23



TOTAL 888.10

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jun 2019 Sendback Est	21 Jun 2019 14:27 S\$10,427.00	23 Jun 2019 20:25 Edit Adj Rpt	S\$7,175.00 Edit Estimates	S\$7,175.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS	
Insured:	GOH SONG SIN , ID: S7313561C, Tel: +6597950979, Email: songsin12@gmail.com
Vehicle Reg. No.:	SKX8106U
Claim Type:	OD / 1201900017375
Vehicle Reg. No. (TP):	SBW7280S
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/07/2019]
Driver/Custodian:	GOH SONG SIN (46 / Male) , NRIC: S7313561C, Tel: +6597950979 Email: songsin12@gmail.com

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> • FWD_SG (24/06/2019): Alert - Adj Mandate Approved (S\$8277.00) - SKX8106U - Claim Handler: Lionel Tan 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

SKX8106U (1201900017375)
[SBW7280S]
OD
Jun 20 2019 7:00AM
[GOH SONG SIN]
ETHOZ Protect Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)		Thumbnail Print
1	21/06/19 14:27	Repairer Estimates	1	Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	24/06/19 14:09	Adjuster Immediate Advice	1	Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	24/06/19 14:09	Odometer Reading	1	Load JPG <input checked="" type="checkbox"/>
2	24/06/19 14:09	Chassis Number	1	Load JPG <input checked="" type="checkbox"/>
3	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
4	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
5	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
6	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
7	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
8	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
9	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
10	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
11	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
12	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
13	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
14	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
15	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
16	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
17	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
18	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
19	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
20	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
21	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
22	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
23	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
24	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
25	24/06/19 14:09	General View	1	Load JPG <input checked="" type="checkbox"/>
26	24/06/19 14:10	General View	1	Load JPG <input checked="" type="checkbox"/>
27	24/06/19 14:10	General View	1	Load JPG <input checked="" type="checkbox"/>
28	24/06/19 14:10	General View	1	Load JPG <input checked="" type="checkbox"/>
29	24/06/19 14:10	General View	1	Load JPG <input checked="" type="checkbox"/>
30	24/06/19 14:10	General View	1	Load JPG <input checked="" type="checkbox"/>
31	24/06/19 14:10	General View	1	Load JPG <input checked="" type="checkbox"/>
32	24/06/19 14:10	General View	1	Load JPG <input checked="" type="checkbox"/>
33	24/06/19 14:10	General View	1	Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
34	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
35	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
36	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
37	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
38	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
39	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
40	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
41	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
42	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
43	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
44	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
45	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
46	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
47	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
48	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
49	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
50	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
51	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
52	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
53	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
54	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
55	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
56	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
57	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
58	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
59	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
60	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
61	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
62	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
63	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
64	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
65	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
66	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
67	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
68	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
69	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
70	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
71	24/06/19 14:10	General View		<input checked="" type="checkbox"/>
72	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
73	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
74	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
75	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
76	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
77	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
78	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
79	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
80	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
81	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
82	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
83	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
84	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
85	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
86	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
87	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
88	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
89	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
90	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
91	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
92	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
93	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
94	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
95	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
96	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
97	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
98	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
99	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
100	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
101	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
102	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
103	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
104	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
105	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
106	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
107	16/07/19 15:51	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	20/06/19 12:43	E-filed GIA report		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/06/19 14:11	ESTIMATE		<input type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	20/06/19 12:31	Accident Statement		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
2	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
3	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
4	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
5	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
6	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
7	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
8	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
9	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
10	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
11	20/06/19 12:29	Accident Photo		<input checked="" type="checkbox"/>
12	20/06/19 12:29	Accident Photo		<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
				<input checked="" type="checkbox"/>
13	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	20/06/19 12:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	20/06/19 12:22	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19011059/R1QD3E2

Date: 17/07/2019

REFERENCE

Insured/Claimant: GOH SONG SIN Policy No: PNPV2016-00000666-02
Date of Loss: 20/06/2019 Nature of Claim: OD Claim No: 1201900017375

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX8106U**
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4024873
Reg. Date: 29/12/2015 (Man. Year: 2015) Chassis No: RU11104870
Colour: Blue Odometer: 120550 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$65,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm
Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,777.00	5,375.00	2,402.00	30.89
Miscellaneous Items	65.00	65.00	0.00	0.00
Labour	2,585.00	1,735.00	850.00	32.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,427.00	7,175.00	3,252.00	31.19
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	10,427.00	6,675.00	3,752.00	35.98
+ GST 7.00/7.00% (S\$)	729.89	467.25	262.64	35.98
Nett Amount (S\$)	11,156.89	7,142.25	4,014.64	35.98

INSPECTION

Date of Assignment: 23/06/2019 Present Location: ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected: 24/06/2019 Inspected At: ETHOZ Protect Pte Ltd (Bukit Batok)
30 Bukit Batok Crescent
Singapore 658075

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2019)	
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKX8106U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	580.00 F	*580.00 F
2	1		*FRONT BONNET HINGE LH	Bent	40.00 F	*40.00 F
3	1		*FRONT BONNET HINGE RH	Bent	40.00 F	*40.00 F
4	10		*FRONT BONNET INSULATOR CLIP	Necessary	30.00 F	*30.00 F
5	1		*FRONT BONNET LOCK	Bent	75.00 F	*75.00 F
6	1		*FRONT FENDER LH (NPA)	Repair	-	*- F
7	1		*FRONT FENDER RH	Repair	220.00 F	*- F
8	1		*FRONT FENDER INNER SHIELD RH	Serviceable	80.00 F	*- F
9	10		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	30.00 F	*- F
10	1		*FRONT DOOR RH (NPA)	Serviceable	-	*- F
11	1		*HEADLAMP LH	Cracked	980.00 F	*980.00 F
12	1		*HEADLAMP RH	Cracked	980.00 F	*980.00 F
13	1		*HEADLAMP LOWER BRACKET LH	Cracked	36.00 F	*36.00 F
14	1		*HEADLAMP LOWER BRACKET RH	Cracked	36.00 F	*36.00 F
15	1		*FRONT GRILLE (INNER)	Cracked	220.00 F	*220.00 F
16	1		*FRONT GRILLE (OUTER)	Scratched	160.00 F	*160.00 F
17	1		*FRONT GRILLE CHROME MOULDING LH	Necessary	36.00 F	*36.00 F
18	1		*FRONT GRILLE CHROME MOULDING RH	Necessary	36.00 F	*36.00 F
19	1		*FRONT GRILLE LOGO	Necessary	35.00 F	*35.00 F
20	1		*FRONT GRILLE BRACKET LH	Cracked	24.00 F	*24.00 F
21	1		*FRONT GRILLE BRACKET RH	Cracked	24.00 F	*24.00 F
22	1		*FRONT GRILLE BRACKET CENTRE	Cracked	30.00 F	*30.00 F
23	1		*FRONT BUMPER (UPPER)	Deformed	320.00 F	*320.00 F
24	1		*FRONT BUMPER (LOWER)	Cut	200.00 F	*200.00 F
25	1		*FRONT BUMPER SIDE RETAINER LH	Necessary	24.00 F	*24.00 F
26	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	24.00 F	*24.00 F
27	1		*FRONT BUMPER LOWER GRILLE	Cracked	70.00 F	*70.00 F
28	1		*FOG LAMP LH	Cracked	240.00 F	*240.00 F
29	1		*FOG LAMP RH	Serviceable	240.00 F	*- F
30	1		*FRONT BUMPER REINFORCEMENT	Bent	200.00 F	*200.00 F
31	1		*SUPPORT PANEL	Bent	380.00 F	*380.00 F
32	1		*SUPPORT PANEL TOP GARNISH	Deformed	75.00 F	*75.00 F
33	10		*SUPPORT PANEL TOP GARNISH CLIP	Necessary	30.00 F	*30.00 F
34	1		*RADIATOR AIR GUIDE (LH)	Serviceable	36.00 F	*- F
35	1		*RADIATOR AIR GUIDE (RH)	Serviceable	36.00 F	*- F
36	1		*CONDENSER	Bent	450.00 F	*450.00 F
37	1		*RADIATOR	Serviceable	900.00 F	*- F
38	1		*RADIATOR FAN COWLING	Not Necessary	95.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
39	1		*RADIATOR FAN MOTOR	Not Necessary	220.00 F	*- F	
40	1		*RADIATOR FAN BLADE	Not Necessary	60.00 F	*- F	
41	1		*AIR COND FAN COWLING	Not Necessary	90.00 F	*- F	
42	1		*AIR COND FAN MOTOR	Not Necessary	220.00 F	*- F	
43	1		*AIR COND FAN BLADE	Not Necessary	70.00 F	*- F	
44	1		*RADIATOR SPARE TANK	Serviceable	45.00 F	*- F	
45	1		*WIPER TANK	Serviceable	60.00 F	*- F	
					Total Parts (\$\$)	7,777.00	5,375.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE (CRACKED)	35.00	35.00
2	1	RADIATOR COOLANT (NECESSARY)	30.00	30.00
Sub Total (S\$)			65.00	65.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO CARRY OUT FRONT REPAIR	New	900.00	660.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	35.00	35.00
3	TO SPRAY PAINTING ON FRONT AFFECTED AREA	New	1,200.00	720.00
4	TO REMOVE & FIX AIR COND CONDENSER INCLUDING TOP UP AIR COND GAS	New	150.00	100.00
5	TO PULL OFF STRAIGHTENING FRONT CHASSIS MEMBER LH RH	New	300.00	220.00
Gross Labour Cost (S\$)			2,585.00	1,735.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >