

ASS. REC. BY:

REF:

CS/CTI/19011066/kqd3n2

Special Instruction:

Singer: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Tay

of CTI

Date/Time: 24/06/2019 @ 11:34am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ1072P

Insured:

YP5418R

at Workshop w/e

BH Auto Services

Tel:

6559 8944.

of

Blk 1 Sin Ming Ind. Est. Sec. C

Policy No:

DM CVN 1824271800

Claim No:

SNM19D202829

Sum Insured:

Excess:

Make of Veic

(Client's Record)

D.O.A.

15/06/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:28pm @ 24/6/19

Person Contacted:

Junshi

Vehicle IN/OUT

Date/Time

Action/Instruction

Tshvmd /

YP5418R: NA / CTI 19010736 / kqd D.O.A: 15/06/2019

SJJ1072P. GS / AXN 16009731 / M2 abc 2 D.O.A: 14/05/2016

Kenneth confirmed LS \$6100, 10 days (Ref @ 10589.28, 63%)

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 951k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 6/28 Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

1 File pass to

RECEIVED 3-8 JUL 2019

Date/Time, File Pass to?

11/30/19 train

Date/Time, File Return to?

☐ : Prel. Report☐ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Fuel:

Others:

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$ _____)

MER-TP

6100

220

Veh No: STJ 1072P Yr Regn: 09, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPV

Make: Toy Wish c.c. 1794

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 353317 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDER12W30300527

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 15/6/19 D.O.I. 24/6/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 24 June 2019 11:34 AM
To: BHAS - Chan Yun Shi; assignments
Cc: BHAS - Bernard Kee; BHAS - Moo Wen Zheng
Subject: RE: OUR REF: SNM19D202829 - PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

Dear Ms Chan,

We will proceed to appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with BHAS.

Thank you.

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: BHAS - Chan Yun Shi [mailto:yunshi.chan@bhauto.com.sg]

Sent: Monday, 24 June, 2019 11:31 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>

Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Moo Wen Zheng

<wenzheng.moo@bhauto.com.sg>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: FW: OUR REF: SNM19D202829 - PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

Reminder

Dear Irene,

Please take note our vehicle SJJ1072P currently in our workshop, can be survey on immediately.

Kindly assist and thank you.

Best Regards,

Yun Shi

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8942 (F) +65-6515 3144 / +65-6269 2404

Email: yunshi.chan@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: yunshi.chan@bhauto.com.sg <yunshi.chan@bhauto.com.sg>

Sent: Monday, 24 June, 2019 10:57 AM

To: 'Irene Tay' <irene.tay@sg.cntaiping.com>

Cc: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>; 'BHAS - Bernard Kee' <Bernard.kee@bhauto.com.sg>;

'BHAS - Moo Wen Zheng' <wenzheng.moo@bhauto.com.sg>

Subject: RE: OUR REF: SNM19D202829 - PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

Reminder

Dear Irene,

Please take note our vehicle SJJ1072P currently in our workshop, can be survey on immediately.

Kindly assist and thank you.

Best Regards,

Yun Shi

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8942 (F) +65-6515 3144 / +65-6269 2404

Email: yunshi.chan@bhauto.com.sg
Website: <http://www.bhauto.com.sg>

From: yunshi.chan@bhauto.com.sg <yunshi.chan@bhauto.com.sg>
Sent: Friday, 21 June, 2019 6:07 PM
To: 'Irene Tay' <irene.tay@sg.cntaiping.com>
Cc: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>; BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>
Subject: RE: OUR REF: SNM19D202829 - PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

Dear Irene,

Till date we didn't receive any response from your side.
Appreciate kindly send surveyor list to us ASAP.

Thank you and kindly assist.

Best Regards,

Yun Shi

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate
#01-111/113/115/117 Singapore: 575636
(T) +65-6559 8944 / 8942 (F) +65-6515 3144 / +65-6269 2404
Email: yunshi.chan@bhauto.com.sg
Website: <http://www.bhauto.com.sg>

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Friday, 21 June, 2019 5:57 PM
To: BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>
Subject: RE: OUR REF: SNM19D202829 - PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

Hi,

Please note that the officer in charge is Irene.

thanks

From: BHAS - Chan Yun Shi [<mailto:yunshi.chan@bhauto.com.sg>]
Sent: Friday, 21 June, 2019 5:54 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Lim Shu Min <shumin.lim@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D202829 - PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

Dear Shu Min,

Till date we didn't receive any response from your side.
Appreciate kindly send surveyor list to us ASAP.

Thank you and kindly assist.

Best Regards,

Yun Shi

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8942 (F) +65-6515 3144 / +65-6269 2404

Email: yunshi.chan@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: yunshi.chan@bhauto.com.sg <yunshi.chan@bhauto.com.sg>

Sent: Thursday, 20 June, 2019 12:05 PM

To: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>

Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Moo Wen Zheng

<wenzheng.moo@bhauto.com.sg>; 'Chee So Chow' <sochow.chee@sg.cntaiping.com>; 'Irene Tay'

<irene.tay@sg.cntaiping.com>; 'Lim Shu Min' <shumin.lim@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D202829 - PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

Dear Sir/Madam,

Refer to previous email.

Kindly advise as soon as possible.

Thank you

Best Regards,

Yun Shi

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8942 (F) +65-6515 3144 / +65-6269 2404

Email: yunshi.chan@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: yunshi.chan@bhauto.com.sg <yunshi.chan@bhauto.com.sg>

Sent: Wednesday, 19 June, 2019 4:54 PM

To: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>

Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Moo Wen Zheng

<wenzheng.moo@bhauto.com.sg>; 'Chee So Chow' <sochow.chee@sg.cntaiping.com>; 'Irene Tay'

<irene.tay@sg.cntaiping.com>; 'Lim Shu Min' <shumin.lim@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D202829 - PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

Dear Sir/Madam,

Any update ? could you send to us surveyor list for choosing?

We can proceed to the next step of arrange appointment for survey.

Thank you and kindly assist.

Best Regards,

Yun Shi

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapre: 575636

(T) +65-6559 8944 / 8942 (F) +65-6515 3144 / +65-6269 2404

Email: yunshi.chan@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: Lim Shu Min <shumin.lim@sg.cntaiping.com>

Sent: Wednesday, 19 June, 2019 11:37 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>;

yunshi.chan@bhauto.com.sg

Subject: OUR REF: SNM19D202829 - PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

Dear Irene,

Please conduct PRS – SJJ1072P soonest possible.

File with Officer-In-Charge – Irene Tay – 63896192.

Thank you

Lim Shu Min

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: BHAS - Chan Yun Shi [<mailto:yunshi.chan@bhauto.com.sg>]
Sent: Wednesday, 19 June, 2019 10:51 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>
Subject: PRE REPAIR INSPECTION & CHECKING LIABILITY - ACCIDENT INVOLVING - SJJ1072P AND YP5418R ON 15/06/2019

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor and check liability on of the above mentioned accident vehicle.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Thank you.

Best Regards,

Yun Shi

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate
#01-111/113/115/117 Singaopre:575636
(T) +65-6559 8944 /8942 (F) +65-6515 3144 / +65-6269 2404
Email: yunshi.chan@bhauto.com.sg
Website: <http://www.bhauto.com.sg>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



ARWIN (1994) Pte Ltd

Posted: 18-Jun-2019 Tags: 2015 Toyota Wish, 2015 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 2.0A **\$30,800** **\$16,730 /yr** **24-Aug-2010** **1,967 cc** **160,120 km** **MPV** **Available**

Well Maintained By The Only Owner. Flexible Loan Scheme Available, Consignment Unit, Viewing Strictly By Appointment Only.

CONTACT US

Car Search

Posted: 18-Jun-2019 Tags: 2010 Toyota Wish, 2010 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A **\$36,800** **\$13,070 /yr** **10-Aug-2011** **1,798 cc** **118,308 km** **MPV** **Available**

High/Full Loan Available. Excellent Condition. 1 Owner! Cheapest In The Market With Low Depreciation. Perfect Car For A Big Family! Call For A Viewing Appointment Today!

CONTACT US

Mayfair Motoring

Posted: 18-Jun-2019 Tags: 2011 Toyota Wish, 2011 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 03/2024) **\$36,800** **\$7,720 /yr** **25-Mar-2009** **1,794 cc** **120,500 km** **MPV** **Available**

100% Loan Approval! New Paint And Fully Done Up. Immaculate Condition! 6 Months Gear Box And Engine Warranty. In-house / Bank Loan Available.

Viking Motor Pte Ltd

Posted: 18-Jun-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 05/2021) **\$17,800** **\$9,500 /yr** **03-May-2006** **1,794 cc** **165,000 km** **MPV** **Available**

1 Owner, One Year In-House Warranty, High Loan Available, Price Above Stated Is Actual Selling Price, Fully Refurbished, New Paintwork Done, Wear And Tear Replaced, Accident Free, STA Or VICOM Evaluat...

Carway

Posted: 18-Jun-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Don't be fooled by these car insurance myths!

Is it true that my NCD will still be affected even if the accident is not my fault? Let's find out what is true and false about car insurance in Singapore.

Find out more!



Toyota Wish 1.8A (COE till 03/2029) **\$56,800** **\$5,800 /yr** **08-May-2009** **1,794 cc** **142,438 km** **MPV** **Available**

100% Full Loan Very Good Condition View At Phoenix Motor Trading Enterprise

Posted: 18-Jun-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X (New 5-yr COE) **\$42,800** **\$6,550 /yr** **14-Jul-2009** **1,797 cc** **124,200 km** **MPV** **Available**

Very Clean And Well Maintained, Wear And Tear Parts Replaced, \$5,800 Down Payment, \$817 Monthly. Buyer May Opt For New 10 Years COE Renewal At \$64,300.

CONTACT US

Posted: 17-Jun-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 09/2027) **\$49,800** **\$6,010 /yr** **23-Nov-2007** **1,794 cc** **118,000 km** **MPV** **Available**

6 Months Warranty, Brand New Engine Mounting, Loan Available, Trade In Welcome.

Posted: 17-Jun-2019 Tags: 2007 Toyota Wish, 2007 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 08/2023) **\$35,800** **\$8,520 /yr** **31-Aug-2008** **1,794 cc** **-** **MPV** **Available**

Get Full Loan, Full Reconditioned Engine, Transmission And Aircon, Worn Parts Replaced And Repaired, We Provide In House Loans And Other Financial Services To Meet Your Budget. Call Us Or Even Better...

Posted: 17-Jun-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

Toyota Wish 1.8A X (New 10-yr COE) **\$61,800** **\$6,170 /yr** **26-Jun-2009** **1,797 cc** **106,988 km** **MPV** **Available**

1 Owner
Condition: As Advertised! Meticulously Well Taken Care Of By Previous Owner With Smooth Running Engine! Immaculate! Is Even Cheaper, Do Not Miss! Our ...

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2299I

Vehicle Details

Vehicle No.: SJJ1072P
Vehicle to be Exported: No
Intended Deregistration Date: 18 Jun 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 1.8 AUTO
Primary Colour: Silver
Manufacturing Year: 2008
Engine No.: 1ZZ3124353
Chassis No.: JTDER12W303000527
Maximum Power Output: 97.0 kW (130 bhp)
Open Market Value: \$18,803.00
Original Registration Date: 01 Sep 2008
First Registration Date: 01 Sep 2008
Transfer Count: 2
Actual ARF Paid: \$18,803.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2028
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$37,906.00
COE Rebate Amount: \$34,241.00
Total Rebate Amount: \$34,241.00

The information contained herein is correct as at 18 Jun 2019

OK

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

China Taiping Insurance (Singapore) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Tel: 63896111 Fax: 6224 7175/7478

E-mail: claimsdept@sg.cntaiping.com

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SJJ 1072P

MODEL : TOYOTA WISH 1.8 AUTO

POLICY NO : 5101365776

CHASSIS NO : JTDER12W303000527

YEAR OF MANUFACTURE : 2008

DATE / TIME OF ACCIDENT: 15/06/2019 Time: 1015Hrs at CTE NEAR EXIT 4 ORCHARD ROAD.

THIRD PARTY VEHICLE NO: YP5418R

Not Authorised
1/1 Pay @ ?
Before After Paint

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

Date: 20/06/2019

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount	
S/N			SG		SG	
1	Tailgate	1	1,372.40	Dented	1,372.40	✓
2	Tailgate hinge LH	1	78.02	Bented	78.02	X
3	Tailgate hinge RH	1	78.02	Bented	78.02	X
4	Tailgate stand absorber LH	1	241.70	Bented	241.70	X
5	Tailgate stand absorber RH	1	241.70	Bented	241.70	X
6	Tailgate weatherstrip	1	356.70	Cut	356.70	50% ✓
7	Tailgate stopper LH	1	28.02	Necessary	28.02	X
8	Tailgate stopper RH	1	28.02	Necessary	28.02	X
9	Tailgate lock assy	1	363.40	Bented	363.40	X
10	Tailgate lock striker	1	41.70	Bented	41.70	X
11	Tailgate inner trim board	1	414.60	Kinked	414.60	✓
12	Tailgate inner side trim board LH	1	161.67	Kinked	161.67	X
13	Tailgate inner side trim board RH	1	161.67	Kinked	161.67	X
14	Tailgate emblem	1	55.90	Necessary	55.90	✓
15	Tailgate outer moulding chrome	1	271.60	Cracked	271.60	✓
16	Tailgate pull pocket	1	42.98	Torn	42.98	✓
17	Tailgate opener button switch	1	99.70	Malfunction	99.70	7X
18	Rear license plate lamp LH	1	61.75	Cracked	61.75	X
19	Rear license plate lamp RH	1	61.75	Cracked	61.75	X
20	Rear windscreen	1	1,013.70	Broken	1,013.70	✓
21	Rear windscreen moulding set	1	150.00	Necessary	150.00	✓
22	Rear wiper blade	1	49.75	Scratches	49.75	7X
23	Rear wiper arm	1	58.60	Scratches	58.60	7X
24	Rear wiper motor	1	601.70	Malfunction	601.70	7X
25	Rear tail lamp assy LH	1	524.76	Broken	524.76	✓
26	Rear tail lamp assy RH	1	524.76	Cracked	524.76	X
27	Rear bumper	1	581.40	Torn	581.40	✓
28	Rear bumper clip	12	3.59	Necessary	43.08	✓
29	Rear bumper side retainer LH	1	65.70	Necessary	65.70	✓
30	Rear bumper side retainer RH	1	65.70	Necessary	65.70	X
31	Rear bumper reflector LH	1	61.75	Scratches	61.75	X
32	Rear bumper reflector RH	1	61.75	Scratches	61.75	X
33	Rear end panel	1	522.60	Dented	522.60	✓
34	Rear end panel top garnish	1	265.70	Kinked	265.70	✓

35	Rear floor panel	1	751.30	Dented	<i>R</i>	751.30	<i>X</i>
36	Rear floor storage box	1	303.70	Kinked	<i>R</i>	303.70	<i>X</i>
37	Rear fender LH	1	1,033.90	Dented	<i>Bu</i>	1,033.90	<i>✓</i>
38	Rear fender shield LH	1	66.70	Cut	<i>Sm</i>	66.70	<i>X</i>
39	Rear fender shield clip	12	3.21	Necessary	<i>na</i>	38.52	<i>X</i>
40	Rear fender quarter glass moulding LH	1	386.70	Necessary	<i>SV</i>	386.70	<i>7 X</i>
41	Rear fender inner trim board LH	1	677.50	Kinked	<i>SV</i>	677.50	<i>7 X</i>
42	Rear fender inner trim board RH	1	677.50	Kinked	<i>SV</i>	677.50	<i>7 X</i>
43	Rocker panel skirting LH	1	377.63	Cut	<i>R</i>	377.63	<i>X</i>

Sub-Total: 13,065.70
Less: 25% discount - 3,266.43
Total Parts after 25% discount: 9,799.28

Special Nett Items

1	Anti-rust coating	3	80.00		<i>Sm</i>	240.00	<i>90d</i>
2	Rear number plate with casing	1	100.00		<i>Sm</i>	100.00	<i>X</i>
3	Rear windscreen sealant	1	120.00		<i>na</i>	120.00	<i>40sm</i>
4	Rear end panel seal	1	80.00		<i>na</i>	80.00	<i>30sm</i>
5	Rear floor panel seal	1	80.00		<i>na</i>	80.00	<i>X</i>
6	Rear bumper sensor set	1	250.00		<i>na</i>	250.00	<i>200sm</i>
7	Reverse camera assy	1	280.00		<i>SV</i>	280.00	<i>7 X</i>

1,150.00

Total Parts: 10,949.28

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.					2,750.00	<i>120d</i>
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities					2,000.00	<i>90d</i>
3	Provide skill labour to disconnect and check electrical wiring					60.00	<i>2d</i>
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs					150.00	<i>10d</i>
5	Provide skill labour to remove and refit rear windscreen					250.00	<i>120d</i>
6	Dismantle and transfer tailgate fitting and mechanism to new/facilitate repair					100.00	<i>60d</i>
7	Provide skill labour to remove and replace bumper sensor					60.00	<i>5d</i>
8	Provide skill labour to mount vehicle onto chassis alignment bench				<i>na</i>	250.00	<i>X</i>
9	Towing Fee					120.00	<i>5d</i>

Total Labour:

5,740.00

Total Parts & Labour: 16,689.28

GST 7% 1,168.25

Grand Total: 17,857.52

Estimate Repair Duration 20 days

ACCIDENT VEHICLE OF : SJJ1072P

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Survey attended by:

Name : *Kenneth*
Company : *CKK*
Date : *24/6/19*
Time : *1.35pm*
Contact No : *98910602*
Email :

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

China Taiping Insurance (Singapore) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Tel: 63896111 Fax: 6224 7175/7478

E-mail: claimsdept@sg.cntaiping.com

DEAR SIR / MADAM :

*Not Authorised
L1 Reg & 6100ph
Recovery After Paint*

ACCIDENT REPAIR ON: SJJ 1072P

MODEL : TOYOTA WISH 1.8 AUTO

POLICY NO : 5101365776

CHASSIS NO : JTDER12W303000527

YEAR OF MANUFACTURE : 2008

DATE / TIME OF ACCIDENT: 15/06/2019 Time: 1015Hrs at CTE NEAR EXIT 4 ORCHARD ROAD.

THIRD PARTY VEHICLE NO: YP5418R

Date: 20/06/2019

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price S\$	Condition	Amount S\$	
1 Tailgate	1	1,372.40	Dented	1,372.40	—
2 Tailgate hinge LH	1	78.02	Bented	78.02	x
3 Tailgate hinge RH	1	78.02	Bented	78.02	x
4 Tailgate stand absorber LH	1	241.70	Bented	241.70	x
5 Tailgate stand absorber RH	1	241.70	Bented	241.70	x
6 Tailgate weatherstrip	1	356.70	Cut	356.70	soin
7 Tailgate stopper LH	1	28.02	Necessary	28.02	x
8 Tailgate stopper RH	1	28.02	Necessary	28.02	x
9 Tailgate lock assy	1	363.40	Bented	363.40	x
10 Tailgate lock striker	1	41.70	Bented	41.70	x
11 Tailgate inner trim board	1	414.60	Kinked	414.60	✓
12 Tailgate inner side trim board LH	1	161.67	Kinked	161.67	x
13 Tailgate inner side trim board RH	1	161.67	Kinked	161.67	x
14 Tailgate emblem	1	55.90	Necessary	55.90	✓
15 Tailgate outer moulding chrome	1	271.60	Cracked	271.60	✓
16 Tailgate pull pocket	1	42.98	Torn	42.98	✓
17 Tailgate opener button switch	1	99.70	Malfunction	99.70	x
18 Rear license plate lamp LH	1	61.75	Cracked	61.75	x
19 Rear license plate lamp RH	1	61.75	Cracked	61.75	x
20 Rear windscreen	1	1,013.70	Broken	1,013.70	✓
21 Rear windscreen moulding set	1	150.00	Necessary	150.00	✓
22 Rear wiper blade	1	49.75	Scratches	49.75	✓
23 Rear wiper arm	1	58.60	Scratches	58.60	✓
24 Rear wiper motor	1	601.70	Malfunction	601.70	x
25 Rear tail lamp assy LH	1	524.76	Broken	524.76	✓
26 Rear tail lamp assy RH	1	524.76	Cracked	524.76	x
27 Rear bumper	1	581.40	Torn	581.40	—
28 Rear bumper clip	12	3.59	Necessary	43.08	✓
29 Rear bumper side retainer LH	1	65.70	Necessary	65.70	✓
30 Rear bumper side retainer RH	1	65.70	Necessary	65.70	x
31 Rear bumper reflector LH	1	61.75	Scratches	61.75	x
32 Rear bumper reflector RH	1	61.75	Scratches	61.75	x
33 Rear end panel	1	522.60	Dented	522.60	✓
34 Rear end panel top garnish	1	265.70	Kinked	265.70	✓

35	Rear floor panel	1	751.30	Dented	1	751.30	X
36	Rear floor storage box	1	303.70	Kinked	1	303.70	X
37	Rear fender LH	1	1,033.90	Dented	1	1,033.90	✓
38	Rear fender shield LH	1	66.70	Cut	1	66.70	X
39	Rear fender shield clip	12	3.21	Necessary	12	38.52	X
40	Rear fender quarter glass moulding LH	1	386.70	Necessary	1	386.70	X
41	Rear fender inner trim board LH	1	677.50	Kinked	1	677.50	X
42	Rear fender inner trim board RH	1	677.50	Kinked	1	677.50	X
43	Rocker panel skirting LH	1	377.63	Cut	1	377.63	X

\$6358.32 - 25%

= \$4768.74

Sub-Total: 13,065.70
Less: 25% discount - 3,266.43
Total Parts after 25% discount: 9,799.28

Special Nett Items

1	Anti-rust coating	3	80.00		1	240.00	9d
2	Rear number plate with casing	1	100.00		1	100.00	X
3	Rear windscreen sealant	1	120.00		1	120.00	4d
4	Rear end panel seal	1	80.00		1	80.00	3d
5	Rear floor panel seal	1	80.00		1	80.00	X
6	Rear bumper sensor set	1	250.00		1	250.00	20d
7	Reverse camera assy	1	280.00		1	280.00	X
						1,150.00	

\$410.00 360

Total Parts: 10,949.28

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.				2,750.00	120d
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities				2,000.00	90d
3	Provide skill labour to disconnect and check electrical wiring				60.00	2d
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs				150.00	10d
5	Provide skill labour to remove and refit rear windscreen				250.00	120d
6	Dismantle and transfer tailgate fitting and mechanism to new/facilitate repair				100.00	6d
7	Provide skill labour to remove and replace bumper sensor				60.00	5d
8	Provide skill labour to mount vehicle onto chassis alignment bench				250.00	X
9	Towing Fee				120.00	5d
Total Labour:					5,740.00	

\$2480.00

Total Parts & Labour: 16,689.28
GST 7% 1,168.25
Grand Total: 17,857.52

Estimate Repair Duration

20 days

ACCIDENT VEHICLE OF : SJJ1072P

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Survey attended by:

Name : Kenneth
Company : CLKK
Date : 29/11/19
Time : 1.35pm
Contact No : 96910663
Email :

Part = \$4768.74
S/N \$410.00
Labour \$2480.00
Total = \$7658.74 - 20%
= \$6126.99

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119011066/KQD3N2

Date: 31/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18242718000	
Claimant Vehicle No :	SJJ1072P	Insured Vehicle No :	YP5418R	
Date of Loss:	15/06/2019	Nature of Claim:	TP	Claim No: SNM19D202829C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ1072P	Engine No:	1ZZ3124353
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12W303000527
Reg. Date:	01/09/2008 (Man. Year: 2008)	Odometer:	353317 km
Colour:	Metallic Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,709.28	5,217.09	5,492.19	51.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,980.00	2,590.00	3,390.00	56.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,689.28	7,807.09	8,882.19	53.22
Approved Total (Overridden) (\$\$)		6,100.00		
(\$\$)	16,689.28	6,100.00	10,589.28	63.45
+ GST 7.00/7.00% (\$\$)	1,168.25	427.00	741.25	63.45
Nett Amount (\$\$)	17,857.53	6,527.00	11,330.53	63.45

INSPECTION

Date of Assignment:	01/07/2019	
Date Inspected:	24/06/2019	Inspected At: BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ1072P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Bent	1,372.40 FL	*1,372.40 FL
2	1	*TAILGATE HINGE LH	Repair	78.02 FL	*- FL
3	1	*TAILGATE HINGE RH	Repair	78.02 FL	*- FL
4	1	*TAILGATE STAND ABSORBER LH	Serviceable	241.70 FL	*- FL
5	1	*TAILGATE STAND ABSORBER RH	Serviceable	241.70 FL	*- FL
6	1	*TAILGATE STOPPER LH	Serviceable	28.02 FL	*- FL
7	1	*TAILGATE STOPPER RH	Serviceable	28.02 FL	*- FL
8	1	*TAILGATE LOCK ASSY	Repair	363.40 FL	*- FL
9	1	*TAILGATE LOCK STRIKER	Repair	41.70 FL	*- FL
10	1	*TAILGATE INNER TRIM BOARD	Mtg Cracked	414.60 FL	*414.60 FL
11	1	*TAILGATE INNER SIDE TRIM BOARD LH	Serviceable	161.67 FL	*- FL
12	1	*TAILGATE INNER SIDE TRIM BOARD RH	Serviceable	161.67 FL	*- FL
13	1	*TAILGATE EMBLEM	Necessary	55.90 FL	*55.90 FL
14	1	*TAILGATE OUTER MOULDING CHROME	Cracked	271.60 FL	*271.60 FL
15	1	*TAILGATE PULL POCKET	Dented	42.98 FL	*42.98 FL
16	1	*TAILGATE OPENER BUTTON SWITCH	Serviceable	99.70 FL	*- FL
17	1	*REAR LICENSE PLATE LAMP LH	Serviceable	61.75 FL	*- FL
18	1	*REAR LICENSE PLATE LAMP RH	Serviceable	61.75 FL	*- FL
19	1	*REAR WINDSCREEN	Shattered	1,013.70 FL	*1,013.70 FL
20	1	*SET REAR WINDSCREEN MOULDING	Necessary	150.00 FL	*150.00 FL
21	1	*REAR WIPER BLADE	Serviceable	49.75 FL	*- FL
22	1	*REAR WIPER ARM	Serviceable	58.60 FL	*- FL
23	1	*REAR WIPER MOTOR	Serviceable	601.70 FL	*- FL
24	1	*REAR TAIL LAMP ASSY LH	Cracked	524.76 FL	*524.76 FL
25	1	*REAR TAIL LAMP ASSY RH	Serviceable	524.76 FL	*- FL
26	1	*REAR BUMPER	Buckled	581.40 FL	*581.40 FL
27	12	*REAR BUMPER CLIP	Necessary	43.08 FL	*43.08 FL
28	1	*REAR BUMPER SIDE RETAINER LH	Distorted	65.70 FL	*65.70 FL
29	1	*REAR BUMPER SIDE RETAINER RH	Serviceable	65.70 FL	*- FL
30	1	*REAR BUMPER REFLECTOR LH	Serviceable	61.75 FL	*- FL
31	1	*REAR BUMPER REFLECTOR RH	Serviceable	61.75 FL	*- FL
32	1	*REAR END PANEL	Bent	522.60 FL	*522.60 FL
33	1	*REAR END PANEL TOP GARNISH	Distorted	265.70 FL	*265.70 FL
34	1	*REAR FLOOR PANEL	Repair	751.30 FL	*- FL
35	1	*REAR FLOOR STORAGE BOX	Serviceable	303.70 FL	*- FL
36	1	*REAR FENDER LH	Buckled	1,033.90 FL	*1,033.90 FL
37	1	*REAR FENDER SHIELD LH	Serviceable	66.70 FL	*- FL
38	12	*REAR FENDER SHIELD CLIP	Not Necessary	38.52 FL	*- FL
39	1	*REAR FENDER QUARTER GLASS MOULDING LH	Serviceable	386.70 FL	*- FL
40	1	*REAR FENDER INNER TRIM BOARD LH	Serviceable	677.50 FL	*- FL
41	1	*REAR FENDER INNER TRIM BOARD RH	Serviceable	677.50 FL	*- FL
42	1	*ROCKER PANEL SKIRTING LH	Serviceable	377.63 FL	*- FL
43	1	*TAILGATE WEATHERSTRIP (50%)	Distorted/Dented	267.53 FS	*178.35 FS
44	1	*REAR NUMBER PLATE WITH CASING	Serviceable	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
46	1	*REAR END PANEL SEAL	Necessary	80.00 FS	*30.00 FS
47	1	*REAR FLOOR PANEL SEAL	Not Necessary	80.00 FS	*- FS
48	1	*SET REAR BUMPER SENSOR	Necessary	250.00 FS	*200.00 FS
49	1	*REVERSE CAMERA ASSY	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,886.53	6,806.67
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,177.25	1,589.58
Total Parts (\$\$)	10,709.28	5,217.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI-RUST COATING	New	240.00	90.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	2,750.00	1,200.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	2,000.00	900.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	20.00
5	REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	100.00
6	PROVIDE SKILL LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	New	250.00	120.00
7	DISMANTLE AND TRANSFER TAILGATE FITTING AND MECHANISM TO NEW/FACILITATE REPAIR	New	100.00	60.00
8	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSOR	New	60.00	50.00
9	PROVIDE SKILL LABOUR TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH	New	250.00	0.00
10	TOWING FEE	New	120.00	50.00
Gross Labour Cost (S\$)			5,980.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >