

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 25 Jun 2019

Preliminary Advice

Insured Vehicle No : SMH2062L
TP Vehicle No : SMB3513C
Make : ALEXANDER DENNIS ENVIRO500
Date of Inspection : 24/06/2019
Inspection At : Tower Transit Singapore Pte Ltd (HQ)
21 Bulim Drive, Bulim Bus Depot
Singapore 648170

Accident Date : 20/06/2019
Assignment Date : 24/06/2019
Est. Duration of Repair : 8 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,916.12
Revised Amount	:S\$	17,916.12
Check Items (Estimated)	:S\$	0.00
Total	:S\$	17,916.12
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.