

Mon 15/07 @ 10am
 SZR
 SCM678R

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

JINLE



GST REG. NO : M2 - 0020081 - X

ESTIMATE

21 JUN 2019

Estimate No. : b1 51653	Page No. : 1 of 5
Date Estimated : 21/06/2019	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Ng Hin Meng 33 Jalan Minggu Singapore 577366	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM678R	D334786	24/06/2014	520iA	0

DESCRIPTION	VALUE
To replace front bumper, front right fender including to knock out dented area caused by the accident	1700 2,550.00
To respray front bumper and front right fender	1730 1,923.00
To carry out body cavity preservation. (Per panel).	100 118.00
To replace right headlight.	408 481.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 171.00
Sundries.	80 150.00
Total Labour 1:	5,399.00

DESCRIPTION	QTY	PRIC	VALUE
PLASTIC NUT ? xan	10	0.90	9.00
# FRT RH FENDER bt	1	888.85	888.85
RIVET ? nu	10	0.50	5.00
FRT BUMPER RH SPACER ? xan	1	10.05	10.05
FRT BUMPER PANEL PRIMED (PDC) repair	1	1,335.40	1,335.40
C CLIP NUT ? xan	10	1.30	13.00
RH HEADLIGHT LED TECHNOLOGY cm	1	4,203.70	4,203.70
Total Parts :			6,465.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51653
Date Estimated : 21/06/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM678R	D334786	24/06/2014	520ia	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD <u>3rd Party</u> / Uninsured losses / Direct Settlement	
Regn No	Claim No.
Date & Time <u>15/07/19 0145</u>	Excess S\$
Surveyor's Name <u>Rafael</u>	Sign
Surveyor's Tel <u>90060068</u>	Authorised Yes / No
Authorised Date	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail	
No. of Working Days Recommend <u>5 days</u>	

Labour 1	:	5,399.00
Parts	:	6,465.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	830.48
Grand Total	:	12,694.48

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 51653
Date Estimated : 21/06/2019
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Ng Hin Meng
33 Jalan Minggu

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 577366

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM678R	D334786	24/06/2014	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front RH fender and attachments include making good the front bumper and knocking out dents caused by the accident	1700.00		1,700.00 ✓
To respray front bumper and front RH fender	1730.00		1,730.00 ✓
To carry out body cavity preservation (Per panel)	100.00		100.00 ✓
To replace RH LED technology headlight include programming and conducting tests for proper function	408.00		408.00 ✓
To check electrical wiring systems at the front section for proper function	150.00		150.00 ✓
Sundries	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT RH FENDER	888.85	1.00		888.85 ✓
# LH LEVER *	7.65	1.00		7.65 (S)
RIVET	0.45	3.00		1.35
# GASKET SET *	46.80	1.00		46.80 (S)
RH HEADLIGHT LED TECHNOLOGY	4,203.70	1.00		4,203.70

SUPPLEMENTARY ITEMS

Total Labour :	4,168.00
Total Parts :	5,148.35
Total Labour & Parts :	9,316.35
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,316.35
GST @7%:	652.14
Grand Total :	9,968.49

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 51653
Date Estimated : 21/06/2019
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Ng Hin Meng
33 Jalan Minggu

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 577366

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM678R	D334786	24/06/2014	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# LH LEVER * <i>3 new</i>	7.65	1.00		7.65
# GASKET SET *	46.80	1.00		46.80

Total Labour :	0.00
Total Parts :	54.45
Total Labour & Parts :	54.45