



Case Details

Case Reference Number : BUS/06/19/5031
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB3611C

Company Type : SMRT Buses Ltd
 Estimation ID : EST-7379-ID
 Assigned By : Bus Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 16/06/2019 10:13 AM
 Vehicle Age(In Months) : 44

Documents / Photographs

View Documents / Photographs

Total Documents: 2

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main	CONSUMABLE	4006313	PRIMER (SIKA 206 G+P)	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace <i>nee</i>
Standard	Main	CONSUMABLE	4006314	ADHESIVE:DIRECT GLAZING	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace <i>nee</i>
Standard	Main	CONSUMABLE	4006315	ACTIVATOR	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace <i>nee</i>
Standard	Main	GLASS	6011143	GLASS:EXIT DOOR, FOR ADL E500 DD BUS	1	1,035.04	1,035.04	10.00	931.54	Replace	1	931.54	Replace <i>CRA</i>
Standard	Main	Body	6011241	MOULDING,WHEELARCH:LH & RH, FOR ADL DD	1	88.03	88.03	10.00	79.23	Replace	1	79.23	Replace <i>SCR</i>
One Time Key In	Main			STICKER EMERGENCY EXIT CONTROL	1	75.00	75.00	0.00	75.00	Replace	1	75.00	Replace <i>nee</i>
Total Spare Part Cost									1,356.77	Surveyor Total 1,356.77			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20			
Final Spare Part Cost									1,085.42	Final Sur Total 1,085.42			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL REAR DOOR GLASS LH	795.00	530	
2	Main	TO REPAIR LH PORTION CENTER	530.00 <i>1060</i>	265 <i>795</i>	
Total:			1,325.00	795.00 <i>1325</i>	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	708.00	538	
Total:			708.00	538.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,085.42	1,085.42
Total Labour Cost	1,325.00	795.00
Total Spray Painting	708.00	538.00
Other	0.00	0.00
Overall Total	3,118.42	2,418.42
Lump Sum Repair Option	☒	☒
Lump Sum Total	3,100.00	2,400.00
Surveyor Approved Amount		2,400.00
No of Repair Days*	4	3
Remarks	-	I/s repair, photo after paint.
Surveyor Name		Hwoo jia
Signature		
Survey Date	21/06/2019	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



SMRT Accident Vehicle Repair Estimates


SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/07/2019

User ID : CatherineLee


Section A - Accident Details

Registration Number	SMB3611C
Case Reference Number	BUS/06/19/5031
Registration Date	1/10/2015
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Xu Li Guang
Type of Accident	Side Swipe
Accident Date and Time	16/6/2019 6:13 PM
Accident Reported Date and Time	16/6/2019 7:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102069
Special Instruction to ARC, if any	SMB3611C-LEFT CENTER DOOR GLASS BROKEN AND BODY SCRATCHES SMK2206Z (TP)-INSURED WITH AIG
Prepared Date and Time	20/6/2019 10:56 AM
Chassis Number	SFD76CLR5FMTL4093
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,855.00	\$1,325.00
Total Spray Cost	\$708.00	\$538.00
Total Spare Part Cost	\$1,085.42	\$1,085.42
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,648.42	\$2,948.42
Lump Sum Total	\$3,650.00	\$2,950.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	Hwee Jie
ARC / Surveyor Sign Off Date	20/06/2019 11:24 AM	21/06/2019 11:44 AM
Signature		
Remarks	I/s repair, photo after paint.	



Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/07/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL REAR DOOR GLASS LH	\$795.00	\$530.00
TO REPAIR LH PORTION CENTER	\$1,060.00	\$795.00
Total Labour	\$1,855.00	\$1,325.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$708.00	\$538.00
Total Spray Painting & Panel Beating	\$708.00	\$538.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE: DIRECT GLAZING	3.00	\$37.00	0.00	\$111.00	Replace	Replace
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
6011143	GLASS	7210802L120	GLASS: EXIT DOOR, FOR ADL E500 DD BUS	1.00	\$1,035.04	10.00	\$931.54	Replace	Replace
6011241	Body	3612001L02	MOULDING, WHEEL ARC H: LH & RH, FOR ADL DD	1.00	\$88.03	10.00	\$79.23	Replace	Replace
			STICKER EMERGENCY EXIT CONTROL	1.00	\$75.00	0.00	\$75.00	Replace	Replace
Total					\$1,395.07		\$1,356.77		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									