



Case Details

Case Reference Number : BUS/06/19/5031
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB3611C

Company Type : SMRT Buses Ltd
 Estimation ID : EST-7379-ID
 Assigned By : Bus Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 16/06/2019 10:13 AM
 Vehicle Age(In Months) : 44

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 2

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main	CONSUMABLE	4006313	PRIMER (SIKA 206 G+P)	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace <i>nel</i>
Standard	Main	CONSUMABLE	4006314	ADHESIVE:DIRECT GLAZING	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace <i>nel</i>
Standard	Main	CONSUMABLE	4006315	ACTIVATOR	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace <i>nel</i>
Standard	Main	GLASS	6011143	GLASS:EXIT DOOR, FOR ADL E500 DD BUS	1	1,035.04	1,035.04	10.00	931.54	Replace	1	931.5	Replace <i>CRA</i>
Standard	Main	Body	6011241	MOULDING,WHEELARCH:LH & RH, FOR ADL DD	1	88.03	88.03	10.00	79.23	Replace	1	79.23	Replace <i>SCR</i>
One Time Key In	Main			STICKER EMERGENCY EXIT CONTROL	1	75.00	75.00	0.00	75.00	Replace	1	75.00	Replace <i>nel</i>
Total Spare Part Cost									1,356.77		Surveyor Total		1,356.77
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20
Final Spare Part Cost									1,085.42		Final Sur Total		1,085.42

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL REAR DOOR GLASS LH	795.00	530	
2	Main	TO REPAIR LH PORTION STICKER	530.00	265	
Total:			1,325.00	795.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	708.00	538	
Total:			708.00	538.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,085.42	1,085.42
Total Labour Cost	1,325.00	795.00
Total Spray Painting	708.00	538.00
Other	0.00	0.00
Overall Total	3,118.42	2,418.42
Lump Sum Repair Option	☒	☒
Lump Sum Total	3,100.00	2,400.00
Surveyor Approved Amount		2,400.00
No of Repair Days*	4	3
Remarks	-	I/s repair, photo after paint.
Surveyor Name		Hwee jie
Signature		 Save Clear
Survey Date	21/06/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: