

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jun 2019 Edit Reg		21 Jun 2019 00:00 Edit Adj Rpt	S\$14,200.00 Edit Estimates	S\$14,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LOO SWEE LEONG , ID: S7200004H									
Main Claimant: EVERGREEN SEAFOOD PTE LTD , Co. Reg. No.: 199501536N									
Vehicle Reg. No.:	GBG7755Z	Date of Loss:	19/06/2019 13:00 - :59 [19 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8527782225SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SDW692J	Policy No. (Claimant):	5096004353-01						
		Excess:							
Repairer: J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578, 539186 Defu Lane - Tel: 63430934									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (26/07/2020): Alert - Adj Mandate Approved (S\$18194.00) - GBG7755Z - Claim Handler: MdNoor, No...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBG7755Z (8527782225SG)**
[SDW692J]
TP
EVERGREEN SEAFOOD PTE LTD
Jun 19 2019 1:00PM
[LOO SWEE LEONG]
J-mart Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser ▼

Video

1 per page ▼
☒

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	18/09/19 17:20	Video - Accident From:OD - Reg. No: SDW692J, Claimant: LOO SWEE LEONG		Load AVI	

Letters/Correspondences

1 per page ▼
☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images

3 per page ▼
☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/09/19 11:52	General View		Load JPG	☒
2	12/09/19 11:52	General View		Load JPG	☒
3	12/09/19 11:52	General View		Load JPG	☒
4	12/09/19 11:52	General View		Load JPG	☒
5	12/09/19 11:52	General View		Load JPG	☒
6	12/09/19 11:52	General View		Load JPG	☒
7	12/09/19 11:52	General View		Load JPG	☒
8	12/09/19 11:52	General View		Load JPG	☒
9	12/09/19 11:52	General View		Load JPG	☒
10	12/09/19 11:52	General View		Load JPG	☒
11	12/09/19 11:52	General View		Load JPG	☒
12	12/09/19 11:52	General View		Load JPG	☒
13	12/09/19 11:52	General View		Load JPG	☒
14	12/09/19 11:52	General View		Load JPG	☒
15	12/09/19 11:52	General View		Load JPG	☒
16	12/09/19 11:52	General View		Load JPG	☒
17	12/09/19 11:52	General View		Load JPG	☒
18	12/09/19 11:52	General View		Load JPG	☒
19	12/09/19 11:52	General View		Load JPG	☒
20	12/09/19 11:52	General View		Load JPG	☒
21	12/09/19 11:52	General View		Load JPG	☒
22	12/09/19 11:52	General View		Load JPG	☒
23	12/09/19 11:52	General View		Load JPG	☒
24	12/09/19 11:52	General View		Load JPG	☒
25	12/09/19 11:52	General View		Load JPG	☒
26	12/09/19 11:52	General View		Load JPG	☒
27	12/09/19 11:52	General View		Load JPG	☒
28	12/09/19 11:52	General View		Load JPG	☒
29	12/09/19 11:52	General View		Load JPG	☒
30	12/09/19 11:52	General View		Load JPG	☒
31	12/09/19 11:52	General View		Load JPG	☒
32	12/09/19 11:52	General View		Load JPG	☒
33	12/09/19 11:52	General View		Load JPG	☒

Video				1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
34	12/09/19 11:52	General View		Load JPG	☒
35	12/09/19 11:52	General View		Load JPG	☒
36	12/09/19 11:52	General View		Load JPG	☒
37	12/09/19 11:52	General View		Load JPG	☒
38	12/09/19 11:52	General View		Load JPG	☒
39	12/09/19 11:52	General View		Load JPG	☒
40	12/09/19 11:52	General View		Load JPG	☒
41	12/09/19 11:52	General View		Load JPG	☒
42	12/09/19 11:52	General View		Load JPG	☒
43	12/09/19 11:52	General View		Load JPG	☒
44	12/09/19 11:52	General View		Load JPG	☒
45	12/09/19 11:52	General View		Load JPG	☒
46	12/09/19 11:52	General View		Load JPG	☒
47	12/09/19 11:52	General View		Load JPG	☒
48	12/09/19 11:52	General View		Load JPG	☒
49	12/09/19 11:52	General View		Load JPG	☒
50	12/09/19 11:52	General View		Load JPG	☒
51	12/09/19 11:52	General View		Load JPG	☒
52	12/09/19 11:52	General View		Load JPG	☒
53	12/09/19 11:52	General View		Load JPG	☒
54	12/09/19 11:52	General View		Load JPG	☒
55	12/09/19 11:52	General View		Load JPG	☒
56	12/09/19 11:52	General View		Load JPG	☒
57	12/09/19 11:52	General View		Load JPG	☒
58	12/09/19 11:52	General View		Load JPG	☒
59	12/09/19 11:52	General View		Load JPG	☒
60	12/09/19 11:52	General View		Load JPG	☒
61	12/09/19 11:52	General View		Load JPG	☒
62	12/09/19 11:52	General View		Load JPG	☒
63	12/09/19 11:52	General View		Load JPG	☒
64	12/09/19 11:53	Reinspection Photo		Load JPG	☒
65	12/09/19 11:53	Reinspection Photo		Load JPG	☒
66	12/09/19 11:53	Reinspection Photo		Load JPG	☒
67	12/09/19 11:53	Reinspection Photo		Load JPG	☒
68	12/09/19 11:53	Reinspection Photo		Load JPG	☒
69	12/09/19 11:53	Reinspection Photo		Load JPG	☒
70	12/09/19 11:53	Reinspection Photo		Load JPG	☒
71	12/09/19 11:53	Reinspection Photo		Load JPG	☒
72	12/09/19 11:53	Reinspection Photo		Load JPG	☒
73	12/09/19 11:53	Reinspection Photo		Load JPG	☒
74	12/09/19 11:53	Reinspection Photo		Load JPG	☒
75	12/09/19 11:53	Reinspection Photo		Load JPG	☒
76	12/09/19 11:53	Reinspection Photo		Load JPG	☒
77	12/09/19 11:53	Reinspection Photo		Load JPG	☒
78	12/09/19 11:53	Reinspection Photo		Load JPG	☒
79	12/09/19 11:53	Reinspection Photo		Load JPG	☒
80	12/09/19 11:53	Reinspection Photo		Load JPG	☒
81	12/09/19 11:53	Reinspection Photo		Load JPG	☒
82	12/09/19 11:53	Reinspection Photo		Load JPG	☒
83	12/09/19 11:53	Reinspection Photo		Load JPG	☒
84	12/09/19 11:53	Reinspection Photo		Load JPG	☒
85	12/09/19 11:53	Reinspection Photo		Load JPG	☒
86	12/09/19 11:53	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
87	12/09/19 11:53	Reinspection Photo		Load JPG	☒
88	12/09/19 11:53	Reinspection Photo		Load JPG	☒
89	12/09/19 11:53	Reinspection Photo		Load JPG	☒
90	12/09/19 11:53	Reinspection Photo		Load JPG	☒
91	12/09/19 11:53	Reinspection Photo		Load JPG	☒
92	12/09/19 11:53	Reinspection Photo		Load JPG	☒
93	12/09/19 11:53	Reinspection Photo		Load JPG	☒
94	12/09/19 11:53	Reinspection Photo		Load JPG	☒
95	12/09/19 11:53	Reinspection Photo		Load JPG	☒
96	12/09/19 11:53	Reinspection Photo		Load JPG	☒
97	12/09/19 11:53	Reinspection Photo		Load JPG	☒
98	12/09/19 11:53	Reinspection Photo		Load JPG	☒
99	12/09/19 11:53	Reinspection Photo		Load JPG	☒
100	12/09/19 11:53	Reinspection Photo		Load JPG	☒
101	12/09/19 11:53	Reinspection Photo		Load JPG	☒
102	12/09/19 11:53	Reinspection Photo		Load JPG	☒
103	12/09/19 11:53	Reinspection Photo		Load JPG	☒
104	12/09/19 11:53	Reinspection Photo		Load JPG	☒
105	12/09/19 11:53	Reinspection Photo		Load JPG	☒
106	12/09/19 11:53	Reinspection Photo		Load JPG	☒
107	12/09/19 11:53	Reinspection Photo		Load JPG	☒
108	12/09/19 11:53	Reinspection Photo		Load JPG	☒
109	12/09/19 11:53	Reinspection Photo		Load JPG	☒
110	12/09/19 11:53	Reinspection Photo		Load JPG	☒
111	12/09/19 11:53	Reinspection Photo		Load JPG	☒
112	12/09/19 11:53	Reinspection Photo		Load JPG	☒
113	12/09/19 11:53	Reinspection Photo		Load JPG	☒
114	12/09/19 11:53	Reinspection Photo		Load JPG	☒
115	12/09/19 11:53	Reinspection Photo		Load JPG	☒
116	12/09/19 11:53	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/06/19 15:52	TP GIA REPORT		Load PDF	
2	14/10/19 11:32	LETTER TO OI		Load PDF	
3	20/07/20 22:06	LOD, REPAIR INVOICE, AUTHORISATION LETTER		Load PDF	
4	20/07/20 22:15	Google Map STOP SIGN AT OID PATH		Load JPG	☒
5	27/08/20 10:34	Authorisation to Act		Load PDF	
6	27/08/20 10:34	Release Voucher		Load PDF	
7	27/08/20 10:34	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	25/06/19 09:40	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDW692J (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D 5MT
	GBG7755Z (TP veh)		(M)
Date of Accident:	19/06/2019		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:\$	28,309.31	
Final Repair Cost	:\$	15,194.00	
Loss of Use	:\$	3,000.00	20.00 days at \$150.00 per day
Rental (if any)	:\$		days
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum	:\$	18,194.00	
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	J-Mart Motor Pte Ltd	:\$	18,194.00
2)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

27 Aug
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19011079/AKA3S2**Date:** 27/08/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBG7755Z**Insured Vehicle No :** SDW692J

Date of Loss: 19/06/2019

Nature of Claim: TP

Claim No: 8527782225SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBG7755Z**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Engine No: 1KD2752574

Reg. Date: 30/10/2017 (Man. Year: 2017)

Chassis No: JTFAT35Y60K209198

Colour: Silver

Odometer: 64018 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R12C

Front Left Side: Michelin 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,967.30	13,362.42	7,604.88	36.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,490.00	4,440.00	1,050.00	19.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,457.30	17,802.42	8,654.88	32.71
Approved Total (Overridden) (S\$)		14,200.00		
(S\$)	26,457.30	14,200.00	12,257.30	46.33
+ GST 7.00/7.00% (S\$)	1,852.01	994.00	858.01	46.33
Nett Amount (S\$)	28,309.31	15,194.00	13,115.31	46.33
+ Loss of Use (20.0 x S\$150.00/day) (S\$)		3,000.00		
Nett Liability (S\$)		18,194.00		

INSPECTION

Date of Assignment: 21/06/2019

Date Inspected: 21/06/2019

Inspected At:

J-mart Motor Pte Ltd (HQ)

Blk 5 Defu Lane 10, #01-578

Singapore 539186

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT PANEL	Dented	1,150.00 FL	*1,150.00 FL
2	1		*DYNA EMBLEM	Necessary	65.00 FL	*65.00 FL
3	1		*FRT GRILLE	Cracked	572.60 FL	*572.60 FL
4	1		*FRT GRILLE LOGO	Necessary	75.00 FL	*75.00 FL
5	8		*FRT GRILLE CLIPS	Necessary	64.00 FL	*30.00 FL
6	1		*RH HEADLAMP	Smashed	975.00 FL	*975.00 FL
7	1		*RH HEADLAMP SOCKET	Smashed	45.00 FL	*45.00 FL
8	1		*RH HEADLAMP CLIP	Necessary	805.00 FL	*8.50 FL
9	1		*FRT BUMPER	Distorted	727.10 FL	*727.10 FL
10	1		*FRT BUMPER BEAM	Not Necessary	355.00 FL	*- FL
11	1		*FRT BUMPER RH FOG LAMP COVER	Deformed	125.00 FL	*125.00 FL
12	1		*FRT RH BUMPER BRACKET	Bent	255.00 FL	*255.00 FL
13	1		*FRT RH CORNER PANEL	Dented	385.00 FL	*385.00 FL
14	1		*FRT RH DOOR	Distorted	1,600.00 FL	*1,310.00 FL
15	1		*FRT RH DOOR OUTER HANDLE	Deformed	185.50 FL	*185.50 FL
16	1		*FRT RH WING MIRROR	Cracked	296.00 FL	*296.00 FL
17	1		*FRT RH DOOR OUTER MOULDING	Not Necessary	103.00 FL	*- FL
18	2		*FRT RH DOOR HINGES	Bent	190.00 FL	*190.00 FL
19	1		*FRT RH DOOR CHECK	Bent	150.00 FL	*150.00 FL
20	1		*FRT RH DOOR RUBBER (LONG)	Cut	195.00 FL	*195.00 FL
21	1		*FRT RH DOOR RUBBER (SHORT)	Cut	100.00 FL	*100.00 FL
22	1		*FRT RH DOOR CHANNEL	Not Necessary	165.00 FL	*- FL
23	1		*FRT RH DOOR REGULATOR GEAR	Damaged	375.00 FL	*375.00 FL
24	1		*FRT RH DOOR REGULATOR GEAR MOTOR	Cracked	553.00 FL	*553.00 FL
25	1		*FRT RH DOOR TRIMBOARD	Cracked	565.00 FL	*565.00 FL
26	1		*FRT RH DOOR LOCK	Jammed	286.00 FL	*286.00 FL
27	1		*FRT RH DOOR CENTRE LOCK MOTOR	Damaged	385.00 FL	*385.00 FL
28	1		*FRT RH DOOR SPEAKER	Not Necessary	368.00 FL	*- FL
29	1		*FRT RH INNER HANDLE	Not Necessary	56.30 FL	*- FL
30	1		*FRT RH STEP GARNISH	Cracked	400.00 FL	*276.00 FL
31	1		*FRT RH DOOR PILLAR	Distorted	470.00 FL	*470.00 FL
32	1		*FRT RH WHEEL ARCH PANEL	Distorted	475.00 FL	*475.00 FL
33	1		*FRT RH WHEEL ARCH PANEL RUBBER	Cut	58.00 FL	*58.00 FL
34	1		*FRT RH STEP PANEL	Bent	362.10 FL	*362.10 FL
35	1		*FRT STEP PANEL INNER GARNISH RH	Deformed	195.00 FL	*195.00 FL
36	1		*FLOORBOARD PANEL	Repair	2,750.00 FL	*- FL
37	1		*BRAKE PUMP AIR BOX	Dented	234.10 FL	*234.10 FL
38	1		*BRAKE PUMP AIR BOX SWITCH	Not Necessary	96.60 FL	*- FL
39	1		*STEERING PUMP	Damaged	985.00 FL	*985.00 FL
40	1		*DASHBOARD	Deformed	1,285.00 FL	*1,285.00 FL
41	1		*FRT KNUCKLE ARM	Bent	607.10 FL	*607.10 FL
42	1		*FRT RH KNUCKLE BEARING OUTER	Necessary	153.90 FL	*153.90 FL
43	1		*FRT RH KNUCKLE BEARING INNER	Necessary	173.00 FL	*173.00 FL
44	1		*FRT RH LOWER ARM	Bent	667.00 FL	*667.00 FL
45	1		*FRT RH UPPER ARM	Bent	1,450.00 FL	*685.00 FL
46	1		*REAR RH TAILLAMP	Not Necessary	220.10 FL	*- FL
47	1		*RH TAILLAMP BRACKET	Not Necessary	175.00 FL	*- FL
48	1		*STEERING SHAFT	Not Necessary	1,980.00 FL	*- FL
49	1		*FRT RH RIM	Cut	250.00 FS	*250.00 FS
50	1		*FRT RH TYRE	Cut	250.00 FS	*180.00 FS
51	1		*BODY STICKER	Necessary	10.00 FS	*10.00 FS
52	1		*CO LOGO	Necessary	500.00 FS	*400.00 FS
53	1		*ERP BRACKET	Not Necessary	26.00 FS	*- FS
54	1		*RH SIDE BRACKET	Bent	1,000.00 FS	*800.00 FS
55	1		*RH STAINLESS STEEL BRACKET	Not Necessary	1,000.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					26,944.40	17,269.90
- List Item Discount on L Items 25.00/25.00% (\$)					5,977.10	3,907.48
Total Parts (\$)					20,967.30	13,362.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	2,500.00	2,000.00
2	SPRAY PAINTING.	New	2,000.00	1,600.00
3	WIRING.	New	30.00	30.00
4	REMOVE & REFIT FRT W/SCREEN.	New	100.00	100.00
5	REMOVE & REFIT DASHBOARD.	New	300.00	220.00
6	TOWING.	New	100.00	80.00
7	TRANSFER DOOR PARTS.	New	80.00	80.00
8	ALIGNMENT.	New	80.00	80.00
9	UNDERCARRIAGE.	New	300.00	250.00
Gross Labour Cost (S\$)			5,490.00	4,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >