

PERSONAL

ASS. REC. BY:

Surveyor: Kenneth

REP:

CS/ASM190110ES/Kgd302

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Chan Kian Chuan

of

ASM (AXA)

Date/Time:

24/6/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / IVA / INV / MV / CS

To Inspect Vehicle No:

SKN1716H

Insured:

at Workshop no:

Ah Lim Motor

Tel:

64831244

of

10 AMK Ind. park 2A #01-09

Policy No:

Claim No:

S9M01RGV

Sum Insured:

Excess:

\$400.00

Make of Veh:

D.O.A

21/06/2019

(Claim's Record)

CA REV / REP. / REV 24 HRS

H.O.D. Endowment:

Date/Time:

3:20pm 24/6/19

Person Contacted:

Zila

Vehicle:

IN/OUT

Date/Time

Action/Instruction

1 - Initial ✓

SKN1716H-X

25/6/19 @ 4.31pm Visit to Chan Kian Chuan via Smart Claim (T/L)

09/7/19 @ 11.15am 2nd visit to Chan Kian Chuan via Smart Claim (repairs willing to undertake cost at \$7K on p/f due to no 2nd hand parts available).

05/7/19 @ 10.59am Chan Kian Chuan informed o/a within repair limit via Smart claim

05/7/19 @ 11.16am Informed Zila C/o not more than \$7K on p/f 2 ex. \$ for by an

Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$34k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 5 days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN171614Yr Regn: 02 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: PeugeotWagon3008 cc1598Colour: M. L. Blue

A/C: Insured / Std / Nil / NA

Sp. Reading: 144331

T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: VF30E5FVAB335312Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim orTyre Size: F205/55R16Black lion

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Black lion

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 21/6/19D.O.I. 24/6/19

Survey held at _____

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1File pass tochecked with Jha, they estimate cost \$8k - \$10k.20/12/19 13.15pm confirmed with Mini Hong final AG \$3940.38, 5 days.(Red \$5498.33, 58%)No lump sum

RECEIVED 23 DEC 2019

Date/Time, File Pass to?

20/12/19☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1Survey Fee: 700

Transportation: _____

S - RS - SI

Furnish

Others

TOTAL

700Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format: Smart Claim

Lump Sum / I.B.I. (\$

3940.38

◀ Service Request Details

Claim

S9M01RGV

Reference

None 

Loss Date

June 21, 2019

Report Date

Jun 24, 2019 9:17:00 AM

Request Date

June 24, 2019

Due Date

July 1, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKN1716H

ISSUE

5008 1.6 TURBO

Service Address

23 CANBERRA DRIVE, . . 768077

Primary Contact/Insured

TAN TUAN ENG (CHEN DUANRONG)
23 CANBERRA DRIVE, #01-47, 768077, Singapore
91766633
AHTANND@GMAIL.COM

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

XS \$400.00 WS AH LIM MOTOR COMPANY

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 20 December 2019 3:15 PM
To: Mui Hong @ Ah Lim Motor; Kenneth Kong (LKKAUTO); SUR
Subject: RE: Draft Finalisation - SKN1716H

Dear Mui Hong,

WITHOUT PREJUDICE

Confirm final fig \$3,940.38 before excess \$400.00 & GST and 5 repair days.

Kindly upload the relevant documents in Smart Claim.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mui Hong @ Ah Lim Motor <muihong@ahlimmotor.com.sg>
Sent: Friday, 22 November 2019 5:05 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Draft Finalisation - SKN1716H

Dear Mr Kenneth,

Pls see attached the Draft Finalisation – SKN1716H

We have also send the Audatex Report over too.

Thanks !

Best Regards,

Kee Mui Hong

Ah Lim Motor @ AMK

10, Ang Mo Kio Industrial Park 2A

#01-09 AMK Autopoint S568047

Tel : 6483 1244 Fax : 6483 6170

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 5 July 2019 11:16 AM
To: Zila @ Ah Lim Motor Company
Cc: Kenneth Kong (LKKAUTO); SUR
Subject: RE: SKN1716H - EST COR

Dear Zila,

As instructed by our client, please proceed to repair the insured vehicle **SKN 1716H at repair cost not more than \$7,000.00 on part by part basis (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zila @ Ah Lim Motor Company <zila@ahlimmotor.com.sg>
Sent: Wednesday, 3 July 2019 3:25 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Subject: RE: SKN1716H - EST COR

Hi Shiau Chan,

Yes, my technician says they can repair within the limit given.

Zila

Ah Lim Motor @ AMK

No 10 Ang Mo Kio Ind Pk 2A

#01-09 AMK Autopoint

S 568047

Tel: 64831244 Fax: 64836170

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]
Sent: Wednesday, July 3, 2019 3:22 PM
To: Zila @ Ah Lim Motor Company <zila@ahlimmotor.com.sg>
Cc: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Subject: RE: SKN1716H - EST COR

<< Re:RE: Re:OI IA OF VEHICLE SKN 1716H UPLOADED

Type

🔗 Question

Message

PLS PROCEED TO AUTHORISE REPAIRS WITHIN REPAIR LIMITS.

[Reply](#)



Auto
Consultants
Pte Ltd

51 UBI AVE L, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

4/7/2019

Survey Details:

Date of loss	21-Jun-19
Date of appointment	24-Jun-19
Date of survey	24-Jun-19
Location of survey	AH LIM MOTOR

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKN 1716H
Make and Model	PEUGEOT 5008 1.6 TURBO (LUX) EXTN
Date of registration	15/2/2012
Excess	\$ 400.00
Market Value	\$ 34,000.00
Parf Rebate	\$ 29,718.00
Nett Loss	\$ 4,282.00

Repair details:

Initial Estimate	\$ 9,438.71
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,575.70
Check items (estimate)	\$ 3,926.50
Labour	\$ 1,686.51
Total	\$ 9,188.71
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>5</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL
(BASED ON THE RANGE OF MARKET VALUE \$35K-\$37K).
REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT
MORE THAN \$7,000.00 ON PART BY PART BASIS DUE TO
NO SECOND HAND PARTS AVAILABLE. WE HAVE NOT
AUTHORISE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

25/6/2019

Survey Details:

Date of loss	21-Jun-19
Date of appointment	24-Jun-19
Date of survey	24-Jun-19
Location of survey	AH LIM MOTOR

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKN 1716H
Make and Model	PEUGEOT 5008 1.6 TURBO (LUX) EXTN
Date of registration	15/2/2012
Excess	\$ 400.00
Market Value	\$ 34,000.00
Parf Rebate	\$ 29,718.00
Nett Loss	\$ 4,282.00

Repair details:

Initial Estimate	CTL
------------------	-----

Proposed/Revised repair cost:

Parts	CTL
Check items (estimate)	\$ -
Labour	\$ -
Total	#VALUE!
Lump Sum(if applicable)	\$ -

Number of days for repair	0
---------------------------	---



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST NOT ECONOMICAL.
WE HAVE NOT AUTHORISE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4659E

Vehicle Details

Vehicle No.: SKN1716H
Vehicle to be Exported: No
Intended Deregistration Date: 21 Jun 2019
Vehicle Make: PEUGEOT
Vehicle Model: 5008 1.6 TURBO (LUX) EXTN
Primary Colour: Blue
Manufacturing Year: 2011
Engine No.: 10FJBW1373872
Chassis No.: VF30E5FVABS335312
Maximum Power Output: 115.0 kW (154 bhp)
Open Market Value: \$25,273.00
Original Registration Date: 15 Feb 2012
First Registration Date: 15 Feb 2012
Transfer Count: 2
Actual ARF Paid: \$25,273.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Feb 2022
PARF Rebate Amount: \$15,163.00

Intended COE Rebate Details

COE Expiry Date: 14 Feb 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$54,887.00
COE Rebate Amount: \$14,555.00
Total Rebate Amount: \$29,718.00

The information contained herein is correct as at 21 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2019 14:54
Date Of Accident	21/06/2019 11:10
Exact Location Of Accident	BLK 761 YISHUN AVE 3 OSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN1716H
Insured/Policyholder	
Name Of Registered Owner	TAN TUAN ENG (CHEN DUANRONG)
NRIC No	S7134659E
Email Address	AHTANND@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91766633
Alternative Phone No	OTHERS-91766633

Vehicle Particulars

Manufacturer	PEUGEOT
Model	5008-1.6 TURBO LUXURY (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA255220
Cover Note Number	07/09/2018 - 06/09/2019

Driver

Name of Driver	TAN TUAN ENG (CHEN DUANRONG)
NRIC No	S7134659E
Date Of Birth	02/10/1971
Occupation	INDOOR
Date Of Driving Pass	23/01/1996
Driving Experience	23 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91766633
Fax Number	
Contact Number	OTHERS-91766633
Email Address	AHTANND@GMAIL.COM

Address	23 CANBERRA DRIVE #01-47
Postcode	768077
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA1158Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LIM YONG HUAT
NRIC/Passport Number	S1122469E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

Date of accident: 2/6/19 Time: 11:10 AM Location: 8th Floor, NUSUN Ave 3 DCP
 My Vehicle A: CRN 7164 Vehicle B: PHAT 84 Vehicle C: -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I'm coming out from the carpark lot. I did not notice vehicle B driving at a fast speed, collided into my front bumper.

Car B - LIM YONG SUAT
 SLIPPER

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my effie accident report to:

My workshop :
 Email address :
 & myself : ahlimmotor@gmail.com
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Center/ Ah Lim Motor's Signature
 Name:
 NRIC/FIN No.:
22 81 1111 1111





POLICYHOLDER ACKNOWLEDGEMENT FORM

Date: 21/06/19To: Owner of Vehicle Number: SKN 1716H

The following has been advised to you via your workshop, AH LIM MOTOR COMPANY through their staff, ZILA/EILEEN/MUI HONG

Please tick the applicable box if you had been advised on any of the following:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☒ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☒ The estimated waiting time for the spare parts to arrive is 13A. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/ personnel that the vehicle may not be road worthy.
- ☒ For vehicles below three (3) years old or under warranty with a local distributor, your insurance company will use only original parts to repair your vehicle.
- For vehicles above three (3) years old and no longer under warranty with a local distributor, your insurance company will be carrying out repairs where any damaged part that can be repaired will be repaired and any part that needs to be replaced will be replaced using **any combination** of original parts and/or original equipment manufacturer (OEM) parts and/or second-hand parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☒ Others claim own Damage

Signed and acknowledged by:

Name and signature of policyholder/ authorized driver* and company stamp (where applicable)

*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

Name and signature of workshop personnel including company stamp





TAN TUAN ENG (CHEN DUANRONG)
23 CANBERRA DRIVE
#01-47
SINGAPORE 768077

Renewal

date
20/07/2018

your servicing distributor
M PLUS SERVICES / 04553

your servicing distributor contact
9856 6914 (KEN)

Policy Schedule

Your SmartDrive Comprehensive Essential

Your policy snapshot

Policyholder name	TAN TUAN ENG (CHEN DUANRONG)	Policy number	VA1 / GA255220
Cover	Comprehensive	FIN / NRIC	S7134659E
Period of Insurance	from 07/09/2018 to 06/09/2019 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	SGD 893.40
Total Discounts	- SGD 47.63
7% GST	SGD 59.20
Final Premium	SGD 904.97

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Essential Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Guaranteed Repairs for twelve (12) Months
- Loss Or Damage
- Legal Liability

Vehicle details

Make & Model of Vehicle	PEUGEOT 5008 1.6 TURBO	Year of manufacture	2011
Vehicle registration number	SKN1716H	Type of Use	Private use
Body type	MPV	Engine capacity (c.c.)	1598
Seating capacity (excl driver)	4	Engine number	10FJBW1373872
Off-Peak car	No	Chassis number	VF30E5FVABS335312

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	KENSO LEASING PTE LTD

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 400.00
Windscreen Excess	SGD 100.00

Drivers details

AXA Insurance Pte Ltd (199903512M)
8 Shenton Way, #24-01, AXA Tower,
Singapore 068811
Customer Centre, #B1-01

AH LIM MOTOR COMPANY

NO 10, ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT SINGAPORE 568047
TEL: 6483 1244 FAX: 64836170
GST REG NO: M9-000773-A

SURVEYOR COPY

Your Ref:

Date: 24/06/2019

Our Ref: VEHICLE NO. SKN1716H
MODEL: PEUGEOT 5008 1.6 TURBO

lxx

M/S AXA INSURANCE (S) PTE LTD
143 CECIL STREET
#01-01 GB BUILDING
SINGAPORE 069542

Not Authored
Ex 8400

ATTENTION: MOTOR CLAIMS DEPARTMENT
OWN DAMAGE

Dear Sirs

Accident involving Your Insured Vehicle No SKN1716H accident on 21/06/2019

We refer to the above matter.

Vehicle sustained extensive damage & car was registered in 15 Feb 2012.

We are not putting up the estimate for the time being & kindly arrange for survey soonest possible. After the survey if there is a need, we will furnish the estimate accordingly.



Thank You
Yours faithfully,

Zila
Ah Lim Motor Company



AH LIM MOTOR COMPANY

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

SURVEYOR COPY

Claim Reference:
Assessment number: MC1900471
Version: 1810
Date calculated: 01/07/2019 9:47 AM

Full Report
Registration: SKN1716H
Printed: 01/07/2019 9:47 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	21/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	PEUGEOT
Model:	5008 (0A-0E)
Sub Model:	BASE MODEL
Model Sheet Number:	11 83 01
Registration:	SKN1716H
VIN number:	VF30E5FVABS335312
Odometer:	

Model Specs

FROM 09/2011	AUTO AIR CON	AIR CON 2 BLOWER	DEAD LOCKS
FRT/RR ELECT WINDOWS	ELEC CHILD LOCKING	ELECT FOLDING MIRROR	PHONE SYS BLUETOOTH
RADIO SYSTEM RD4 MP3	S-WHEEL RADIO CONT	RECEPTION IMPROVED	BI-TUNER
FOG LAMPS	CLOTH TRIM	HEIGHT ADJ PASS SEAT	7 SEATS
ACOUSTICS IMPROVED	RAIN SENSOR	TRIM TRAMONTANE	S/BELT W/WARNING DEV
MODULAR PASS SEAT	USB SOCKET	ENTRANCE LAMPS	WDW MOULDING CHROME
INNER MIRROR/SENSOR	BATTERY 12V 60AH	1.6 LTR 82/84KW	LEATH S-WHEEL 3 SPK
HOUSING PREHEATING	HEAD-UP DISPLAY	CRUISE CONTROL	TYRES 215/55 VR 16
DUST ATMOSPHERE	WHEELS 7J X 16 ALLOY	SPARE WHEEL	ENGINE FAN 140W
SPARE WHEEL WINCH	ALTERNATOR 150 AMP	CATALYST MORE 50PPM	HEAD AIRBAG
FRONT SIDE AIRBAG	PAINTED ROOF MLDG	PANORAMA SUNROOF	EMISSION STD EURO 5
STARTER MTR CLASS 3	PAINTED MOULDINGS	TWO COAT METALLIC	PREPARE OFF VEHICLE

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900471
 Version: 1810
 Date calculated: 01/07/2019 9:47 AM

Full Report
 Registration: SKN1716H
 Printed: 01/07/2019 9:47 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
74.E7UA	REMOVE AND REFIT FRONT PART INCLUDES: FRONT BUMPER AND BOTH R + R HEADLAMP		15.0	67.50
74.E34A)	RENEW FRONT BUMPER		7.0	31.50
72.E1ES)	R + R FRONT C-MEMBER FRONT PART		2.0	9.00
72.E1ES)	RENEW FRONT C-MEMBER FRT PART (REMOVED)		1.0	4.50
62.E4HA)	RENEW BOTH HEADLAMPS (REMOVED)		1.0	4.50
78.E1WA)	R + R RIGHT FRONT WING		5.0	22.50
79.E0YA	R + R BONNET		4.0	18.00
79.E0WA)	RENEW BONNET (REMOVED)		1.0	4.50
79.E0FS)	RENEW L/BONNET HINGE		1.0	4.50
79.E0FS)	RENEW R/BONNET HINGE		1.0	4.50
64.E3UA)	R + R AIR CONDITIONING CONDENSER		2.0	9.00
64.EFYA)	R + R WASHER RESERVOIR		2.0	9.00
64.ESBA)	R + R WASHER PUMP		2.0	9.00
74.EP4A)	R + R FRONT LOWER AIR GUIDE		2.0	9.00

Kg

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
Assessment number: MC1900471
Version: 1810
Date calculated: 01/07/2019 9:47 AM


Full Report
Registration: SKN1716H
Printed: 01/07/2019 9:47 AM

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



83940-38

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
74.E7UA	REMOVE AND REFIT FRONT PART INCLUDES: FRONT BUMPER AND BOTH R + R HEADLAMP		15.0	67.50
74.E34A)	RENEW FRONT BUMPER		7.0	31.50
72.E1ES)	R + R FRONT C-MEMBER FRONT PART		2.0	9.00
72.E1ES)	RENEW FRONT C-MEMBER FRT PART (REMOVED)		1.0	4.50
62.E4HA)	RENEW BOTH HEADLAMPS (REMOVED)		1.0	4.50
78.E1WA)	R + R RIGHT FRONT WING		5.0	22.50
79.E0YA	R + R BONNET		4.0	18.00
79.E0WA)	RENEW BONNET (REMOVED)		1.0	4.50
79.E0FS)	RENEW L/BONNET HINGE		1.0	4.50
79.E0FS)	RENEW R/BONNET HINGE		1.0	4.50
64.E3UA)	R + R AIR CONDITIONING CONDENSER		2.0	9.00
64.EFYA)	R + R WASHER RESERVOIR		2.0	9.00
64.ESBA)	R + R WASHER PUMP		2.0	9.00
74.EP4A)	R + R FRONT LOWER AIR GUIDE		2.0	9.00

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900471
 Version: 1810
 Date calculated: 01/07/2019 9:47 AM

Full Report
 Registration: SKN1716H
 Printed: 01/07/2019 9:47 AM

Code	Description	WU	Price SGD
74.E86A)	RENEW FRONT LOWER AIR GUIDE (REMOVED)	1.0	4.50
NO NUMBER	R + R LEFT FRONT IMPACT DAMPER	1.0	4.50
NO NUMBER	R + R RIGHT FRONT IMPACT DAMPER	1.0	4.50
03.E41A)	R + R AIR INTERCOOLER	1.0	4.50
NO NUMBER	R + R TURBOCHARGER RESONATOR	2.0	9.00
14.E6CA)	R + R AIR BATCHER	3.0	13.50
13.E76A)	R + R RADIATOR	3.0	13.50
	(BUMPER REMOVED)		
74.E9LA)	RENEW FRONT PART (REMOVED)	4.0	18.00
13.E15S	DRAIN + REFILL COOLING SYSTEM	4.0	18.00
64.E3US	ADD: DRAIN + REFILL AIR CONDITIONING	5.0	22.50
62.E1KS	ADD: ADJUST HEADLAMPS	3.0	13.50
62.E1KS	ALIGN FRONT FOG LAMPS	3.0	13.50
0741	L/F WING REPAIR	10 20.0*	90.00
1111	L/F WHEELHOUSE CPL REPAIR	40.0* 7	180.00
1112	R/F WHEELHOUSE CPL REPAIR	40.0* 7	180.00
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	17.70	177.0
	Total of Labour		796.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	16.0
	FRONT UPPER BUMPER NEW PART PAINT K1G/P	30.0
	FRONT LOWER BUMPER NEW PART PAINT K1G/P	18.0
	R/F WING NEW PART PAINT K1R	5.0
	L/F WING REPAIR PAINT PLASTIC	11.0
	L/F WHEELHOUSE CPL SURFACE PAINT	6.0
	R/F WHEELHOUSE CPL SURFACE PAINT	6.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	45.41
0281	FRONT UPPER BUMPER NEW PART PAINT K1G/P	122.40
0285	FRONT LOWER BUMPER NEW PART PAINT K1G/P	64.80
0742	R/F WING NEW PART PAINT K1R	15.74
0741	L/F WING REPAIR PAINT PLASTIC	12.96

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900471
 Version: 1810
 Date calculated: 01/07/2019 9:47 AM

Full Report
 Registration: SKN1716H
 Printed: 01/07/2019 9:47 AM

Paint Material Per Part

Code	Description	Price SGD
1111	L/F WHEELHOUSE CPL SURFACE PAINT	12.45
1112	R/F WHEELHOUSE CPL SURFACE PAINT	12.45

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		92.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
Total	10 WU/h	125.0	562.50

Material Cost - Paint	Price SGD
New Part Painting	45.41
New Part Painting - Plastic K1R	15.74
New Part Painting - Plastic K1G/PUR	187.20
Repair Painting Plastic	12.96
Surface-/Blend Paint	24.90
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	327.51

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2001-01-01 Price SGD
0281	FRONT UPPER BUMPER	7401 SS	Bur	530.00 ✓
0285	FRONT LOWER BUMPER	7401 SV	CM	230.00 ✓
0291	L/F BUMPER COVER	7453-05	See	95.00 ✓
0292	R/F BUMPER COVER	7453-06	See	95.00 ✓
0304	FR LWR BUMPER GRILLE	7422 E2	Ad 10.0	190.00 ✓
0305	FRT BUMPER GRILLE	7422 V0	CM	160.00 7 photo
0308	FR-UPP BUMPER GRILLE	7422 H7	See	160.00 ✓
0311	L/F BUMPER MOULDING	7453 07	See	120.00 ✓
0312	R/F BUMPER MOULDING	7453 08	See	120.00 ✓
0315	C-MEMBER FRONT PART	7104 LE	See	260.00 ✓
0319	FRONT BUMPER DAMPING	7422 C9	See	90.00 7 photo
0325	FT IMPACT DAMPER SET	7422 93	See	85.00 7 photo
0340	FRT UPP BUMPER CARR	7422 E7	CM	150.00 7 photo
0341	FRONT LOWER CARRIER	7422 E8	See	0.00 ✓

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900471

Version: 1810

Date calculated: 01/07/2019 9:47 AM

Full Report

Registration: SKN1716H

Printed: 01/07/2019 9:47 AM

Code	Description	Part Number	Supplier	Price SGD
0353	FRT LWR AIR DEFLECT	7013 GQ		95.00
0471	BONNET	7901 R2		730.00
0475	L/BONNET HINGE	7912 F8		50.00
0476	R/BONNET HINGE	7913 48		50.00
0481	BONNET INSULATION	7979 L2		130.00
0493	BONNET LOCK	7934 E6		45.00
0561	LEFT HEADLAMP ASSY	6208 P6		360.00
0562	RIGHT HEADLAMP ASSY	6206 P6		360.00
0637	L/F FOG LAMP	96-854-252-80		80.00
0638	R/F FOG LAMP	96-854-252-80		80.00
0742	R/F WING	7841 AF		300.00
0840	R/F WHEELHOUSE COVER	7136 JW		80.00
0920	FRONT PART	96-765-687-80		190.00
1435	WASHER RESERVOIR	6431 N2		80.00
4465	AIR CON CONDENSER	6455 GH		470.00
7753	L/RADIATOR AIR GUIDE	7104 LG		45.00
7754	R/RADIATOR AIR GUIDE	7104 LJ		45.00
7761	RADIATOR	1330 W2		330.00
7769	FRT AIR GRILLE	1308 V4		15.00
7773	LWR RADIATOR HOSE	1352-23		55.00
7776	UPPER RADIATOR HOSE	1343 LP		25.00
7790	ELECTRIC FAN	1253 K4		190.00
8739	INTERCOOLER	0384 N9		360.00
1000	INSULATOR CLIP SX10	1		30.00
1001	FRT GRILLE CLIP SX6	1		18.00
1002	SIDE RETAINERS SX2	1		110.00
1003	BUMP CLIP SX15	1		45.00
1004	BUMP TOW COVER RH	1		20.00
1005	FEND COWL CLIP X8	1		24.00
Savings				0.00
Subtotal				6,652.00
Addition(+10.00%)				665.20
Total				7,317.20

i: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1006	NUMBER PLATE	35.00*
1007	RADIATOR COOLANT	30.00*
1008	AIR CON GAS	50.00*

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900471
 Version: 1810
 Date calculated: 01/07/2019 9:47 AM

Full Report
 Registration: SKN1716H
 Printed: 01/07/2019 9:47 AM

Code	Description	Price SGD
1009	CHECK WIRING	40.00*
1010	RESET & DIAGNOSTIC	280.00*
	Total Extras	435.00

20h
X

Final Calculation

	SGD	SGD
Parts		
Addition (+10.00%)	6,652.00	
Total Parts	665.20	7,317.20
Labour Time Base 10 WU/h		
Total 177.0 WU X 45.00 SGD/h	796.50	
Total of Labour		796.50
Total Of Extras		435.00
Paint Work Time Base 10 WU/h		
Labour Cost 125.0 WU X 45.00 SGD/h	562.50	
Material Cost	327.51	
Total Paint Including Material		890.01
Repair Cost Excludes GST		9,438.71
GST (+7.0%)		660.71
Repair Cost Included GST		10,099.42

Comments
 * - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	10,099.42
---	------------------

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900471
 Version: 1810
 Date calculated: 01/07/2019 9:47 AM

Full Report
 Registration: SKN1716H
 Printed: 01/07/2019 9:47 AM

Code	Description	WU	Price SGD
74.E86A)	RENEW FRONT LOWER AIR GUIDE (REMOVED)	1.0	4.50
NO NUMBER	R + R LEFT FRONT IMPACT DAMPER	1.0	4.50
NO NUMBER	R + R RIGHT FRONT IMPACT DAMPER	1.0	4.50
03.E41A)	R + R AIR INTERCOOLER	1.0	4.50
NO NUMBER	R + R TURBOCHARGER RESONATOR	2.0	9.00
14.E6CA)	R + R AIR BATCHER	3.0	13.50
13.E76A)	R + R RADIATOR	3.0	13.50
	(BUMPER REMOVED)		
74.E9LA)	RENEW FRONT PART (REMOVED)	4.0	18.00
13.E15S	DRAIN + REFILL COOLING SYSTEM	4.0	18.00
64.E3US	ADD: DRAIN + REFILL AIR CONDITIONING	5.0	22.50
62.E1KS	ADD: ADJUST HEADLAMPS	3.0	13.50
62.E1KS	ALIGN FRONT FOG LAMPS	3.0	13.50
0741	L/F WING REPAIR	10 20.0*	90.00
1111	L/F WHEELHOUSE CPL REPAIR	40.0* 7	180.00
1112	R/F WHEELHOUSE CPL REPAIR	40.0* 7	180.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		17.70	177.0
Total of Labour			796.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	16.0
	FRONT UPPER BUMPER NEW PART PAINT K1G/P	30.0
	FRONT LOWER BUMPER NEW PART PAINT K1G/P	18.0
	R/F WING NEW PART PAINT K1R	5.0
	L/F WING REPAIR PAINT PLASTIC	11.0
	L/F WHEELHOUSE CPL SURFACE PAINT	6.0
	R/F WHEELHOUSE CPL SURFACE PAINT	6.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	45.41
0281	FRONT UPPER BUMPER NEW PART PAINT K1G/P	122.40
0285	FRONT LOWER BUMPER NEW PART PAINT K1G/P	64.80
0742	R/F WING NEW PART PAINT K1R	15.74
0741	L/F WING REPAIR PAINT PLASTIC	12.96

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900471
 Version: 1810
 Date calculated: 01/07/2019 9:47 AM

Full Report
 Registration: SKN1716H
 Printed: 01/07/2019 9:47 AM

Paint Material Per Part

Code	Description	Price SGD
1111	L/F WHEELHOUSE CPL SURFACE PAINT	12.45
1112	R/F WHEELHOUSE CPL SURFACE PAINT	12.45

Labour Cost - Paint

Factor	Hrs	WU	Price SGD
Time Paint		92.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
Total	10 WU/h	12.50	562.50

Material Cost - Paint

	Price SGD
New Part Painting	45.41
New Part Painting - Plastic K1R	15.74
New Part Painting - Plastic K1G/PUR	187.20
Repair Painting Plastic	12.96
Surface-/Blend Paint	24.90
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	327.51

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2001-01-01	Price SGD
0281	FRONT UPPER BUMPER	7401 SS		Bu	530.00 ✓
0285	FRONT LOWER BUMPER	7401 SV		CM	230.00 ✓
0291	L/F BUMPER COVER	7453 05		SVC	95.00 7X
0292	R/F BUMPER COVER	7453 06		SVC	95.00 7X
0304	FR LWR BUMPER GRILLE	7422 E2		Sn Redding	190.00 7X
0305	FRT BUMPER GRILLE	7422 V0		GRA 150 CM	160.00 7 ✓
0308	FR UPP BUMPER GRILLE	7422 H7		SVC	160.00 7X
0311	L/F BUMPER MOULDING	7453 07		Nu Nu	120.00 7X
0312	R/F BUMPER MOULDING	7453 08		110 Nu	120.00 7
0315	C-MEMBER FRONT PART	7104 LE		7	260.00 7XR
0319	FRONT BUMPER DAMPING	7422 C9		00 85	90.00 7 ✓
0325	FT IMPACT DAMPER SET	7422 93		00 80	85.00 7 ✓
0340	FRT UPP BUMPER CARR	7422 E7		CKA 150	105.00 7 ✓
0341	FRONT LOWER CARRIER	7422 E8		SVC	0.00 7X

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:

Assessment number: MC1900471

Version: 1810

Date calculated: 01/07/2019 9:47 AM

Full Report

Registration: SKN1716H

Printed: 01/07/2019 9:47 AM

Code	Description	Part Number	Supplier	Price SGD
0353	FRT LWR AIR DEFLECT	7013 GQ		95.00
0471	BONNET	7901 R2		730.00
0475	L/BONNET HINGE	7912 F8		50.00
0476	R/BONNET HINGE	7913 48		50.00
0481	BONNET INSULATION	7979 L2		130.00
0493	BONNET LOCK	7934 E6		45.00
0561	LEFT HEADLAMP ASSY	6208 P6		360.00
0562	RIGHT HEADLAMP ASSY	6206 P6		360.00
0637	L/F FOG LAMP	96 854 252 80		80.00
0638	R/F FOG LAMP	96 854 252 80		80.00
0742	R/F WING	7841 AF		300.00
0840	R/F WHEELHOUSE COVER	7136 JW		80.00
0920	FRONT PART	96 765 687 80		190.00
1435	WASHER RESERVOIR	6431 N2		80.00
4465	AIR CON CONDENSER	6455 GH		470.00
7753	L/RADIATOR AIR GUIDE	7104 LG		45.00
7754	R/RADIATOR AIR GUIDE	7104 LJ		45.00
7761	RADIATOR	1330 W2		330.00
7769	FRT AIR GRILLE	1308 V4		15.00
7773	LWR RADIATOR HOSE	1352 23		55.00
7776	UPPER RADIATOR HOSE	1343 LP		25.00
7790	ELECTRIC FAN	1253 K4		190.00
8739	INTERCOOLER	0384 N9		360.00
1000	INSULATOR CLIPX10	1		30.00
1001	FRT GRILLE CLIPX6	1		18.00
1002	SIDE RETAINERSX2	1		110.00
1003	BUMP CLIPX15	1		45.00
1004	BUMP TOW COVER RH	1		20.00
1005	FEND COWL CLIPX8	1		24.00
f: OEM Parts				Savings
n: Non-OEM Parts				Subtotal
u: Used parts				Addition(+10.00%)
Total				7,317.20

Extras

Code	Description	Price SGD
1006	NUMBER PLATE	35.00*
1007	RADIATOR COOLANT	30.00*
1008	AIR CON GAS	50.00*

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang
Mo Kio Ind. Park 2A
568047

Claim Reference:
 Assessment number: MC1900471
 Version: 1810
 Date calculated: 01/07/2019 9:47 AM

Full Report
 Registration: SKN1716H
 Printed: 01/07/2019 9:47 AM

Code	Description	Price SGD
1009	CHECK WIRING	40.00*
1010	RESET & DIAGNOSTIC	280.00*
	Total Extras	435.00

Final Calculation

	SGD	SGD
Parts	6,652.00	
Addition(+10.00%)	665.20	
Total Parts		7,317.20
Labour Time Base 10 WU/h		
Total 177.0 WU X 45.00 SGD/h	796.50	
Total of Labour		796.50
Total Of Extras		435.00
Paint Work Time Base 10 WU/h		
Labour Cost 125.0 WU X 45.00 SGD/h	562.50	
Material Cost	327.51	
Total Paint Including Material		890.01
Repair Cost Excludes GST		9,438.71
GST (+7.0%)		660.71
Repair Cost Included GST		10,099.42

Comments
 * - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
 Signature:
 Date:

4631.21

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC1900471

Date: 10 Jul 2019

Policy No: GA255220

Veh Reg No: SKN1716H

Make/Model: PEUGEOT 5008 1.6
TURBO (LUX)

Your Ref No: S9M01RGV

Claim Type: Own Damage

Accident Date: 21/06/2019

Estimate Repair Cost to Vehicle No :SKN1716H

Description	U/Price	Quantity	Cost SS	Amount SS
Supplementary Parts to Repair				
SPARE PARTS				
1 FRONT SUPPORT TOP GARNISH		1 PC CM	50.00	✓
2 FRONT FENDER SHIELD LH		1 PC CM	80.00	✓
			130.00	
	Add 10%		13.00	143.00

Amount Before Excess SS 143.00

GST Amount SS 10.01

Total Amount payable SS 153.01

The above vehicle was surveyed by KENNETH KONG -LKK on 24/06/2019

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MC1900471

Ref No: MF1900733

Date: 22 Nov 2019

Policy No: GA255220

Veh Reg No: SKN1716H

Make/Model: PEUGEOT 5008 1.6
TURBO (LUX)

Your Ref No: S9M01RGV

Claim Type: Own Damage

Accident Date: 21/06/2019

Chassis No:

Repair Cost to Vehicle No (For Finalization): SKN1716H

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET INNER LOCK		1 PC	45.00	
2 HEADLAMP LH & RH		2 PC	720.00	
3 FRONT GRILLE WITH CHROME MOULDING		1 PC	150.00	
4 FRONT BUMPER		1 PC	530.00	
5 FRONT BUMPER SIDE RETAINER LH		1 PC	50.00	
6 FRONT BUMPER SIDE CHROME MOULDING RH		1 PC	110.00	
7 FRONT BUMPER LOWER		1 PC	230.00	
8 FRONT BUMPER SPONGE		1 PC	85.00	
9 FRONT BUMPER TOP BEAM		1 PC	150.00	
10 FRONT BUMPER DAMPER		1 PC	80.00	
11 FRONT BUMPER LOWER COVER		1 PC	90.00	
12 FRONT FENDER COWLING RH		1 PC	80.00	
13 FRONT SUPPORT TOP GARNISH		1 PC	50.00	
14 FRONT FENDER SHIELD LH		1 PC	80.00	
			2,450.00	
	Add 10%		245.00	2,695.00
Special Nett				
15 NUMBER PLATE		1 PC	35.00	
16 RADIATOR COOLANT		1 PC	20.00	
				55.00
LABOUR				
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
18 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	50.00	
19 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL TO KNOCK & REPAIR FRT CHASSIS LH & RH, FRONT FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	360.00	
20 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT CHASSIS LH & RH, FRONT WHEELHOUSE PANEL LH & RH.		1 PC	760.38	
				1,190.38

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: S9M01RGV

Claim Type: Own Damage

Accident Date: 21/06/2019

Claim No: MC1900471

Ref No: MF1900733

Date: 22 Nov 2019

Policy No: GA255220

Veh Reg No: SKN1716H

Make/Model: PEUGEOT 5008 1.6
TURBO (LUX)

Chassis No:

DRAFT

Repair Cost to Vehicle No (For Finalization): SKN1716H

Amount Before Excess	S\$ 3,940.38
Less Excess	S\$ 400.00
Amount Before GST	S\$ 3,540.38
Add GST @ 7%	247.83
Total Amount payable	S\$ 3,788.21

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED EIGHTY EIGHT AND CENTS TWENTY ONE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 24/06/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

(P1)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 9745 9639

Arrange By

Driver

000000



Dept Direct: 6205 9616

Dept Direct: 6205 9611

Dept Direct: 6417 9733



Dept Direct: 6417 9734

Dept Direct: 6417 9735

Dept Direct: 6417 9736

Dept Direct: 6417 9737

Wiper blade: NWB (Nippon Wiper blade), Silcior (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201907-04256
DATE : 08/07/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SKN1716H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
0493	1. 7934 E6 5008	BONNET LOCK (05)	CC CC10-I-09AG	1	45.00	45.00
0562	2. 6206 P6 3008	HEADLAMP RH (10)	CC CC10-K-01C	1	360.00	360.00
0561	3. 6208 P6 3008	HEADLAMP LH (10)	CC CC10-I-04B	1	360.00	360.00
0701	4. 7401 SS 5008	FRT BUMPER (30)	CC CC10-A-03C	1	530.00	530.00
0704	5. 7401 SV 5008	FRT BUMPER SPOILER (10)	CC CC10-A-01D	1	230.00	230.00
0740	6. 7422 E7 5008	FRT BUMPER BRACKET UPPER	CC CC10-H-08B	1	150.00	150.00
0740	7. 7104 LK 5008	FRT SUPPORT TOP GARNISH	CC CC10-H-07A	1	50.00	50.00

CONTINUE NEXT PAGE

[P] 08/07/2019 13:44:49

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 08/07/2019 1:01:14PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AHLIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

WINDSCREEN GLASS
Dept Direct: 6417 8701 / 8745 8929



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 8702



Dept Direct: 6417 8734

Dept Direct: 6417 8735

Dept Direct: 6417 8736

Dept Direct: 6417 8737

Wiper blade: NWB (Nippon Wiper blades), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201907-04256
DATE : 08/07/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SKN1716H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
0319	8. 7422 C9 5008	FRT BUMPER ABSORBER	CC CC10-H-07A	1	85.00	85.00
0408	9. 7937 V0	BONNET LOCK CABLE return	CC CC10-J-08AH	1	50.00	50.00
0426	10. 7422 93 3008	FRT BUMPER BRACKET (SET)	CC CC10-J-080D	1	80.00	80.00
0453	11. 7013 EE 3008	ENG UNDER COVER CENTER	CC CC10-B-13	1	90.00	90.00

SUB-TOTAL : 2,030.00
ADD GST 7.00 % 142.10

E. & O.E

TOTAL AMOUNT SGD : 2,172.10

[P] 08/07/2019 13:44:49

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 08/07/2019 1:01:14PM

JAE Auto Pte. Ltd.

Sales Executive: HUA

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9781 / 9745 9938



Dept Direct: 6305 9610



Dept Direct: 6417 9784



Dept Direct: 6305 9611



Dept Direct: 6417 9790



Dept Direct: 6417 9795



Dept Direct: 6417 9790



Dept Direct: 6417 9790



Dept Direct: 6417 9790



Dept Direct: 6417 9790



Dept Direct: 6417 9790



Dept Direct: 6417 9790



Dept Direct: 6417 9790



Dept Direct: 6417 9790



Dept Direct: 6417 9790



Dept Direct: 6417 9790

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AHLIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL: 64831244 FAX: 64836170
ATTN: SIMON 96205405

TAX INVOICE : AR201907-04344
DATE : 08/07/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SKN1716H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
0312 1. 7453 08	HEADLAMP LOWER GARNISH RH	CC	1	110.00	110.00
5008		CC10-J-07AJ			

SUB-TOTAL : 110.00
ADD GST 7.00 % 7.70

E & O E

TOTAL AMOUNT SGD : 117.70

[P] 08/07/2019 14:18:56

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 08/07/2019 2:16:29PM

JAE Auto Pte. Ltd.

Sales Executive: HUA

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8781 / 6745 9000

Arrange By

Driver

MIC



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 8782



Dept Direct: 6417 8784

Dept Direct: 6417 8785

Dept Direct: 6417 8786

Dept Direct: 6417 8787

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL: 64831244 FAX: 64836170

ATTN: SIMON 96205405

TAX INVOICE : AR201907-04444
DATE : 08/07/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SKN1716H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
54P 1. 7136JT 5008	✓ FRT FENDER SHIELD LH (05)	CC CC10-G-11FRT	1	80.00	80.00
0840 2. 7136JW 5008	FRT FENDER SHIELD RH (05)	CC CC10-G-11FRT	1	80.00	80.00

SUB-TOTAL : 160.00
ADD GST 7.00 % 11.20

E. & O.E

TOTAL AMOUNT - SGD : 171.20

[P] 08/07/2019 15:24:56

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 08/07/2019 3:23:32PM

JAE Auto Pte. Ltd.

Sales Executive: HUA

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9781 / 6745 9929



Dept Direct: 6325 9618

Dept Direct: 6325 9611

Dept Direct: 6417 9782



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9786

Dept Direct: 6417 9790

Wiper blade: HWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AHLIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201907-04562
DATE : 08/07/2019
CUSTOMER ID : AHL008
VEH REG. NO. : SKN1716H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
03081 1. 7422 H7 5008	FRT BUMPER GUARD GRILLE (SUP-FXT-BLACK CORNELIE WITH CHROME FINISHER)	CC	1	150.00	150.00
1501 2. 7119 QC 5008	FRT BUMPER SIDE RETAINER LH	CC10-G-10A CC CC10-J-100D	1	50.00	50.00

SUB-TOTAL : 200.00
ADD GST 7.00 % 14.00

E & OE

TOTAL AMOUNT SGD : 214.00

[P] 08/07/2019 17:27:38

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 08/07/2019 3:11:12PM

JAE Auto Pte. Ltd.

Sales Executive: HUA

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang Mo Kio
Ind. Park 2A
568047

Insurer Reference:
Repairer Reference: MC1900471
Date calculated: 22/11/2019 1:44 PM

Full Report
Registration: SKN1716H
Printed: 22/11/2019 1:44 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	21/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	PEUGEOT
Model:	5008 (0A-0E)
Sub Model:	BASE MODEL
Model Sheet Number:	11 83 01
Registration:	SKN1716H
VIN number:	VF30E5FVABS335312
Odometer:	

Model Specs

FROM 09/2011	AUTO AIR CON	AIR CON 2 BLOWER	DEAD LOCKS
FRT/RR ELECT WINDOWS	ELEC CHILD LOCKING	ELECT FOLDING MIRROR	PHONE SYS BLUETOOTH
RADIO SYSTEM RD4 MP3	S-WHEEL RADIO CONT	RECEPTION IMPROVED	BI-TUNER
FOG LAMPS	CLOTH TRIM	HEIGHT ADJ PASS SEAT	7 SEATS
ACOUSTICS IMPROVED	RAIN SENSOR	TRIM TRAMONTANE	S/BELT W/WARNING DEV
MODULAR PASS SEAT	USB SOCKET	ENTRANCE LAMPS	WDW MOULDING CHROME
INNER MIRROR/SENSOR	BATTERY 12V 60AH	1.6 LTR 82/84KW	LEATH S-WHEEL 3 SPK
HOUSING PREHEATING	HEAD-UP DISPLAY	CRUISE CONTROL	TYRES 215/55 VR 16
DUST ATMOSPHERE	WHEELS 7J X 16 ALLOY	SPARE WHEEL	ENGINE FAN 140W
SPARE WHEEL WINCH	ALTERNATOR 150 AMP	CATALYST MORE 50PPM	HEAD AIRBAG
FRONT SIDE AIRBAG	PAINTED ROOF MLDG	PANORAMA SUNROOF	EMISSION STD EURO 5
STARTER MTR CLASS 3	PAINTED MOULDINGS	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
74.EBGA)	R + R FRONT BUMPER		8.0	36.00
74.E34A)	RENEW FRONT BUMPER		7.0	31.50
NO NUMBER	R + R FRONT UPPER BUMPER CARRIER		2.0	9.00
NO NUMBER	R + R FRONT LOWER BUMPER CARRIER		2.0	9.00
71.EDOA)	R + R LEFT FRONT WHEELHOUSE SHELL		2.0	9.00
71.EDOA)	R + R RIGHT FRONT WHEELHOUSE SHELL		2.0	9.00
62.E4KA)	R + R L/HEADLAMP		1.0	4.50
	(FRONT BUMPER REMOVED)			
62.E4KA)	R + R R/HEADLAMP		1.0	4.50
	(FRONT BUMPER REMOVED)			
62.E4HA)	RENEW BOTH HEADLAMPS (REMOVED)		1.0	4.50
NO NUMBER	R + R BONNET LOCK		1.0	4.50
64.E3UA)	R + R AIR CONDITIONING CONDENSER		2.0	9.00
74.EP4A)	R + R FRONT LOWER AIR GUIDE		2.0	9.00
74.E86A)	RENEW FRONT LOWER AIR GUIDE (REMOVED)		1.0	4.50
NO NUMBER	R + R LEFT FRONT IMPACT DAMPER		1.0	4.50
NO NUMBER	R + R RIGHT FRONT IMPACT DAMPER		1.0	4.50
13.E76A)	R + R RADIATOR		3.0	13.50
	(BUMPER REMOVED)			
NO NUMBER	R + R UPPER RADIATOR AIR GUIDE		1.0	4.50
13.E15S	DRAIN + REFILL COOLING SYSTEM		4.0	18.00
64.E3US	ADD: DRAIN + REFILL AIR CONDITIONING		5.0	22.50
62.E1KS	ADD: ADJUST HEADLAMPS		3.0	13.50
0471	BONNET REPAIR		20.0*	90.00
0741	L/F WING REPAIR		10.0*	45.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	8.00	80.0	360.00
Total of Labour			360.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRONT UPPER BUMPER NEW PART PAINT K1G/P	30.0
	FRONT LOWER BUMPER NEW PART PAINT K1G/P	18.0
	BONNET REPAIR PAINTING <50%	17.0
	L/F WING REPAIR PAINT PLASTIC	11.0

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT UPPER BUMPER NEW PART PAINT K1G/P	122.40
0285	FRONT LOWER BUMPER NEW PART PAINT K1G/P	64.80
0471	BONNET REPAIR PAINTING <50%	28.42
0741	L/F WING REPAIR PAINT PLASTIC	12.96

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		76.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.80	8.0	36.00
Total	10 WU/h	10.90 109.0	490.50

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1G/PUR	187.20
Repair Painting	28.42
Repair Painting Plastic	12.96
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	269.88

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2001-01-01
				Price SGD
0281	FRONT UPPER BUMPER	7401 SS		530.00
0285	FRONT LOWER BUMPER	7401 SV		230.00
0308	FR UPP BUMPER GRILLE	7422 H7		150.00
0312	R/F BUMPER MOULDING	7453 08		110.00
0319	FRONT BUMPER	7422 C9		85.00
	DAMPING			
0325	FT IMPACT DAMPER SET	7422 93		80.00
0340	FRT UPP BUMPER CARR	7422 E7		150.00
0353	FRT LWR AIR DEFLECT	7013 GQ		90.00
0493	BONNET LOCK	7934 E6		45.00
0561	LEFT HEADLAMP ASSY	6208 P6		360.00

Code	Description	Part Number	Supplier	Price SGD
0562	RIGHT HEADLAMP ASSY	6206 P6		360.00
0839	L/F WHEELHOUSE COVER	7136 JT		80.00
0840	R/F WHEELHOUSE COVER	7136 JW		80.00
7751	UPPER AIR GUIDE	7104 LK		50.00
1002	SIDE RETAINERS LH	1		50.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	2,450.00
Addition(+10.00%)	245.00
Total	2,695.00

Extras

Code	Description	Price SGD
1006	NUMBER PLATE	35.00*
1007	RADIATOR COOLANT	20.00*
1008	AIR CON GAS	50.00*
1009	CHECK WIRING	20.00*
	Total Extras	125.00

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	2,450.00	
Total Parts	245.00	2,695.00
Labour Time Base 10 WU/h		
Total 80.0 WU X 45.00 SGD/h	360.00	
Total of Labour		360.00
Total Of Extras		125.00
Paint Work Time Base 10 WU/h		
Labour Cost 109.0 WU X 45.00 SGD/h	490.50	
Material Cost	269.88	
Total Paint Including Material		760.38
Repair Cost Excludes GST		3,940.38
GST (+7.0%)		275.83
Repair Cost Included GST		4,216.21

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.