

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 26/12/2018
 TP Veh Reg No: SDJ3663S

Estimate No: ES1991788/YISHUN
 Date: 24 Jul 2019
 Policy No: 5099960554
 Veh Reg No: SLX8325S
 Make/Model: HONDA SHUTTLE 1.5G CVT
 Chassis No: GK81201778
 Engine No: L15B5462074
 Reg. Date: 12/04/2018

Estimate Repair Cost to Vehicle No :SLX8325S

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	1,050.80	1 PC	1,050.80	✓
2 FRONT BUMPER REINFORCEMENT	297.00	1 PC	297.00	✓
3 FRONT BUMPER LH RETAINER	37.10	1 PC	37.10	✓
4 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
5 HEADLAMP LH	1,280.00	1 PC	1,280.00	?
6 LH HEADLAMP LOWER GARNISH	39.80	1 PC	39.80	?
			2,725.70	
	Less 20%		545.14	2,180.56
Labour				
7 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMP, KNOCK & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	480.00	1 LA	480.00	300
8 PUTTY & RESPRAY ON FRT BUMPER, SUPPORT PANEL, FRT BUMPER REINFORCEMENT	480.00	1 LA	480.00	400
			960.00	960.00
			Total	S\$ 3,140.56
			Add GST @ 7%	219.84
			Total Amount Payable	S\$ 3,360.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE