

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SGZ 3217C**
 Model : Honda Jazz
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 903.60	\$ 830.60 903.60	DDV
2	Tailgate logo	1	\$ 48.10	\$ 22.00 48.10	} NEC
3	Tailgate emblem 'Jazz'	1	\$ 42.80	\$ 38.00 42.80	
4	Tailgate inner lock	1	\$ 288.60	\$ 168.50 288.60	BTv
5	Tailgate striker	1	\$ 48.90	\$ 48.90 48.90	BTv
6	Tailgate weatherstrip	1	\$ 165.60	\$ 152.40 165.60	CUtV
7	Tailgate inner trim board	1	\$ 296.30	\$ 194.40 296.30	BRV
8	Tailgate inner handle	1	\$ 36.00	\$ 36.00 36.00	BRV
9	Tailgate outer garnish	1	\$ 118.50	\$ 118.50 118.50	BRV
10	Tailgate no plate lamp	2	\$ 88.50	\$ 177.00 177.00	BRV
11	Tailgate solenoid switch	1	\$ 235.00	\$ 235.00 235.00	NNX
12	Tailgate windscreen	1	\$ 980.00	\$ 675.50 980.00	BRV
13	Tailgate windscreen moulding	1	\$ 90.50	\$ 90.50 90.50	NEC
14	Tailgate windscreen wiper arm	1	\$ 93.20	\$ 93.20 93.20	NNX
15	Tailgate windscreen wiper motor	1	\$ 269.60	\$ 269.60 269.60	NNX
16	Tailgate windscreen wiper garnish	1	\$ 45.50	\$ 45.50 45.50	MIS
17	Tailgate third brake lamp	1	\$ 268.70	\$ 268.70 268.70	NNX
18	Rear bumper	1	\$ 680.90	\$ 520.80 680.90	BRV
19	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NEC
20	Rear bumper side retainer	2	\$ 48.60	\$ 97.20 97.20	NEC
21	Rear bumper bracket	2	\$ 39.60	\$ 79.20 79.20	BTv
22	Rear end panel	1	\$ 525.60	\$ 365.30 525.60	DDV
23	Rear end panel top garnish	1	\$ 124.80	\$ 124.80 124.80	DLV
24	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00	NEC
25	Spare tyre panel	1	\$ 881.70	\$ 781.60 881.70	DISV
26	Spare tyre panel top board	1	\$ 250.00	\$ 238.50 250.00	DISV
27	Spare tyre panel insulator	1	\$ 188.60	\$ 150.00 188.60	NEC
28	Taillamp rh	1	\$ 386.00	\$ 386.00 386.00	BRV
29	Taillamp clips rh	1	\$ 50.00	\$ 30.00 50.00	NEC
30	Taillamp lower bracket rh	1	\$ 48.40	\$ 37.00 48.40	BRV
31	Taillamp base panel rh	1	\$ 138.00	\$ 138.00 138.00	BTv
32	Taillamp lh	1	\$ 386.00	\$ 386.00 386.00	BRV
33	Taillamp clips lh	1	\$ 50.00	\$ 30.00 50.00	NEC
34	Taillamp bracket lh	1	\$ 48.40	\$ 37.00 48.40	BRV
35	Taillamp panel lh	1	\$ 138.00	\$ 138.00 138.00	DDV
36	Rear fender rh	1	\$ 648.40	\$ 648.40 648.40	DDV
37	Rear fender inner trim rh	1	\$ 350.00	\$ 350.00 350.00	BRV
38	Rear fender inner cowling	1	\$ 115.90	\$ 115.90 115.90	NNX
39	Rear fender quarter glass moulding	1	\$ 88.00	\$ 88.00 88.00	NEC
40	Rear fender lh	1	\$ 648.40	\$ 648.40 648.40	NNX
41	Rear fender inner trim Lh	1	\$ 350.00	\$ 350.00 350.00	BRV
42	Exhaust pipe	1	\$ 728.20	\$ 552.80 728.20	BTv
43	Exhaust pipe mounting	2	\$ 38.20	\$ 76.40 76.40	NEC

44	Exhaust pipe heat shield	1	\$	156.00	\$ 60.00	156.00	DD✓
45	Rear door lock assy rh	1	\$	268.90	\$	✓ 268.90	JAM✓
				Parts Sub Total :	\$ 8591.70	11,710.90	
				20% Discount :	\$ 1718.34	2,342.18	
				PARTS TOTAL :	\$ 6873.36	9,368.72	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$	60.00	\$ -60.00 NNX
2	Tailgate inner trim board clips	1	\$	50.00	\$ 30.00 50.00
3	Tailgate outer garnish clips	1	\$	50.00	\$ 30.00 50.00 } NEC✓
4	Tailgate windscreen clips	1	\$	50.00	\$ 30.00 50.00
5	Tailgate primer and cleaner	1	\$	80.00	\$ 80.00 NNX
6	Tailgate windscreen sealant	1	\$	100.00	\$ 60.00 100.00 } NEC✓
7	Rear no plate with cover	1	\$	80.00	\$ 50.00 80.00 ✓ BR
8	Rear bumper reverse sensor	2	\$	200.00	\$ 200.00 400.00 ✓ UT
9	Rear end panel sealant	1	\$	100.00	\$ 60.00 100.00 } NEC✓
10	Taillamp inner seal	2	\$	80.00	\$ 160.00 NNX
11	Rear fender inner trim clips rh	1	\$	50.00	\$ 30.00 50.00
12	Rear fender inner trim clips Lh	1	\$	50.00	\$ 30.00 50.00 } NEC
13	Rear fender inner cowlings clips rh	1	\$	50.00	\$ 30.00 50.00
14	Rear fender sealant rh	1	\$	100.00	\$ 60.00 200.00 } NEC✓
15	Spare tyre panel sealant	1	\$	100.00	\$ 60.00 100.00
16	Rear fender quarter glass clips rh	1	\$	50.00	\$ 30.00 100.00
				SPECIAL NETT TOTAL :	\$ 700.00 1,680.00

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 50.00	100.00 ✓
2	R&R rear windscreen	\$ 120.00	250.00 ✓
3	R&R upholstery	\$ 100.00	180.00 ✓
4	R&R exhaust pipe assy	\$ 120.00	250.00 ✓
5	R&R fuel tank	\$	100.00 NNX
6	R&R rear fender quarter glass Lh and RH	\$ 60.00	150.00 ✓
7	R&R reverse sensor	\$ 60.00	80.00 ✓
8	Mount bench work	\$ 100.00	350.00 ✓
9	Rear Chasis alignment	\$	300.00 NNX
10	Disconnect wire harness to facilitate repair, reconnect and check function	\$ 50.00	80.00 ✓
11	Panel beat	\$ 1200.00	1,800.00 ✓
12	Rust proofing	\$ 60.00	150.00 ✓
13	Spray painting	\$ 1000.00	1,800.00 ✓
		LABOUR TOTAL :	\$ 2920.00 5,590.00

PARTS TOTAL : \$ 9,368.72
 SPECIAL NETT TOTAL : \$ 1,680.00
 LABOUR TOTAL : \$ 5,590.00
GRAND TOTAL : \$ 16,638.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey on
25/6/19

Lump Sum repairs

Repair days 9

Parts 6873.36

SN 700.00

Labour 2920.00

10493.36

@ 20% 2098.67

8394.69

L/S 8,350 1/2