

SM SPRAY PAINTING

ON BEHALF OF OWNER :

POLICY PARTICULARS:-THIRD PARTY CLAIM

INSURED VEH: **GBH1746J** EXCESS:
POLICY NO: **5098532869** COVERAGE:
CLAIMING AGAINST: **SHD4103U**
INSURED UNDER: **NTUC INCOME INSURANCE CO-OPERATIVE LTD**

VEHICLE PARTICULARS & CONDITION

MAKE& MODEL: **MERCEDES BENZ**
ENGINE NO: **K9KE628D399983**
CHASSIS NO: **WDF4156052U222123**
ODOMETER:
ENGINE CC:
YEAR OF REG: **2018**
COLOUR: **SILVER**
PARF/COE REBATE: **\$32039.00**

CONDITIONS OF TYRES

| SIZE | MAKE |
|----------------|------|
| R/H FRONT TYRE | |
| L/H FRONT TYRE | |
| R/H REAR TYRE | |
| L/H REAR TYRE | |

DESCRIPTION OF DAMAGES

FRONT /REAR PORTION

GENERAL INFORMATION

ACCIDENT DATE : **15/06/2019**
SURVEY HELD AT : **YEW TEE AUTOMOBILE TECH PTE LTD**
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S417800

REMARKS

A: x

ESTIMATE DAYS OF REPAIR

ESTIMATE NORMAL PERIOD FOR REPAIR: DAYS

SM SPRAY PAINTING

| <u>QTY</u> | <u>DESCRIPTION OF PARTS</u> | <u>PRICING</u> |
|------------|--------------------------------|----------------|
| 1 | FRONT BUMPER | \$1,380 |
| 1 | FRONT AIR GRILLE OUTER GARNISH | \$158 |
| 1 | FRONT GRILLE | \$945 |
| 1 | FRONT CENTRE LOWER GRILLE | \$66 |
| 1 | FRONT HEADLAMP LH | \$430 |
| 1 | FRONT HEADLAMP RH | \$430 |
| 1 | FRONT BUMPER SIDE RETAINER LH | \$35 |
| 1 | FRONT BUMPER SIDE RETAINER LH | \$35 |
| 1 | AIR CON CONDENSER | \$665 |
| 1 | RADIATOR | \$1,810 |
| 1 | FRONT SUPPORT PANEL | \$725 |
| 1 | FRONT CARPLATE | \$35 |
| 1 | FRONT CARPLATE GARNISH | \$40 |
| 1 | REAR BUMPER | \$1,170 |
| 1 | REAR BUMPER PAD LH | \$368 |
| 1 | REAR BUMPER PROTECTOR CENTRE | \$458 |
| 1 | REAR BUMPER REFLECTOR LH | \$120 |
| 1 | REAR BUMPER SIDE RETAINER LH | \$60 |
| 1 | REAR BUMPER SIDE RETAINER RH | \$60 |
| 2 | REAR BUMPER REVERSE SENSOR | \$400 |
| 1 | REAR FENDER LH | \$2,510 |
| 1 | REAR FENDER INNER SHIELD LH | \$310 |
| 1 | REAR DOOR LH | \$1,545 |
| 1 | REAR DOOR HINGE UPPER LH | \$285 |
| 1 | REAR DOOR HINGE BOTTOM LH | \$285 |
| 1 | REAR DOOR LOCK LH | \$480 |
| 1 | REAR DOOR LOCK CATCH LH | \$108 |
| 1 | REAR DOOR INNER BOARD LH | \$130 |
| 1 | REAR DOOR RUBBER | \$245 |
| 1 | REAR DOOR VERTICAL RUBBER LH | \$115 |
| 1 | REAR WIPER | \$111 |
| 1 | REAR WIPER BLADE | \$48 |
| 1 | REAR WIPER MOTOR | \$490 |
| 1 | REAR DOOR HANDLE | \$148 |
| 1 | REAR TAILLAMP LH | \$325 |
| 1 | REAR "MERC" LOGO EMBLEM | \$52 |
| 1 | REAR "CITAN" LOGO EMBLEM | \$65 |
| 1 | REAR NUMBER PLATE | \$35 |
| 2 | REAR NUMBER PLATE LAMP | \$45 |
| 1 | REAR NUMBER PLATE GARNISH | \$250 |
| 1 | REAR REVERSE CAMERA | \$500 |
| 1 | REAR END PANEL | \$685 |

| | |
|-------------|-----------------|
| List item : | \$18,157 |
| Less 5% : | \$ 907.84 |
| Sub Total: | <u>\$17,249</u> |

| | | |
|----|-------------------------------|------|
| 10 | FRONT BUMPER CLIP | \$10 |
| 10 | REAR BUMPER CLIP | \$9 |
| 1 | REAR FENDER INNER SHIELD CLIP | \$9 |

S/N: \$28

SM SPRAY PAINTING

| QTY | DESCRIPTION OF PARTS | PRICING |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|
| <u>LABOUR</u> | | |
| | TO DISCONNECT AND RECONNECT , CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKET,REPLACE DAMAGE PARTS. | \$30 |
| | TO CARRY-OUT BODY CAVITY PRESERVATION. | \$100 |
| | TO REMOVE AND REFIT REAR BUMPER SENSOR . | \$80 |
| | TO REMOVE & REPLACE THE ABOVE DAMAGE PARTS , STRAIGHTEN , KNOCK OUT ,REALIGN&REPAIR INCULDING CUT & WELD BODY PANELS. TO RE-AJUST TO THE ORIGINAL POSITION USING POWER TOOLS. | \$800 |
| | TO SPRAY PAINTINGON THE REPLACED& REPAIR PARTS, PREPARE SPRAY SUCH AS MARKING TAPE THE UNAFFECTED AREAS WITH PAPERS, CLEANING & SANDING OF SURFACE, FINAL POLISING & WAXING ARE ALSO AVAILABLE . | \$850 |
| | LABOUR : | <u>\$1,860</u> |
| | TOTAL: | \$19,137 |
| | 7% GST : | <u>\$1,340</u> |
| | SUB TOTAL : | <u>\$20,477</u> |

**IF THE DAMAGE IS BEYOND THE MARKET VALUE,
KINDLY COUNTER OFFER THE ECONOMY REPAIR VALUE
OF THE VEHICLE FOR US TO CONSIDER.**