

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

LKR/Kalwin

Like 4/2um

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	21/06/2019
Vehicle Reg. No.:	SHC8744Z	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	21/01/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDFU579591	Chassis No:	KMHLB41UMGU083323
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	3,461.86
Labour	11.00
Paintwork Labour	1,530.00
Towing	0.00
	0.00
Gross Total (\$\$)	5,002.86
+ GST 7.00% (\$\$)	350.20
Nett Amount (\$\$)	5,353.06

This claim is handled by: LIM KWOK ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 21 Jun 2019)
Parts: 143 **HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC8744Z/21/06/2019 18:43
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID ✕	20.00	0.00	*2,174.90 FL
2	1		*BOOTLID RUBBER ✕	20.00	0.00	*96.50 FL
3	1		*BOOTLID LOCK UPPER ✕	20.00	0.00	*102.60 FL
4	1		*BOOTLID LOCK LOWER ✕	20.00	0.00	*31.70 FL
5	1		*BOOTLID H EMBLEM ✕	20.00	0.00	*27.90 FL
6	1		*BOOTLID CRDI PLATE ✕	20.00	0.00	*28.70 FL
7	1		*BOOTLID i40 EMBLEM ✕	20.00	0.00	*28.70 FL
8	1		*REAR BUMPER ✓	20.00	0.00	*553.00 FL
9	1		*REAR BUMPER REINFORCEMENT ?	20.00	0.00	*428.40 FL
10	1		*REAR BUMPER REINFORCEMENT BRACKET STAY RH ?	20.00	0.00	*80.30 FL
11	1		*REAR BUMPER REINFORCEMENT BRACKET STAY LH ?	20.00	0.00	*80.30 FL
12	10		*REAR BUMPER CLIPS ✓	20.00	0.00	*22.00 FL
13	1		*REAR BUMPER BRACKET SIDE RH ?	20.00	0.00	*35.60 FL
14	1		*REAR BUMPER BRACKET SIDE LH ?	20.00	0.00	*35.60 FL
15	1		*REAR BUMPER SPONGE ?	20.00	0.00	*103.50 FL
16	1		*REAR BUMPER UNDER COVER ✓	20.00	0.00	*228.00 FL
17	1		*REAR BUMPER REVERSE SENSOR ✓	0.00	0.00	*135.70 F
18	1		*REAR BUMPER RUBBER MAT ✓	0.00	0.00	*50.00 F
19	1		*BOOTLID COMFORT LOGO ✕	0.00	0.00	*20.00 F
20	1		*BOOTLID TEL NO. STICKER ✕	0.00	0.00	*10.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,273.40
- List Item Discount on L Items (S\$)	811.54
Total Parts (S\$)	3,461.86

ComfortDelGro Engineering Pte Ltd/SHC8744Z/21/06/2019 18:43. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	2.00 850.00
2	SPRAY PAINTING CHARGE	New	2.00 500.00
3	WIRING CHARGE	New	X 50.00
4	TUFF KOTE	New	X 50.00
5	REMOVE/REFIX REVERSE SENSOR	New	3.00 80.00
Gross Labour Cost (\$\$)			1,530.00

ComfortDelGro Engineering Pte Ltd/SHC8744Z/21/06/2019 18:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Kalvin LK/14

//

24/6/19

11106

24/1

4/5

After Rep'r p Lts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: