## COMFORTDELGRO ENGINEERING PTE LTD **REPAIR ESTIMATE\***

. VEHICLE NO: SHD 3787C

MAKE

MODEL : HYUNDAI IONIO DATE 22/6/2019 10:34

Qty	: HYUNDAI IONIQ  Parts Description/ Labour		Unit Price		Amount		
	Rear Bumper	Type			\$	459.40	
	Rear Bumper Reinforcement				\$	294.80	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$	138.10	\$	276.20	
	Rear Bumper Centre Moulding Assy				\$	451.25	
	Rear Bumper Lower Centre Moulding Assy X				\$	47.50	
	Rear Bumper Cover Clips				\$	22.00	
	SUB TOTAL				\$	1,551.15	
	LESS 20%				\$	310.23	
	DISCOUNTED TOTAL				\$	1,240.92	
	Rear No.Plate				\$	25.00	
	Rear No.Plate Trim Cover				\$	30.00	
	Rear Bumper Reserve Sensor X				\$	135.70	
	Rear Bumper Rubber Mat				\$	50.00	
					\$	240.70	
				1			
		ultants henc	e notify				
	Labour Charge Panel Beating Spray Painting Charge Wiring Charge	of the following	painting resurvey	basis	0	250.00	
	Panel Beating Spray Painting Charge	16(01c. 3 0311/2	COUNTY OF STATE	150	0	350.00	
	Wining Change	Jan Sugar On	s is aloned	eled a A Japano	3	250.00	
	1.15	2000	1 " P. II. " I'EN		\$	50.00 120.00	
	Remove/Refix Reverse Sensor	gal mostly com	Sionar,		0	12000	
	TOTAL LABOUR	history to item	Sulfurat		6	770.00	
	/ IIII	Medged D			\$	770.00	
	Kabr (CHO)	cknow.			\$	2,251.62	
	ESTIMATE TOTAL	Oate:			Þ	2,251.02	
	TOTAL LABOUR  ESTIMATE TOTAL  24/6/19  1/3. 4  PIP Alle Repropertion of the						
	16						
	010						
	I'l All Pear in	16					
	17/W 17 P						

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.